

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8029 Technical Specification Involved Table 3.1.A

Reported Under Technical Specification 6.7.2.b(1)

Date of Occurrence 7/22/80 Time of Occurrence 1400 Unit 2

Identification and Description of Occurrence:

Reactor low water level switch LIS-3-203C operated 1.48 in H₂O below the T.S. limits when tested in accordance with SI 4.1.A-7

Conditions Prior to Occurrence:

Unit 1 at 96% MWe

Unit 2 at 97% MWe

Unit 3 at 98% MWe

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Setpoint drift

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

The switch was inspected, recalibrated and functionally tested for operability. The switch will be replaced with an analog system in accordance with Design Change Request 1398.

Failure Data:

260/804, 259/7824, 259/741 and 259/7333.

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 



2