

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ALBRF2 | 200-000000-00 | 341111 | 4 | 5

CON'T
01 | REPORT SOURCE | L605000260 | 7081580 | 8090880 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | With the unit at 93 percent power in steady state operation, it was found during TT-
03 | 36A-that there was an indicated leak on 2B RHR heat exchanger. Redundant systems
04 | LPCI, 1 pump in each RHR loop, and cross-connect capabilities were available. There
05 | was no danger to the health or safety of the public and no significant resulting chain,
06 | of events. See Technical Specification 3.5.B.5. Previous occurrence reported on LER
07 | BFRO-50-260/80034.

09 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE
CF | X | Z | HTEXCH | X | Z

17 | LER/RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.
80 | - | 033 | | 03 | L | 0

ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
Z | X | Z | Z | 0000 | Y | Y | N | P160

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

17 | The probable cause is a leaking gasket on the RHR heat exchanger due to loose
11 | flange nuts resulting from thermal cycling and vibration. Corrective action has not
12 | been completed. Several possible modifications are being evaluated to correct the
13 | loosening of the flange nuts. Interim corrective action consists of increased torque
14 | value on nuts.

15 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION
E | 093 | NA | B | Routine test

16 | ACTIVITY CONTENT RELEASED OF RELEASE | AMOUNT OF ACTIVITY | LOCATION OF RELEASE
Z | Z | NA | NA


17 | PERSONNEL EXPOSURES NUMBER | TYPE | DESCRIPTION
000 | Z | NA

18 | PERSONNEL INJURIES NUMBER | DESCRIPTION
000 | NA

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | DESCRIPTION
Z | NA

20 | PUBLICITY ISSUED | DESCRIPTION
Y | Press release

NAME OF PREPARER: 8009160440 PHONE: _____



LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8033 Technical Specification Involved 3.5.B.5

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 8/15/80 Time of Occurrence 3:35 p.m. Unit 2

Identification and Description of Occurrence:

During routine test TI-36A it was found that there was an indicated leak on RHR heat exchanger 2B.

Conditions Prior to Occurrence:

Unit 1 - 96% steady state power

Unit 2 - 93% steady state power

Unit 3 - 97% steady state power

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

LPCI, 1 pump in each RHR loop, and cross connect capabilities were available.

Apparent Cause of Occurrence:

The heat exchanger has not been disassembled. Probable cause is a leaking flange gasket due to loose flange nuts caused by thermal cycling and vibration.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no damage to plant or equipment, and no resulting significant chain of events.

Corrective Action:

Several modifications are being evaluated to prevent the loosening of the nuts. A DCR has been drafted to install locking tabs for these nuts. RHRSW monitoring will detect any release of activity. Routine inspection will detect heat exchanger problems. Interim corrective action consists of increased torque value on nuts.

Failure Data: LER BFRO-50-260/80034; BFRO-50-259/80043;
BFRO- 50-259/78023.

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

