

Handwritten marks or scribbles in the top right corner.



LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8044 Technical Specification Involved Table 3.2.A

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 10/12/80 Time of Occurrence 0900 Unit 2

Identification and Description of Occurrence:

While performing S.I. 4.2.A-16 "Calibration Reactor Building Isolation and/or Logic Timers" (refueling zone and reactor zone) units 1, 2, and 3, the refueling zone inboard isolation relay R3A did not time out in 60 ± 3 cycles. There was no fuel handling activity during this time.

Conditions Prior to Occurrence:

Unit 1 @ 94%

Unit 2 @ 0% refueling outage

Unit 3 @ 98%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

NA

Apparent Cause of Occurrence:

Cause of event, was relay failure.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

The timer was replaced and calibrated per SI 4.2.A-16.

Failure Data:

BFRO-50-259/80007

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

