

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ALBRF2200-00000-00341111145

CON'T
01 REPORT SOURCE L605000260710318081128809

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 Drywell pressure transmitter 2-PT-64-67 was not qualified for radiation environment
03 following LOCA as defined in IE Bulletin 79-01B (T.S. 3.2.F). Notification received
04 10/31/80 at 4 p.m. There was no effect on the health or safety of the public.
05 Redundant transmitter 2-PT-64-50 was operable and qualified. Previous events: None
06
07
08

09 SYSTEM CODE IC11 CAUSE CODE B12 CAUSE SUBCODE A13 COMPONENT CODE INSTRU14 COMP. SUBCODE T15 VALVE SUBCODE Z16
17 LER/RO REPORT NUMBER 80 EVENT YEAR 048 SEQUENTIAL REPORT NO. 03 OCCURRENCE CODE L REPORT TYPE 0 REVISION NO.
ACTION TAKEN C18 FUTURE ACTION Z19 EFFECT ON PLANT Z20 SHUTDOWN METHOD Z21 HOURS 0000 ATTACHMENT SUBMITTED Y23 NPRD-4 FORM SUB. N24 PRIME COMP. SUPPLIER N25 COMPONENT MANUFACTURER G080

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Transmitter GEMAC Model 556 was not qualified to meet the environmental conditions
11 of a LOCA. The transmitter was replaced on 11/9/80 with a Foxboro Model E11GM.
12
13
14

15 FACILITY STATUS H28 % POWER 00029 OTHER STATUS NA30 METHOD OF DISCOVERY D31 DISCOVERY DESCRIPTION Design Review32
16 ACTIVITY RELEASED Z33 CONTENT OF RELEASE Z34 AMOUNT OF ACTIVITY NA35 LOCATION OF RELEASE NA36
17 PERSONNEL EXPOSURES NUMBER 00037 TYPE Z38 DESCRIPTION NA39
18 PERSONNEL INJURIES NUMBER 00040 DESCRIPTION NA41
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z42 DESCRIPTION NA43
20 PUBLICITY ISSUED N44 DESCRIPTION NA45

NAME OF PREPARER _____

PHONE: _____

8013820 421

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8048 Technical Specification Involved 3.2.F
Reported Under Technical Specification IE Bulletin 79-01B
Date of Occurrence 10/31/80 Time of Occurrence 1600 Unit 2

Identification and Description of Occurrence:

Pressure transmitter 2-PT-64-67 was not qualified for radiation environment following LOCA as defined in IE Bulletin 79-01B.

Conditions Prior to Occurrence:

Unit 1 at 98% power.

Unit 2 refueling

Unit 3 96% power

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Transmitter not qualified to meet LOCA environmental conditions as defined by NRC Bulletin 79-01B.

Analysis of Occurrence:

There has been no effect on the public health or safety, no release of activity, no damage to plant equipment and no significant chain of events.

Corrective Action:

Replaced the transmitter with a qualified Foxboro Model E11GM.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

