

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CONT  
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 0 | 7 | 1 | 0 | 3 | 1 | 8 | 0 | 8 | 1 | 1 | 2 | 8 | 8 | 0 | 9

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Drywell pressure transmitter 2-PT-64-67 was not qualified for radiation environment  
0 3 | following LOCA as defined in IE Bulletin 79-01B (T.S. 3.2.F). Notification received  
0 4 | 10/31/80 at 4 p.m. There was no effect on the health or safety of the public.  
0 5 | Redundant transmitter 2-PT-64-50 was operable and qualified. Previous events: None  
0 6 |  
0 7 |  
0 8 |

0 9 | SYSTEM CODE | I | C | 11 | CAUSE CODE | B | 12 | CAUSE SUBCODE | A | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | T | 15 | VALVE SUBCODE | Z | 16 |

17 | LER/RO REPORT NUMBER | 8 | 0 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 4 | 8 | 24 | 26 | OCCURRENCE CODE | 0 | 3 | 28 | 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32 |

ACTION TAKEN | C | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | 40 | ATTACHMENT SUBMITTED | Y | 23 | 41 | NPD-4 FORM SUB. | N | 24 | 42 | PRIME COMP. SUPPLIER | N | 25 | 43 | COMPONENT MANUFACTURER | G | 0 | 8 | 0 | 44 |

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Transmitter GEMAC Model 556 was not qualified to meet the environmental conditions  
1 1 | of a LOCA. The transmitter was replaced on 11/9/80 with a Foxboro Model E11GM.  
1 2 |  
1 3 |  
1 4 |

1 5 | FACILITY STATUS | H | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | D | 31 | DISCOVERY DESCRIPTION | Design Review | 32 |

1 6 | ACTIVITY RELEASED | Z | 33 | CONTENT OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36 |

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39 |


1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41 |

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43 |

2 0 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45 | NRC USE ONLY

NAME OF PREPARER \_\_\_\_\_ PHONE: \_\_\_\_\_

8013030 421



LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8048 Technical Specification Involved 3.2.F  
Reported Under Technical Specification IE Bulletin 79-01B  
Date of Occurrence 10/31/80 Time of Occurrence 1600 Unit 2

Identification and Description of Occurrence:

Pressure transmitter 2-PT-64-67 was not qualified for radiation environment following LOCA as defined in IE Bulletin 79-01B.

Conditions Prior to Occurrence:

Unit 1 at 98% power.

Unit 2 refueling

Unit 3 96% power

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Transmitter not qualified to meet LOCA environmental conditions as defined by NRC Bulletin 79-01B.

Analysis of Occurrence:

There has been no effect on the public health or safety, no release of activity, no damage to plant equipment and no significant chain of events.

Corrective Action:

Replaced the transmitter with a qualified Foxboro Model E11GM.

Failure Data:

None

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 

