

LICENSEE EVENT REPORT

CONTROL BLOCK:         1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 0 | 7 | 1 | 1 | 1 | 5 | 8 | 0 | 8 | 1 | 2 | 1 | 2 | 8 | 0 | 9  
7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  
0 2 | During a refueling outage while performing SI 4.1.A-8, the scram discharge volume  
0 3 | tank three gallon level alarm switch 2-LS-85-45F was found to be stuck and would not  
0 4 | operate. Reported under IE Bulletin 80-14. Rod block and scram switches were  
0 5 | operable and the UT monitors on the headers were operable. There was no effect  
0 6 | on the health and safety of the public. Previous events reported under IE Bulletin  
0 7 | 80-14.

0 9 | I | D | 11 | E | 12 | E | 13 | I | N | S | T | R | U | 14 | S | 15 | Z | 16  
7 8 SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 14 COMPONENT CODE 15 16 VALVE SUBCODE

17 | LER/RO REPORT NUMBER | 8 | 0 | 21 22 | | | 23 24 | 0 | 5 | 2 | 76 27 | | | 28 29 | 0 | 3 | 30 31 | | | 32  
18 | X | 19 | Z | 20 | Z | 21 | 22 | 0 | 0 | 0 | 0 | 23 | Y | 24 | Y | 25 | L | 26 | R | 2 | 9 | 0 | 27  
33 34 35 36 37 38 39 40 41 42 43 44 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  
1 0 | The Robert Shaw Model SL-305-EI-X switch float was stuck. Switch was back flushed  
1 1 | with water and proper operation verified. The switch will be replaced by the  
1 2 | analog system per DCR 1398.  
1 3 |  
1 4 |

1 5 | H | 28 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Surveillance Testing | 32  
7 8 9 FACILITY STATUS 10 11 % POWER 12 13 OTHER STATUS 30 31 METHOD OF DISCOVERY 32 DISCOVERY DESCRIPTION 32

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36  
7 8 9 ACTIVITY CONTENT 33 34 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39  
7 8 9 PERSONNEL EXPOSURES NUMBER 11 12 TYPE 13 DESCRIPTION 39

1 8 | 0 | 0 | 0 | 40 | NA | 41  
7 8 9 PERSONNEL INJURIES NUMBER 11 12 DESCRIPTION 41

1 9 | Z | 42 | NA | 43  
7 8 9 LOSS OF OR DAMAGE TO FACILITY TYPE 11 12 DESCRIPTION 43

2 0 | N | 44 | NA | 45  
7 8 9 PUBLICITY ISSUED DESCRIPTION 45

NAME OF PREPARER \_\_\_\_\_

PHONE: \_\_\_\_\_

Handwritten scribbles or marks in the top right corner.

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260/ 8052 Technical Specification Involved 80-14

Reported Under Technical Specification NRC IE Bulletin 80-14

Date of Occurrence 11/15/80 Time of Occurrence 1300 Unit 2

Identification and Description of Occurrence:

Scram discharge volume tank three gallon level alarm switch 2-LS-85-45F was found to be stuck and would not operate during the performance of SI 4.1.A-8.

Conditions Prior to Occurrence:

Unit 1 at 98% power

Unit 2 refueling

Unit 3 at 86% power

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

No technical specification on the level alarm switches. Report is made under IE Bulletin 80-14.

Apparent Cause of Occurrence:

Float on level switch stuck.

Analysis of Occurrence:

There was no damage to the plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

Back flushed the switch with water and functionally checked satisfactorily. The switch will be replaced by DCR 1398, completion date not known at this time.

Failure Data:

None

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 

