

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
0 1 | L | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 0 | 7 | 1 | 1 | 1 | 9 | 8 | 0 | 8 | 1 | 2 | 1 | 2 | 8 | 0 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On initial startup following refueling outage, IRM's B, D, and H did not respond.
0 3 | The minimum number of operable instrument channels in trip system "B" was less than
0 4 | allowed by T.S. Table 3.1.A. Redundant IRM's in trip system A were operable. There
0 5 | was no effect on the health or safety of the public. Previous events: None.
0 6 |
0 7 |
0 8 |

0 9 | I | B | X | Z | I | N | S | T | R | U | X | Z | L | 0 | T | 2 | 1 | 5
7 8 9 10 11 12 13 18 19 20 21 22 23 24 26 27 28 29 30 31 32
LEI/HO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
17 8 0 - 0 5 0 / 0 3 L - 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
B G C A 0 0 2 4 Y N Z T 2 1 5
33 34 35 36 37 40 41 42 43 44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The Time Wire RG 114 a/u cables for IRM B, D, and H were found open in the drywell.
1 1 | Cable on H and connectors on B and D IRM's were repaired. SMI 92.7 has been
1 2 | written to identify any problems after cable reroute by January 2, 1981.
1 3 |
1 4 |

1 5 | D | 0 | 0 | 0 | NA | A | Operator observation
7 8 9 10 11 12 13 44 45 46

1 6 | Z | Z | NA | NA
7 8 9 10 11 12 13 44 45

1 7 | 0 | 0 | 0 | Z | NA
7 8 9 10 11 12 13

1 8 | 0 | 0 | 0 | NA
7 8 9 10 11 12 13

1 9 | Z | NA
7 8 9 10 11 12

2 0 | N | NA | 8012170 | 647
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80



LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8050 Technical Specification Involved 3.1

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 11/19/80 Time of Occurrence 1730 Unit 2

Identification and Description of Occurrence:

During startup following a refueling outage, IRM's B, D, and H did not respond.

Conditions Prior to Occurrence:

Unit 1 at 99% power.

Unit 2 startup following refueling outage

Unit 3 at 87% power.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

All rods inserted within the required 4-hour limit of Tech Spec Table 3.1.A.

Apparent Cause of Occurrence:

Open cables in the drywell on IRM's B, D, and H.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no effect on the health and safety of the public.

Corrective Action:

Repaired cables and connectors. SMI 92.7 has been written to identify any problems at cable reroute.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

