

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	B	R	F	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	14						15	25										26	30					57	CAT	58	
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE								

CON'T

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90									
		L	6	0	5	0	0	0	2	6	0	7	1	1	2	1	8	0	8	1	2	1	2	8	0	9															

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 7 During heatup after a refueling outage while performing SI 4.2.B-1, reactor water level switch 2-LIS-3-58C switch 4 (LPCI initiation) was found not to operate at the proper setpoint. (T.S. 3.2.B). Redundant switches were operable. There was no effect on the health or safety of the public. Previous events: 260/805, 260/801 and 259/7437.

0 6

0 7

0 8

7 8 9

SYSTEM CODE 0 9		CAUSE CODE I A		CAUSE SUBCODE X		COMPONENT CODE I N S T R U						COMP. SUBCODE X		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER 17		EVENT YEAR 8 0		SEQUENTIAL REPORT NO. 0 5 1		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN X		FUTURE ACTION Z	
23		24		25		26		27		28		29		30	
EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORMS SUB. N		PRIME COMP. SUPPLIER L		COMPONENT MANUFACTURER Y 0 1 0			
31		32		33		34		35		36		37			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The Yarway catalog number 4418C had dirty switch contacts. The contacts were
1	1	cleaned and functionally checked several times at the proper setpoint. No recurrence.
1	2	control action is planned.
1	3	
1	4	

7	8	9	FACILITY STATUS [1][5] [C] (28)	% POWER [0][0][0] (29)	OTHER STATUS NA (30)	METHOD OF DISCOVERY [B] (31)	DISCOVERY DESCRIPTION Surveillance testing (32)
7	8	9	ACTIVITY CONTENT RELEASED OF RELEASE [1][6] [Z] (33)	AMOUNT OF ACTIVITY [Z] (34) NA	LOCATION OF RELEASE NA (36)		
7	8	9	PERSONNEL EXPOSURES NUMBER [1][7] [0][0][0] (37)	TYPE [Z] (38)	DESCRIPTION NA (39)		
7	8	9	PERSONNEL INJURIES NUMBER [1][8] [0][0][0] (40)	DESCRIPTION NA (41)			
7	8	9	LOSS OF OR DAMAGE TO FACILITY TYPE [1][9] [Z] (42)	DESCRIPTION NA (43)			
7	8	9	PUBLICITY ISSUED [2][0] [N] (44)	DESCRIPTION NA (45)	NRC USE ONLY		

LER SUPPLEMENTAL INFORMATION

BFRO-50-260 / 8051 Technical Specification Involved 3.2.B

Reported Under Technical Specification 6.7.2.b(1)

Date of Occurrence 11/21/80 Time of Occurrence 1500 Unit 2

Identification and Description of Occurrence:

During heatup after a refueling outage while performing SI 4.2.B-1, level switch 2-LIS-3-58C switch 4 (LPCI initiation) was found not to operate at the proper set point.

Conditions Prior to Occurrence:

Unit 1 at 99% power

Unit 2 startup after refueling

Unit 3 at 84% power

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Redundant switch in same trip channel and in redundant trip channel were operable.

Apparent Cause of Occurrence:

Dirty switch contacts.

Analysis of Occurrence:

There was no damage to the plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health and safety of the public.

Corrective Action:

Cleaned the switch and functionally tested at the proper setpoint several times.

Failure Data:

260/805, 260/801, and 259/7437.

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

