

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9306150200 DOC. DATE: 93/06/09 NOTARIZED: NO DOCKET #
 FACIL: 50-368 Susquehanna Steam Electric Station, Unit 2, Pennsylvania 05000388
 AUTH. NAME AUTHOR AFFILIATION
 METER, J.J. Pennsylvania Power & Light Co.
 STANLEY, H.G. Pennsylvania Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 90-007-01: on 900705, primary power supply to RPS A power distribution panel lost when one electrical protection assembly (EPA) breakers tripped. EPA logic cards reviewed & RPS power supply will be redesigned. W/930609 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 6
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	
	PDI-2 LA	1 1	PDI-2 PD	1 1	
	CLARK, R	1 1			
INTERNAL:	ACNW	2 2	ACRS	2 2	
	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1	
	AEOD/ROAB/DSP	2 2	NRR/DE/EELB	1 1	
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1	
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1	
	NRR/DRIL/RPEB	1 1	NRR/DRPW/OEAB	1 1	
	NRR/DRSS/PRPB	2 2	NRR/DSSA/SPLB	1 1	
	NRR/DSSA/SRXB	1 1	<u>REG FILE</u> 02	1 1	
	RES/DSIR/EIB	1 1	RGNI FILE 01	1 1	
EXTERNAL:	EG&G BRYCE, J.H	2 2	L ST LOBBY WARD	1 1	
	NRC PDR	1 1	NSIC MURPHY, G.A	1 1	
	NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 32 ENCL 32

A04



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

June 9, 1993

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 90-007-01
FILE R41-2
PLAS - 566

Docket No. 50-388
License No. NPF-22

Attached is Licensee Event Report 90-007-01 which is an update to LER 90-007-00. The event was determined reportable per 10CFR50.73(a)(2)(iv) in that unplanned actuations of Engineered Safety Features occurred due to the loss of the primary power supply to the Division 1 Reactor Protection System power distribution panel when one Electrical Protection Assembly breaker tripped.



H.G. Stanley
VP - Nuclear Operations

JJM/mjm

cc: Mr. T. T. Martin
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. G. S. Barber
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 35
Berwick, PA 18603-0035

140010
9306150200 930609
PDR ADDCK 05000388
S PDR



LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Unit 2 Susquehanna Steam Electric Station	DOCKET NUMBER (2) 0 5 0 0 0 3 8 8	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 0	- 0 0 7	- 0 1	0 2	OF	0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT

At 1633 on July 5, 1990 with the Unit operating at 100% power, the primary power supply to the "A" Reactor Protection System (RPS; EIIS Code: JC) power distribution panel 2Y201A was lost when one of its Electrical Protection Assembly (EPA) breakers, 2CB-S003A-C, tripped. This power interruption resulted in Primary Containment Isolation System (EIIS Code: JM) actuations and automatic system initiations. RPS as well as other plant systems functioned as designed in response to the event. The major actuations were as follows:

- 1) Reactor Building HVAC (EIIS Code: VA) Zones II and III Isolated.
- 2) Reactor Water Cleanup System (EIIS Code: CE) inboard isolation valve closed.
- 3) Cooling water isolation valves to the Reactor Recirc Pumps closed (EIIS Code: CC).
- 4) "A" Standby Gas Treatment System (EIIS Code: BH) auto initiated.
- 5) "A" Control Room Emergency Outside Air Supply System (EIIS Code: BH) auto initiated.

The EPA breaker was reset at 1640, all isolation signals were reset by 1646, and all affected systems were subsequently restored. Full power operations of the Unit continued without interruption.

CAUSE OF EVENT

The loss of power to the "A" RPS bus was due to an unexpected trip of the downstream primary power supply EPA breaker. The EPA logic cards monitor RPS power for conditions of overvoltage, undervoltage, and underfrequency and trip the EPA breakers when these conditions exist or when the logic card fails. EPA breakers are in series and the trip of either breaker will interrupt power to the distribution panel.

The cause of this EPA breaker trip as well as others at the Station have been investigated. In general, the majority of the EPA breaker trips at the station have been linked to a failure/anomaly of an electrical subcomponent on the EPA logic

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Unit 2 Susquehanna Steam Electric Station	DOCKET NUMBER (2) 0 5 0 0 0 3 8 8	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 0	- 0 0 7	- 0 1	0 3	OF	0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

card. A subcomponent failure such as a capacitor or a transistor would cause the logic card to fail and subsequently trip the EPA breaker.

Contributing factors to subcomponent failures were increasing subcomponent age and higher than optimum temperature of the subcomponent environment. As a subcomponent life increases, particularly capacitors, the EPA cards with subcomponents become less reliable and eventually fails. This "aging" process was found to be applicable when the EPA logic card was both in service and in storage. The higher the temperature a subcomponent is subjected to, the shorter its reliable life becomes. In May of 1991 a task team was formed to address the reliability of the RPS power supply systems at the Station. Prior to the task team being formed and reaching its conclusions, logic cards that experienced a trip were not examined on a subcomponent basis. Failed logic cards were typically returned to the manufacturer for analysis. The manufacturer would then replace the subcomponent(s) that failed. The card would then be returned and either put into service or stored for future use. In both instances the logic cards contained both new and used subcomponents. The temperature of the EPA logic card environment was found to be greater than optimum. The ambient room temperature where EPA cards are located was near 90 degrees F. In addition the EPA cards were mounted in a sealed junction box which further increased subcomponent temperature.

CORRECTIVE ACTIONS

As described above, in May of 1991 a task team was formed to address the reliability of the RPS power supply systems at the Station. Two main objectives were established. The first objective was short term and was to reduce the number of spurious RPS power supply trips by enhancing and better maintaining the components in the present systems. The second was long term and was to reduce spurious RPS power supply trips and increase reliability via the modification process.

In the short term, EPA logic cards were reviewed on an individual basis and subcomponents lifetime upgrades were performed so that each card could be reasonably expected not to fail within a five year lifetime. The junction boxes that house the EPA logic cards were equipped with ventilation louvers thereby reducing the ambient temperatures for the logic card subcomponents. Other short term actions included cleaning, inspecting and optimizing performance of RPS power supply components such as motor-

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Unit 2 Susquehanna Steam Electric Station	DOCKET NUMBER (2) 0 5 0 0 0 3 8 8	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		9 0	- 0 0 7	- 0 1	0 4	OF 0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

generator sets, regulating transformers, relays and connection panels.

The long term corrective action was to develop an RPS power supply modification that reduced spurious trips and increased reliability. After extensive analysis, modifications have been designed for the RPS power supply systems. The redesigned RPS power supply will utilize an improved version of EPA logic cards in lieu of the existing models and forced cooling to the EPA enclosures will be provided.

REPORTABILITY/ANALYSIS

This event was determined to be reportable under 10CFR50.73(a)(2)(iv) in that unplanned actuations of Engineered Safety Features (ESF) occurred when the RPS EPA breaker tripped.

Since all ESF systems and components functioned properly and per design, there were no safety consequences or compromises to the health or safety of the public.

Had this event occurred with the Unit in cold shutdown or refueling, the safety significance would have been greater due to the fact that shutdown cooling could have been temporarily lost. Even under these conditions the safety significance would be minimal since the plant is more than adequately designed to safely handle this type of event.

In accordance with the guidance provided in NUREG 1022 Supplement 1 items 14.1 and 14.10, the original submission date for this report was 8-6-90. No further updates to this report are expected.

ADDITIONAL INFORMATION

Failed Component Information:

Component - EPA Logic Card

Model - 147D8652 G001 & G003

Manufacturer - General Electric

A review of past Licensee Event Reports (LERs) for the station identified twelve other events where EPA breakers trips resulted in ESF actuations.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Unit 2 Susquehanna Steam Electric Station	DOCKET NUMBER (2) 0 5 0 0 0 3 8 8	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		9 0	— 0 0 7	— 0 1	0 5	OF 0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

UNIT 1 (Docket No. 50-387/License No. NPF-14)

LER 92-007	LER 87-024
LER 92-001	LER 86-029
LER 91-006	LER 86-023
LER 91-004	LER 83-172
LER 90-005	

UNIT 2 (Docket No. 50-388/Licensee No. NPF-22)

LER 91-008
LER 91-007
LER 88-005