

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8104100435 DOC. DATE: 81/04/03 NOTARIZED: NO
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylvania
 AUTH. NAME: CURTIS, H. W. AUTHOR AFFILIATION: Pennsylvania Power & Light Co.
 RECIP. NAME: GRIER, B. H. RECIPIENT AFFILIATION: Region 1, Philadelphia, Office of the Director

DOCKET #
 05000387
 05000388

SUBJECT: Interim deficiency report re GE HFA relays which have coils wound on Lexan spools, initially reported on 810206, Cause not yet specifically determined. Addl info by June 1981.

DISTRIBUTION CODE: 8019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 3
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Send I&E 3 copies FSAR & all amends.
 Send I&E 3 copies FSAR & all amends.

05000387
 05000388

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME	COPIES	
			LTR	ENCL		LTR	ENCL
ACTION:	A/D LICENSNG	04	1		YOUNGBLOOD, B	05	1
	RUSHBROOK, M.	06	1		STARK, R.	07	1
INTERNAL:	ASLBP/J. HARD		1		D/DIR HUM FAC15		1
	EDO & STAFF	19	1		EQUIP QUAL BR11		1
	HYD/GEO BR	22	1		I&E	09	1
	LIC GUAL BR	12	1		MPA	20	1
	NRC PDR	02	1		OELD	21	1
	PROC/TST REV	13	1		QA BR	14	1
	REG FILE	01	1		RUTHERFORD, W. IE		1
EXTERNAL:	STANDARDS DEV	21	1				
	ACRS	16	16	1	LPDR	03	1
	NSIC	08	1				


APR 13 1981

MOI

PP&L

TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101 PHONE: (215) 770-5151

NORMAN W. CURTIS
Vice President-Engineering & Construction-Nuclear
770-5381



April 3, 1981

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
INTERIM REPORT OF A DEFICIENCY RELATING TO
GE HFA RELAYS
ER's 100450/100508 FILES 840-4/821-10
PLA-708

Dear Mr. Grier:

This letter serves to provide the Commission with an interim report of a deficiency involving General Electric HFA relays. The deficiency was originally reported by telephone to NRC Region I Representative, Mr. R. T. Carlson, by Mr. A. R. Sabol of PP&L on February 6, 1981. During that conversation, Mr. Carlson was advised that the condition was being evaluated for reportability under the provisions of 10 CFR 50.55(e).

The deficiency involves GE HFA relays which have coils wound on Lexan spools. These Lexan spools are susceptible to cracking. The problem was the subject of NRC Information Notice #81-01.

The condition has been identified by PP&L on NCR #81-083 for Unit 1 and by Bechtel on NCR #7138 for Unit 2. The condition has since been determined to be reportable under the provisions of 10 CFR 50.55(e) and this report is submitted pursuant thereto.

GE has conducted an inspection of HFA relays in Unit 2 panels under their scope of supply. The inspection was performed in accordance with GE FDI MDEP. The inspection resulted in discovery of 16 broken and 65 cracked coils out of the 358 checked.

B019
5
1/0

5 8104100 435

April 3, 1981

The cause of the deficiency has not yet been specifically determined. PP&L has requested GE to evaluate the cause of this deficiency and whether the cracking is affected by vibration, age or relay utilization (normally energized or deenergized) and if hydrocarbons may have an influence on the problem.

In analyzing the safety implications of the coil spool breakage, the results of the GE inspection conducted under FDI MDEP were evaluated. PP&L has concluded that these relays are used in safety applications such as the Reactor Protection, High Pressure Coolant Injection and Nuclear Steam Supply Shutdown Systems. The failure of one of these relays is considered a significant construction deficiency that could prevent a system from performing its intended safety function.

PP&L has since directed 100% inspections of the remaining GE HFA relays outside the scope of the original GE inspection. All relays with cracked or broken coil spools discovered in Class IE systems will be replaced. In non-class IE systems, only the coils with cracked or broken spools will be replaced. The need for alternative or additional corrective action will be evaluated upon receipt of information regarding cause determination and GE aging test results.

Since replacement relays will not be available until July, 1981, we expect to complete our inspection program for Unit 1 shortly thereafter. The inspection and replacement process for both units will be controlled through appropriate instructions and quality checks.

Since the details of this report provide information relevant to the reporting requirements of 10 CFR 21, this correspondence is considered to also discharge any formal responsibility PP&L may have in compliance thereto.

We expect to provide additional information on this deficiency in June, 1981. We trust the Commission will find this report to be acceptable.

Very truly yours,



N. W. Curtis
Vice President-Engineering & Construction-Nuclear

FLW:sab

Mr. Boyce H. Grier

- 3 -

April 3, 1981

cc: Mr. Victor Stello (15)
Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director (1)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Gary Rhoads
U. S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655