

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7905160424 DOC. DATE: 79/05/11 NOTARIZED: NO DOCKET #
 FACIL: 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1, PENNSYLVA 05000387
 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2, PENNSYLVA 05000388
 AUTH. NAME AUTHOR AFFILIATION
 BARTO, M.C. PENNSYLVANIA POWER & LIGHT CO.
 RECIP. NAME RECIPIENT AFFILIATION
 GRIER, B.H. REGION 1, PHILADELPHIA, OFFICE OF THE DIRECTOR

SUBJECT: FORWARDS CORRECTED PAGE 1 OF PLA-352 WHICH INCLUDES MISSING DATE OF 790507.

DISTRIBUTION CODE: 8019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: SEND I&E 3 CYS FSAR & ALL AMDTs. L.A. 1CY EVERYTHING (CORNL)

| | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL |
|-----------|---------------------------|---------------------|---------------------------|---------------------|
| ACTION: | 14 PM MINER | 1 1 | 15 BC LWR #3 | 1 1 |
| | 20 LA LWR #3 | 1 1 | 21 AD VASSALLO | 1 1 |
| INTERNAL: | 01 REG FILE | 1 1 | 02 NRC PDR | 1 1 |
| | 05 I&E | 2 2 | 07 EDO & STAFF | 1 1 |
| | 08 MPA | 1 1 | 09 DEPY. DIR DPM | 1 1 |
| | 10 QAB | 1 1 | 11 STANDRDS DEV | 1 1 |
| | 12 JORDAN, E/IE | 1 1 | 13 FIELD COOR/IE | 1 1 |
| | 16 AD FOR ENGR | 1 1 | 17 AD PLANT SYS | 1 1 |
| | 17 AD REAC SFTY | 1 1 | 19 AD SYS/PROJ | 1 1 |
| | 22 DIR DPM | 1 1 | 23 OELD | 1 1 |
| | AD/SITE TECH | 1 1 | DIRECTOR DSE | 1 1 |
| | GEOSCIENCES BR | 1 1 | STRUCT ANLYS BR | 1 1 |
| EXTERNAL: | 03 LPDR | 1 1 | 04 NSIC | 1 1 |
| | 24 ACRS | 16 16 | | |

MAY 18 1979

mt 4
67

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 43

May 11, 1979

TO ALL RECIPIENTS OF PLA-352
COOPER-BESSEMER COMPANY REPORT OF A
DEFICIENT PART IN THE SSES STANDBY DIESEL-GENERATOR

Attached please find Corrected Copy of Page 1 of subject PLA which includes missing date of May 7, 1979.

Please replace the original letter Page 1 with the attached corrected copy. Any questions regarding above, please call (215) 821-5936.

A. R. Sabol

By

Martha C. Barto
Martha C. Barto
Administrative Assistant-NQA

Attachment

7905160424

3019
8 1/1



TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101

PHONE: (215) 821-51

NORMAN W. CURTIS
Vice President-Engineering & Construction
821-5381

MAY 7 1979

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
612 Park Avenue
King of Prussia, Pennsylvania 18406

SUSQUEHANNA STEAM ELECTRIC STATION (SSES)
COOPER-BESSEMER COMPANY REPORT OF A
DEFICIENT PART IN THE SSES STANDBY DIESEL-GENERATOR
ERs 100450/100508 FILE 840-4
PLA-352

Dear Mr. Grier:

This relates to a deficiency which Cooper-Bessemer had reported to the Commission on November 3, 1978 under the provisions of 10CFR Part 21. The report stated that Cooper Energy Services, supplier of the emergency standby diesel-generators for SSES, had, during performance testing of engines similar to those for SSES, found that the surface of a roller pin in a crosshead assembly had exhibited abnormal wear. It was further stated that, though no engine shutdown nor malfunction had been experienced, it was felt that, for longer periods of engine operation, the abnormal wear condition could progress far enough to cause the engine to malfunction.

Although C.E.S. had reported the condition on November 3, 1978, it was not until April 25, 1979, when NRC Resident Inspector R. M. Gallo provided A. R. Sabol, PP&L, a copy of the C.E.S. report, that PP&L Susquehanna Project personnel became aware of the report.

Therefore, since the reporting responsibility under 10CFR Part 21 has already been discharged by C.E.S., PP&L recognizes its remaining responsibility for evaluating the condition under the terms of 10CFR 50.55(e).

Based upon the C.E.S. report, we conclude that the deficiency has potential for reportability and consider the details of the C.E.S. report to serve as an interim report in satisfaction of the provisions of 10CFR 50.55(e). However, we intend to further evaluate the safety impact of the deficiency