

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

5N 157B Lookout Place

SEP 23 1988

PR

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

*copy all three  
USNRC*

Gentlemen:

In the Matter of  
Tennessee Valley Authority

)  
)  
)

Docket Nos. 50-259  
50-260  
50-296

BROWNS FERRY NUCLEAR PLANT (BFN) UNITS 1, 2, AND 3 - SAFETY SYSTEM FUNCTIONAL INSPECTION (SSFI) REPORT NO. BFA 88811

TVA is submitting the subject report as requested by G. E. Gears, TVA Project Manager, NRC Office of Special Projects.

SSFI Report No. BFA 88811 considers the emergency equipment cooling water (EECW) and the residual heat removal service water (RHRSW) to be functional. The inspection was a TVA managed task with joint participation by TVA and ERC International.

Currently, affected BFN organizations are preparing recommendations for each inspection observation. These recommendations and subsequent corrective actions should provide confidence in the functional readiness and restart of BFN.

The enclosures contain proprietary information and should be withheld from public disclosure as provided in 10 CFR 2.790. They are, therefore, deemed to be commercial or financial information with the meaning of 10 CFR 9.5(a)(4) and shall be subject to public disclosure only in accordance with the provisions of 10 CFR 9.12.

If you have any questions, please telephone Wayne Ivey at (205) 729-2071.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*R. L. Gridley*  
R. L. Gridley, Manager  
Nuclear Licensing and  
Regulatory Affairs

Enclosures  
cc: See page 2

*8609250002/2pp*



*[Faint, illegible text or markings at the bottom right corner of the page.]*

U.S. Nuclear Regulatory Commission

SEP 23 1988

cc: (Enclosures)

Mr. F. R. McCoy, Acting Assistant Director  
for Inspection Programs  
TVA Projects Division  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Mr. S. C. Black, Assistant Director ✓  
for Projects  
TVA Projects Division  
U.S. Nuclear Regulatory Commission  
One White Flint, North  
11555 Rockville Pike  
Rockville, Maryland 20852

Browns Ferry Resident Inspector  
Browns Ferry Nuclear Plant  
Route 12, P.O. Box 637  
Athens, Alabama 35611



BROWNS FERRY SSFII DEFLECTION OBSERVATIONS  
SUMMARY

(7/28/88)

		OLD CAQR	NEW CAQR	OTHER
<b>I. <u>Mechanical Maintenance</u></b>				
<b>OBSERVATION/ITEM</b>				
WCS-1	(67-32) Nonperformance of preventive maintenance on equipment, Rev. 1		880515	
WCS-2	(23-46) Discrepancies in preventive maintenance for MOVs, Rev. 0		880514	
WCS-3	(23-47) Weak housekeeping and maintenance practices, Rev. 1		880508	
WCS-4	(23-61) Failure analysis not adequate to determine root causes, Rev. 0		880510	
WCS-5	(67-69) Method for upgrading maintenance procedure may be too narrowly focused, Rev. 1			U/R
WCS-6	(23-64) Control and documentation of postmaintenance testing is weak, Rev. 1		880509	
WCS-7	(23-72) Upper torque limits for service water pumps mounting bolts., Rev. 1		880501	
<b>II. <u>Mechanical Design</u></b>				
SHK-1	(67-31) EECW may not be capable of providing required flows, Rev. 1		880505	
SHK-2	(23-38) Traveling screens could become inoperable affecting RHRSW flow, Rev. 0			D/B P/L 2-1273
SHK-3	(23-37) Safety related boundary valve not installed on U-3 heat exchanger, Rev. 0	880419		
SHK-4	(67-54) Isolation valves;FCV-67-50 and 51 may not close on demand, Rev. 2	871058		
SHK-5	(67-53) Inadequacies in design analyses and testing for EECWs, Rev. 1	870872		
SHK-6	(23-59) RHR heat exchanger relief valve may not be adequately sized, Rev. 0		880491	
SHK-7	(23-69) Platforms,railings,and other equipment in the RHRSW pump rooms are not seismically anchored,Rev. 0		880506	
WAP-1	(23-30) Incorrect relief valve settings for system piping, Rev. 0			D/B P/L 2-1264
WAP-2	(67-74) Design pressure limitations for EECW components can be exceeded, Rev. 0			D/B P/L 2-1313
<b>III. <u>Electrical Design</u></b>				
SFK-1	(67-59) Adequacy of Q-list as a controlled document, Rev. 0	870018		
SFK-2	(23-49) D/G derating on high outside ambient temperature, Rev. 0			
SFK-3	(23-60) Inadequate motor OL heater selection for MOVs, Rev. 1			PIR # BFN-EEB-8816
SFK-4	(23-63) Lack of surveillance testing of motor thermal OL relays, Rev. 0		880516	
SFK-5	(67-72) Weaknesses in dynamic load study for standby D/Gs, Rev. 0			PIR # BFN-EEB-8820
SFK-6	(23-70) Inadequacy of motor thermal OL calculation methodology, Rev. 0	880447		PIR # BFN-EEB-8817
<b>IV. <u>Instrumentation and Controls</u></b>				
BL-1	(67-58) Logic diagrams are not under configuration control, Rev. 1	870657		
BL-2	(23-48) Flow instruments are not qualified consistent with safety importance, Rev. 0			U/R
BL-3	(67-61) Flow transmitters installed in a harsh environment; Rev. 0			PIR # BFN-EEB-8815
BL-4	(67-62) Press switches for EECW strainer start not seismically qualified, Rev. 1	880099		
BL-5	(23-73) Process instrumentation instructions do not provide for complete channel/loop calibration, Rev. 0		880511	



V. Testing

## OBSERVATION/ITEM

RB-1 (67-64) Surveillances do not adequately verify EECW pump auto start, Rev. 1  
 RB-2 (67-63) No test to verify remote indicating lights for 67-50, 51, and 53, Rev. 0  
 RB-3 (67-73) Inadequacies in the flow balance of the EECW system, Rev. 0  
 RB-4 (23-68) Lack of adequate testing in the restart program for RHRSW and EECW, Rev. 0

OLD  
CAQRNEW  
CAQR

OTHER

880472

880507

870872

880472

VI. Operations

JJB-1 (67-41) Weakness in operating instruction OI-67, Rev. 0  
 JJB-2 (67-55) Failure to follow requirements of PHI 8.1, Temporary Alterations, Rev. 0  
 JJB-3 (23-62) Failure to identify number of sump pumps for LCO, Rev. 0  
 JJB-4 (23-67) Failure to follow PHI 12.12, Conduct of Operations, Rev. 0

COTS

880420

D/B P/L 2-0638

I

VII. Management Systems

JLT-1 (67-60) Drawings are not being updated, Rev. 0  
 JLT-2 (23-65) Weakness in plant valve identification labels, Rev. 0  
 JLT-3 (23-66) System status file is not being maintained current, Rev. 0  
 JLT-4 (67-71) Failure to notify operations personnel of D/G load study calculations, Rev. 0

870657

880479

I

\* - Indicates plant agreement with CAQR, but number not yet issued.

D/B P/L - Indicates design baseline punchlist item.

U/R - Indicates observation still under review by plant.

I - Indicates area for improvement.

COTS - Indicates item corrected on the spot.

PIR - Problem Investigation Report