

VOLUME 5
WELDING CATEGORY


SUBCATEGORY REPORT 50100 BROWNS FERRY NUCLEAR PLANT

UPDATED



TVA NUCLEAR POWER






REPORT NUMBER: 50100

REPORT TYPE: Subcategory REVISION NUMBER: 4 TITLE: BFN Site Specific Welding Subcategory Report Page 1 of 13 REASON FOR REVISION: Editorial Revision **PREPARATION** PREPARED BY: SIGNATURE REVIEWS PEER: SIGNATURE TAS: CONCURRENCES SIGNATURE DATE APPROVED BY


*SRP Secretary's signature denotes SRP concurrences are in files.



Preface, Glossary, and List of Acronyms for ECTG Subcategory Reports

HISTORY OF REVISION

REV NUMBER	PAGES REVISED	REASON FOR CURRENT REVISION
3	i	To clarify that one or more attachments will help the reader find where a particular concern
	*	is evaluated



REPORT NUMBER: 50100

FRONT MATTER REV: 3

PAGE i OF viii

Preface

This subcategory report is one of a series of reports prepared for the Employee Concerns Special Program (ECSP) of the Tennessee Valley Authority (TVA). The ECSP and the organization which carried out the program, the Employee Concerns Task Group (ECTG), were established by TVA's Hanager of Nuclear Power to evaluate and report on those Office of Nuclear Power (ONP) employee concerns filed before February 1, 1986. Concerns filed after that date are handled by the ongoing ONP Employee Concerns Program (ECP).

The ECSP addressed over 5800 employee concerns. Each of the concerns was a formal, written description of a circumstance or circumstances that an employee thought was unsafe, unjust, inefficient, or inappropriate. The mission of the Employee Concerns Special Program was to thoroughly investigate all issues presented in the concerns and to report the results of those investigations in a form accessible to ONP employees, the NRC, and the general public. The results of these investigations are communicated by four levels of ECSP reports: element, subcategory, category, and final.

Element reports, the lowest reporting level, will be published only for those concerns directly affecting the restart of Sequoyah Nuclear Plant's reactor unit 2. An element consists of one or more closely related issues. An issue is a potential problem identified by ECTG during the evaluation process as having been raised in one or more concerns. For efficient handling, what appeared to be similar concerns were grouped into elements early in the program, but issue definitions emerged from the evaluation process itself. Consequently, some elements did include only one issue, but often the ECTG evaluation found more than one issue per element.

Subcategory reports summarize the evaluation of a number of elements. However, the subcategory report does more than collect element level evaluations. The subcategory level overview of element findings leads to an integration of information that cannot take place at the element level. This integration of information reveals the extent to which problems overlap more than one element and will therefore require corrective action for underlying causes not fully apparent at the element level.

To make the subcategory reports easier to understand, three items have been placed at the front of each report: a preface, a glossary of the terminology unique to ECSP reports, and a list of acronyms.

Additionally, at the end of each subcategory report will be a Subcategory Summary Table that includes the concern numbers; identifies other subcategories that share a concern; designates nuclear safety-related, safety significant, or non-safety related concerns; designates generic applicability; and briefly states each concern.

Either the Subcategory Summary Table or another attachment or a combination of the two will enable the reader to find the report section or sections in which the issue raised by the concern is evaluated.

REPORT NUMBER: 50100

FRONT MATTER REV: 2

PAGE ii OF viii

The subcategories are themselves summarized in a series of eight category reports. Each category report reviews the major findings and collective significance of the subcategory reports in one of the following areas:

- management and personnel relations
- industrial safety
- construction
- material control
- operations
- quality assurance/quality control
- welding
- engineering

A separate report on employee concerns dealing with specific contentions of intimidation, harassment, and wrongdoing will be released by the TVA Office of the Inspector General.

Just as the subcategory reports integrate the information collected at the element level, the category reports integrate the information assembled in all the subcategory reports within the category, addressing particularly the underlying causes of those problems that run across more than one subcategory.

A final report will integrate and assess the information collected by all of the lower level reports prepared for the ECSP, including the Inspector General's report.

For more detail on the methods by which ECTG employee concerns were evaluated and reported, consult the Tennessee Valley Authority Employee Concerns Task Group Program Manual. The Manual spells out the program's objectives, scope, organization, and responsibilities. It also specifies the procedures that were followed in the investigation, reporting, and closeout of the issues raised by employee concerns.

REPORT NUMBER: 50100

FRONT MATTER REV: 2

PAGE iii OF viii

ECSP GLOSSARY OF REPORT TERMS*

classification of evaluated issues the evaluation of an issue leads to one of the following determinations:

- Class A: Issue cannot be verified as factual
- Class B: Issue is factually accurate, but what is described is not a problem (i.e., not a condition requiring corrective action)
- Class C: Issue is factual and identifies a problem, but corrective action for the problem was initiated before the evaluation of the issue was undertaken
- Class D: Issue is factual and presents a problem for which corrective action has been, or is being, taken as a result of an evaluation
- Class E: A problem, requiring corrective action, which was not identified by an employee concern, but was revealed during the ECTG evaluation of an issue raised by an employee concern.
- collective significance an analysis which determines the importance and consequences of the findings in a particular ECSP report by putting those findings in the proper perspective.
- concern (see "employee concern")
- corrective action steps taken to fix specific deficiencies or discrepancies revealed by a negative finding and, when necessary, to correct causes in order to prevent recurrence.
- criterion (plural: criteria) a basis for defining a performance, behavior, or quality which ONP imposes on itself (see also "requirement").
- element or element report an optional level of ECSP report, below the subcategory level, that deals with one or more issues.
- employee concern a formal, written description of a circumstance or circumstances that an employee thinks unsafe, unjust, inefficient or inappropriate; usually documented on a K-form or a form equivalent to the K-form.

REPORT NUMBER: 50100

FRONT MATTER REV: 2

PAGE iv OF viii

evaluator(s) the individual(s) assigned the responsibility to assess a specific grouping of employee concerns.

<u>findings</u> includes both statements of fact and the judgments made about those facts during the evaluation process; negative findings require corrective action.

<u>issue</u> a potential problem, as interpreted by the ECTG during the evaluation process, raised in one or more concerns.

K-form (see "employee concern")

requirement a standard of performance, behavior, or quality on which an evaluation judgment or decision may be based.

root cause the underlying reason for a problem.

*Terms essential to the program but which require detailed definition have been defined in the ECTG Procedure Manual (e.g., generic, specific, nuclear safety-related, unreviewed safety-significant question).

REPORT NUMBER: 50100

FRONT MATTER REV: 2

PAGE v OF viii

Acronyms

AI	Administrative Instruction
AISC	American Institute of Steel Construction
ALARA	As Low As Reasonably Achievable
ANS	American Nuclear Society
ANSI	American National Standards Institute
ASHE	American Society of Hechanical Engineers
ASTM	American Society for Testing and Materials
AWS	American Welding Society
BFN	Browns Ferry Nuclear Plant
BLN	Bellefonte Nuclear Plant
CAQ	Condition Adverse to Quality
CAR	Corrective Action Report
CATD	Corrective Action Tracking Document
CCTS	Corporate Commitment Tracking System
CEG-H	Category Evaluation Group Head .
CFR	Code of Federal Regulations .
CI	Concerned Individual
CMTR	Certified Haterial Test Report
coc	Certificate of Conformance/Compliance
DCR,	Design Change Request
DNC	Division of Nuclear Construction (see also NU CON)

REPORT NUMBER: 50100

FRONT HATTER REV: 2

PAGE vi OF viii

DNE Division of N	uclear Engineering
-------------------	--------------------

DNQA Division of Nuclear Quality Assurance

DNT Division of Nuclear Training

DOE Department of Energy

DPO Division Personnel Officer

DR Discrepancy Report or Deviation Report

ECN Engineering Change Notice

ECP Employee Concerns Program

ECP-SR Employee Concerns Program-Site Representative

ECSP Employee Concerns Special Program

· ECTG Employee Concerns Task Group

EEOC Equal Employment Opportunity Commission

EQ Environmental Qualification

EMRT Emergency Medical Response Team

EN DES Engineering Design

ERT Employee Response Team or Emergency Response Team

FCR Field Change Request

FSAR Final Safety Analysis Report

FY Fiscal Year

GET General Employee Training

HCI Hazard Control Instruction

HVAC Heating, Ventilating, Air Conditioning

II Installation Instruction

INPO. Institute of Nuclear Power Operations

IRN Inspection Rejection Notice

REPORT NUMBER: 50100

FRONT MATTER REV: 2

PAGE vii OF viii

L/R Labor Relations Staff

M&AI Modifications and Additions Instruction

HI Maintenance Instruction

MSPB Merit Systems Protection Board

MT Magnetic Particle Testing

NCR Nonconforming Condition Report

NDE Nondestructive Examination

NPP Nuclear Performance Plan

NPS Non-plant Specific or Nuclear Procedures System

NQAH Nuclear Quality Assurance Hanual

NRC Nuclear Regulatory Commission

NSB. Nuclear Services Branch

NSRS Nuclear Safety Review Staff

NU CON Division of Nuclear Construction (obsolete abbreviation, see DNC)

NUMARC Nuclear Utility Management and Resources Committee

OSHA Occupational Safety and Health Administration (or Act)

ONP Office of Nuclear Power

OWCP Office of Workers Compensation Program

PHR Personal History Record

PT Liquid Penetrant Testing

QA Quality Assurance

QAP ' Quality Assurance Procedures

QC Quality Control

QCI Quality Control Instruction

REPORT NUMBER: 50100

FRONT HATTER REV: 2


PAGE viii OF viii

(QCP	Quality Control Procedure
(QTC	Quality Technology Company
]	RIF	Reduction in Force
- 1	RT	Radiographic Testing
:	SQN	Sequoyah Nuclear Plant
;	sī	Surveillance Instruction
:	SOP	Standard Operating Procedure
,	SRP	Senior Review Panel
;	SWEC	Stone and Webster Engineering Corporation
:	TAS	Technical Assistance Staff
:	T&L	Trades and Labor
•	AVI	Tennessee Valley Authority
:	IVTLC	Tennessee Valley Trades and Labor Council
1	UT	Ultrasonic Testing
1	VI	Visual Testing
,	WBECSP	Watts Bar Employee Concern Special Program
ţ	J BN	Watts Bar Nuclear Plant
,	JR	Work Request or Work Rules
,	NP	Workplans

1.0 CHARACTERIZATION OF ISSUES

2.0 METHODOLOGY

- 3.0 ISSUES(s), FINDINGS, AND CONCLUSION(s)
 - 3.1 Control of Welding Filler Material
 - 3.2 Inspection of Welds Through Carbo-Zinc Primer
 - 3.3 Welder Qualification and Continuity
 - 3.4 Availability of Inspection Tools
 - 3.5 <u>Inspector Training and Certification</u>
 - 3.6 Welder Training and Experience
 - 3.7 Surface Grinding of Welds
 - 3.8 Adequacy of Welding Equipment
 - 3.9 Structural Steel Preweld Inspections
 - 3.10 Welder Qualification
 - 3.11 Weld Repairs Not Meeting ASME Code Requirements
 - 3.12 Structural Support Welds
 - 3.13 Weld Inspection Procedures
- 4.0 COLLECTIVE SIGNIFICANCE
- 5.0 CAUSE
- 6.0 CORRECTIVE ACTION
- ·7.0 ATTACHMENTS
 - A. Subcategory Summary Table
 - B. Summary of Issues
- 8.0 REFERENCE
 - A. Welding Project Evaluation Reports



REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER: 4

TITLE: BFN Site-Specific Welding Subcategory Report Page 2 of 13

1.0 CHARACTERIZATION OF ISSUES

1.1 Introduction

The characterization of issues for this subcategory report are derived from 63 Employee Concerns. Of the 63 Employee Concerns, 7 were specific to BFN (49 specific to WBN, 3 specific to BLN, 3 specific to SQN, 1 non plant specific). The Employee Concerns were divided into 13 similar issues and were investigated by the Weld Project, Quality Technology Company (QTC) and/or the Nuclear Safety Review Staff (NSRS). Each of the 13 issues was addressed by a Weld Project Evaluation Report which will be provided to the USNRC as a portion of the Weld Project effort.

IR4

1.2 Description of Issues

- 1.2.1 Control of Welding Filler Material
- 1.2.2 Inspection of Welds Through Carbo-Zinc Primer
- 1.2.3 Welder Qualification and Continuity
- 1.2.4 Availability of Inspection Tools
- 1.2.5 <u>Inspector Training and Certification</u>
- 1.2.6 Welder Training and Experience
- 1.2.7 Surface Grinding of Welds
- 1.2.8 Adequacy of Welding Equipment
- 1.2.9 Structural Steel Preweld Inspection
- 1.2.10 Welder Qualification
- 1.2.11 Weld Repair Not Meeting ASME Code Requirements
- 1.2.12 Structural Support Welds
- 1.2.13 Weld Inspection Procedures

2.0 METHODOLOGY

The procedure and specification histories of Browns Ferry Nuclear Plant from the beginning of construction to the present were reviewed. These procedures and specifications were compared with the construction codes that were in effect during each phase of the procedure history. The Browns Ferry Weld Project Phase I Report was reviewed. The expurgated text of the concerns was compared with the requirements

184

REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER: 4

TITLE: BFN Site-Specific Welding Subcategory Report Page 3 of 13

defined in the construction codes and the commitments made in the Topical Report (TVA-TR-75-1A). A review was made of quality indicators such as USNRC Inspection Reports and TVA audit and deficiency reporting documents issued over the life of the plant. As appropriate to the issues, discussions were held with cognizant TVA Construction, Engineering, Quality and Craft Supervisory personnel.

3.0 ISSUES, FINDINGS, AND CONCLUSIONS

3.1 Control of Welding Filler Material

The concerns stated that weld rods are not required to be kept in rod ovens after issue; questioned the adequacy of weld rod control; questioned the quality of E-7018 coated electrodes; and questioned the administrative practices for the return of unused and waste welding materials.

Portable rod ovens are used at BFN to protect certain high strength electrodes from moisture absorption from the atmosphere. The most commonly used electrodes (E7018) are not required to be issued in portable ovens. Rather, the atmospheric exposure time limits prescribed by the Structural Welding Code, AWS D1.1 are adhered to. In the event that electrodes are exposed to the atmosphere beyond the specified time limit, they are disposed of.

The investigation of this issue did not indicate a problem with control of filler material. Controls are in place to ensure that only qualified welders are issued welding materials and that welders use weld filler materials specified for the work being performed. Unused and waste filler material is controlled by a procedure more stringent than the applicable code requirements.

The quality of coated electrodes has not been a problem at BFN. However, one lot of coated electrodes was returned to the vendor from Watts Bar for a concentricity problem. Welding electrodes from this lot were not issued at Browns Ferry.

Welding filler material used for permanent plant installations at BFN is purchased and tested in accordance with the requirements of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code, Sections II and III. Additionally, TVA performs operability tests beyond the code requirements for all electrodes not already having a satisfactory performance history with TVA.

REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER: 4

TITLE: BFN Site-Specific Welding Subcategory Report Page 4 of 13

The administrative practices for return of unused and waste filler material are not technically significant. This part of the filler material control issue is generically evaluated in Management Practices Subcategory 70200, and is not addressed further by this report.

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-01-BFN.

3.2 Inspection of Welds Through Carbo-Zinc Primer

Evaluation showed that this issue is not applicable to Browns Ferry. In early 1982 General Construction Specification G-29C, Process Specification 3.C.5.4 was revised to permit certain reinspections of structural welds which had been primed. This process specification is site unique to Watts Bar, and was never implemented at BFN.

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-02-BFN

3.3 Welder Qualification and Continuity

The concerns stated the possibility that one wolder's test plate could be completed by another welder; the possibility of welding being performed by an unqualified individual; questioned the adequacy of the basis for welder qualification continuity updates; and questioned maintenance of welder qualifications for personnel whose duties do not regularly require welding.

No one except the Weld Test Supervisor is allowed to enter the test booth while a test is in process. If the Supervisor leaves the test shop for any reason, he collects all weld rod, making it impossible for one welder to work on another's test coupon.

There have been isolated occurrences of welders performing work outside their limits of qualification, i.e., diameter and thickness, or when their qualification continuity for the work could not be verified.

These isolated instances were identified and corrected through the ongoing quality assurance activities. They do not represent a breakdown in the welder qualification program at BFN. Browns Ferry uses manually prepared documents to verify and suspense welder qualification and continuity. The repeated manual preparation of listings to control continuity inevitably leads to error and

1R4

I

i

ı

IR4

REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER: 4

TITLE: BFN Site-Specific Welding Subcategory Report Page 5 of 13

omission. CATQ 50103-BFN-01 recommends that all TVA nuclear activities adopt a uniform computerized system comparable to that used at BLN and WBN in order to minimize the likelihood of a welder working outside of his parameters or allowing a qualification to expire.

Corrective Action Plan

Effective July 1, 1987, BFN implemented Site Director's Standard Practice (SDSP) 13.9, "Welding/Brazing/Soldering Filler Material Issue and Welder/Brazer/Solderer Qualification Computer Program." The computer program is seen as a program enhancement and is similar to the ones at BLN and WBN.

The program is used in conjunction with existing Site Procedures SDSP 13.2, "Welding, Brazing and Soldering Filler Material Control at Browns Ferry Nuclear Plant" and Solderer Qualification and Continuity at Browns Ferry Nuclear Plant."

Welder qualification continuity is based on the welder's utilizing the welding process(s) which they were previously qualified within the specified the limit. TVA uses the issue of weld filler material as evidence brodess usage. This is a widely used practice throughout the nutlear construction industry, and is not in violation of code of commitment.

Welder qualification continuity for personnel whose duties normally do not require unitained in not a violation of code or commitment. Many welders progress to Foreman or higher, and continue to weld occasionally the large in proficiency. This may be done on production work or at the weld test shop. In maintenance of these qualifications the required code and procedural controls apply.

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-03-BFN.

3.4 Availability of Inspection Tools

These concerns state either that inspection tools were never issued, or that inspection tools were not issued prior to 1979.

Inspection tools, locally manufactured and commercially procured, were available to the inspectors throughout construction and operation. While not all inspectors had a full set of tools at all times, any tool necessary for a given task was available upon request.



REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER:

TITLE: BFN Site-Specific Welding Subcategory Report Page 6 of 13

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-O4-BFN.

IR4

3.5 Inspector Training and Certification

The concerns questioned the adequacy of inspector training; qualification of inspectors for the tasks assigned; and exceptions to ANSI N45.2.6 as specified in the Topical Report. Additionally, one concern states that welding inspectors should also be welders. The question of the adequacy of inspector training evolved from concerns which state that personnel with no prior experience are permitted to inspect welds after training periods of two weeks to two months. TVA did issue limited weld inspection certifications based in part on two weeks on the job training. These certifications were limited to verification of weld size, length and location only. Training and testing were appropriate to the limits of this certification. Such limited certifications are in accordance with the Nuclear Quality Assurance Program.

The BFN ISI Group was requested to assist in the USNRC Bulletin 79-14 pipe support walkdown. The inspectors received special training for the visual weld examination portion of the walkdown. When the program actually began, it was learned that the inspectors were expected to perform tasks for which they were not trained or certified. These inspectors were removed from the assignment, and did not actually perform any work for which they were not qualified.

It is true that the TVA program for certification of welding inspectors would not meet the requirements of ANSI N45.2.6. TVA welding inspectors have historically been treated as nondestructive examination (NDE) personnel under the guidelines of the American Society for Nondestructive Testing Recommended Practice SNT-TC-1A, rather than under the rules of ANSI N45.2.6. SNT-TC-1A does not mandate specific experience requirements, and does not specifically deal with visual inspection. It is intended to be used as a guide for employers in establishing their own written practices for qualification and certification of NDE personnel. The TVA practice of using SNT-TC-1A satisfies TVA's commitments as stated in the Topical Report (TVA-TR-75-1A).

There is no code or regulatory requirement for a welding inspector to also be a welder.

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-06-BFN

REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER:

TITLE: BFN Site-Specific Welding Subcategory Report Page 7 of 13

3.6 Welder Training and Experience

The concerns questioned the qualification of subjourneymen for the work to which they are assigned and the adequacy of the TVA welder training program.

1R4

The primary purpose of the subjourneyman is to free the journeyman from trade related tasks which do not effectively utilize his skills. It is possible, however, for the subjourneyman to progress beyond the menial tasks to those requiring a higher degree of skill. This includes becoming a qualified welder. With appropriate training and experience, the subjourneyman may become a qualified welder through satisfactory performance testing under the rules of AWS D1.1 and/or ASME Section IX. These rules establish the ability of the welder to deposit sound weld metal within the parameters of the same performance qualification tests taken by journeyman welders.

The TVA Welder Training Program, a voluntary off-duty course, was offered at BFN approximately during the years 1974 through 1976. The length of training was dependent on the progress of the individual trainee. When sufficient competence was demonstrated, the trainee was given a performance qualification test in accordance with the rules of the governing code. This test was the same test as that given to journeyman welders, with acceptance standards governed by AWS D1.1 and ASME Section IX. The governing codes, industry standards or regulatory requirements do not quantify the experience required of a welder. The code specified performance qualification test is the measure of a welder's capability to deposit sound weld metal.

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-07-BFN.

184

3.7 Surface Grinding of Welds

The concerns questioned the surface grinding of welds and raised the issue of excessive circumferential shrinkage in stainless steel welded joints.

The concerns state that surface grinding of pipe welds may mask surface defects and stainless steel butt welds seem to have excessive metal removed. Grinding of welds is not a violation of codes, standards or BFN procedures. Rather, in many cases these standards require grinding to obtain suitable surfaces for the proper interpretation of the specified NDE and to eliminate or reduce surface defects.

REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER: 4

TITLE: BFN Site-Specific Welding Subcategory Report Page 8 of 13

The construction codes, specifications and procedures do not quantify an acceptance criteria for circumferential shrinkage in welded butt joints. Distortation, including shrinkage is inherent in stainless steel weldments. This distortation is controlled through application of sound engineering practices in development of the detailed weld procedure specifications and design detail. Factors considered are material type and thickness, filler material size, heat input (amperage), and maximum interpass temperature. TVA has implemented detailed welding procedures to minimize distortion and warping when welding stainless steels.

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-11-BFN.

IR4

3.8 Adequacy of Welding Equipment

These concerns stated that the welding machines did not have remote switches and suitable amperage settings.

Browns Ferry has, since beginning construction, used the Lincoln Idealarc TIG 300, K1312 welding machines. These machines are equipped with remote adjustment controls, and operate at a current output range of two to 375 amps. The TIG 300 is suitable for welding with either the shielded metal arc or the gas tungsten arc processes.

This concern was made generically applicable to BFN from WBN where some of the Lincoln Idealarc welding machines were removed from the power block and replaced with multigrid welding machines which generally do not have remote switches and amperage control gradients as fine as the Lincoln Idealarc welding machines.

IR4

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-13-BFN.

IR4

3.9 Structural Steel Preweld Inspections

This issue centers around the fact that TVA does not require 100% mandatory fitup inspection by certified welding inspectors on all structural joints. The foreman is responsible to ensure that the preweld requirements, including correct fitup are met prior to weld out. Certified inspectors monitor each foreman at least bi-weekly to ensure that the foremen are properly performing the required activities. This issue has been evaluated by NSRS, and determined not to be in violation of the Structural Welding Code or ANSI N45.2.5. It was also evaluated for all TVA nuclear sites after being reported (in a Bellefonte Quality Assurance Audit) to the USNRC under the provisions of 10 CFR 50.55(e), and again found to be an acceptable practice.

REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER:

TITLE: BFN Site-Specific Welding Subcategory Report Page 9 of 13

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-16-BFN.

IR4

3.10 Welder Qualification

This issue evolved from a misinterpretation of ASME Section IX, due to the omission of Article QW-302.3 from the 1974 edition.

The concern stated that welders qualified at Muscle Shoals may not have had the required number of bend tests. The same misinterpretation occurred at BFN, resulting in only two guided bend tests being performed for certain qualifications where four bend tests were required. The problem was identified through the ongoing Quality Assurance program, and corrected by retesting all of the affected welders. All of the retested welders were requalified. The production welds made by these welders were evaluated and found to be acceptable.

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-24-BFN.

IR4

3.11 Weld Repairs not Meeting ASME Code Requirements

This issue involves the practice of making temporary repairs by overlay welding and patching. The concern also mentioned the use of furmanite, a viscous sealing compound. The use of furmanite is addressed by Operations Subcategory Report 30800, and is not considered further by this report.

TVA does use mechanical and welded patches to temporarily contain leakage. At Browns Ferry, this has occurred principally in the fire protection system. These patches are not intended or used to substitute for proper repairs in accordance with the code and regulatory requirements. The affected piping is replaced as soon as practicable.

TVA also makes repairs to ASME piping by using welded overlays. Stainless steel piping in boiling water reactors is susceptible to intergranular stress corrosion cracking (IGSCC). Overlay welding is the most commonly used practice to correct for IGSCC. With regard to overlay welding, the USNRC has issued Safety Evaluation Reports to allow Units 1 and 3 to be returned to power in their repaired condition.

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-25-8FN.

REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER: 4

TITLE: BFN Site-Specific Welding Subcategory Report Page 10 of 13

3.12 Structural Support Welds

The concern questions the adequacy of the structural support welds. The concerned individual stated that the process followed today with regard to welding and weld inspection is more detailed and that the original welds would not meet today's requirements.

The concern is factual, in that some of the support welds do not meet the visual acceptance criteria required by the original installation specification (AWS D1.0-1966). Whether or not this is a problem requires engineering evaluation. Also, relative to supports, the process (program) is now clearly defined, where prior to mid-1983 some support welds were not subject to the controls of the Quality Inspection Program.

Field construction at BFN began in September, 1966. It should be noted that construction of BFN was largely completed prior to the TVA commitment to 10 CFR 50, Appendix B in July, 1972.

Discussion with cognizant DNE (Weld Project) personnel revealed that the Welding Project Phase II reinspection of structural supports was an engineering biased sample representative of welding performed over the life of the plant. These inspections included groups of large bore, small bore, instrument pipe and tubing supports, conduit and cable tray supports, HVAC duct supports, and electrical equipment and instrument supports.

Preliminary results of the weld reinspection indicate that the discrepancies identified were largely configurational, i.e., weld size, length and location. It was noted, however, that some of the supports also had rejectable discontinuities in one or more welds. Engineering analysis of these results has thus far shown that, with the exception of instrumentation piping supports, the identified discrepancies are not design significant, i.e., the support welds are suitable for service. The suitability for service of the instrumentation piping support welds is being evaluated, and has not been established to date. Corrective Action will be tracked on CATD 50132-BFN-01.

Corrective Action Plan

Evaluation of the results of the Welding Project reinspection show that the attributes of presence, size, length, and location are the significant attributes affecting welding serviceability. The other attributes (undercut, lack of fusion, etc.) were sometimes present but did not contribute significantly to any overstresses in welds. Thus the action outlined in this Corrective Action Program is needed to provide sufficient confidence in any future engineering stress evaluation of structures at BFN.

IR4

1R4

REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER: 4

TITLE: BFN Site-Specific Welding Subcategory Report Page 11 of 13

The actions specified are required based on the results of the Welding Project basis sample reinspections and a review of welding-related employee concerns. In order to incorporate this at BFN, the following should be included in an engineering procedure and/or in each program/activity that considers structural adequacy:

- 1. Identify that the purpose of the engineering data collection is for use in evaluation of structures.
- 2. Define the training and qualification requirements of the personnel performing the engineering data collection. The training should be similar to that used for Mechanical Maintenance Instruction 99 (MMI), Instruction for the Implementation of Phase I, NRC IE Bulletins 79-14 Units I, II, and III, which appears to have the basic requirements included.
- 3. Specify that the engineering data collection will consist of the weld presence, type, size, length and location. The data collectors should also be aware of such indications as burn through, missing welds, excessive slag, etc. and document their presence for consideration in the structural evaluation.
- 4. The data collection criteria should be the same tolerance as specified in G29C Process Specification 3.C.5.4 for size, length, and location.

Documentation shall consist of:

- 1. A means to identify the item from which the data has been taken.
- A structural sketch indicating presence or lack thereof along with type, size, length, location, and those indications deemed necessary by the engineer of all welds for the identified item.
- 3. A date and sign off by the data collector.
- The engineering data collected should be included in a calculation package and a statement made concerning its acceptability.
- 5. The calculation should be documented in accordance with BFN procedure.
- 6. Document and retain training records.

U

IR4



REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report REVISION NUMBER: 4

TITLE: BFN Site-Specific Welding Subcategory Report Page 12 of 13

Furthermore, it is felt that this need not be backfitted to the cable tray and conduit supports already completed because the United Engineers and Constructors' evaluation should be the basis for Unit 2 restart and the unresolved safety issue A-46, Seismic Qualification of Equipment in Operating Plants, the basis for long-term qualification (both programs address welding) of cable tray and conduit supports.

Action to prevent recurrence is not required, in that Standard Practice 6.2; and later Site Director Standard Practice 13.1 place all safety related welding at BFN under an inspection program. This program has been in effect since mid-1983.

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-32-BFN.

IR4

IR4

3.13 Weld Inspection Procedures

The concerns questioned the adequacy of weld inspection procedures and the adequacy of the inspection criteria; inspection of welding and brazing on HVAC ductwork; and the reporting of defects.

Adequate inspection criteria has been available at BFN since the beginning of construction. Initially, inspection was performed by direct application of the governing codes. A system of procedures evolved and at the time TVA committed to compliance with 10 CFR 50 Appendix B, these procedures contained or made reference to all of the detail and criteria necessary to facilitate weld inspections.

The HVAC ductwork at BFN was fabricated and erected by mechanical means. In mid 1986, welded modifications to the sheet metal ductwork were specificed. At that time, TVA emplaced a procedure which included all of the necessary inspection requirements.

The concerns relating to reporting of defects state that the NDE Inspectors can only use a Notice of Indication for inservice defects, and a Maintenance Request for preservice defects. The Notice of Indication is the specified form for reporting of all defects identified within the scope of a defined examination. The Maintenance Request is used to report all observations by any plant personnel, outside the scope of a defined examination. This practice is in accordance with the Nuclear Quality Assurance Manual.

Complete details of the evaluation of this issue are discussed in Weld Project Evaluation Report WP-35-BFN.

REPORT NUMBER: 50100

REPORT TYPE: Subcategory Report

REVISION NUMBER: 4

TITLE: BFN Site-Specific Welding Subcategory Report Page 13 of 13

4.0 COLLECTIVE SIGNIFICANCE

Through the subcategory overview of the evaluation report findings and the IR4 subsequent integration of information, no new significant items were identified.

The evaluation report investigations and the subcategory overview indicated IRA that the welding procedures and the practices used at BFN were consistent with good industry practices used throughout the country even though a few quality problems appeared.

TVA's welding control practices at BFN were adequate and reflected common industry practices. Some problems were identified, as one would expect with the size of the operation and the time frame, and were addressed by the ongoing QA program and the Weld Project Evaluation Report Investigations.

IR4

IR4

5.0 CAUSE -

The cause of a perceived problem or the cause of a problem which initiated a CATD is limited to the cause identified in the evaluation report.

6.0 CORRECTIVE ACTION

No corrective action is specified as a result of this subcategory report. Corrective actions for problems or perceived problems are limited to the issued CATDs as a portion of the Weld Project Evaluation Reports. Discussion of enhancements to the existing TVA system, other than CATD 50103-BFN-01, will be deferred to the category report. CATD 50103-BFN-01 was issued as a program enhancement. This enhancement recommends that BFN (and all TVA Nuclear Sites) adopt a uniform computerized system comparable to the system used at WBN and BLN in order to minimize the likelihood of a welder working outside his parameters or allowing a qualification to expire.

7.0 ATTACHMENTS

- A. Subcategory Summary Table
- B. Summary of Issues

8.0 REFERENCE

A. Welding Project Evaluation Reports

REFERENCE - ECPS120J-ECPS121C FREQUENCY - REQUEST ONP - ISSS - RIM

CATEGORY: WE NOW QA/QC HELDING

HE 50201 S HUH

1 H Y H H 2 HA SR HA HA

TENNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR PONER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50101 TRACEABILITY, ACCOUNTABILITY, AND CONDITIONING

PAGE - 1 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ IIB	HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
EX -85-039-00101 T50146	HE	50301	s иви	1 N N Y N 2 NA NA SR NA	141-85-053-004	QTC	HBHP: THERE ARE NO PORTABLE OVERS FOR STORING HELD ROD AFTER IT HAS BEEN ISSUED TO THE HELDER AND
02	HE	50101	S HBH	1 Y II II II 2 SR NA NA NA			THE HELD ROD IS NOT ADEQUATELY ACCOUNTED FOR WHEN IT IS RETURNED, I.E. ROD STUBS AND UNUSED ROD. CONST. DEPT. CONCERN. CI HAS NO FURTHER INFORMATION. NO FOLLOHUP REQUIRED. (SQN ISSUES ADDRESSED IN
034	HE	50201	S HBH	1 H Y H H 2 HA SR HA HA	•		. NO FOLLOHUP REQUIRED. (SQN ISSUES ADDRESSED IN RPT NP-01-SQN R3)
04	ИЕ	50401	S MBM	Î II H II Y 2 HA HA HA SR			•
IN -85-234-00101 T50027	HE	50301	S LIBIL	1 II II Y II 2 IIA IIA SR IIA	EX-85-021-001	QTC	HELD RODS ARE NOT REQUIRED TO BE KEPT IN ROD OVENS AFTER ISSURANCE TO STEAMFITTER HELDERS. THE ROD CAN BE KEPT UNHEATED FOR 8 HOURS AT A TIME IN A LE
02	ИЕ	50101	5 HBN	1 Y N N N 2 SR NA NA NA	•		ATHER POUCH. (SQN ISSUES ADDRESSED IN RPT HP-01-SQ'N R3)
03	нЕ	50201	S HBN	1 H Y H H 2 HA SR HA HA			
. 04	HE	50401	S MBH	1 H H H Y 2 HA, HA HA SR	-		
IN -85-247-00101 T50022	ИЕ	50312	S HBN	1 H H Y H 2 HA HA SR HA	In-85-284-001	QTC.	7018 RODS (PURCHASED) ARE OF POOR QUALITY. THIS CONTRIBUTES TO POROSITY AND PINHOLES. (SQN ISSUES AD
02	HE	50101	s iiiii	1 Y II II II 2 SR NA NA NA			DRESSED IN RPT HP-12-SQN R2)
03	HE	50412	S HBN	1 II II II Y 2 IIA IIA IIA SR			•

Á



CATEGORY: HE NON QA/QC HELDING

- ECPS120J-ECPS121C - REQUEST

REFERENCE - ECP FREQUENCY - REQ ONP - ISSS - RIM

TEHNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POHER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50101 TRACEABILITY, ACCOUNTABILITY, AND CONDITIONING

PAGE - 2 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CONCERN HUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ IIB	HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
IN -85-352-00201 T50040	НЕ	50301	S IIBII	1 II II Y II 2 IIA IIA SR IIA	EX-85-021-001	QTC	NO PORTABLE OVENS ARE USED ON HATTS BAR. HELD ROD CAN BE KEPT OUT OF OVEN FOR AN ENTIRE SHIFT AND RETURNED TO OVEN FOR LATER USE. (SQN ISSUES ADDRESS
02	HE	50101	S HBH	1 Y H H H 2 SR HA HA HA			ED IN RPT HP-01-SQN R3)
03	HE	50201	S HBN	1 H Y H H 2 HA SR HA HA		•	
04	HE	50401	S HBH	1 H H H Y 2 HA HA HA SR	F		•
IN -85-424-00101 T50041	ИЕ	50301	S HBH	1 H H Y H 2 HA HA SR HA	EX-85-021-001	QTC	NO PORTABLE OVENS USED/REQUIRED ON HATTS BAR. THE ROD OFTEN COLLECTS MOISTURE AND SHOULD NOT BE USE D. (SQN ISSUES ADDRESSED IN MP-01-SQN R3)
02	HE	50101	S HBH	1 Y H H H 2 SR HA HA HA			p. (Jell 1999rs uppurger II III of Jell 199
03	HE	50201	S HBH	1 II Y II II 2 IIA SR IIA IIA			
04 -	ИЕ	50401	S MBN	1 II II II Y 2 IIA IIA NA SR			
IN -85-424-00401 T50040	HE	50301	S IIBN	1 H H Y H 2 HA HA SR HA	EX-85-021-001	· QTC	QA TRAINING CLASS, 6-5-85, INFORMED CRAFT THAT STE AMFITTERS COULD NITHDRAIL AND CONTROL HELD ROD IF T HEY HAD A HELDER SIGNED HELD SLIP AND THE HEDERS C
- 02	HE	50101	S IIBII	1 Y II II II 2 SR IIA IIA IIA			ARD. (SQN ISSUES ADDRESSED IN RPT INP-01-SQN R3)
0.3	HE	50201	S HBN	1 II Y H H 2 HA SR HA HA			•
04	HE	50401	S HBH	1 II II II Y 2 IIA IIA IIA SR			•

REFERENCE - ECPS120J-ECPS121C FREQUENCY - REQUEST ONP - ISSS - RHM

CATEGORY: HE NON QA/QC HELDING

TENNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POWER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50101 TRACEABILITY, ACCOUNTABILITY, AND CONDITIONING

PAGE - 3 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ WB	HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
IN -85-424-00601 T50040	HE	50301	S HBH	1 H H Y H 2 HA HA SR HA	EX-85-021-001	QTC .	NO ACCOUNTABILITY OF HELD ROD DURING ISSUANCE OR RETURN OF UNUSED ROD AND STUBS. (SQN ISSUES ADDRESS
02	HE	50101	S IIBN	1 Y H H H 2 SR HA HA HA			ED IN RPT NP-01-SQN R3)
. 03	HE	50201	S IIBN	1 H Y H H 2 HA SR HA HA			•
04	ИЕ	50401	S HBN	1 H H H Y 2 HA HA HA SR		4 8 8	•
IN -85-424-00701 T50102	HE	50301	S HBII	1 H H Y H 2 HA HA SR HA	EX-85-021-001	QTC	LACK OF HELD ROD CONTROL: HELDORS GET ADDITIONAL R OD FROM OTHER HELDORS RATHER THAN GOING BACK TO THE
02	HE	50101	S HBN	1 Y H H H H 2 SR HA HA HA		d •	E ROD ROOM FOR MORE. SITE POLICY ALLOWS LEAVING R OD HITH OTHER WELDORS, OR LETTING SUB-JOURNEYMEN C-HECK-OUT ROD AND RETURN ROD. (CAN ALSO LEAVE ROD IN TOOL BOXES). THE ROD ROOM DOES NOT COUNT ROD H
03	HE	50201	S HBN	1 H Y H H 2 HA SR HA HA		•	HEN IT IS ISSUED, AND DOES NOT REQUIRE ACCOUNTING FOR ROD STUBS. OCCASSIONALLY, HELDORS ARE REPRIMA NIDED FOR NOT TURNING IN ROD HITHDRAHAL SLIPS, EVEN
04	HE	50401	S MBN .	1 N H H Y 2 HA HA HA SR			THOUGH (SQN ISSUES ADDRESSED IN RPT NP-01-SQN R3)
* IN -85-426-00101 T50065	HE	50301	S ИВН	1 H H Y H' 2 HA HA SR HA	EX-85-021-001	QTC	PORTABLE OVEHS ARE NOT REQUIRED. HELD ROD IS KEPT OUT OF OVEH FOR AN ENTIRE SHIFT. NO FOLLON-UP. (SQN ISSUES ADDRESSED IN RPT NP-01-SQN R3)
02	ИЕ	50101	S IIBH	1 Y N II II 2 SR NA NA NA			3411 1330E3 ADDRESSED TH KET HE-01-341 K37
03	HE	50201	S 'IBN	1 H Y H H 2 HA SR HA HA		*	
- 04	HE	50401	S HBN	1 N N H Y 2 NA NA NA SR			•

PAGE RUN TIME - 11:45:02 RUN DATE - 12/17/87

REFERENCE - ECPS120J-ECPS121C - REQUEST FREQUEICY ONP - ISSS - RUM

04

HE

50401

S HBH

1 11

HHY 2 HA HA HA SR

OFFICE OF NUCLEAR PONER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY SUBCATEGORY: 50101 TRACEABILITY, ACCOUNTABILITY, AND CONDITIONING

TENNESSEE VALLEY AUTHORITY

CATEGORY: HE NON QA/QC HELDING н 1 REPORT APPL R PLT 2 SAF RELATED HISTORICAL CONCERN CONCERN NUMBER CAT D LOC BF BL SQ HB REPORT ORIGIN CONCERN DESCRIPTION IN -85-441-00301 HE 50301 S MBN EX-85-021-001 QTC 1 H H Y H NO PORTABLE OVENS ON HATTS BAR. THE ROD SOMETIMES COLLECTS MOISTURE BY THE END OF THE SHIFT AND CAN T50040 2 HA HA SR HA NOT BE USED. (SQII ISSUES ADDRESSED IN RPT HP-01-SQ 02 HE 50101 S HBH 1 Y N N N H R3) 2 SR HA HA HA IRY R 03 ИE 50201 S HBN 2 HA SR HA HA 04 50401 S HBH 1 H H H Y 2 HA HA HA SR IN -85-453-00901 1 H H Y H EX-85-021-001 QTC HELDERS FREQUENTLY GIVE HELD ROD TO OTHER HELDERS. 50301 S WBN T50030 2 HA HA SR HA (SQN ISSUES ADDRESSED IN RPT HP-01-SQN R3) ИE 1 Y H H H 02 50101 S HBH 2 SR IIA IIA IIA 03 HE 50201 S HBN INYN 2 HA SR HA HA 04 HE 1 H H H Y 50401 S WBN 2 HA HA HA SR IN -85-454-00401 HE 50301 S NBN 1 H H Y H EX-85-021-001 QTC HELDERS FREQUENTLY GET ROD FROM EACH OTHER INSTEAD T50030 2 HA HA SR HA OF HITHDRAHING FOR ROD ROOM, (SQN ISSUES ADDRESSE D IN RPT HP-01-SQN R3) 02 HE 50101 S 11BII 1 Y H H H 2 SR HA HA HA 03 HE 50201 S 11BN 1 N Y N N 2 HA SR HA HA

- ECPS120J-ECPS121C - REQUEST · REFERENCE FREQUEICY - RECOUP - ISSS - RUM

CATEGORY: HE HON QA/QC HELDING

PAGE - 5 RUN TIME - 11:45:02 RUN DATE - 12/17/87

TENNIESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR PONER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50101 TRACEABILITY, ACCOUNTABILITY, AND CONDITIONING

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ IIB	HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
IN -85-501-00101 T50031	HE	50319	S HBH	1 II II Y II 2 IIA IIA SR IIA	III-85-501-001	QTC	UNUSED BUNDLES OF HELD ROD FREQUENTLY FOUND IN TRASH CAME I.E. TURBINE BLDG., 708°, 729°, AND 755° E LEVATIONS, UNIT #2 (15-20 RODS FOUND 6-7-85) (SQN
02	HE	50101	S IIBII	1 Y N II H 2 SR HA HA HA			ISSUES ADDRESSED IN RPT WP-19-SQN R1)
.03	HE	50201	S IIBH	1 H Y H H 2 HA SR HA HA			
. 04	HE	50401	S ИВН	1 II II II Y 2 IIA IIA IIA SR			
IN -85-672-00301 T50207	MP	70202	S ИВИ	1 II H H H H 2 HA HA HA HA	•	QTC	AT SHIFT END, WELD ROD SLIPS ARE TURNED IN. THE SLIPS ARE CHECKED THEN THROWN ANALY. IF THE ISSUE R
02	HE	50301	S HBH	1 II II Y H 2 HA HA SR HA			OON DETERMINES AT A LATER DATE THAT A HELDER DID NOT CONFORM TO "TURN IN" PROCEDURES, IT IS HIS MORDAGAINST THEIRS AND HE GETS THE MARNING LETTER. THESE LETTERS HAVE BEEN ISSUED MITHOUT PROOF OF MRO
03	HE	50101	S IIBN	1 Y H H H 2 SR HA HA HA			NGDOING. CONSTRUCTION DEPT. CONCERN. (SQN ISSUES ADDRESSED IN RPT NP-01-SQN R3)
04	HE	50201	S IIBII	1 II Y II II 2 NA SR NA NA			
. 05	HE	50401	S IIBII	1 H H H Y 2 HA HA HA SR			•
IN -86-047-00101 T50110	HE	50314	S IIBII	1 II II Y II 2 IIA IIA SR IIA		QTC	A SYSTEM IS NEEDED THAT VERIFYS THAT THE MELDER DID RETURN THE UNUSED MELD ROD AND STUBS AND MILL PROVIDE THE MELDER A RECEIPT SO THAT THE MELDER CAN
02	HE	50101	S HBH	1 Y II II II 2 SR IIA IIA IIA			PROVE HE DID RETURN THE NATERIAL IN CASE AN ERROR HAS NADE. CI HAS NO ADDITIONAL INFORMATION. CONSTRUCTION DEPARTMENT. (SQN ISSUES ADDRESSED IN RPY
03	HE	50201	S IIBII	1 H Y H H 2 HA SR HA HA			WP-14-SQN R1)
04	HE	50401	S IIBN	1 II H H Y 2 HA HA HA SR			



REFERENCE - ECF FREQUENCY - REC ONP - ISSS - RIM - ECPS120J-ECPS121C - REQUEST

PAGE - 6 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CATEGORY: HE NON QA/QC HELDING

TEHNESSEE VALLEY AUTHORITY
OFFICE OF HUCLEAR POHER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50101 TRACEABILITY, ACCOUNTABILITY, AND CONDITIONING

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ IIB		CDNCERN ORIGIN	CONCERN DESCRIPTION
. WI -85-053-00401- T50135	HE	__ 50301	S HBH	1 H H Y H 2 HA HA SS HA	HI-85-053-004	QTC	WELD ROD CONTROL DOES NOT SATISFY CODE REQUIREMENT S. TVA ATTITUDE IS "ALL MATERIAL IS CODE MATERIAL". CONSTRUCTION DEPT CONCERN. CI HAS NO FURTHER
02	HE	50101	S HBH	1 Y H H H 2 SS HA HA HA			INFORMATION. (SQN ISSUES ADDRESSED IN RPT NP-01-SQN R3)
03	HE	50201	S HBH	1 H Y H H 2 HA SS HA HA			-
04	нЕ	50401	S HBH	1 H H H Y 2 HA HA HA SS			· ·

16 CONCERNS FOR CATEGORY HE SUBCATEGORY 50101

REFERENCE - ECPS120J-ECPS121C FREQUENCY - REQUEST ONP - ISSS - RHM

CATEGORY: HE NON QA/QC HELDING

TENNESSEE VALLEY AUTHORITY
OFFICE OF HUCLEAR PONER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50102 INSPECTION OF HELDS THROUGH PAINT

PAGE - 7 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ IIB	HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
IN -85-458-00101 T50105	HE	50102	S HBH	1 Y II II H 2 SS NA NA NA	IN-85-458-001	QTC	TVA USED IMPROPER INSPECTION CRITERIA FOR ANS MELD S - MENO FROM KNOXVILLE (POSSIBLY ENDES, 1980 OR 1 981) ALLOHED INSPECTION THROUGH PAINT. INDIVIDUAL
02	HE	50202 ^	S HBH	1 H Y H H 2 HA SS HA HA			FROM KNOXVILLE (KNONN) INVESTIGATED THIS, BUT RES ULTS ARE UNKNOWN. CI HAS NO MORE INFORMATION. (SQ N ISSUES ADDRESSED IN RPT NP-02-SQN R2)
_ 03	ИЕ	50302	S HBH	1 H N Y H 2 HA NA SS HA		•	
04	HE	50402	S HBN	1 H H H Y 2 HA HA HA SS			•
IN -86-019-00101 T50219	HE	50102	S MBN	1 Y II II II 2 SR NA NA NA		QTC'	CI IS CONCERNED THAT HELDS NERE ACCEPTED THROUGH C ARBO-ZINC. INSPECTORS NERE DIRECTED VIA MENO TO A CCEPT NELDS THROUGH PAINT. CI COULD NOT PROVIDE A
02	HE	50202	S HBH	1 II Y II II 2 IIA SR IIA IIA			NY ADDITIONAL INFORMATION. UNIT 1. CONSTRUCTION DEPT. CONCERN. (SQN ISSUES ADDRESSED IN RPT HP-02-SQN R2)
03	HE	50302	S HBH	1 H H Y H 2 HA HA SR HA		•	,
04	HE	50402	S HBN	1 II II II Y 2 IIA IIA IIA SR			
HS -85-001-00101 T50022	HE	50102	S IIBII	1 Y II II II 2 SR IIA IIA IIA	NS-85-001-001	QTC	HELDS (ANS) INSPECTED SUBSEQUENT TO PROTECTIVE COATING (CARBOZINC PRIMER) APPLICATION; FINAL VISUAL
02	HE	50202	S HBN	1 H Y H H 2 HA SR HA HA			HELD EXAMINATION OF STRUCTURAL HELDS IN CATEGORY I STRUCTURES, INCLUDING PIPE HANGERS, CABLE TRAY SU PPORTS AND DUCT SUPPORTS; UNIT 1 & 2 (SQN ISSUES A DDRESSED IN RPT HP-02-SQN R2)
03	HE	50302	S WBN	1 H H Y H 2 HA HA SR HA			. ,
, 04 -	NE	50402	S MBH	1 H H H Y 2 HA HA HA SR	p.	•	

CATEGORY: HE HON QA/QC HELDING

TENNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POHER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50102 INSPECTION OF NELDS THROUGH PAINT

PAGE - 8 RUN TIME - 11:45:02 RUN DATE - 12/17/87

	,		-				
CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ HB	HISTORICAL REPORT	CONCERNORIGIN	CONCERN DESCRIPTION
PH -85-040-00101 T50203	HE	50102	S HBH	1 Y N N N 2 SR NA NA NA	IN-85-458-001	QTC:	QA HANGERS HERE FREQUENTLY PAINTED BEFORE THE HELD S HERE INSPECTED. AUX. BUILDING, REACTOR BUILDING \$1, ELEV. 742'-0", & 745'-0". 1983. CONSTRUCTION DEPT. CONCERN. CI HAS NO FURTHER DETAILS. (SQN)
. 02	ИЕ	50202	S HBII	1 H Y H H 2 HA SR HA HA		!	N DEPT. CONCERN. CI HAS NO FURTHER DETAILS. (SQN ISSUES ADDRESSED IN RPT NP-02-SQN R2)
03	ИЕ	50302	S HBH	1 H H Y H 2 HA HA SR HA		* * *	
04	ИЕ	50402	S НВИ	1 H H H Y 2 HA HA HA SR			
HI -85-013-00301 T50114	HE	50102	S HBN	1 Y H H H 2 SS HA HA HA	WI-85-013-003	QTC*	G29C (CONSTRUCTION SPECIFICATIONS)ALLONED WELDS TO DE INSPECTED AFTER PAINTING FROM 1981 THROUGH THE END OF THE WELDING SAMPLING PROGRAM. THIS IS IN
02	, IIE	50202	S IIBN	1 H Y H H 2 HA SS HA HA			VIOLATION OF AMS DI.1. CI HAS NO MORE INFORMATION . (NOTE: THIS ITEM IS CURRENTLY UNDER INVESTIGATY ON DY ERT. THE REVISION HAS MADE TO SEPARATE THE ORIGINAL 003 CONCERN INTO THO DISTINCT CONCERNS.)
03	HE	50302	S HBH	1 II II Y II 2 IIA IIA SS IIA			ORIGINAL 003 CONCERN INTO THO DISTINCT CONCERNS.) (SQN ISSUES ADDRESSED IN RPT NP-02-SQN R2)
0,4	HE	50402	S HBH	1 H H H Y 2 HA HA HA SS	*	!	, y,
HI -85-030-00701 T50185.	HE	50116	S HBH	1 Y II II H 2 SR IIA IIA IIA		QTC.	THE NBN FSAR COMMITS TVA TO THE REQUIREMENTS OF AN S D.1.1 FOR STRUCTURAL HELDING. CONTRARY TO THESE
. 02	HE	50102	S HBH	1 Y H H H 2 SR HA HA HA			REQUIREMENTS, THE G-29C PROCESS SPECIFICATION MAS MODIFIED TO REFLECT LESS STRINGENT INSPECTION REQUIREMENTS (E.G. VISUAL INSPECTION OF MELDS THROUGH PAINT (CARBO ZINC PRIMER) AND NO DOCUMENTED INSPE
03	HE	50216	S HBN	1 H Y H H 2 HA SR HA HA		1	ROCESS) PRIOR TO FINAL INSPECTION.) CI HAS NO ADDI
04	HE	50316	S HBN	1 H H Y H 2 HA HA SR HA		•	TIONAL INFORMATION. NUC. POHER DEPT. CONCERN. (SQ N ISSUES ADDRESSED IN RPT NP-16-SQN R2)
. 05	HE	50416	S HBH	1 H H H Y 2 HA HA HA SR			
06	HE	50202	S HBII	1 H Y H H 2 HA SR HA HA			

1 H H H Y 2 HA HA HA SR

HE 50402 S HBH

CATEGORY: HE HON QA/QC HELDING

PAGE - 9 RUN TIME - 11:45:02 RUN DATE - 12/17/87

TEMMESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POMER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50102 INSPECTION OF NELDS THROUGH PAINT

CONCERN NUMBER	CAT	SUB CAT	H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ HB	HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
NI -85-030-00801 T50185	HE	50319	S HBH	1 II II Y II 2 IIA IIA SR IIA		QTC	THERE MAY HAVE BEEN THOUSANDS OF HELDS INSPECTED T HROUGH CARBO-ZINC PRIMER. HONEVER, TVA REPORTS IN DICATE THAT ONLY 100-150 HELDS HERE INSPECTED IN T
02	HE	50102	S HBH	1 Y N N N 2 SR NA NA NA	*		HIS MANNER EVEN THOUGH THERE IS NO DOCUMENTATION I DENTIFYING WHICH WELDS MERE INSPECTED THROUGH CARB O-ZINC PRIMER. NUC. POMER CONCERN. CI HAS NO ADDI
03	HE	50202	S HBII	1 H Y H H 2 HA SR HA HA		. :	TIONAL INFORMATION. (SQN ISSUES ADDRESSED IN RPT N P-19-SQN R1)
04	HE	50402	S ИВН	1 H H H Y 2 HA HA HA SR		•	
HI -85-041-00601 T50193	HE	50102	S IIBN	1 Y H H H 2 SS HA HA HA	EX-85-052-005	QTC	ANS WELD INSPECTOR(S) (UNKNOWN) DID NOT UNDERSTAND THE "5 MIL" PROVISION FOR INSPECTION OF COATED (C ARBO-ZINC PRIMER) WELDS AS CONTAINED IN REVISIONS
. 02	HE	50202	S IIBII	1 H Y H H 2 HA SS HA HA			OF SPECIFICATION G-29C, PROCEDURE QCP-4.13, AND ME MORANDUM DATED HOVEMBER 1981. INSPECTOR(S) REFERR ED TO CRITERIA AS "MILLIAMPS" AND THEREFORE COULD
. 03	ИЕ	50302	S HBH	1 H H Y H 2 HA HA SS HA		•	HOT HAVE IMPLEMENTED/INSPECTED FOR CONFORMANCE. C I HAS NO ADDITIONAL INFORMATION. NUC POWER DEPT. CONCERN. (SON ISSUES ADDRESSED IN RPT NP-02-SQN R2
04	HE	50402	S IIBII	1 H H H Y 2 HA HA HA SS	,)
III -85-041-00801 T50193	HE	50102	S IIBII	1 Y II II II 2 SS IIA IIA IIA	IN-85-458-001	QTC	PROCESS SPECIFICATION #3.C.5.4 OF G-29C PERMITTED INSPECTION OF AMS MELDS THROUGH COATING (CARBO-ZIN C PRIMER) FOR ELEVEN MONTHS AFTER ENGINEERING EVAL
02	HE	50202	s иын	1 H Y H H 2 HA SS HA HA			UATION/TEST SHOWED THAT WELD QUALITY (POROSITY, CR ACKS, ETC) COULD NOT BE INSPECTED THROUGH PAINT. NUC POWER DEPT. CONCERN. CI HAS NO ADDITIONAL INF
03	ИЕ	50302	S MBN	1 II II Y II 2 IIA IIA SS IIA			ORMATION. (SQN ISSUES ADDRESSED IN RPT NP-02-SQN R
04	HE	50402	S HBH	1 H H H Y 2 HA HA HA SS		;	



PAGE - 10 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CATEGORY: HE NON QA/QC HELDING

TENHESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POHER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50103 NELDER PERFORMANCE QUALIFICATION CONTINUITY

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ HB	HISTORICAL REPORT	-CONCERN ORIGIN	CONCERN DESCRIPTION
EX -85-021-00201 T50069	HE	50103	S HBII	1 Y H H H 2 SR HA HA HA	IN-85-352-001	QTC	THERE IS NO METHOD/OBJECTIVE EVIDENCE TO VERIFY TH AT A HELDER HAS USED A SPECIFIC PROCESS WHEN THEIR
02	ИЕ	50203	S ИВИ	1 H Y H H 2 HA SR HA HA			HELD CARDS ARE STAMPED/UP-DATED BY QC. NO FOLLOW-UP REQUIRED - NO ADDITIONAL INFORMATION AVAILABLE . (SQN ISSUES ADDRESSED IN RPT NP-03-SQN R3)
03	HE	50303	S HBH	1 II N Y II 2 IIA IIA SR IIA -			·
04	HE	50403	S NBN	1 II II II Y 2 IIA IIA IIA SR			•
HI -85-077-H1701	HE	50103	н вей	1 Y N H H 2 SR NA NA NA		HRC	NRC IDENTIFIED THE FOLLOWING CONCERN FROM REVIEW OF THE QTC FILE: "WELDING BY UNCERTIFIED NELDER AT BROWNS FERRY."
IN 6-85-346-00301 T50026	HE	50103	S HBH	1 Y H H H 2 SR HA HA HA	IN-85-352-001	QTC	HELDER CERTIFICATIONS ARE UPDATED ON EVIDENCE OF R OD HITHDRAMAL SLIPS. THE PROCESS MAY NOT HAVE BEE
02	HE	50303	S IIBII	1 H H Y H 2 HA HA SR HA			N USED IN THE APPLICABLE TIME PERIOD, 90 DAY OR/80 DAY, DEPENDING ON ASME OR AMS. (SQN ISSUES ADDRES SED IN RPT MP-03-SQN R3)
03	HE	50403	S HBH	1 H H H Y 2 HA HA HA SR	-		•
IN -85-426-00201 T50065	HE	50103	S HBH	1 Y II II II 2 SR IIA IIA IIA	IN-85-352-001	QTC	UPDATING OF NELDER CERTIFICATIONS IS INADEQUATE IN THAT A MELDER IS ONLY REQUIRED TO PRESENT THEIR C ARD FOR UPDATING AND SOMETIMES IS ASKED TO RUN A B
02	нЕ	50203	S HBH	1 H Y H H 2 HA SR HA HA		1	EAD- HEVER A COMPLETE HELD. HO FOLLOW-UP. (SQN IS SUES ADDRESSED IN RPT MP-03-SQN R3)
03	HE	50303	S IIBN	1 II II Y II 2 IIA IIA SR IIA			•
- 04	NE	50403	S NBN	1 H H H Y 2 HA HA HA SR			•

CATEGORY: HE HOH QA/QC HELDING

TEMMESSEE VALLEY AUTHORITY
OFFICE OF HUCLEAR POMER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50103 HELDER PERFORMANCE QUALIFICATION CONTINUITY

PAGE - 11 RUH TIME - 11:45:02 RUH DATE - 12/17/87

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ IIB	HISTORICAL REPORT	COHCERH ORIGIN	CONCERN DESCRIPTION
IN -85-480-00401 T50031	HE	50103	S ИВН	1 Y N N N 2 SR NA NA NA	IN-85-770-002	QTC	HELDER CERTIFICATION UPDATE IS INADEQUATE. PERSON NEL MAY HORK IN A POSITION THAT DOES HOT REQUIRE A
02	ИE	50203	S ИВИ	1 H Y H H 2 HA SR HA HA			NY NELDTING FOR 5-6 YEARS BUT CERTIFICATIONS ARE CONTINUALLY UPDATED. WHEN THESE PERSONS RETURN TO WELDTING NO TESTS ARE CONDUCTED. THEY JUST RUN STRYNGERS TO UPDATE CERTIFICATIONS. (SQN ISSUES ADDRES
, 03	HE	50303	S WBN	1 H H Y H 2 HA HA SR HA			SED IN RPT NP-03-SQN R3)
. 04	HE	50403	S HBH	1 H H H Y 2 HA HA HA SR			•
IN -85-725-X1401 T50167	ИЕ	50319	S IIBII	1 H H Y H 2 HA HA SR HA	IN-85-725-X14	QTC	WELDER RECERTIFICATION PROGRAM HAD INADEQUATE SUPE RVISORY OVERSIGHT: IT COULD HAVE BEEN POSSIBLE FO P. A. GOOD HELDER TO HELD THE TEST PLATES FOR AN INC
02	HE	50103	S HBH	1 Y H H H 2 SR HA HA HA			RVISORY OVERSIGHT: IT COULD HAVE BEEN POSSIBLE FOR A GOOD HELDER TO WELD THE TEST PLATES FOR AN INC APABLE MELDER. DETAILS KNOWN TO QTC, MITHELD TO MAINTAIN CONFIDENTIALITY. (SQN ISSUES ADDRESSED IN RPT MP-19-SQN R1)
03	HE	50403	S HBN	1 H H H Y 2 HA HA HA SR			
IN -85-725-X1501 T50167	HE	50319	S ИВН	1 H H Y H 2 HA HA SR HA	IN-85-725-X15	QTC	THE CONTROL OF HELDER RECERTIFICATION TEST PLATES HAS INADEQUATE: TEST PLATES BEGUN BY ONE HELDER C
02	HE	50103	S HBH	1 Y II II II 2 SR IIA IIA IIA		•	OULD HAVE BEEN COMPLETED BY ANOTHER MELDER. DETAIL KNOWN TO QTC-HITHELD TO MAINTAIN CONFIDENTIALITY. (SQN ISSUES ADDRESSED IN RPT MP-19-SQN R1)
03	ИE	50203	S WBN	1 N Y N N 2 NA SR NA NA			
04	HE	50403	S IIBII	1 H H H Y 2 HA HA HA SR	•		·

REFERENCE - ECF FREQUENCY - REC ONP - ISSS - RHM - ECPS120J-ECPS121C - REQUEST

CATEGORY: HE NON QA/QC HELDING

PAGE - 12 RUN TIME - 11:45:02 RUN DATE - 12/17/87

TEMMESSEE VALLEY AUTHORITY
OFFICE OF MUCLEAR POWER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50104 INSPECTION TOOLS AT BFNP

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ HB	HISTORICAL CO REPORT OR	ONCERN RIGIN	CONCERN DESCRIPTION
IN -85-007-00101, T50001	HE	50104	S HBH	1 Y" H H H 2 SR HA HA HA	Q	QTC I	INSPECTION TOOLS FOR HELDING INSPECTORS HERE NEVER ISSUED. I.E. FILLET HELD SIZE GAGES, FIT-UP GUAGES, ETC. (SQN ISSUES ADDRESSED IN RPT HP-04-SQN R2
02	ИЕ	50204	S HBH	1 H Y H H 2 HA SR HA HA	-)	S, EIC. (SQN 1550E5-ADDRESSED IN RPT NP-04-SQN R2
03	HE	50304	S HBH	1 II II Y H 2 HA HA SR HA			•
. 04	IIE	50404	S HBN .	1 H H H Y 2 HA HA HA SR			
IN -85-134-00201 T50050	HE	50104	S ИВИ	1 Y H H H 2 SS HA HA HA	Q	J STP	UNTIL RECENTLY (PAST 2 YEARS), TVA DID NOT PROVIDE QC INSPECTORS NITH HELDING INSPECTION TOOLS. SON
02	HE	50204	S IIBII	1 H Y H H 2 HA SS HA HA	. •	i A	QC THISPECTORS WITH HELDING THISPECTION TOOLS. SOME THISPECTORS PROVIDED THEIR OWN TOOLS BUT OTHERS DELATED HOT. CI HAS PASSED AWAY, NO FURTHER DETAILS AVAILABLE. (SQN ISSUES ADDRESSED IN RPT HP-04-SQN R2
03	HE	50304	S LIBN	1 H H Y H 2 HA HA SS HA		•	
. 04	HE	50404	ווכוי צ	1 H H H Y 2 HA HA HA SS			
IN -85-406-00301 T50013	HE	50104	S IIBII	1 Y H H H 2 SS HA HA HA	. · Q	1	PRIOR TO 1979, NO HELD INSPECTION TOOLS HERE ISSUED TO INSPECTORS. (SQN ISSUES ADDRESSED IN RPT HP-0 (-SQN R2)
02	liE	50204	S 41BH	1 H Y H H 2 HA SS HA HA	,	•	-5411 K2)
03	HE	50304	S IIBII	1 H H Y H 2 HA HA SS HA		•	*
. 04	. HE	50404	S I'BII	1 H H H Y 2 HA HA HA SS			,

CATEGORY: HE NON QA/QC HELDING

PAGE - 13 RUN TIME - 11:45:02 RUN DATE - 12/17/87

TEMMESSEE VALLEY AUTHORITY
OFFICE OF MUCLEAR POWER
ENPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50106 TRAINING & CERTIFICATION OF CONST WELD INSPECTORS

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ IIB	HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
IN -85-476-00402 T50037	HE	50206	S HBH	1 N Y N N 2 NA SR NA NA	EX-85-052-005	QTC	APPROX. 1980, TVA IMPLEMENTED A HELDING INSPECTORS TRAINING PROGRAM AND PEOPLE WITH A GROCERY CLERK BACKGROUND WERE INSPECTING HELDS WITHIN THO WEEKS.
03	HE	50106	S HBH	1 Y H H H 2 SR HA HA HA		•	(SQN ISSUES ADDRESSED IN RPT MP-06-SQN RD)
04	HE	50306	S HBH	1 H H Y H 2 HA HA SR HA			•
. 05	HE	50406	S HBN	1 N N N Y 2 NA NA NA SR			
IN -85-981-00102 T50111	WE	50206	S HBH	1 N Y N N 2 NA SR NA NA	EX-85-052-005	QTC	HELDING INSPECTORS HERE INADEQUATELY TRAINED PIROR TO 1981, I.E., PERSONNEL WITH NO EXPERIENCE INVOL VING HELDING HERE SENT TO A THO HEEK TRAINING CLAS
03	HE	50106	S HBH	1 Y H H H 2 SR NA NA NA		·	S AND THEN FUNCTIONED AS A MELDING INSPECTOR. CI HAS NO MORE INFORMATION. NO FOLLOW UP REQUIRED. (SQN ISSUES ADDRESSED IN RPT MP-06-SQN RO)
. 04	HE	50306	S ИВИ	1 H H Y H 2 HA HA SR HA	•	•	
05	HE	50406	S HBN	1 H H H Y 2 HA HA HA SR	•	•	
SQH-86-035-00101	НЕ	50106	N BFN	1 Y II II II 2 SS IIA IIA IIA		HSRS	DURING THE INTERVIEW CONTACT THE CI STATED AND LAT ER DUCUMENTED THAT THE CI AND FELLOW ISI INSPECTOR S HERE ASKED TO PERFORM HELD INSPECTIONS WITHOUT B EING QUALIFIED.
SQN-86-035-00201	HE	50106	N BFN	1 Y H H H 2 SS HA HA HA		HSRS	DURING AN INTERVIEW CONTACT THE CI STATED AND LATE R DOCUMENTED THAT THE CI AND FELLOW ISI INSPECTORS HERE REMOVED FROM PERFORMING WELD INSPECTIONS BECAUSE THEY HERE NOT QUALIFIED. AFTER THEY HERE REMOVED FROM THE JOB THEY HERE REPLACED BY INSPECTORS ALSO NOT QUALIFIED.

- ECPS120J-ECPS121C REFERENCE FREQUENCY - REQUEST OHP - ISSS - RIM

PAGE - 14 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CATEGORY: HE HON QA/QC HELDING

TEMMESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POWER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50106 TRAINING & CERTIFICATION OF CONST WELD INSPECTORS

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ HB		CONCERN ORIGIN	CONCERN DESCRIPTION
ИІ -85-041-00202 Т50103	HE	50206	S ИВИ	1 H Y H H 2 HA SS HA HA	EX-85-052-005	QTC.	QUALIFICATION/TRAINING OF INSPECTORS FOR STRUCTURA L (AMS) HELD VISUAL EXAMINATION IS QUESTIONABLE; L EVEL II CERTIFICATION IS GRANTED WITH ONLY THO MON
03	HE	50106	S HBII	1 Y II II II 2 SS NA NA NA	•		THS OF OJT, MHICH IS NOT DOCUMENTED; THE TOPICAL R EPORT HAS "BASTARDIZED" ANSI N45.2.6, REGARDING QU ALIFICATION OF INSPECTION/EXAMINATION PERSONNEL.
• 04	HE	50306	S HBH	1 H H Y H 2 HA HA SS HA			CT HAS NO FURTHER INFORMATION. NO FOLLOW UP REQUI RED. (SQN ISSUES ADDRESSED IN RPT HP-06-SQN RO)
. 05	ИЕ	50406	S IIBII	1 H H H Y 2 HA HA HA SS	,		
WI -85-081-00702 T50237	NE.	50206	S HBH	1 H Y H H 2 HA SR HA HA	EX-85-052-005	. QTC	CI EXPRESSED THAT HELDING INSPECTORS ARE NOT QUALIFIED FOR THE JOB. CI STATED THAT AN INSPECTOR NEED TO BE A HELDER SO THE INSPECTOR HOULD KNOW HHA
. 03	ИE	50106	S HBH	1 Y H H H 2 SR HA HA HA			T TO LOOK FOR IN A GOOD HELD. CI DECLINED TO PROVIDE ANY ADDITIONAL INFORMATION. CONSTRUCTION DEPARTMENT CONCERN. NO FOLLOW UP REQUIRED. (SQN ISSUE
04	IIE	50306	S HBN	1 H H Y H 2 HA HA SR HA	•		S ADDRESSED IN RPT HP-06-SQN RO)
05	HE	50406	S IIBII	1 H H H Y	•		

6 CONCERNS FOR CATEGORY HE SUBCATEGORY 50106


2 HA HA HA SR

PAGE ' - 15 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CATEGORY: HE HON QA/QC HELDING

TEHNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POHER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50107 HELDER TRAINING PROGRAM FOR CONST AND HELDING INSP

4						• "	
CONCERN NUMBER	CAT	SUB CAT	H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ MB	. HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
EX -85-008-00101 T50051·	ИЕ	50107	S HBH	1 Y II H H 2 SR HA HA HA	EX-85-010-002	QTC	SUBJOURNEYMEN USED TO DO HORK THAT THEY'RE NOT QUA LIFIED TO DO: THEY NEEDN'T HAVE ANY SPECIFIC TRAI NING, BUT DO HORK (EG PIPE FIT-UPS AND HELDS ON 1/
02	HE	50207	S MBN	1 H Y H H 2 HA SR HA HA			4" LINES) NORMALLY DONE BY A JOURNEYMAN WITH 5 YEARS MINIMUM EXPERIENCE. SUBJOURNEYMEN REQUIRE CLOSER TECHNICAL SUPERVISION THAN TVA PROVIDES. WHEN
03	ИЕ	50307	S WBN	1 H H Y H 2 HA HA SR HA	•	CRAFTS COMPLAIN, THEY ARE "CHEVIED OF REASONABLE LIMITS. NO MORE DETAILS	CRAFTS COMPLAIN, THEY ARE "CHEMED OUT" BEYOND ALL REASONABLE LIMITS. NO MORE DETAILS KNOWN. (SQN IS SUES ADDRESSED IN RPT MP-07-SQN R1)
04	HE	50407	S MBN	1 H H H Y 2 HA HA HA SR			-
IN -85-706-00101 T50064	HE	50107	S MBN	1 Y H H H 2 SR HA HA HA		QTC	HELDERS WHO WENT THROUGH TVA'S HELDER TRAINING PROGRAM HAVE INSUFFICIENT TRAINING AND EXPERIENCE TO HANDLE ALL VARIABLES INVOLVED TO PERFORM ADEQUATE
02	HE	50207	S MBN	1 H Y H H 2 HA SR HA HA			HELDS FOR A HUCLEAR INSTALLATION. THIS INADEQUACY- HAS CREATED A LOT OF REHORK. CI HAS NO MORE DETA ILS. (SQN ISSUES ADDRESSED IN RPT MP-07-SQN R1)
03	HE	50307	S HBN	1 H H Y H 2 HA HA SR HA			TES. (SQN 1550E5 ADDRESSED AN IN OF GAN IN-
04	HE	50407	S ИВИ	1 H H H Y 2 HA HA HA SR			
IN -86-158-00601 T50180	ИĘ	50314	S HBH	1 H H Y H 2 HA HA SR HA		QTC	UNTIL 1973 TVA DID NOT LET THEIR APPRENTICESHIP PE OPLE HELD. DURING THAT YEAR, EVEN HITH THO OR THR EE HOHTHS EXPERIENCE, AN APPRENTICE COULD TAKE THE
02	HE	50107	S IIBH	1 Y H H H 2 SR HA HA HA			TEST, PASS, AND BE ABLE TO NELD IN THE FIELD. THE SYSTEM HAS HORKED THAT MAY EVEN SINCE 1973. CONST. DEPT. CONCERN. C/I HAS NO FURTHER INFORMATION
03	HE	50207	S IIBII	1 H Y H H 2 HA SR NA HA			. (SQII ISSUES ADDRESSED III RPT HP-14-SQII R1)
04	HE	50407	S HBII	1 H H H Y 2 HA HA HA SR			



PAGE - 16 RUN TIME - 11:45:02 RUN DATE - 12/17/87

REFERENCE - ECPS120J-ECPS121C FREQUENCY - REQUEST ONP - ISSS - RIM . TEMMESSEE VALLEY AUTHORITY
OFFICE OF MUCLEAR PONER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50111 SURFACE GRINDING OF HELDS

CATEGORY: HE HON QA/QC HELDING

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ HB	HISTORICAL CONCE	
IN -85-282-00202 T50014	HE	50111	S HBH	1 Y N N N 2 SR NA NA NA	IN-85-282-002 QTC	UNTIL RECENTLY, TVA HELD INSPECTORS REQUIRED ALL P IPE HELDS TO BE SURFACE GROUND TO A SMOOTH FINISH.
03	ИЕ	50234	S HBH	1 H Y H H 2 HA SR HA HA		THE CONCERN IS THAT SMOOTH GRINDING MAY ACTUALLY MASK A SURFACE DEFECT WHICH HOULD OTHERHISE BE DE TECTABLE. NO FURTHER DETAILS HERE AVAILABLE. (SQN
04	ИЕ	50311	S HBH	1 H H Y H 2 HA HA SR HA		ISSUES ADDRESSED IN RPT NP-11-SQN R1)
. 05	HE	50411	S HBN	1 H H H Y 2 HA HA HA SR		· ·
IH -85-299-00301 T50188	ИЕ	50319	S HBH	1 H H Y H 2 HA HA SR HA	QTC	SS HELDS SEEM TO HAVE EXCESS METAL REMOVED AT BUTT HELD JOINTS, ALSO THE HELDS EXHIBIT EXCESSIVE SHR
02	ИЕ	50234	S HBH	1 H Y H H 2 HA SR HA HA	•	INKAGE AT JOINTS. THIS CONCERN IS GENERIC BUT HAVE E EXAMPLES. THIS HAS BEEN NOTICED FOR THE PAST 6 YEARS IN BOTH UNITS. DETAILS KNOWN TO GIC, HITHHEL
03	HE	50111	S IIBII	1 Y H H H 2 SR HA HA HA		D DUE 10 CONFIDENTIALITY. CONSTRUCTION DEPT CONCE R. (SQN ISSUES ADDRESSED IN RPT NP-19-SQN R1)
. \$04	IJΕ	50432	S IIBN	1 H H H Y '		
* 05	HE	50411	S HBH	1 H H H Y 2 HA HA HA SR		

CATEGORY: HE NON QA/QC HELDING

TENNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR PONER
ENPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50113 SUITABILITY OF HELDING EQUIPMENT

PAGE - 17 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ HB	HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
IN -85-247-00201 T50022	HE	50113	S HBN	1 Y H H H 2 SR HA HA HA		QTC	WELDING MACHINES (MCKAY & HOBART) USED IN FIELD BY STEAM FITTERS HAVE 2 SETTINGS 50 & 100 AMPS BOTH
. 02	ИЕ	50213	S WBN	1 N Y N N 2 NA SR NA NA			OF WHICH ARE UNSUITABLE FOR MELDING WITH 3/32" ROD. THIS CONTRIBUTES TO POROSITY AND PINHOLES. (SQN ISSUES ADDRESSED IN RPT MP-13-SQN RO)
03	НЕ	50313	S IIBN,	1 N N Y N 2 NA NA SR NA		,	ì
04.	ИЕ	50413	S HBN	1 N N N Y 2 NA NA NA SR	4	-	•
IN -85-303-00101 T50021 .	.HE	50113	S HBN	1 Y H H H 2 SR HA HA HA	•	QTC	ALL THE WELDING MACHINES SHOULD HAVE REMOTE SHITCH ES SO THAT THE TUNGSTEN TIP DOESN'T HAVE TO TOUCH THE BASE METAL TO START THE WELD. PRESENTLY THE N
02	НЕ	50213	S MBN	1 N Y N N 2 NA SR NA NA			ON-HOBART MELDERS, MIEN USED, MAY CAUSE TUNGSTEN TO BE LEFT IN THE WELD. (SQN ISSUES ADDRESSED IN RP
03	НЕ	50313	S HBN ·	1 N N Y N 2 NA NA SR NA		•	T HP-13-SQH RO)
04	ИЕ	50413	S IIBN	1 H H H Y 2 HA HA HA SR			•



CATEGORY: HE NON QA/QC HELDING

TENNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POHER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50116 PERFORMANCE OF PRE-WELD INSPECTION

PAGE - 18 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CONCERN NUMBER	CAT	SUB CAT	H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ HB	HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
BEM-85-001-00101 . T50227	WE	50116	S BLN	1 Y H H H 2 SR HA HA HA		QTC	BELLEFONTE - THE GENERAL CONST. SPEC. G-29C, PROCE SS SPEC. D.C.1.1 IS IN CONFLICT WITH THE TVA QUALITY ASSURANCE COMMITMENTS AS STATED BY THE TVA TOPI CAL REPORT, TVA-TR75-1A, IN THAT PROCESS SPEC. D.C.
02	HE	50216	S BLN	1 H Y H H 2 HA SR HA HA		,	CAL REPORT, TVA-TR75-1A, IN THAT PROCESS SPEC. O.C. 1.1, SECTION 6.0 ALLOWS UNCERTIFIED WELDER FOREMEN, WHO HAVE DIRECT RESPONSIBILITY FOR THE INSTALLA
03	не	50316	S BLH	1 H H Y H 2 HA HA SR HA			TION, TO PERFORM PREHELD INSPECTIONS. NUCLEAR PON ER CONCERN. CI HAS NO FURTHER INFORMATION. (SQN I SSUES ADDRESSED IN RPT NP-16-SQN R2)
04	HE	50416	S BLII	1 H H H Y 2 HA HA HA SR			· · · · · · · · · · · · · · · · · · ·
BEM-85-001-00201 T50227	HE	50116	S BLN	1 Y II II II 2 SR IIA IIA IIA	•	QTC	BELLEFONTE - UNCERTIFIED WELDER FOREMEN ARE REQUIR ED BY TVA TO PERFORM PRENELD INSPECTIONS ON INSTAL LATIONS THEY ARE DIRECTLY RESPONSIBLE FOR WHICH IS
02	HE	50216	S BLN	1 II Y II II 2 IIA SR IIA IIA			LATIONS THEY ARE DIRECTLY RESPONSIBLE FOR WHICH IS A VOILATION OF ANSI REQUIREMENTS. NUCLEAR POWER CONCERN. CI HAS NO FURTHER INFORMATION. (SQN ISSUES ADDRESSED IN RPT NP-16-SQN R2)
03	HE	50316	S BLN	1 H H Y H 2 HA HA SR HA			LO NOSILLOSLO IN IN VIII LO OUI ILLO
. 04	ИЕ	50416	S BLN	1 H H H Y . 2 HA HA HA SR	•		
BFM-85-001-00101 T50221	ИЕ	50116	S BLN	1 Y H H H 2 SR HA HA HA	-	QTC	BELLEFONTE - THE GENERAL CONST. SPEC. G-29C, PROCE SS SPEC.O.C.1.1 IS IN CONFLICT WITH THE TVA QUALITY ASSURANCE COMMITMENTS AS STATED BY THE TVA TOPIC AL REPORT, TVA-TR75-1A, IN THAT PROCESS SPEC. O.C.
02	ИЕ	50216	S BLN	1 H Y H H 2 HA SR HA HA	•		1.1. SECTION 6.0 ALLONS UNCERTIFIED HELDER FORMEN.
03	HE	50316	S BLII	1 H H Y H 2 HA HA SR HA			INO HAVE DIRECT RESPONSIBILITY FOR THE INSTALLATION, TO PERFORM PREMELD INSPECTIONS. NUCLEAR POMER CONCERN. CI HAS NO FURTHER INFORMATION. (SQN ISSUES ADDRESSED IN RPT NP-16-SQN R2)
04	HE	50416	S BLH	1 H H H Y 2 HA HA HA SR			

REFERENCE - ECF FREQUENCY - REC ONP - ISSS - RNM

TERRIESSEE VALLEY AUTHORITY
OFFICE OF HUCLEAR POWER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50116 PERFORMANCE OF PRE-HELD INSPECTION

PAGE - 19 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CATEGORY: HE NON QA/QC HELDING

- ECPS120J-ECPS121C - REQUEST

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ IIB	HISTORICAL REPORT	CONCERN ORIGIN	CONCERN DESCRIPTION
BFM-85-001-00201 T50221	HE '	50116	S BFN	1 Y II H II 2 SR HA HA HA		QTC	BROWN'S FERRY - UNCERTIFIED WELDER FOREMEN ARE REQUIRED BY TVA TO PERFORM PRE-HELD INSPECTIONS ON IN
02	WE	50216	S BFN	1 N Y N N 2 NA SR NA NA	ď		STALLATIONS THEY ARE DIRECTLY RESPONSIBLE FOR WHICH IS A VIOLATION OF ANSI REQUIREMENTS. NUCLEAR POWER CONCERN. CI HAS NO FURTHER INFORMATION. (SQN ISSUES ADDRESSED IN RPT MP-16-SQN R2)
. 03	HE	50316	S BFN	1 H II Y II 2 IIA IIA SR IIA			1330L3 ADDRESSED IN ACT MC-10-34N K2)
04	NE	50416	S BFII	1 II II II Y 2 IIA IIA IIA SR		•	
ИВИ-85-001-00102 Т50227	ИЕ	50116	S ИВИ	1 Y H H H 2 SR HA HA HA		QTC	HATTS BAR - THE GENERAL CONST. SPEC. G-29C, PROCES S SPEC. O.C.1.1 IS THE CONFLICT WITH THE TVA QUALITY OF THE TYPE TYPE THE TYPE TYPE THE TYPE TYPE TYPE TYPE TYPE TYPE TYPE TYP
03	HE	50216	S IIBH	1 H Y H H 2 HA SR HA HA			Y ASSURANCE COMMITMENTS AS STATED BY THE TVA TOPIC AL REPORT, TVA-TR75-1A, IN THAT PROCESS SPEC. O.C. 1.1, SECTION 6.0 ALLOWS UNCERTIFIED HELDER FOREMEN, WHO HAVE DIRECT RESPONSIBILITY FOR THE INSTALLAT
04	HE	50316	S HBH	1 H H Y H 2 HA HA SR HA			ION, TO PERFORM PREHELD INSPECTIONS. NUCLEAR PONE R CONCERN. CI HAS NO FURTHER INFORMATION. (SQN IS SUES ADDRESSED IN RPT NP-16-SQN R2)
05	ИЕ	50416	S HBN	1 H H H Y 2 HA HA HA SR	•		
ИВМ-85-001-00201 Т50227	ИЕ	50116	S SQN	1 Y II H H 2 SR HA HA HA		QTC	SEQUOYAH - UNCERTIFIED HELDER FOREMEN ARE REQUIRED BY TVA TO PERFORM PREHELD INSPECTIONS ON INSTALLA TIONS THEY ARE DIRECTLY RESPONSIBLE FOR WHICH IS A
02	ИЕ	50216	S SQN	1 II Y II II 2 IIA SR IIA IIA		1	VIOLATION OF ANSI REQUIREMENTS. NUCLEAR POHER CO NCERN. CI HAS NO FURTHER INFORMATION. (TRANSFERRE
03	HE	50316		1 II II Y II 2 IIA IIA SR IIA			D TO MBH-85-001-003, CONCERN MAS ADDRESSED BY HELD ING CATEGORY BEFORE TRANSFER MAS DOCUMENTED, AND MILL HOT BE IMPUT TO GH CATEGORY, SQN ISSUES ADDRES SED IN RPT MP-16-SON R2)
04 •	HE	50416	S SQII	1 II II II Y 2 IIA IIA IIA SR			

TENNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POWER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50116 PERFORMANCE OF PRE-WELD INSPECTION

PAGE - 20 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CONCERN DESCRIPTION

THE MBN FSAR COMMITS TVA TO THE REQUIREMENTS OF AU S D.1.1 FOR STRUCTURAL HELDING. CONTRARY TO THESE

S D.1.1 FOR STRUCTURAL HELDING. COMMARY TO THESE REQUIREMENTS, THE G-29C PROCESS SPECIFICATION HAS MODIFIED TO REFLECT LESS STRINGENT THISPECTION REQUIREMENTS (E.G. VISUAL INSPECTION OF HELDS THROUGH PAINT (CARBO ZINC PRIMER) AND NO DOCUMENTED INSPECTION BY CERTIFIED VISUAL INSPECTORS (FIT-UP, IN-PROCESS) PRIOR TO FINAL INSPECTION.) CI HAS NO ADDITIONAL INFORMATION. NUC. POMER DEPT. CONCERN. (SQ N ISSUES ADDRESSED IN RPT NP-16-SQN R2)

CATEGORY: HE HON QA/QC HELDING

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ HB	HISTORICAL CONCERN REPORT ORIGIN
III -85-030-00701 T50185	ИЕ	50116	S HBH	1 Y H H H 2 SR HA HA HA	QTC
. 02	HE	50102	S IIBN	1 Y H H H 2 SR HA HA HA	•
) o 3	HE	50216	S IIBN	1 N Y N. II 2 NA SR NA NA	•
04	HE	50316	S IIBII	1 H H Y H 2 HA HA SR HA	
05	HE	5041é	S HBII	1 II II II Y 2 IIA IIA IIA SR	
06	WE	50202	S HBH	1 N Y H H 2 NA SR HA NA	-
08	HE	50402	S WBN	1 H H H Y 2 HA HA HA SR	•

7 CONCERNS FOR CATEGORY HE SUBCATEGORY 50116

4

TENNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POWER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50124 WELDER PERFORMANCE QUALIFICATION

PAGE - 21 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CATEGORY: HE HON QA/QC HELDING

CONCERN NUMBER	CAT	SUB CAT	H R PL D LO	1 REPORT APPL 2 SAF RELATED BF BL SQ HB	HISTORICAL CONCERN REPORT ORIGIN	CONCERN DESCRIPTION
JLH-85-002 01	HE	50124	s so	1 Y II II II 2 SS IIA IIA IIA	OECP	THIS CONCERN HAS NOT DOCUMENTED PER SQA166 BUT HAS BEEN INCLUDED IN THE ENPLOYEE CONCERN LOG. HELDE RS FROM MUSCLE SHOALS MAY NOT HAVE RECEIVED THE AP
02	HE	50203	S 50	1 H Y H H 2 HA SS HA HA		PROPRIATE NUMBER OF BEID TESTS WHEN TAKING WELD QU ALIFICATION TESTS. (SQN ISSUES ADDRESSED IN RPT MP -24-SQN RO)
03	HE	50324	S S (1 H H Y H 2 HA HA SS HA		24 341 1107
04	HE	50424	S 50	1 H H H Y 2 HA HA HA SS	•	



HISTORICAL REPORT

PAGE RUN TIME - 11:45:02 RUN DATE - 12/17/87

CONCERN DESCRIPTION

TVA MAKES REPAIRS TO THEIR NUCLEAR PLANTS WHICH AR E NOT IN ACCORDANCE WITH ASME CODES, SUCH AS OVERL AYS, PATCHES, AND EVEN FURMATITE (SOPHISTICATED GLUE). (SQN ISSUES ADDRESSED IN RPT WP-25-SQN RO)

CATEGORY: HE NON QA/QC HELDING

TÉMMESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POMER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50125 EFFECTS OF HELD REPAIRS NOT MEETING ASME CODE

COLICERIA

ORIGIN

HRC

S

CONCERN NUM	BER	CAT	SUB CAT	H R PLT D LOC	1 2	SAI	FRI	ELAT SQ	ED	
2850162005	01	OP	30803	S NPS	1 2	Y SS	Y SS	Y SS	Y SS	
	02	HE	50125	ș NPS	1 2	Y SS	H HA	H HA	II IIA	
	03	HE	50236	S NPS	1 2	N NA	Y SS	N NA	H HA	
	04	ИĒ	50325	S IIPS	1 2	H	H HA	Y SS	H HA	
	05	HE	50425	S HPS	1 2	N NA	H HA	N NA	Y SS	

TENNESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POWER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50132 ADEQUACY OF STRUCTURAL SUPPORT HELDS

HSRS

PAGE - 23 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CATEGORY: WE NOW QA/QC WELDING

BFN-85-019-00101

S
H 1 REPORT APPL
SUB R PLT 2 SAF RELATED HISTORICAL CONCERN
CONCERN NUMBER CAT CAT D LOC BF BL SQ NB REPORT ORIGIN

1 Y H H H

2 SS HA HA HA

DURING AN EXIT INTERVIEN THE CI EXPRESSED HIS CONC ERN THAT MANY WELDS AND HANGERS ARE QUESTIONABLE M ITH RESPECT TO THEIR ADEQUACY. THE PROCESS FOLLOW ED TODAY WITH REGARD TO MELDING AND HELD INSPECTION IN IS MORE DETAILED AND THAT ORIGINAL MELDS IN QUES TION HOULD NOT PASS CURRENT REQUIREMENTS.

CONCERN DESCRIPTION

1 CONCERNS FOR CATEGORY, HE SUBCATEGORY 50132

ИЕ 50132 N BFN

CATEGORY: HE HOH QA/QC HELDING

TEMMESSEE VALLEY AUTHORITY
OFFICE OF NUCLEAR POWER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50135 NELD INSPECTION PROCEDURES

PAGE - 24 RUN TIME - 11:45:02 RUN DATE - 12/17/87

ly.	CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ NB	HISTORICAL REPORT	CONCERNORIGIN	CONCERN DESCRIPTION
	IN -85-406-00201 T50013	NE	50135	S HBH	1 Y H H H 2 SS NA NA NA		QTC	PRIOR TO 1979 THERE WAS NO SPECIFIC WELD INSPECTION IN CRITCRIA FOR USE BY INSPECTION PERSONNEL. IT IS BELIEVED THAT THIS PROBLEM WAS VALID TVA SYSTEM WILDER ALL PLANTS. (SQN ISSUES ADDRESSED IN RPT HP-0
	02	HE	50309	SHBII	1 H H Y H 2 HA HA SS HA			IDE- ALL PLANTS. (SQN ISSUES ADDRESSED IN RPT NP-0 9-SQN R1)
	, 03	HE	50243	S HBH	1 N Y N N 2 NA SS NA NA	•		1
		HE	50432	S WBN	1 H H H Y 2 HA HA HA SS			
	PH -85-012-X0301 T50077	HE.	50135	S HBH	1 Y H H H 2 SR HA HA HA	PH-85-012-X03	QTC	HELDING AND BRAZING INSPECTION OF SAFETY-RELATED H VAC DUCTHORK HAS DELETED SUBSEQUENT TO 1981 FROM T
	02	ИЕ	50305	s ивн	1 H H Y H 2 HA HA SR HA			VAC DUCTHORK HAS DELETED SUBSEQUENT TO 1981 FROM THE QA PROGRAM HITHOUT ADEQUATE JUSTIFICATION. HAT TS BAR UNITS 1 & 2, SAFETY RELATED DUCTHORK. ADDITIONAL DETAILS ARE AVAILABLE IN FILE. (SQN ISSUES ADDRESSED IN RPT HP-05-SQN RI)
	03	HE	50235	S HBN	1 H Y H H 2 HA SR HA HA			
	04	ИЕ	50405	S HBH	1 H H H Y .			
	XX -85-102-00601 T50172	QA	80201	S BFH	1 H H Y H 2 HA HA SR HA		QTC	BROWN'S FERRY: THE VISUAL EXAMINATION PROCEDURE WHICH COVERS ASME SECTION II IS VERY NON SPECIFIC. NUCLEAR POWER DEPT. CONCERN. CI HAS NO ADDITIONAL
	03	ИЕ	50135	S BFH	1 Y H H H 2 SR HA HA HA		•	INFORMATION. NO FOLLOW UP REQUIRED.
	04	HE	50243	S BFN	1 H Y H H 2 HA SR HA HA			. •
_	05	HE	50432	S BFH	1 II N II Y 2 IJA IIA IIA SR			•
	06	QA	80252	S BFII	1 II II Y II 2 IIA IIA SR IIA			·

114




TENNESSEE VALLEY AUTHORITY
OFFICE OF HUCLEAR PONER
EMPLOYEE CONCERN PROGRAM SYSTEM (ECPS)
EMPLOYEE CONCERN INFORMATION BY CATEGORY/SUBCATEGORY
SUBCATEGORY: 50135 WELD INSPECTION PROCEDURES

PAGE - 25 RUN TIME - 11:45:02 RUN DATE - 12/17/87

CONCERN NUMBER	CAT	SUB CAT	S H R PLT D LOC	1 REPORT APPL 2 SAF RELATED BF BL SQ MB	HISTORICAL CONCERN REPORT ORIGIN	CONCERN DESCRIPTION
XX -85-102-00701 T50172	ИЕ	50243	S BFN	1 N Y N N 2 NA SR NA NA	QTC	BROWN'S FERRY: NDE INSPECTORS CAN ONLY WRITE A NOT ICE OF INSPECTION ON IN-SERVICE RELATED DEFECTS.
02	ИE	50135	S BFII	1 Y H H H 2 SR HA HA HA		PRESERVICE DEFECTS CAN ONLY BE IDENTIFIED BY A MAI NTENANCE REQUEST. NUCLEAR POHER DEPT. CONCERN. C I HAS NO ADDITIONAL INFORMATION. NO FOLLOW UP REQUIRED.
03	HE	50426	S BFN	1 H H H Y 2 HA HA HA SR	-	OIRLD.
XX -85-102-01101 T50172	HE	50243	s sqn	1 H Y H H 2 HA SR HA HA	I-85-735-SQN QTC	SEQUOYAH: NDE INSPECTORS CAN ONLY HRITE A HOTICE OF INSPECTION ON IN-SERVICE RELATED DEFECTS. PRESERVICE RELATED DEFECTS CAN ONLY BE IDENTIFIED BY A
. 02	HE	50399	s sqii	1 N N Y N 2 NA NA SR NA	A	MAINTENANCE REQUEST. NUCLEAR PONER DEPT. CONCERN. CI HAS NO FURTHER INFORMATION. NO FOLLOW UP REQUIRED. (SQN ISSUES ADDRESSED IN MSRS RPT I-85-735-S
03	HE	50135	s squ	1 Y H H H 2 SR HA HA HA		QII)
. 04	HE	50426	S SQII	1 N N N Y 2 NA NA NA SR		

CONCERN	DESCRIPTION OF ISSUES	I COMMENTS
EX-85-039-001 IN-85-234-001 IN-85-247-001 IN-85-352-002 IN-85-424-004 IN-85-424-006 IN-85-424-007 IN-85-424-007 IN-85-424-007 IN-85-453-009 IN-85-453-009 IN-85-672-003 IN-85-672-003 IN-86-047-001 WI-85-053-004 IN-85-458-001 IN-86-019-001 NS-85-001-001 PH-85-040-001 WI-85-030-007 WI-85-030-007 WI-85-030-008 WI-85-041-006 WI-85-041-008	Lack of portable rod ovens to protect coated electrodes from moisture absorption. Inadequate control of weld rod. Poor quality E7018 electrodes Administrative practices for return of filler material. The Process Specification permitted inspection of AWS welds through coating of carbo-zinc primer. Thousands of welds may have been inspected through primer. There is no documentation to show which welds were involved. Inspectors did not under- stand the coating thickness limit for inspecting primed welds.	The Browns Ferry program for control of welding filler material meets' the requirements of ANSI/AWS D1.1 Section 4, ASME Section III NB-4000 and ASME Section XI IWB-4000. The quality of the electrodes purchased meets the requirements of ASME Section II and III. This issue has been address- ed by Weld Project Evalua- tion Report WP-01-BFN. The Process Specification in question was site unique for Watts Bar, and was never implemented at Browns Ferry. The BFN specifications and procedures meet the requirements of ANSI/AWS D1.1. This issue has been address- ed by Weld Project Evalua- tion Report WP-02-BFN.
EX-85-021-002 HI-85-077-N17 IN-85-346-003 IN-85-426-002 IN-85-480-004 IN-85-725-X14 IN-85-725-X15	The possibility exists that I one welder could weld or I complete a test plate for I another welder. I Welding by an uncertified I welder.	No one except the Weld Test Supervisor is allowed to enter the test booth while a welder is being tested. There have been isolated instances of welders operating outside their



CONCERN	DESCRIPTION OF ISSUES	I COMMENTS
	I Inadequate basis for Welders' qualification continuity updates. I Personnel whose duties do not require welding continue to have their qualification continuity updated. I I	I identified and corrected by I the ongoing Quality I Assurance activities. The
IN-85-007-001 IN-85-134-002 IN-85-406-003		Inspection tools were available throughout construction and operation. This issue has been addressed by Weld Project Evaluation Report WP-04-BFN.
IN-85-476-004 IN-85-981-001 SQN-86-035-001 SQN-86-035-002 WI-85-041-002 WI-85-081-007	Qualification of Welding I Inspectors. I Topical Report not in I compliance with ANSI I N45.2.6.	Welding Inspectors are qualified in accordance with the Nuclear Quality Assurance Manual. Welding Inspectors are qualified and certified using SNT-TC-1A as a guide, rather than ANSI N45.2.6. Appropriate exceptions to Regulatory Guide 1.58 are made in the Topical Report. This issue has been addressed by Weld Project Evaluation Report WP-06-BFN.

CONCERN	DESCRIPTION OF ISSUES	COMMENTS
EX-85-008-001 IN-85-706-001 IN-86-158-006	Qualification and experience of Subjourneymen. Adequacy of TVA Welder Training Program.	Subjourneymen are utilized in accordance with the applicable labor agreement and good management practices.
	1 1 1 1	Welders are tested and qualified in accordance with AWS D1.1 and ASME Section IX.
	 	 This issue has been address- ed by Weld Project Evalua- tion Report WP-07-BFN.
IN-85-282-002 IN-85-299-003	Surface grinding of welds. Shrinkage of stainless steel butt joints. Surface grinding and shrinkage	Surface grinding of welds is provided for by the ASME, ANSI and AWS codes. Some shrinkage is inherent in girth butt welded joints in stainless steels. Heat input during welding is controlled by adherence to approved welding procedures. This issue has been addressed by Weld Project Evaluation Report WP-11-8FN.
IN-85-247-002 IN-85-303-001	1	I The Lincoln IDEALARC TIG I 300 welding machine was I used at Browns Ferry. This I machine features remote I current adjustment, soft I start, and current output I range of two through 375 I amperes. I This issue has been address— I ed by Weld Project Evalua— I tion Report WP-13-BFN.

CONCERN	DESCRIPTION OF ISSUES	I COMMENTS
BEM-85-001-001 BEM-85-001-002 BFM-85-001-001 BFM-85-001-002 WBM-85-001-001 WBM-85-001-002 WI-85-030-007	Foremen perform preweld inspections, which is not in accordance with the Topical Report, ANSI N45.2.5 and AWS D1.1.	I AWS D1.1 allows preweld I activity examinations to be I on a sampling basis. Browns I Ferry procedures and I specifications mandated I surveillance programs of all I welding activities. I Practice at Growns Ferry I does not violate the TVA I Topical Report or ANSI I N45.2.5. I This issue has been address— I ed by Weld Project Evalua—
JHL-85-002	I Welders from Muscle Shoals I may not have had the	I tion Report WP-16-BFN. I All affected welders at BFN were regualified to the
	l appropriate number of bend l tests.	requirements of ASME Section IX.
	§ 1 1 1	I This issue has been I addressed by Weld Project I Evaluation Report WP-24-BFN. I
2850162005	l overlays, patches and I Furmanite (viscous fluid	Overlay welding is an acceptable method of making temporary repairs to correct for intergranular stress corrosion cracking. TVA's plan for use of overlays was approved by the USNRC.
		Temporary mechanical and to the little patches are used to contain leakage. They do not substitute for permanent repairs in accordance with applicable codes.

CONCERN	DESCRIPTION OF ISSUES	COMMENTS
		This issue has been address— Hed by Weld Project Evalua— Hed tion Report WP-25-BFN. HUSE of viscous fluid Hedlant is outside the Hescope of the Weld Project, Hand has been addressed by Hescope of Subcategory 30800
BFN-85-019-001	I would not meet today's	
IN-85-406-002 PH-85-012-X03 XX-85-102-006 XX-85-102-007 XX-85-102-011	Welding and brazing	commitment to 10CFR50 Appendix B, a procedure system was in place and provided all of the

CONCERN	DESCRIPTION OF ISSUES	I COMMENTS
	 	The Notice of Indication is used to report defects identified within the defined scope of an inspection, inservice or preservice. The Maintenance Request is used to report observations identified outside the defined scope of an inspection.
•	1	This system is in compliance with the Nuclear Quality Assurance Manual.
•	1 	I This issue has been address- I ed by Weld Project Evalua- I tion Report WP-35-BFN.

