

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9503140057 DOC. DATE: 95/03/07 NOTARIZED: NO DOCKET #
 FACIL: 50-260 Browns Ferry Nuclear Power Station, Unit 2, Tennessee 05000260
 AUTH. NAME AUTHOR AFFILIATION
 Hsieh, C.S. Tennessee Valley Authority
 MACHON, R.D. Tennessee Valley Authority
 RECIPIENT NAME RECIPIENT AFFILIATION

SUBJECT: LER 95-003-00: on 950207, test results showed that SRVs failed setpoint test acceptance criteria. Caused by corrosion bond of SRV pilot disc/seal interface. Two out-of-tolerance target rock valves being refurbished & retested. W/950307 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 7
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-4-PD	1 1	WILLIAMS, J.	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	1 1
	AEOD/SPD/RRAB	1 1	FILE CENTER 02	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DISP/PIPB	1 1
	NRR/DOPS/OECB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRSS/PRPB	2 2	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SRXB	1 1	RES/DSIR/EIB	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	2 2
	NOAC MURPHY, G.A	1 1	NOAC POORE, W.	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1


NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 27 ENCL 27

A04

P
R
I
C
R
I
T
Y
1
D
C
U
M
E
N
T





Tennessee Valley Authority, Post Office Box 2000, Decatur, Alabama 35609-2000

R. D. (Rick) Machon
Vice President, Browns Ferry Nuclear Plant

March 7, 1995

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

10 CFR 50.73

Dear Sir:

BROWNS FERRY NUCLEAR PLANT (BFN) - UNITS 1, 2, AND 3 - DOCKET
NOS. 50-259, 50-260, AND 296 - FACILITY OPERATING LICENSE
DPR-33, 52, AND 68 - LICENSEE EVENT REPORT 50-260/95003

The enclosed report provides details concerning the Unit 2
main steam safety/relief valves (SRVs) exceeding the
technical specifications setpoint limit during tests. A
supplemental report will be submitted after the test results
of all 13 SRVs have been received.

This report is submitted in accordance with 10 CFR 50.73
(a)(2)(i)(B) as a condition prohibited by the plant's
technical specifications.


Sincerely,

R. D. Machon
Site Vice President

Enclosure
cc: See page 2

9503140057 950307
PDR ADDCK 05000260
S PDR

TEK
11



U.S. Nuclear Regulatory Commission
Page 2
March 7, 1995

Enclosure

cc (Enclosure):

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Paul Krippner
American Nuclear Insurers
Town Center, Suite 300S
29 South Main Street
West Hartford, Connecticut 06107

NRC Resident Inspector
Browns Ferry Nuclear Plant
Route 12, Box 637
Athens, Alabama 35611

Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Mr. J. F. Williams, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

E. V. Imbro, NRR/RSIB
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

E. J. Leeds, NRR/DRPW
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852



LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MHBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Browns Ferry Nuclear Plant (BFN) Unit 2	DOCKET NUMBER (2) 05000260	PAGE (3) 1 OF 5
---------------------------------------------------------------------	--------------------------------------	---------------------------

TITLE (4) Main Steam Safety/Relief Valves Exceeded the Technical Specifications Required Setpoint Limit as a Result of Disc/Seat Bonding

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
02	07	95	95	003	00	03	07	95	NA	NA
									NA	

OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)										
POWER LEVEL (10) 100	20.402(b)			20.405(c)			50.73(a)(2)(iv)			73.71(b)	
	20.405(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(v)			73.71(c)	
	20.405(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vii)			OTHER	
	20.405(a)(1)(iii)			X 50.73(a)(2)(i)(B)			50.73(a)(2)(viii)(A)			(Specify in Abstract below and in Text, NRC Form 366A)	
	20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)				
	20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(x)				

LICENSEE CONTACT FOR THIS LER (12)

NAME Clare S. Hsieh, Compliance Licensing Engineer	TELEPHONE NUMBER (Include Area Code) (205) 729-2635
--------------------------------------------------------------	---------------------------------------------------------------


COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYS TEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
X	SB	RV	T020	Y						

SUPPLEMENTAL REPORT EXPECTED (14)				EXPECTED SUBMISSION DATE (15)		
X	YES (If yes, complete EXPECTED SUBMISSION DATE).		NO	04	10	95

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On February 7, 1995, Wyle Laboratories notified TVA that tests had been completed for 2 of the 13 Unit 2 main steam safety/relief valves (SRVs). The results of the tests showed that the SRVs failed the setpoint test acceptance criteria. The SRV setpoints were found outside the Technical Specification (TS) limit of +/- one-percent setpoint tolerance. This condition is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B) as a condition prohibited by the plant's TS. The apparent cause was attributed to corrosion bonding of the SRV pilot disc/seat interface resulting in an upward setpoint drift. TVA will submit a supplemental report following receipt of the test results of the remaining SRVs. TVA has implemented one of the Boiling Water Reactor Owners Group's recommendations to reduce corrosion. During the Unit 2 Cycle 7 refueling outage, TVA removed the SRV pilot cartridges from the main steam SRVs and replaced them with cartridges refurbished with a 0.3 percent platinum alloyed stellite pilot disc.



LICENSEE EVENT REPORT
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Browns Ferry Unit 2	05000260	95	003	00	2 of 5

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

I. PLANT CONDITIONS

Unit 2 was operating at approximately 100 percent power. During the Unit 2 Cycle 7 refueling outage, the safety/relief valve (SRV) pilot cartridges were removed from the Unit 2 main steam [SB] SRVs [RV] for testing. Units 1 and 3 were shutdown and defueled.

II. DESCRIPTION OF EVENT

A. Event:

On February 7, 1995, Wyle Laboratories notified TVA that the tests on the first 2 of the 13 Unit 2 main steam SRVs (Target Rock Two-Stage SRV Model No. 7576F) had been completed. The results of the tests showed that the SRVs failed the setpoint test acceptance criteria.

During the Unit 2 Cycle 7 refueling outage, the SRV pilot cartridges were removed from the Unit 2 main steam SRVs and sent to Wyle Laboratories for testing. On February 7, 1994, the first two SRV pilot cartridges were bench tested, and the test results showed that the pilot cartridges caused the SRVs to open outside the Technical Specifications (TS) limit of +/- one-percent of setpoint tolerance (i.e., the test results were +3.85 percent and +1.95 percent, respectively).

The above condition is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B) as a condition prohibited by the plant's TS.

B. Inoperable Structures, Components, or Systems that Contributed to the Event:


None.

C. Dates and Approximate Times of Major Occurrences:

During the Unit 2 Cycle 7 outage (October 1, 1994 through November 23, 1994), SRVs pilot cartridges were removed from the Unit 2 main steam SRVs and shipped to Wyle Laboratories for testing. On February 7, 1995, TVA was notified on the results of the first two SRVs tested.

D. Other Systems or Secondary Functions Affected:

None.



LICENSEE EVENT REPORT
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Browns Ferry Unit 2	05000260	95	003	00	3 of 5

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

E. Method of Discovery:

The deviation from the SRV setpoints was identified during bench testing at Wyle Laboratories in Huntsville, Alabama.

F. Operator Actions:

None.

G. Safety System Responses:

None.

III. CAUSE OF THE EVENT

A. Immediate Cause:

The immediate cause was the deviation of SRV setpoints outside the testing setpoint limit of +/- one-percent tolerance required by TS 2.2.A.

B. Root Cause:

The apparent cause of this event was attributed to corrosion bonding at Target Rock two-stage SRV pilot disc/seat interface. Since corrosion bonding caused an increase in the valve opening pressure due to the need for additional opening force above the setpoint value, this resulted in an upward setpoint drift.

IV. ANALYSIS OF THE EVENT

Thirteen main steam relief valves (MSRVs) on the main steam piping perform the safety/relief function for the primary reactor system boundary. Each valve is designed to open at a pressure sensed in the valve body of 1105, 1115, or 1125 psig providing a safety/relief function. The safety/relief function of the MSRVs is to limit primary reactor system pressure to <1375 psig in the event of a pressurization transient resulting from a turbine trip or a main steam isolation valve closure.

TVA has performed a cycle specific limiting pressurization transient analysis assuming a spectrum of MSRV failures and setpoint drifts. Even if four MSRVs completely fail to open and the remainder operating ten percent above setpoint, the analysis conservatively



LICENSEE EVENT REPORT
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MHBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Browns Ferry Unit 2	05000260	95	003	00	4 of 5

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

shows that the primary reactor system pressure would not have exceeded 1355 psig. As this is within the safety limit of 1375 psig given in TS section 1.2.A, the plant and the public safety would not have been adversely affected and the safety of plant personnel was not compromised.

V. CORRECTIVE ACTIONS

A. Immediate Corrective Actions:

The two out-of-tolerance Target Rock valves are currently being refurbished, retested, and recertified by Wyle Laboratories for use as spares.


B. Corrective Actions to Prevent Recurrence:

The setpoint drift is a generic concern experienced by all utilities using this brand of SRV in boiling water reactors (BWR) and is being investigated by the BWR Owners' Group (BWROG) SRV Drift Fix Development Committee and the manufacturer, Target Rock Corporation.

The Committee recommended replacing the existing stellite 6B pilot disc with a 0.3 percent platinum alloyed stellite or installing several parts in the pilot disc/seat area with catalyst plated platinum alloy to act as a recombiner of excess oxygen, thereby reducing the oxygen available for corrosion. (Note: corrosion is being attributed to radiologically produced oxygen collecting at the disc/seat interface.)

The Committee's recommendation on replacing the stellite 6B pilot disc with a platinum alloyed stellite has been implemented at BFN. During the Unit 2 Cycle 7 refueling outage, TVA replaced the Unit 2 main steam SRVs with a 0.3 percent platinum alloyed stellite pilot disc. Per TS requirements, the valves are bench tested and checked for any increased setpoint deviation or drift at the end of each Unit 2 operating cycle. As a SRV Drift Fix Committee member, TVA is continuing to participate in the BWROG evaluation on the long term solution concerning the SRV setpoint drift problem.

TVA will provide a supplemental report after receiving the test results of all 13 Unit 2 SRVs from Wyle Laboratories.



LICENSEE EVENT REPORT
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Browns Ferry Unit 2	05000260	95	003	00	5 of 5

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

VI. ADDITIONAL INFORMATION

A. Failed Components:

Target Rock Two-Stage SRVs Model No. 7567F.

B. Previous LERs on Similar Events:

Since the early 1980s, TVA has issued several LERs (e.g., 296/81074, 259/83036, 260/87005, 259/88053, 260/93003) regarding MSRV setpoint drift due to disc/seal corrosion bonding. The BWROG and the valve manufacturer are pursuing corrective actions for the disc/seal corrosion bonding problem. TVA expects the corrective action of using platinum alloy for disc/seal interface should help toward reducing corrosion bonding and thus, decreasing setpoint drift problems in the future.

VII. Commitments

None

Energy Industry Identification System (EIIS) system and component codes are identified in the text with brackets (e.g., [XX]).

