

PRIORITY 1

ACCELERATED RIDS PROCESSING

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9505020308 DOC. DATE: 95/04/28 NOTARIZED: NO DOCKET #
 FACIL: 50-260 Browns Ferry Nuclear Power Station, Unit 2, Tennessee 05000260
 AUTH. NAME AUTHOR AFFILIATION
 MACHON, R.D. Tennessee Valley Authority
 RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 95-004 re details concerning reactor scram that resulted from personnel error.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+7
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-3-PD		1	1		WILLIAMS, J.		1	1
INTERNAL:	ACRS		1	1		AEOD/SPD/RAB		2	2
	AEOD/SPD/RRAB		1	1		<u>FILE CENTER</u>		1	1
	NRR/DE/ECGB		1	1		NRR/DE/EELB		1	1
	NRR/DE/EMEB		1	1		NRR/DISP/PIPB		1	1
	NRR/DOPS/OECB		1	1		NRR/DRCH/HHFB		1	1
	NRR/DRCH/HICB		1	1		NRR/DRCH/HOLB		1	1
	NRR/DSSA/SPLB		1	1		NRR/DSSA/SPSB/B		1	1
	NRR/DSSA/SRXB		1	1		RES/DSIR/EIB		1	1
	RGN2 FILE 01		1	1					
EXTERNAL:	L ST LOBBY WARD		1	1		LITCO BRYCE, J H		2	2
	NOAC MURPHY, G.A		1	1		NOAC POORE, W.		1	1
	NRC PDR		1	1		NUDOCS FULL TXT		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!


FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 27 ENCL 27

A04

P
R
I
O
R
I
T
Y

1

D
O
C
U
M
E
N
T





Tennessee Valley Authority, Post Office Box 2000, Decatur, Alabama 35609

April 28, 1995

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

10 CFR 50.73

Dear Sir:

BROWNS FERRY NUCLEAR PLANT (BFN) - UNITS 1, 2, AND 3 - DOCKET
NOS. 50-259, 260, AND 296 - FACILITY OPERATING LICENSE DPR-
33, 52, AND 68 - LICENSEE EVENT REPORT 50-260/95004

The enclosed report provides details concerning a reactor
scram on March 30, 1995, that resulted from personnel error
during the performance of a surveillance instruction. The
reactor scram subsequently resulted in actuating the
engineered safety feature system due to a sensed low reactor
water level condition.

This report is submitted in accordance with 10 CFR 50.73
(a)(2)(iv) as a condition that resulted in the automatic
actuation of any engineered safety feature.

Sincerely,

R. D. Machon
Site Vice President

Enclosure

cc: See page 2

9505020308 950428
PDR ADDCK 05000260
S PDR



U.S. Nuclear Regulatory Commission

Page 2

April 28, 1995

Enclosure

cc (Enclosure):

INPO Records Center
700 Galleria Parkway
Atlanta, Georgia 30339

Paul Krippner
American Nuclear Insurers
Town Center, Suite 300S
29 South Main Street
West Hartford, Connecticut 06107

NRC Resident Inspector
Browns Ferry Nuclear Plant
Route 12, Box 637
Athens, Alabama 35611

Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Mr. J. F. Williams, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

E. V. Imbro, NRR/RSIB
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

E. J. Leeds, NRR/DRPW
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

