

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8904280274 DOC. DATE: 89/04/24 NOTARIZED: NO DOCKET #
 FACIL: 50-412 Beaver Valley Power Station, Unit 2, Duquesne Light C 05000412
 AUTH. NAME AUTHOR AFFILIATION
 NOONAN, T.P. Duquesne Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 890414, triaxial time history accelerometer horizontal trigger circuits identified as inoperable.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: LPDR 2cys Transcripts. LPDR 2cys PDR Documents.
 Application for permit renewal filed.

05000412 S

	RECIPIENT		COPIES		
	ID CODE/NAME	LTR	ENCL		
	PD1-4 LA TAM, P	1 1	1 1		
INTERNAL:	ACRS MICHELSON	1	1	ACRS MOELLER	2 2
	ACRS WYLIE	1	1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1	1	AEOD/ROAB/DSP	2 2
	DEDR0	1	1	IRM/DCTS/DAB	1 1
	NRR/DEST/ADE 8H	1	1	NRR/DEST/ADS 7E	1 0
	NRR/DEST/CEB 8H	1	1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/ICSB 7	1	1	NRR/DEST/MEB 9H	1 1
	NRR/DEST/MTB 9H	1	1	NRR/DEST/PSB 8D	1 1
	NRR/DEST/RSB 8E	1	1	NRR/DEST/SGB 8D	1 1
	NRR/DLPQ/HFB 10	1	1	NRR/DLPQ/QAB 10	1 1
	NRR/DOEA/EAB 11	1	1	NRR/DREP/RPB 10	2 2
	<u>NRR/DRS/SIB 9A</u>	1	1	NUDOCS-ABSTRACT	1 1
	<u>REG FILE</u> 02	1	1	RES/DSIR/EIB	1 1
	RES/DSR/PRAB	1	1	RGN1 FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS, S	4	4	FORD BLDG HOY, A	1 1
	L ST LOBBY WARD	1	1	LPDR	1 1
	NRC PDR	1	1	NSIC MAYS, G	1 1
	NSIC MURPHY, G. A	1	1		
NOTES:		2	2		


NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 46 ENCL 45

R
I
D
S
/
A
D
S
/
A
D
D
S

11/12/89





Duquesne Light

Nuclear Group
P.O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 393-6000

April 24, 1989
ND3MNO:1867

Beaver Valley Power Station, Unit No. 2
Docket No. 50-412, License No. NPF-73
Special Report

United States Nuclear Regulatory Commission
Document Control Desk
Washington , DC 20555


Gentleman:

In accordance with Appendix A, Beaver Valley Technical Specification 3.3.3.3, "Seismic Instrumentation," the following Special Report is submitted.... This report is required when the conditions specified in Technical Specification 3.3.3.3.b are not satisfied.

On April 14, 1989, 2ERS-ACS-1 and -3, Triaxial Time History Accelerometer horizontal trigger circuits for the Containment Structure and the Switchyard, were identified as being inoperable since May, 1987, as a result of an incorrect calibration procedure. On April 1, 1989, a Response Spectrum Analyzer Trouble alarm was observed, indicating an internal fault. A maintenance work request was generated to correct this condition. During troubleshooting of the central control cabinet, with a vendor representative present, these accelerometer trigger circuits were identified as having incorrect setpoints. The accelerometer analog trigger circuits cause tape recording of all three directional sensor inputs and annunciation, when the setpoint value is reached. The accelerometer trigger circuit cards contain switches which provide annunciation when their respective setpoint is reached. The setpoints are values measured in g-forces. It was discovered that the horizontal trigger setpoint value (0.01g) for both accelerometer trigger card were set at the vertical alarm switch setpoint value (0.037g). The cause for this event was due to a deficient surveillance procedure which incorrectly specified the setpoint values.

8904280274 890424
PDR ADOCK 05000412
S PDC

JE2
11



April 24, 1989

ND3MNO:1867

Page 2

The surveillance procedure was immediately revised to reflect the correct setpoint values and the accelerometer trigger circuits were calibrated to the correct values.

There were no safety implications to the public as a result of this event because no seismic activity occurred during the entire period the horizontal accelerometer trigger circuits were incorrectly calibrated. The trigger circuits function to initiate automatic magnetic tape recording of the seismic event, no other automatic plant actuations are designed to occur from a trigger circuit. In addition, the vertical accelerometer trigger circuits were correctly calibrated and operational throughout the entire time period.

Very truly yours,



T. P. Noonan
General Manager
Nuclear Operations

JT/cj

Attachment



1

April 24, 1989
ND3MNO:1867
Page three

cc: Mr. William T. Russell
Regional Administrator
United States Nuclear Regulatory Commission
Region 1
King of Prussia, PA 19406

C. A. Roteck, Ohio Edison

Mr. Peter Tam, BVPS Licensing Project Manager
United States Nuclear Regulatory Commission
Washington, DC 20555

J. Beall, Nuclear Regulatory Commission,
BVPS Senior Resident Inspector

Mr. Alex Timme, CAPCO Nuclear Projects Coordinator
Toledo Edison

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

G. E. Muckle, Factory Mutual Engineering, Pittsburgh

Mr. J. N. Steinmetz, Operating Plant Projects Manager
Mid Atlantic Area
Westinghouse Electric Corporation
Energy Systems Service Division
Box 355
Pittsburgh, PA 15230

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange Suite 245
270 Farmington Avenue
Farmington, CT 06032

Mr. Richard Janati
Department of Environmental Resources
P. O. Box 2063
16th Floor, Fulton Building
Harrisburg, PA 17120

Director, Safety Evaluation & Control
Virginia Electric & Power Co.
P. O. Box 26666
One James River Plaza
Richmond, VA 23261



1