U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M I PA L 1 2 00 - 00 0 0 - 0 0 3 4 1 1 1 1 4 5 5 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 2 5 5 7 0 4 0 6 7 9 8 0 4 3 0 7 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	The on-going investigation into the R bus trips which occurred during the
0 3	fall of 1977 has revealed a potential for the 1-1 diesel generator output
0.4	breaker to "lockout open". This potential exists only when the 106D-1
0 5	relay fails to reset following operation of the normal shutdown sequencer.
0 6	This has occurred 4 times. On 3 of these occasions, the plant was in a
0 7	shutdown condition; the fourth occurred with the plant on line and lasted
0 8	for 2 hours. Event had no adverse effect on public health or safety.
0 9 7 8	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21 22 23 29 30 30 31 32
٠.	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER. ACTION ON PLANT METHOD HOURS 22 SUBMITTED FORM SUB, SUPPLIER MANUFACTURER. A 1 8 0 26 37 40 41 42 43 43 44 47 47 48 48 48 47 48 48
1 0	A contact (34-5) on the normal shutdown sequencer failed to operate. The
11	sequencer was repaired. To prevent recurrence, annunciation of relays
1 2	106Dl or 106D2 being energized will be provided.
1 3	L
1 4	L
1 5	9 FACILITY STATUS % POWER OTHER STATUS OTHER STATUS OTHER STATUS A OTHER STATUS O
A	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 AMOUNT OF ACTIVITY 35 N/A LOCATION OF RELEASE 36 SO SO SO SO SO SO SO SO SO S
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) O O O (37) Z (38) N/A
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41 O O NA
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION Z 42 N/A
2 0 .	9 10 80 PUBLICITY SSUED DESCRIPTION 45 NRC USE ONLY 9 10 68 69 80