

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • (517) 788-0550

August 16, 1979

Mr James G Keppler Office of Inspection and Enforcement Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

DOCKET 50-255 - LICENSE DPR-20 -PALISADES PLANT - LER 79-033

On the reverse side is Licensee Event Report 79-033 which is reportable under Technical Specification 6.9.2.b(2).


David P Hoffman

David P Hoffman Assistant Nuclear Licensing Administrator

CC: Director, Office of Nuclear Reactor Regulation Director, Office of Inspection and Enforcement

19050230407

DAB



PALISADES

NRC FORM 366 (7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT CONTROL BLOCK: ں ل (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 
 0
 1
 M
 I
 P
 A
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
 I
] (5) CON'T SOURCE L 6 0 5 0 0 0 2 5 5 0 0 7 3 0 7 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 0 1 75 REPORT DATE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) 02 During piping walkdowns performed for IE Bulletin 79-02, a deficiency with The I-beam to which the snubber is anchored was [0]3] |snubber No. 33 was found. [0]4] [twisted approx 20 degrees at the spot where the snubber bracket was connec-[0]5] [ted, resulting in the snubber being misaligned from the pipe center-line. old In addition, the snubber was mounted such that it would behave as a rigid This condition represented a degraded mode permit, [] ] | support when compressed. Operability was restored in the required time. ted by TS 3.20. 0 8 80 SYSTEM CODE CAUSE CAUSE SUBCODE COMP. VALVE SUBCODE COMPONENT CODE SUBCODE UPORT14 0 9 <u>S</u>F (1) E (12) B (13) S <u>X</u> (15). <u>Z</u> (16) 13 18 20 10 12 19 OCCURRENCE SEQUENTIAL REVISION REPORT LER/RO EVENT YEAR REPORT NO. CODE NO. 17 REPORT NUMBER 01 3 L 0 3 3 0 7 9 28 31 32 ACTION FUTURE TAKEN ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED 37 40 40 41 23 ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. COMPONENT MANUFACTURER SUPPLIER Z 20 |Z |(25)  $[Z]^{(2)}$ Z 9 9 9 26 LC (18) X (19) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Following replacement of the defective segment of the I-beam, it was found that the snubber had to be fully compressed in order to fit between 12 the pipe and the I-beam. Adjustments to a turnbuckle between the snubber Examinations of other snubbers are being and the I-beam corrected this. 13 14 [performed as part of the action required by IE Bulletin 79-02. 9 80 FACILITY METHOD OF DISCOVERY OTHER STATUS Piping Inspection (32) % POWER 15 E(28 09 8 29 N/A 10 13 80 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE N/A N/A 1 6 10 80 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE n 37 7 38 N/A 1 7 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER <u>nlolo</u> M/A 1 8 12 11 80 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION 1 9 N/A 10 PUBLICITY NRC USE ONLY DESCRIPTION (45) Ned N/A 0 68 69