U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M I PAI 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 3 5 5 LICENSE CODE 14 15 ST CAT 58 5
CON'T	REPORT L 6 0 5 0 0 0 2 5 5 7 0 8 2 6 8 0 8 0 9 2 3 8 0 9 SOURCE SO DOCKET NUMBER S8 69 EVENT DATE 74 75 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During performance of control rod interlock testing, group 1 rods
0 3	withdrew to approx. 121 inches. This resulted in unplanned reactivity
04	insertion of 1.6 delta K/K, and is reportable per TS 6.9.2.A.4. Report-
0 5	ability determination made on 9-9-80. During period that rods were with-
0 6	drawn, shutdown margin requirements were met, and reactor remained sub-
0 7	critical.
08	9 80
0 9	SYSTEM CAUSE COMPONENT CODE SUBCODE SUBCODE SUBCODE SUBCODE R B 10 11 E 12 E 13 I N S T R U 14 X 15 Z 16
	TO LER/RO EVENT YEAR REPORT NO. CODE CO
	ACTION FUTURE ON PLANT METHOD HOURS (22) ATTACHMENT FORM SUB. PRIME COMP. COMPONENT MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 V 0 6 5 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	Cause of excessive withdrawal was loss of both primary and secondary
11	data loggers (see LER 80-32). Corrective action included restoration of
1 2	data loggers and reinsertion of control rods.
1 3	<u></u>
14	9 80
15	ACILITY % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 G 28 0 0 0 0 29 Hot Shutdown A 4 45 45 46
	CTIVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 NA NA NA 9 10 NA NA 45 80
1 7	PERSONNEL EXPOSURES NUMBER O O O O O O O O O O O O O O O O O O O
1 8	NUMBER DESCRIPTION (41) O O O (40) NA
	SO LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA
7 8	PUBLICITY (F)
	DESCRIPTION (49) NA SOLED DESCRIPTION (49) N