

November 29, 1983

Docket No. 50-255

MEMORANDUM FOR: Dennis M. Crutchfield, Chief
 Operating Reactors Branch #5
 Division of Licensing

FROM: Thomas V. Wambach, Project Manager
 Operating Reactors Branch #5
 Division of Licensing

SUBJECT: FORTHCOMING MEETING WITH CONSUMERS POWER
 COMPANY

Time & Date: Wednesday
 December 7, 1983
 10:00 a.m.

Location: Rm 220
 Landow Building
 Bethesda, Maryland

Purpose: To report results of Steam Generator Inspection at
 Palisades including depth determination of IGA and
 proposed plugging criteria.

Participants: Consumers Power Company
 D. Vandewalle et. al.

NRC

B.D. Liaw	C. McCracken
C.E. Cheng	E. Murphy
L. Frank	D. Crutchfield
H. Conrad	T. Wambach

Original signed by

Thomas V. Wambach, Project Manager
 Operating Reactors Branch #5
 Division of Licensing

cc: See next page

8312020289 831129
 PDR ADOCK 05000255
 P PDR

DSU use code 5E01
 04 110

OFFICE	DL:ORB #5					
SURNAME	Wambach:jc					
DATE	11/29/83					



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

November 29, 1983

Docket No. 50-255

MEMORANDUM FOR: Dennis M. Crutchfield, Chief
Operating Reactors Branch #5
Division of Licensing

FROM: Thomas V. Wambach, Project Manager
Operating Reactors Branch #5
Division of Licensing

SUBJECT: FORTHCOMING MEETING WITH CONSUMERS POWER
COMPANY

Time & Date: Wednesday
December 7, 1983
10:00 a.m.

Location: Rm 220
Lanow Building
Bethesda, Maryland

Purpose: To report results of Steam Generator Inspection at
Palisades including depth determination of IGA and
proposed plugging criteria.

Participants: Consumers Power Company
D. Vandewalle et. al.

NRC

B.D. Liaw

C.E. Cheng

L. Frank

H. Conrad

C. McCracken

E. Murphy

D. Crutchfield

T. Wambach

Thomas V. Wambach

Thomas V. Wambach, Project Manager
Operating Reactors Branch #5
Division of Licensing

cc: See next page

Mr. David J. Vandewalle

cc

M. I. Miller, Esquire
Isham, Lincoln & Beale
Suite 4200
One First National Plaza
Chicago, Illinois 60670

Mr. Paul A. Perry, Secretary
Consumers Power Company
212 West Michigan Avenue
Jackson, Michigan 49201

Judd L. Bacon, Esquire
Consumers Power Company
212 West Michigan Avenue
Jackson, Michigan 49201

James G. Keppler, Regional Administrator
Nuclear Regulatory Commission, Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Township Supervisor
Covert Townshi
Route 1, Box 10
Van Buren County, Michigan 49043

Office of the Governor (2)
Room 1 - Capitol Building
Lansing, Michigan 48913

Palisades Plant
ATTN: Mr. Robert Montross
Plant Manager
Covert, Michigan 49043

U. S. Environmental Protection Agency
Federal Activities Branch
Region V Office
ATTN: Regional Radiation Representative
230 South Dearborn Street
Chicago, Illinois 60604

Resident Inspector
c/o U. S. NRC
Palisades Plant
Route 2, P. O. Box 155
Covert, Michigan 49043

Lee E. Jager, P.E., Chief
Environmental and Occupational
Health Services Administration
Michigan Department of Public Health
3500 N. Logan Street
Post Office Box 30035
Lansing, Michigan 48909

NOV 8 1983

MEMORANDUM FOR: Richard H. Vollmer, Director
 Division of Engineering

THRU: William V. Johnston, Assistant Director
 Materials, Chemical & Environmental Technology

FROM: B. D. Liaw, Chief
 Materials Engineering Branch

SUBJECT: MEETING WITH CONSUMERS POWER COMPANY ON OCTOBER 25, 1983
 TO DISCUSS INSPECTION OF PALISADES STEAM GENERATORS
 (VIEWGRAPHS ATTACHED)

The agenda covered the results of ongoing steam generator tube inspections, plans to complete 100% inspection of the tubes, proposed tube pulling and laboratory investigatory actions.

In 1982, circumferential cracks were found in two leaking tubes when 4 x 4 differentially linked surface riding pancake coil eddy-current probes were used.

In the present ongoing inspections, of which ~ 10% of the inspection data has been analyzed, approximately 26 tubes with similar circumferential cracks have been found. Two other types of flaws of unquantifiable depth have also been found throughout the steam generators. Tube inspections have been expanded to include 100% of the steam generator tubes using the 4 x 4 technique supplemented as needed by multifrequency and rotating pancake coils to quantify flaw depth.

Circumferential cracks identified by the 4 x 4 probe, irrespective of depth, will be plugged. Disposition of the remaining tubes with other type flaws will await the laboratory examination results of pulled tubes which will undergo ECT correlations with destructive metallurgical examinations. Chemical analyses will also be conducted to determine causative species responsible for the observed degradation.

Corrective actions will be based on the results of the above investigations and others, such as in-situ strength testing of tubes as a backup to ECT depth determinations.

8311160023 831108
 CF ADOCK 05000255
 CF

NOV 8 1983

Richard H. Vollmer

- 2 -

Tube pulling will commence before the eddy current testing is complete with laboratory results expected sometime in January 1984.

Original signed by
B. D. Liaw
B. D. Liaw, Chief
Materials Engineering Branch

Enclosure:
Vugraphs

cc: W. Johnston
B. D. Liaw
C. Cheng
L. Frank
H. Conrad
V. Benaroya

DISTRIBUTION:
Central File
MTEB Reading File
Palisades File

DE: MTEB
LFrank: aj
10/31/83
Frank

DE: MTEB
CCheng
10/28/83
CCheng

DE: MTEB
BDLiaw
10/1/83
BDLiaw

DE: MCET
WJohnston
10/4/83
WJohnston

AGENDA

CONSUMERS POWER COMPANY MEETING WITH NRC

PALISADES PLANT

STEAM GENERATOR PERFORMANCE

OCTOBER 25, 1983

INTRODUCTION AND OVERVIEW	WJBECKIUS
INSPECTION RESULTS AND PLANS	JSJANDOVITZ
TUBE PULLING AND ANALYSIS	JRSCHEPERS
LICENSING ACTIONS	DJVANDEWALLE

OVERVIEW

1. IN 1982 CPCO MADE A COMMITMENT TO DEVELOP AN EDDY CURRENT PROBE THAT COULD SEE CRACKING IN THE U-BEND REGION
2. WE USED THE COIL WE DEVELOPED TO DO THE 1983 INSPECTION AND HAVE SEEN MANY INDICATONS IN THE PALISADES STEAM
3. WE HAVE FORMED A TASK FORCE TO INVESTIGATE AND MAKE RECOMMENDATIONS TO CPCO MANAGEMENT

PURPOSE OF THIS MEETING


1. TO TELL NRC WHAT WE HAVE FOUND SO FAR
2. TO TELL NRC WHAT WE ARE DOING ABOUT IT
3. TO OBTAIN AN UNDERSTANDING OF NRC CONCERNS
AND TO UTILIZE ANY EXPERTISE NRC MAY HAVE DEVELOPED
4. TO OUTLINE WHAT NRC REVIEWS WE ARE LIKELY TO
NEED TO RETURN TO POWER AND BEGIN PLANNING THEN

ACTIONS TAKEN BY CPCO

1. PROCEEDING WITH 100% EDDY CURRENT TEST OF BOTH STEAM GENERATORS USING 4C4 PROBE
2. PROCEED TO PULL SAMPLES OF TUBING FROM THE STEAM GENERATORS
3. PROCEED WITH PLANT SAFETY ANALYSIS CALCULATIONS WHICH ARE PARAMETRIC IN THE NUMBER OF STEAM GENERATOR TUBES PLUGGED
4. DEVELOP THE ECT TECHNOLOGY TO RELIABLY DETERMINE DEPTH OF THE ATTACK
5. INVESTIGATING IN-PLACE STRENGTH TESTING AS A BACK UP TO ECT DEPTH DETERMINATION TECHNOLOGY

1982 SUMMARY


- * LEAKAGE OBSERVED IN A STEAM GENERATOR IN 1ST QUARTER OF 1982
- * TWO LEAKING TUBES NOTED; FOUND BY SECONDARY SIDE PRESSURIZATION
- * TUBES WERE INSPECTED WITH VARIOUS EDDY CURRENT TECHNIQUES. FLAWS CHARACTERIZED AS VERY TIGHT CIRCUMFERENTIAL CRACKS.
- * FLAWS NOT DETECTED WITH BOBBIN STYLE PROBE
- * ADDITIONAL 9% OF TUBES INSPECTED WITH 4x4 PROBE - STRAIGHT SECTIONS ONLY
- * NO FURTHER INDICATIONS NOTED
- * PLANT WAS RETURNED TO SERVICE



- SFW PROBE
- DIFFERENTIAL MULTIFREQUENCY CIRCUMFERENTIAL WINDING


EDDY CURRENT PROBES

4x4



- DIFFERENTIALLY LINKED
- SURFACE RIDING COILS
- PANCAKE COILS .187" DIAMETER

4C4



- DIFFERENTIALLY LINKED
- SURFACE RIDING COILS
- PANCAKE COILS .187" DIAMETER

1983 INSPECTION

WASTAGE

(No increased wastage)

MULTIFREQUENCY BOBBIN PROBE *all > 30%*

35 - 40% OF THE HL TUBES INSPECTED

RESULTS INDICATE ESSENTIALLY ZERO WASTAGE GROWTH

DENTING

4 BLOCKED TUBES FOUND - 3 IN B/HL *not pass*
AND 1 IN A/HL *.540 probe*

PROFILOMETRY PLANNED BUT NOT COMPLETED YET

LESS BLOCKED TUBES IN 1983 THAN IN 1979 AND 1981

SLEEVES

INSPECTED WITH SLOW PULL BOBBIN PROBE AND
ROTATING PANCAKE COIL PROBE

SLEEVES FOUND OK

LOOSE PARTS

PERIPHERY TUBES INSPECTED FROM TOP OF TUBESHEET TO
FIRST SUPPORT

INSPECTED WITH 100 Kz ABSOLUTE MODE BOBBIN TECHNIQUE

NO INDICATIONS OF WEAR NOTED

CIRCUMFERENTIAL CRACKS







3% SAMPLE IN A AND B HOT LEG (INCLUDING U-BENDS)

4c4 TECHNIQUE USED

SEVERAL INDICATIONS NOTED, EXPANDED TESTING INITIATED

*support
plate
9
inside
of joint*

POSTULATED INDICATION CHARACTERIZATION



- ~90° CIRCUMFERENTIAL EXTENT
- .2" AXIAL EXTENT
- LOCATED AT UPPER OR LOWER EDGE OF SUPPORT.

- LESS THAN .1" AXIAL EXTENT
- ~60° CIRCUMFERENTIAL EXTENT
- LOCATED IN AN X OR XS CONDITION
- SIMILAR TO 1982 LEAK INDICATIONS

- LOCATED WITHIN TUBE SUPPORT PLATES
- ▨ MINIMUM AREA 360°x.2"
- ▨ NORMALLY ALSO EFFECTED
- ▨ OCCASIONALLY EFFECTED

NATURE OF INDICATIONS

THE INDICATIONS WERE EVALUATED AND DETERMINED NOT TO BE REPRESENTATIVE OF THESE FLAWS:

WASTAGE
PITTING
DENTING
PLATING
MECHANICAL WEAR

DEPTH OF INDICATIONS

THE 4c4 PROBE IS NOT QUALIFIED FOR DETERMINATION OF CRACK DEPTH. IF INDICATIONS OF CRACKING WERE OBSERVED IT WAS TO BE CONSIDERED PLUGGABLE.

Absolute
CRACK DEPTH IS QUANTIFIABLE THROUGH THE ROTATING PANCAKE PROBE (RPC) TECHNIQUE. SEVERAL CRACKS DETECTED BY 4c4 WERE SIZED WITH RPC AND DETERMINED TO BE 80 - 90% THROUGH WALL.

DEPTH CORRELATION OF THE x AND xs CONDITIONS IS CURRENTLY UNDERWAY AND AS YET DEPTH CANNOT BE QUANTIFIED.

HISTORY OF x, xs

SEVERAL TUBES EXHIBITING x AND xs INDICATION WERE SELECTED AND THEIR RESPECTIVE BOBBIN HISTORIES WERE REVIEWED. IN ALL CASES A SLIGHT (10%) INDICATION HAS BEEN PRESENT SINCE 1974 - 75 AND HAS NOT CHANGED THROUGH 1983.

ALSO, NINE (9) TUBES WERE SELECTED WITH 1982 4x4 RESULTS AND THE SIGNALS COMPARED. RESULTS OF THE COMPARISON SHOW EVIDENCE OF THE SAME TUBE CONDITION IN 1982.

1983 PALISADES STEAM GENERATOR
EXPANDED INSPECTION

<u>S/G LEG</u>	<u>TUBES INSPECTED/ %</u>		<u>INDICATIONS</u>			<u>TUBES AFFECTED %</u>	
			X	XX	XS		
A HL	780	12%	440	13 (10)*	178	459	59%
A CL	704	10%	185	7 (6)*	279	421	60%
B HL	575	9%	408	3 (3)*	1175	544	94%
B CL	682	10%	175	3 (3)*	820	591	87%

* NO OF TUBES WITH INDICATIONS.

100% INSPECTION

- * STARTED ON OCTOBER 15.
- * ALL FOUR LEGS IN PARALLEL.
- * ALL TUBES TO BE INSPECTED WITH 4c4 TECHNIQUE SUPPLEMENTED AS NEEDED BY MULTIFREQUENCY AND ROTATING PANCAKE COIL.
- * INSPECTION RATE OF ABOUT 200 TUBES/DAY/LEG. COMPLETION DATE SCHEDULE TO BE END OF NOVEMBER.

STATUS

<u>S/G LEG</u>	<u>TUBES TO BE INSPECTED</u>	<u>AS OF 10/24</u> <u>TUBES INSPECTED*/ %</u>	
A HL	5703	1845	32%
A CL	5849	2583	44%
B HL	6012	1694	28%
B CL	6012	1365	22%

* DOES NOT INCLUDE TUBES INSPECTED IN ORIGINAL SAMPLE.

INTENDED INVESTIGATORY ACTIONS

- * ET INSPECTION OF TUBES PULLED IN 1974

- * DEPLUG AND ET INSPECTION OF A SAMPLE OF TUBES PLUGGED IN 1974, 1975 AND 1976

- * DATA COMPARISON OF BOBBIN DATA FROM 1974 THROUGH 1983, AND 4c4 DATA OF 1981, 1982 AND 1983

- * INSPECTION OF IGA SAMPLES:
 - EXISTING LABORATORY IGA SAMPLES
 - REAL S/G IGA TUBES
 - LABORATORY SAMPLES FABRICATED BY CPCO TO SIMULATE THE PALISADES INDICATIONS

- * INDEPENDENT DEPTH QUANTIFICATION STUDY

TUBE PULLINGObjectives

1. Validate x and xs ECT indications are defects.
2. Attempt to corrolate ECT signals and defect depth.
3. Attempt to determine the cause of the defects.

Candidates

- Secondary side "A" Steam Generator
"Batwing" Area
- Primary Side "B" Steam Generator
2nd TSP

Schedule

- Tube Pull Complete Mid-December
- Analysis Complete Mid-January

LABORATORY ANALYSIS

- The analysis plan will be developed with assistance from EPRI SGOG.
- Candidate laboratories are the Vendor Labs and Battelle Columbus.
- Two laboratories will probably perform independent analysis.
- The analysis focus will be:
 - a. Defect Morphology
 - b. Extent of Defects (ECT Detectability)
 - c. Metallurgical Microstructure of the Tubing
 - d. Chemical Species Associated With the Defect

A¹¹ Heat Treated?

LABORATORY RESULTS EVALUATION

1. Eddy Current Testing

- Compare post pull ECT with actual defect depth data.
- Develop a signal to depth correlation.

2. Defect Cause

- Review the laboratory results for an assessment as to cause (and rate).
- Review Palisades secondary cycle operation.
- Perform stress analysis of selected steam generator locations.
- Review past ECT results (rate).
- Integrate and assign probable cause.

3. Corrective Action

- Assess corrective actions based upon probable cause and rate of corrosion.

LICENSING ACTIONS

- INSPECTION RESULTS
- ANALYSIS OF PULLED TUBES
- REPAIR CRITERIA
- REVISED OPERATING LIMITS AND SETPOINTS
(IF REQUIRED)

STEAM GENERATOR TUBE PLUGGING CRITERIA

<u>CRITERIA</u>	<u>ALLOWABLE DEGRADATION(%)*</u>	<u>OPERATING LIMIT</u>
1. TUBES MUST NOT BE STRESSED BEYOND YIELD STRENGTH DURING FULL RANGE OF NORMAL OPERATION	64	PRIMARY-TO-SECONDARY $\Delta P < 1380$ PSID**
2. THE FACTOR OF SAFETY AGAINST FAILURE BY BURSTING MUST BE NO LESS THAN 3 DURING NORMAL OPERATION	64	PRIMARY-TO-SECONDARY $\Delta P < 1380$ PSID**
3. STRESSES INDUCED BY THE COMBINATION OF LOADS DUE TO LOCA AND SSE SHALL NOT EXCEED LIMITS FOR FAULTED CONDITIONS (MEMBRANE + BENDING STRESS INTENSITY = 80.6 KSI)	64	PRIMARY PRESSURE < 2100 PSIA
4. STRESSES INDUCED BY LOADS DUE TO A POSTULATED MAIN STEAMLINE BREAK SHALL NOT EXCEED LIMITS FOR FAULTED CONDITIONS	73	PRIMARY PRESSURE < 2100 PSIA

* ASSUMES UNIFORMLY THINNED TUBES

** 1530 PSID DURING ANTICIPATED OPERATIONAL TRANSIENTS

Plugging limit - 58% - 6% ECT area