



JEFF  
your copy  
5/22/84

NUCLEAR POWER SYSTEMS  
COMBUSTION ENGINEERING, INC.  
COMPONENTS ENGINEERING  
Chattanooga, Tennessee

E-2000

DALISADES AUXILIARY FEEDWATER  
NOZZLE GRINDOUTS

SS-51  
CALCULATION NO.

2966 B  
CONTRACT NO.

CONSUMERS POWER  
CUSTOMER

STEAM GENERATOR  
COMPONENT

P. L. Anderson Lead Engineer 5-24-84  
PREPARED TITLE DATE

W. L. Beard Structural Engineer 5-24-84  
CHECKED TITLE DATE  
(Full Review)

W. J. Keith SUPERVISOR 5-24-84  
REVIEWED TITLE DATE

D. L. [Signature] MANAGER 5-24-84  
APPROVED TITLE DATE

8407110382 840709  
PDR ADOCK 05000255  
P PDR





















5/8" A  
AUX FEEDWATER  
NOZZLE RADIUS  
GRINDING  
6:00 POSITION.

Revised  
5-22-84



3/4"



7/16" MAX.

NOZ

5/8" B

AUX FEEDWATER  
NOZZLE RADIUS  
GRINDING

6:00 POSITION


*CW Carter*

5-22-84


SHELL

FALSADES  
PLA

S/G "A" AUX FEEDWATER NOZ. RADIUS GRINDING.



S/G "B"



GRINDING DEPTHS ARE MAX. DEPTH AT LOCATION INDICATED.  
NO LOCAL GRINDOUTS EXIST AS THE TOTAL RADIUS SURFACE  
WAS GROUND WITH TAPERED TRANSITION BETWEEN  
HIGH AND LOW AREAS.

B. Noto 5-22-84



Consumers Power Company

# DEVIATION REPORT

4/2/84

R/HE/REMC/DWR

R/ICMR  
DGM/GY  
3/12/84

average Refn No HU

i	DEVIATION REPORT NO	D- 84 - 015
ii	TIME OF OCCURRENCE	Date 3-9-84 Hour 1800
iii	SAFETY RELATED	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

## IDENTIFICATION & DESCRIPTION

A TITLE: MISSING PIECE OF AUXILIARY FEED RING HANGER  
A STEAM GENERATOR

B PLANT SYSTEM(UFI) 02320 EQUIPMENT - CLASS(UFI) 13370 EQUIPMENT NUMBER E-50A

C DESCRIPTION OF OCCURRENCE OR CONDITION:  
UPON INSPECTING THE AUXILIARY FEEDRING IN A STEAM GENERATOR IT WAS DISCOVERED THAT A PIECE OF ONE AUX FEEDRING HANGER WAS MISSING.

D IMMEDIATE ACTION: VIDEO AND STILL PHOTOS WERE TAKEN. COGNIZANT ENGINEER WAS NOTIFIED.

E REFERENCES: E Pal 84-015

F PREPARED BY: Paolo Tommasi DATE: 3-12-84  
DEPT/PLANT: Palisades SECTION: Tech-  
APPROVED BY: [Signature] DATE: 3/12/84

G NONCONFORMING ITEM: YES  NO  IDENTIFY: E50-A  
DETERMINED BY: P-CARB DATE: 3/12/84

H DR FORWARDED TO: P-CARB DEPT/PLANT: Pal SECTION:

## REPORTABILITY

A TECH SPEC REPORTABLE: YES  NO  ER #: \_\_\_\_\_  
DETERMINED BY: P-CARB DATE: \_\_\_\_\_  
EVALUATOR: JDS  
DEPT/PLANT: Pal SECTION: \_\_\_\_\_  
APPROVED BY: P-CARB DATE: 3/12/84  
EVALUATION DUE DATE: 3/31/84

## EVALUATION AND DISPOSITION

A DESCRIBE CAUSE OF DEVIATION:  
~~Transferred to E Pal 84-015 on 3/12/84~~  
~~(copy attached)~~  
~~ignore this information~~  
Failure of fasteners holding sparger hanger together due to vibration/ water hammer during use.

B CONSIDERED TO BE REPORTABLE UNDER 10CFR21: YES  NO   
(IF YES, NOTIFY NLA FOR FINAL DETERMINATION) DETERMINED BY: \_\_\_\_\_ DATE: \_\_\_\_\_

COMPLETION APPROVED BY: \_\_\_\_\_ DATE: \_\_\_\_\_

COMPLETION REVIEW REVIEWED BY: \_\_\_\_\_ DATE: \_\_\_\_\_

(Gold) - COPY 4 - FORWARD TO QA UPON COMPLETION OF PART 2.  
(Pink) - COPY 3 - FORWARD TO QA UPON COMPLETION OF PART 3.  
(Canary) - COPY 2 - FORWARD TO THE ORIGINATING DEPARTMENT UPON COMPLETION OF PART 5.  
(White) - COPY 1 - FILED IN DOCUMENT CONTROL CENTER UPON COMPLETION OF PART 5.

FORWARD ALL CORRECTIVE ACTION DOCUMENTS THROUGH YOUR CORRECTIVE ACTION COORDINATOR.

# CORRECTIVE ACTION SHEET

i	REPORT NO.
ii	TIME OF OCCURRENCE Date _____ HOUR _____
iii	SAFETY RELATED YES _____ NO _____

EVALUATION	PART 3	COMPLETION	PART 4
------------	--------	------------	--------

PROPOSED REMEDIAL CORRECTIVE ACTION:  
Inspect secondary side of steam generator and remove materials

PRC: YES  NO   
MEETING \_\_\_\_\_  
PRIOR TO PLACING RELIANCE  
YES  NO   
ASSIGNED TO RTC  
DEPT/PLANT 201  
SECTION \_\_\_\_\_  
APPROVED BY R  
DATE APPROVED 4/2/84  
REQD COMPLETION DATE 5/15/84  
PRIORITY: 8 \_\_\_ 7 \_\_\_ 6 \_\_\_ 5 \_\_\_  
4 ✓ 2 \_\_\_ 1 \_\_\_

REMEDIAL ACTION TAKEN:  
Combustion Engineering cleaned and inspected the Annulus of the 'A' steam generator and removed the following pieces: one U-clamp, two U-clamp straps, one Drager tube, one jackknife blade, one spacer and

one bolt.  
Combustion Engineering says that the annulus has no more debris in it and any further missing pieces cannot be retrieved.

DETERMINED BY Jeff Terpstra DATE 3/31/84

COMPLETED BY Ronald Horner DATE 5/22/84  
APPROVED BY P-CARB DATE 5/22/84

PROPOSED CORRECTIVE ACTION TO PREVENT RECURRENCE:  
None applicable (This is being covered in E-PAL-84-015)

PRC: YES  NO   
MEETING \_\_\_\_\_  
PRIOR TO PLACING RELIANCE  
YES  NO   
ASSIGNED TO \_\_\_\_\_  
DEPT/PLANT \_\_\_\_\_  
SECTION \_\_\_\_\_  
APPROVED BY R  
DATE APPROVED 4/2/84  
REQD COMPLETION DATE \_\_\_\_\_  
PRIORITY: 8 \_\_\_ 7 \_\_\_ 6 \_\_\_ 5 \_\_\_  
4 \_\_\_ 3 \_\_\_ 2 \_\_\_ 1 \_\_\_

ACTION TAKEN TO PREVENT RECURRENCE:  
N/A

DETERMINED BY Jeff Terpstra DATE 3/31/84

COMPLETED BY \_\_\_\_\_ DATE \_\_\_\_\_  
APPROVED BY \_\_\_\_\_ DATE 4/2/84

(Gold) - COPY 4 - (FOR ERs) FORWARD TO NUCLEAR LICENSING ADMINISTRATOR UPON COMPLETION OF PART 3; (FOR DRs AND NRs - DISCARD).  
(Pink) - COPY 3 - FORWARD TO QA UPON COMPLETION OF PART 3.  
(Canary) - COPY 2 - FORWARD TO ORIGINATING DEPARTMENT UPON COMPLETION OF PART 5.  
(White) - COPY 1 - FILED IN DOCUMENT CONTROL CENTER UPON COMPLETION OF PART 5.

FORWARD ALL CORRECTIVE ACTION DOCUMENTS THROUGH YOUR CORRECTIVE ACTION COORDINATOR!

# CORRECTIVE ACTION SHEET

REPORT NO. <b>D-PL-84-025</b>	
TIME OF OCCURRENCE	
i) Date <b>3/9/84</b>	HOUR <b>1800</b>
SAFETY RELATED	
iii) YES <b>X</b> NO	

EVALUATION	PART 3	COMPLETION	PART 4
------------	--------	------------	--------

PROPOSED REMEDIAL CORRECTIVE ACTION:

Conduct an evaluation of the effect of leaving the tin retained material in the steam generator including the impact of periodic ECT testing at Refout intervals

PRC: YES  NO   
MEETING \_\_\_\_\_  
PRIOR TO PLACING RELIANCE  
YES  NO   
ASSIGNED TO **PT Cameron**  
DEPT/PLANT **Pal**  
SECTION **Tech**  
APPROVED BY **PCarb**  
DATE APPROVED **5/22/84**  
REQD COMPLETION DATE **6/11/84**  
PRIORITY: 8  7  6  5   
4  3  2  1

REMEDIAL ACTION TAKEN:

C-E says that leaving parts in the generator for another re-fueling cycle will not be detrimental to the system. C-E recommends doing another inspection of the annulus during the next refueling outage. (See attached letter). ECT can locate wall thinning on periphery tubes due to loose parts but its accuracy for actually locating loose parts cannot be guaranteed. If the loose part is not against the tube, the signal will not be of good quality

B

DETERMINED BY **PCarb** **Chay** DATE **5/22/84**

COMPLETED BY **[Signature]** DATE **6/12/84**  
APPROVED BY **[Signature]** DATE **6/14/84**

PROPOSED CORRECTIVE ACTION TO PREVENT RECURRENCE:

PRC: YES  NO   
MEETING \_\_\_\_\_  
PRIOR TO PLACING RELIANCE  
YES  NO   
ASSIGNED TO \_\_\_\_\_  
DEPT/PLANT \_\_\_\_\_  
SECTION \_\_\_\_\_  
APPROVED BY \_\_\_\_\_  
DATE APPROVED \_\_\_\_\_  
REQD COMPLETION DATE \_\_\_\_\_  
PRIORITY: 8  7  6  5   
4  3  2  1

ACTION TAKEN TO PREVENT RECURRENCE:

DETERMINED BY \_\_\_\_\_

DATE \_\_\_\_\_

COMPLETED BY \_\_\_\_\_

DATE \_\_\_\_\_

APPROVED BY \_\_\_\_\_

DATE \_\_\_\_\_

- (Gold) - COPY 4 - (FOR ERs) FORWARD TO NUCLEAR LICENSING ADMINISTRATOR UPON COMPLETION OF PART 3; (FOR DRs AND NRS - DISCARD).
- (Pink) - COPY 3 - FORWARD TO QA UPON COMPLETION OF PART 3.
- (Canary) - COPY 2 - FORWARD TO ORIGINATING DEPARTMENT UPON COMPLETION OF PART 5.
- (White) - COPY 1 - FILED IN DOCUMENT CONTROL CENTER UPON COMPLETION OF PART 5.

FORWARD ALL CORRECTIVE ACTION DOCUMENTS THROUGH YOUR CORRECTIVE ACTION COORDINATOR!

**C-E Power Systems**  
Combustion Engineering, Inc.  
1000 Prospect Hill Road  
Windsor, Connecticut 06095

Tel. 203/688-1911  
Telex: 99297



P-CE-7647

June 8, 1984

Consumers Power Company  
Palisades Plant

Mr. C. Gilmor  
Palisades Nuclear Plant  
Consumers Power Company  
Route 2, P.O. Box 154  
Covert, MI 49043

Subject: Palisades Steam Generator Loose Parts

Dear Mr. Gilmor:

As we previously recommended, the candeck region of the Palisades A steam generator has been reinspected for loose parts. None were found. In addition, an attempt was made to examine the downcomer region of the steam generator for loose parts. This was not practical using the inspection equipment available at this time. Significant difficulty was encountered in controlling video camera movement underwater, with the result that both the primary and backup video inspection equipment was damaged. After reviewing the situation, recognizing that the missing auxiliary feedwater sparger clamp assembly may never reach the tubesheet, even if it is currently lodged in the downcomer region, a decision was made to abort further efforts to perform a downcomer inspection. After reviewing the available information, it was concluded that it was not absolutely necessary to perform an inspection of the tubesheet for the missing sheared bolt head, prior to plant startup. This conclusion was reached based on the similarity in geometry to other loose parts for which flow tests have been conducted. For the parts tested, these flow tests showed that no significant damage should result from a single cycle of operation.

If practical to do so, C-E feels it is always desirable to remove any loose parts in the steam generator.

At the next refueling outage C-E recommends that a tube sheet annulus inspection be conducted to search for the sheared bolt head and to check for any other loose parts which might have been dislodged from the downcomer region. If workable techniques and equipment are available at that time, an inspection of the downcomer region is recommended to provide additional assurance that no potentially damaging loose parts are located there.

Mr. C. Gilmor


-2-

P-CE-7647

The above is submitted in response to your verbal inquiry to Bob Taylor, requesting C-E's recommendations regarding what further action should be taken with regard to the subject unaccounted for loose parts, and to confirm our discussions on this subject yesterday (June 7, 1984).

Very truly yours,

COMBUSTION ENGINEERING, INC.



W.D. Meinert  
Palisades Project Manager

WDM/jbn

cc: J.P. Pomaranski  
D.R. Hughes  
V.A. Anderson  
M.D. Turnmire  
R.W. Taylor  
J.W. Matton



Outage Heatup

JAT:84\*021



Consumers Power Company

# DEVIATION REPORT

Reviewed by CARB  
CARB Review required after evaluation

Date 6/18/84  
CHG/DGM/REMC

DEVIATION REPORT NO	D- Pal - 84 - 137
TIME OF OCCURRENCE	Date <u>N/A</u> Hour
SAFETY RELATED	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

IDENTIFICATION & DESCRIPTION	PART 1
A TITLE: <u>Auxiliary Feedwater Piping Immediately Adjacent to Steam Generator B</u>	

B PLANT SYSTEM(UFI)	<u>03430</u>	EQUIPMENT - CLASS(UFI)	<u>15113</u>	EQUIPMENT NUMBER	<u>DBB-2-4"</u>
---------------------	--------------	------------------------	--------------	------------------	-----------------

C DESCRIPTION OF OCCURRENCE OR CONDITION: Ultrasonic measurement of the wall thickness on the auxiliary feedwater piping immediately adjacent to steam generator B has shown the actual piping wall thickness in some areas to be less than the nominal wall thickness shown within piping tables for schedule 40 4" piping.

D IMMEDIATE ACTION: Transmitted results of ultrasonic test to plant management; Phil Flenner of Operating Services Department, and Denny Hughes of Nuclear Plant Support.

E REFERENCES: <u>Ultrasonic test results for auxiliary feedwater piping immediately adjacent to E-50A (attached)</u>	F PREPARED BY: <u>Jeff Terpstra</u> DATE: <u>4/28/84</u>
	DEPT/PLANT: <u>TECH/BALISADES</u> SECTION: <u>PROJECTS</u>

G NONCONFORMING ITEM YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> IDENTIFY: <u>5/4/84</u>	APPROVED BY: <u>[Signature]</u> DATE: <u>5/4/84</u>
DETERMINED BY: <u>[Signature]</u>	

H DR FORWARDED TO:	DEPT/PLANT:	SECTION:
REPORTABILITY		PART 2

A TECH SPEC REPORTABLE: YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ER #:	B EVALUATOR: <u>JRHumble</u>
DETERMINED BY: <u>[Signature]</u> DATE: <u>5/4/84</u>	DEPT/PLANT: <u>NOD</u> SECTION: <u>NPS</u>
	APPROVED BY: <u>[Signature]</u> DATE: <u>5/7/84</u>
	EVALUATION DUE DATE: <u>5/25/84</u> <u>6/15/84</u> <u>8/5/84</u>
	PRIORITY: 8 <u>7</u> <u>6</u> <u>5</u> <u>4</u> <u>3</u> <u>2</u> <u>1</u>

EVALUATION AND DISPOSITION	PART 3
----------------------------	--------

A DESCRIBE CAUSE OF DEVIATION: The cause of the observed wall thinning is believed to be inherent in the design and failed condition of the steam generator auxiliary feedwater sparger. Under such conditions, Combustion Engineering describes the possibility of steam bubble collapse within the failed sparger (see P-CE-7597, Combustion Engineering Auxiliary Feedwater Sparger Study, Paragraph 1, Page 4 of 7, Attachment 1). During steam bubble collapse large differential pressures are realized which accelerate the incoming cold auxiliary feedwater to velocities which result in erosion of the nozzle liner and pressure boundary piping.

B CONSIDERED TO BE REPORTABLE UNDER 10CFR21: YES  NO  DETERMINED BY: [Signature] DATE: 6/18/84

COMPLETION	PART 4
APPROVED BY:	DATE:

COMPLETION REVIEW	PART 5
REVIEWED BY: <u>QA Representative</u>	DATE:

- (Gold) - COPY 4 - FORWARD TO QA UPON COMPLETION OF PART 2.
- (Pink) - COPY 3 - FORWARD TO QA UPON COMPLETION OF PART 3.
- (Canary) - COPY 2 - FORWARD TO THE ORIGINATING DEPARTMENT UPON COMPLETION OF PART 5.
- (White) - COPY 1 - FILED IN DOCUMENT CONTROL CENTER UPON COMPLETION OF PART 5.

FORWARD ALL CORRECTIVE ACTION DOCUMENTS THROUGH YOUR CORRECTIVE ACTION COORDINATOR.

Date change requested by JRP for EWM 7-5-84

# CORRECTIVE ACTION SHEET

i	REPORT NO. <u>120-84-13</u>
ii	TIME OF OCCURRENCE Date _____ HOUR _____
iii	SAFETY RELATED YES _____ NO _____

EVALUATION	PART 3	COMPLETION	PART 4
------------	--------	------------	--------

PROPOSED REMEDIAL CORRECTIVE ACTION: <u>Remove piping.</u>	PRC: YES _____ NO <u>X</u> MEETING _____ PRIOR TO PLACING RELIANCE YES <u>X</u> NO _____ ASSIGNED TO <u>JAT/CHG</u> DEPT/PLANT <u>DAL</u> SECTION <u>TECH</u> APPROVED BY <u>PLA</u> DATE APPROVED <u>6/18/84</u> REQD COMPLETION DATE <u>6/18/84</u> PRIORITY: 8 _____ 7 _____ 6 _____ 5 _____ 4 <u>X</u> 3 _____ 2 _____ 1 _____	REMEDIAL ACTION TAKEN: <u>Completed per FC-613</u>
DETERMINED BY <u>J. R. Dink</u> DATE <u>6/15/84</u>		COMPLETED BY <u>JAT by chg</u> DATE <u>6/18/84</u> APPROVED BY <u>[Signature]</u> DATE <u>6/18/84</u>

PROPOSED CORRECTIVE ACTION TO PREVENT RECURRENCE: <u>See FC-613.</u>	PRC: YES <u>X</u> NO _____ MEETING _____ PRIOR TO PLACING RELIANCE YES <u>X</u> NO _____ ASSIGNED TO <u>JAT</u> DEPT/PLANT <u>DAL</u> SECTION <u>TECH</u> APPROVED BY <u>CHG-PLA</u> DATE APPROVED <u>6/18/84</u> REQD COMPLETION DATE <u>6/18/84</u> PRIORITY: 8 _____ 7 _____ 6 _____ 5 _____ 4 <u>X</u> 3 _____ 2 _____ 1 _____	ACTION TAKEN TO PREVENT RECURRENCE: <u>Complete</u>
DETERMINED BY <u>J. R. Dink</u> DATE <u>6/15/84</u>		COMPLETED BY <u>chg for JAT</u> DATE <u>6/18/84</u> APPROVED BY <u>[Signature]</u> DATE <u>6/18/84</u>

(Gold) - COPY 4 - (FOR ERs) FORWARD TO NUCLEAR LICENSING ADMINISTRATOR UPON COMPLETION OF PART 3; (FOR DRs AND NRs - DISCARD).  
 (Pink) - COPY 3 - FORWARD TO QA UPON COMPLETION OF PART 3.  
 (Canary) - COPY 2 - FORWARD TO ORIGINATING DEPARTMENT UPON COMPLETION OF PART 5.  
 (White) - COPY 1 - FILED IN DOCUMENT CONTROL CENTER UPON COMPLETION OF PART 5.

FORWARD ALL CORRECTIVE ACTION DOCUMENTS THROUGH YOUR CORRECTIVE ACTION COORDINATOR!



CONSUMERS POWER COMPANY  
 SYSTEM PROTECTION AND LAB SERVICES DEPT  
 NONDESTRUCTIVE TESTING SERVICES  
 THICKNESS MEASUREMENT  
 EXAMINATION REPORT

EXAMINER R. THOMAS HUERTER LEVEL II DATE 4-27-84 SHEET NO RTH-02  
 EXAMINER N/A LEVEL N/A NDT COMPANY CPCo  
 PROJECT NO 238415-225077 REQUESTING DEPT TECH  
 JOB LOCATION PALISADES TOTAL HOURS WORKED \_\_\_\_\_

NDT PROCEDURE NDT-UT-02 REV 0

N/A

ULTRASONIC EQUIPMENT NORTEC 131D SN#  
PANAMETRICS (3743-00285) 5MHz x.50 ULTRAGEL II BATCH 8120  
 COMPONENT IDENTIFICATION AUX FEEDWATER 4" OFF S/G 'B'


ITEM

THICKNESS

	1	2	3	4	5	6	7	8	9	10	
CLOCK POSITIONS	0200		0400		0600		0800		1000		1200
POSITION # 1	278		272		270		273		274		286
2	236		243		225		222		236		218
3	250		358		380		383		222		336
4	260		372		386		364		290		320
5	212		218		226		221		220		235
6	233		240		231		220		233		250
7	241		251		236		231		240		256
8	238		243		250		246		238		253

SKETCH/REMARKS

S/G 'B'



NOTE: L. CLOCKWISE WITH FLOW

To Technical Superintendent, Palisades

From *J.M. Gose*  
PM&MP Resident Engineer, Palisades

Date May 4, 1984

Subject Auxiliary Feedwater Piping

CONSUMERS  
POWER  
COMPANY

Internal  
Correspondence

CC ADMullholand, P13-213B  
JGGose, PM&MP/Palisades  
Doc. Control 950\*42\*10\*06

TEM 13-84

---

Upon being informed of a possible problem in the auxiliary feed lines DBB-1 and DBB-2 installed by the plant during the 1981 outage a review of the drawings, piping class sheets and pipe class summary sheets was made. The possibility of a pipe wall thickness problem arose as a result of UT examination performed on the pipe. The examination provided wall thickness readings greater than the wall thickness of schedule 40 pipe with which the line was constructed. This resulted in speculation that possibly a short section of schedule 80 pipe had somehow been installed immediately adjacent to the Steam Generator nozzle.

Isometrics M101-2937(Q) R/8 and M101-2938(Q) R/8 contain details of an engineered adapter piece manufactured from a section of 5-inch XXS pipe machined on one end to fit-up with the S.G. nozzle and on the other end to fit-up with the schedule 40 pipe. This adapter piece is what was mistakenly thought to be a piece of schedule 80 pipe installed erroneously.

Following the above, questions arose in various quarters regarding the propriety of lines DBB-1 and DBB-2 being schedule 40. To check this situation, copies of the appropriate pipe class sheets and pipe class summary sheets were obtained. Minimum wall calculations per ANSI B31.1, 1980 were made to check the adequacy of the design. Copies of the pipe class sheets, pipe class summary sheets, and check calculations are attached.

The conclusions based upon the checks made are; that no schedule 80 pipe was wrongfully installed adjacent to the vessel nozzle; the line schedule is adequate for the design pressure and the remaining wall thickness based upon UT is greater than the calculated minimum wall including a 14% margin for bending, even though this system appears to be made up of straight sections and fittings.

References:

M101-2937(Q) R/8  
M101-2938(Q) R/8  
5935-M-260 Sh. 35 R/1 (Copy attached)  
5935-M-259 Sh. 100 R/1 (Copy attached)  
Check Calc. 5-3-84 - TEM (Copy attached)

CLASS 900 PRESSURE – TEMPERATURE RATING

CLASS : DBB

CARBON STEEL

CODE: ASME B&PV CODE, SECTION III, CLASS 2

ITEM	MATERIAL SPECIFICATION	SIZE	REMARKS
<u>PIPE:</u>	ASME SA-106, GR. B (SEAMLESS)	6" 4" thru 2 1/2" 2" & smaller	Schedule 80 Schedule 40 Schedule 80 <i>Design P=1100</i>
<u>FITTINGS:</u>	ASME SA-234, GR. WPB ASME SA-105	2 1/2" and larger 2" & smaller	SEAMLESS, BUTT WELDING, WALL THICKNESS TO MATCH PIPE. 3000# Socket Welding
<u>FLANGES:</u>	ASME SA-105, F&D, BORED TO MATCH PIPE	2 1/2" & larger	900# WELDING NECK, SMALL T&G
<u>PLATE:</u>	ASME SA-515, GR. 70	----	----
<u>VALVE BODY:</u>	ASME SA-216, GR. WCB	2 1/2" & larger	CASTINGS
<u>BOLTING:</u>	ASME SA-193, GR. B7 ASME SA-194, GR. 2H	----	AN STANDARD STUD BOLTS WITH HEAVY HEXAGON NUTS.
<u>GASKETS:</u>	"FLEXITALLIC" OR APPROVED EQUAL	2 1/2" & larger	STYLE R-4, STYLE CG FOR 26" & LARGER

<u>VALVES:</u>	<u>GATE</u>	<u>GLOBE</u>	<u>CHECK</u>	<u>BUTTERFLY</u>
2 1/2" & larger	DBB-GT	DBB-GB	DBB-CK	
900# BW:				

FIELD WELD END PREPARATION AND TRANSITION: DRAWING 12447-G-84(Q) Attachment C, Sheet 2

BRANCH CONNECTIONS: 2 1/2" & larger BRANCHES: GROUP A, DRAWING Sheet 62  
2" & Smaller Branches: Drawing Sheet 63

CORROSION ALLOWANCE: None

FIELD WELDING PROCEDURE: DRAWING 12447-G-84(Q)

WELD JOINT NDE: DRAWING 12447-G-84(Q)

1	CNGD. DWG. NO. FORM. M-260 SH. 89 REV. BRANCH CONN. RE. SH. NOS.	JGD	TRV	DIB
---	--	-----	-----	-----

NO.	DATE	REVISIONS	BY	CHK	APPR.
-----	------	-----------	----	-----	-------

		<b>PIPING CLASS SHEET</b>		JOB NO. 12447
---	--	---------------------------	--	---------------

CONSUMERS POWER COMPANY, PALISADES PLANT SOUTH HAVEN, MICHIGAN	Drawing 5935-M-260 REV. 1
---	------------------------------


		SHEET 35
--	--	----------

Document and the design it covers are the property of BECHTEL. This document is to be used only for the project specified. It is not to be re-used, copied, loaned, exhibited, nor used except in the limited way and under the conditions permitted by the lender to the borrower.

ENGINEERING RECORDS  
 INFORMATION COPY  
 MAY 2 1984  
 CON. ...  
*JACKSON*  
 DIB

This drawing and the design it covers are the property of BECHTEL - They are merely loaned and on the borrower's express agreement that they will not be reproduced, copied, loaned, exhibited, or used except in the limited private use permitted by any written consent given by the lender.

CLASS & SERVICE NO.	SERVICE *CRITICAL SERVICES P&ID NO. ( )	SEISMIC CLASS	DESIGN RATING		SERVICE CONDITION				INSUL. CLASS	SAFETY RELATED(S)
			PSIG	°F	NORMAL		MAXIMUM			
					PSIG	°F	PSIG	°F		
DBB-1	Aux. FW from EBB-1 ctmt. pene. #9 to stm. gen. E50A nozzle (207)	I	1,100	550	850	435	1,200	550	-	S
DBB-2	Aux. FW from EBB-2 ctmt. pene. #73 to stm. gen. E50B nozzle (207)	I	1,100	550	850	435	1,200	550	-	S



1	5/6/82	ISSUED FOR RECORD	MAZ	JKL	---	RH	JKL	PKS	---
0	4/14/82	ISSUED FOR USE	MAZ	OK	---	RH	PKL	---	---
No.	DATE	REVISIONS	BY	CHK	DESIGN SUPV	ENGR	PROJ ENGR	APPR	

SCALE	DESIGNED	DRAWN	CHIEF ENGR
ORIGIN AAO	PIPING CLASS SUMMARY CONSUMERS POWER COMPANY PALISADES NUCLEAR PLANT		JOB No. 12447 DRAWING No. 5935-M-259 REV.

-M-081073

5-3-84 TS 2:57pm

1) Check Min. wall requirement for DBS-1  
 Per B31.1 1980 5935-M-260 R-5 sh 85 of 95

$$f_m = \frac{P D_o}{2(SE + P_y)} + A$$

line = SA106 Gr. B 4-inch  $\therefore D_o = 4.50$   
 $P = 1100$  from M-259 sh 100 of 106  
 $T = 550$   
 $SE = 15,000$  from Appendix A, Table A-1 B31.1, 1980  
 $Y = 0.4$  from B31.1, 1980  
 $A = 0$  - designer's discretion

$$f_m = \frac{1100 \times 4.5}{2(15,000 + (1100 \times 4.5))} = \frac{4950}{30880} = 0.1602979$$

Wall allowance for bending - Assume 4 diam effective - 14% (1102.4)  
 $0.1602979 \times 1.14 = 0.1827396 < 0.237 = \text{sch 40 wall}$   
sch 40 is acceptable

2) Check Min wall requirement for DBB -  
 5935-M-9260 R-5 sh 6 of 19  
 Per B31.1 1980

$$f_m = \frac{P D_o}{2(SE + P_y)} + A$$

line = SA106 Gr. B 4-inch  $\therefore D_o = 4.5$   
 $P = 1685$  from M-9259 sh 3 of 20  
 $T = 120$   
 $SE = 15,000$  from Appendix A, Table A-1 B31.1, 1980  
 $Y = 0.4$  from B31.1, 1980  
 $A = 0$  - designer's discretion

$$f_m = \frac{1685 \times 4.5}{2(15,000 + (1685 \times 4.5))} = \frac{31348}{75825} = 0.2418814 > \text{sch 40}$$

Wall allowance for bending - Assume 4 diam effective - 14%  
 $0.2418814 \times 1.14 = 0.2757947 < 0.337 = \text{sch 80 wall}$   
sch 80 is acceptable

**POWER  
SYSTEMS**

P-CE-7597

Consumers Power Company  
Palisades Plant

Mr. D. R. Hughes  
Consumers Power Company  
1945 Parnall Road  
Jackson, Michigan 49201

**SUBJECT: AUXILIARY FEEDWATER SPARGER REPAIR**

References: (A) W. D. Meinert to D. R. Hughes, "Auxiliary Feedwater Sparger Repair," P-CE-7573, dated March 29, 1984.

(B) Corrective Action Review Board Meeting, April 5, 1984.

Attachments: (1) Auxiliary Feedwater Sparger Study.

(2) Response to Consumers Power Company Questions, received April 19, 1984.

(3) C-E Calculation, SS-801, "Evaluation of Palisades Auxiliary Feedwater Piping For A Postulated Water Hammer Event", dated April 19, 1984.

(4) C-E Position on the Palisades Steam Generator Auxiliary Nozzle Sparger Repair, April 16, 1984.

Dear Mr. Hughes:

This letter has been prepared to address the Palisades auxiliary feedwater sparger repair effort. The enclosed attachments discuss the sparger design, damage and repair based on the information presently available.

Attachment (1) has been revised to clarify Reference (A), incorporation of new information, and address items that were discussed during a meeting at Palisades site, Reference (B).

On April 19, 1984, C-E received a list of questions to be answered for Consumers Power Company safety evaluation on the auxiliary feedwater sparger modification. The responses to these questions are provided in Attachment (2). Additionally, C-E has performed a calculation Attachment (3) "Evaluation of Palisades Auxiliary Feedwater Piping for a Postulated Water Hammer Event", that should address some of your concerns.

Attachment (4) is C-E's position on the Palisades steam generator auxiliary feedwater nozzle sparger repair as a result of an internal meeting in Chattanooga, Tennessee, on April 16, 1984.



C-E is also reviewing normal plant operating and emergency procedures that could be affected by auxiliary feedwater flow rate restrictions to help preclude water hammer. A marked-up copy of these procedures will be forwarded to Consumers by Friday, April 27, 1984.

In summary, C-E recommends that the sparger be removed. A new thermal liner with splash shield assembly should be installed to protect the auxiliary feedwater nozzle from direct impingement of cold auxiliary feedwater. Auxiliary feedwater flow rate restrictions will be required when the level in the steam generator is below the auxiliary feedwater nozzle to prevent water hammer in the first horizontal pipe until testing can be performed to provide a basis to relax these restrictions. The modification and flow restrictions will remove the potential for a damaging water hammer to occur inside the steam generator. The external piping will remain full of water during normal operating conditions. Further action to keep the external piping as full of water as possible when the steam generator water level is below the auxiliary feedwater nozzle could be considered. Periodic testing, to demonstrate that a significant portion of the external piping would not void within a reasonable time for operator action, could be performed. This would require installation of a means for monitoring the external piping for line voiding.

If you have any further questions regarding any of the attached information, please let me know.

Very truly yours,

COMBUSTION ENGINEERING, INC.



W. D. Meinert  
Palisades Project Manager

WDM/CJG:jcp

xc: G. B. Slade  
W. J. Beckius  
R. W. Montross  
C. Gilmor  
J. P. Pomaranski  
J. W. Matton  
R. W. Taylor

F44A94

Combustion Engineering  
Auxiliary Feedwater Sparger Study

Background

During a recent inspection of the steam generators, damage was observed to the internal auxiliary feedwater piping in both units. C-E personnel have inspected both steam generators. In one unit the nozzle liner was sheared off and the first support bracket was broken. In the second unit, the weld was cracked between the nozzle liner and the elbow allowing the pieces to separate and the first support bracket was twisted. It is our understanding that a visual inspection of the external auxiliary feedwater piping has been performed and that no significant damage was found.

Investigation

C-E has reviewed the results of the water hammer test that was conducted after the auxiliary feedwater spargers were installed. During the test no water hammer was observed at the test conditions. However, a review of the raw data (strip chart recorder traces) reveals evidence of periodic water hammer(s), between the tests run at steam generator pressures of 200 psi and 900 psi at flow rates of approximately 40 gallons per minute (below the range of test conditions). The indications stopped when the flow rate was raised to 50 gallons per minute, with the steam generator at 900 psi.

Additional verbal information has been received from the site. Based on interviews with the site operating staff and information obtained during the site meeting, Reference (B), it is understood that small water hammers may have occurred during sodium recovery operations during the last cycle of operation. These indications were reported to have been observed when the steam generator level was below the auxiliary feedwater nozzle with estimated flow rates of 15 to 30 gallons per minute. The water hammers were cyclic in nature and stopped when auxiliary feedwater flow was increased above 50 gallons per minute.

### Present Auxiliary Feedwater Sparger Design

The present sparger design incorporates the design features presently used in the industry to preclude water hammer. Top discharge J tubes are used to keep the sparger full of water when steam generator water level is below the sparger. If the sparger becomes partly drained, a water slug formation can occur during the refilling of the sparger. Large vent area to sparger volume ratios were incorporated to minimize the probability of water slug formation. This sparger design compares favorably with the design of other units. An anti-siphon gooseneck was incorporated to prevent sparger draining through the thermal sleeve clearances when steam generator level is below the nozzle for extended periods of time. Consistent with standard PWR practice, every effort was made to maintain the sparger full of water to minimize the probability of water hammer when auxiliary feedwater flow was initiated. Due to the location of the existing supports, the auxiliary feedwater spargers at Palisades were installed close to the normal water level. These supports have limited load carrying capability that prevents hanging the sparger lower in the steam generator. This location results in the top of the anti-siphon gooseneck being in the steam space, at normal steam generator water levels. A small steam void would, therefore, be present in the gooseneck during plant operation.

### Postulated Water Hammer Mechanism(s)

System configuration, operation and physical damage have all been studied to determine a mechanism that could produce the damage observed. A number of different conditions can be postulated that could have resulted in several types of water hammer events of varying severity.

A comparatively large water hammer event would have been required to cause the damage observed in the steam generator. This belief is supported by the inspection of the damaged parts. A large tensile load had to occur to break the nozzle liner and shear the support bracket. There is no known evidence of cyclic failure of these components. The water hammer test conducted following the sparger installation produced pressure spikes of several hundred psi. These water hammers are not believed capable of causing the physical damage observed to the spargers. The sparger damage probably occurred during subsequent plant operation.

When the plant is at power, the auxiliary feedwater system is usually in a standby configuration, i.e., it is only operated monthly for surveillance testing. The sparger gooseneck high point vent is in the steam space during normal plant operation. As a result of back leakage through the auxiliary feedwater system over this extended period of time, steam could have entered the high point vent in the gooseneck and displaced the water in the nozzle liner and some of the external piping. This displacement of water would continue until the system leak rate was balanced by the condensation rate of steam in the uninsulated piping. When the auxiliary feedwater system was manually initiated at a very low flow rate, a region of two phase flow developed in the external horizontal run of piping. When the steam came in contact with the cold auxiliary feedwater, the condensation rate exceeded the venting capacity of the vent on top of the gooseneck, producing a low pressure void in the horizontal pipe. Steam generator pressure would then accelerate a slug of water from the sparger over the gooseneck impacting the piping near the nozzle liner. C-E believes this slug of water would have had enough energy to produce the damage observed.

Several mechanisms have been postulated to explain the small periodic noises reported by the site operating staff. None of the following theories can be definitely proven analytically but are based on the information currently available to C-E. One mechanism assumes the sparger is intact, the other two mechanisms assume the sparger is damaged.

The periodic banging during the original testing could have been due to two-phase flow in the gooseneck section of the sparger. At normal steam generator water level, there is a small steam void in the top of the gooseneck. When cool auxiliary feedwater flow is introduced to the steam generator at very low flow rates, cold water cascades over the gooseneck. Steam rushes in through the high point vent to replenish the steam that is condensing in contact with the cold water. At a critical flow rate, the steam void collapses causing a small differential pressure that pulls a small slug of water up the gooseneck from the sparger. The water then redistributes and a small void of steam is recreated in the top of the gooseneck. Conditions have then been reset to allow this small banging to reoccur. Because the steam space involved is small, the resulting pressure differential would also be small. This mechanism should not result in a damaging water hammer that creates enough energy to damage the sparger. The observed pressure spikes from the test data were a few hundred psi which is consistent with this theory.

Two other theories have been postulated which would produce periodic banging after the sparger had been damaged. A banging noise could have been the result of auxiliary feedwater flow pushing on the internal piping causing it to strike the steam generator internals. Secondly, after the sparger had been damaged, the first horizontal run of auxiliary feedwater piping would drain if the steam generator level was below the nozzle. If auxiliary feedwater flow was initiated manually at a low flow rate, two-phase flow conditions could exist in the first horizontal pipe run outside the steam generator. As the pipe refilled, steam in contact with cold auxiliary feedwater would condense in the pipe. Steam would rush in to replace the condensed steam. At some point during the filling of this horizontal pipe, the steam velocity would increase to a point where it caused a wave to form blocking off the steam flow. The entrapped steam bubble would collapse producing a low pressure zone in the horizontal pipe. Water would then be accelerated into this low pressure zone. When these columns of water collide in the low pressure zone their kinetic energy is transformed into potential energy and is manifested in a pressure pulse. This energy is dissipated as the pressure wave radiates through the auxiliary feedwater piping. It is believed that this mechanism produced the water hammer observed by the operators during the sodium recovery operations during the last cycle of operation.

#### Safety Implications

While the auxiliary feedwater spargers were damaged, the safety function of the system was not impaired.

- Decay heat removal capability was not degraded. Auxiliary feedwater flow capability was demonstrated each month during the surveillance test.
- The steam generator pressure boundary integrity is not believed to have been degraded. The thermal liner stayed in place protecting the thick wall section of the nozzle from cold water induced thermal stress. While not considered likely, the inner radius of the nozzles could have been subjected to cold water splashing. This splashing could give rise to surface cracking of this portion of the nozzle. Visual inspection of the nozzle inner radius will be performed during

the sparger repair work to confirm the present condition of the inner surface of the nozzle.

- The external auxiliary feedwater piping is not believed to be damaged. A visual inspection of the external auxiliary feedwater piping was performed and we understand that no significant damage was found.
  
- Radiographic inspection of the nozzle weld and horizontal piping to the first elbow has been performed. No cracking of the welds or pipe has been reported, however, we understand that some loss of wall thickness near the top of the pipe may have occurred.

### Design Alternatives

Several design alternatives have been considered to reduce the probability of water hammer in the system. Lowering the sparger would prevent steam from entering the gooseneck and the external piping while the steam generator is at normal water level. This had been evaluated previously. The existing brackets can not support the load induced by this design. Based on the apparent successful operation of the plant for some period of time in the existing configuration, the recommended modification is to remove the sparger and install a modified nozzle liner and splash shield to protect the nozzle.

Removal of the sparger and gooseneck eliminate several of the conditions believed to have contributed to the large water hammer. When the steam generator is at normal water level, back leakage through the auxiliary feedwater system will be made up with water from the steam generator. By maintaining the nozzle and external piping full of water, the mechanism to produce a large differential pressure is eliminated. If the steam generator level is below the nozzle, the thermal liner and the first horizontal pipe run of external piping immediately outside the steam generator will drain. C-E has performed a calculation to evaluate the conditions under which water hammer might occur during the refill of this pipe. This analysis assumed that only the first horizontal length of auxiliary feedwater piping is voided. If steam generator level is maintained below the auxiliary feedwater nozzle for a sufficient length of time, there is the potential to void the next horizontal run of piping. A void in the second horizontal pipe run could produce a large water hammer event when auxiliary feedwater flow is initiated.

As discussed during the meeting, Reference (B), water hammer may have occurred in the first horizontal pipe during sodium recovery operations. During this operation, steam generator water level was allowed to drop below the auxiliary feedwater nozzle and auxiliary feedwater flow rates were very low. It is recommended that any time the auxiliary feedwater nozzle is not submerged, auxiliary feedwater flow be initiated at a flow rate that would prevent two-phase flow in this pipe (i.e., >70 gpm).

### Operational Testing

Calculations indicate that water hammer can occur in the first horizontal pipe run. The potential for water hammer exists when steam generator level is below the auxiliary feedwater nozzle and auxiliary feedwater flow is below 70 gallons per minute. For flow rates above 70 gallons per minute the horizontal pipe will flow water solid and will not be susceptible to two-phase flow induced water hammer. When the auxiliary feedwater nozzle is completely submerged in water the horizontal pipe will remain full of water and no restrictions are imposed on the auxiliary feedwater flow rate. As a minimum, flow testing should be performed to verify that water hammer will not occur within the flow restrictions indicated above. With the plant at hot standby conditions, the steam generator level should be quickly dropped below the auxiliary feedwater nozzle. Auxiliary feedwater flow should then be initiated rapidly at a rate of 150 gallons per minute. This test would simulate plant operation for expected transients that would automatically initiate the auxiliary feedwater system. Auxiliary feedwater flow should be slowly throttled from 150 gallons per minute to 70 gallons per minute while the auxiliary feedwater nozzle is uncovered to confirm that water hammer will not occur in the recommended flow range.

More extensive testing could be performed to minimize the operational limitations. This testing would be performed over the entire auxiliary feedwater flow range at reduced steam generator pressures. Reduced steam generator pressures would minimize the magnitude of the water hammer that could occur and would provide a basis for relaxing operational restrictions.

Conclusion

In conclusion, C-E recommends that the sparger be removed. A new thermal liner with splash shield assembly should be installed to protect the auxiliary feedwater nozzle from direct impingement of cold auxiliary feedwater. Auxiliary feedwater flow rate restrictions will be required when the level in the steam generator is below the auxiliary feedwater nozzle to prevent water hammer in the first horizontal pipe until testing can be performed to provide a basis to relax these restrictions. The modification and flow restrictions will remove the potential for a damaging water hammer to occur inside the steam generator. The external piping will remain full of water during normal operating conditions. Further action to keep the external piping as full of water as possible when the steam generator water level is below the auxiliary feedwater nozzle could be considered. Periodic testing, to demonstrate that a significant portion of the external piping would not void within a reasonable time for operator action, could be performed. This would require installation of a means for monitoring the external piping for line voiding.

F44A94



RESPONSES TO LIST OF ITEMS TO BE ANSWERED FOR CPCO SAFETY EVALUATION ON  
AUXILIARY FEEDWATER SPARGER MODIFICATION

1. Justify acceptability of design

Question 1 (a): Why if forces are greater than stress allowable is design acceptable?

Question 1 (b): Why is deviation from normal design practice acceptable?

Question 1 (c): Calculation

See the SUMMARY AND CONCLUSIONS, C-E calculation SS-801, EVALUATION OF PALISADES AUXILIARY FEEDWATER PIPING FOR A POSTULATED WATERHAMMER EVENT. If worst calculated waterhammer pressure pulses of 4000 psi (see Figure 1) were actually experienced, the calculated stress produced at the minimum cross section would slightly exceed the minimum yield stress at temperature. Using ASME fatigue curves a total of approximately 2000 cycles of this transient pressure pulse would be allowable. For 25 cycles (pulses) the fatigue usage factor would be negligible.

There is no normal design practice for waterhammer. SS-801, based on the ASME code, is considered a reasonable approach to evaluate this postulated transient. In view of the ductility of the carbon steel material the stress of 31 KSI (52% of  $S_u$ ) is considered to be well below a damaging stress.

It should be noted that this calculation presupposes undamaged material and a willingness to accept operational restrictions to avoid/limit water hammer occurrences until experimental or theoretical justification is available to provide a basis for relaxing the restrictions.

Question 1 (d): How much certainty does C-E have in the calculation, any tolerance?

The above discussions center around the structural analyses which C-E has performed to demonstrate that the piping system has sufficient structural strength to withstand the calculated worst case loadings due to waterhammer. However, the prediction of the onset of waterhammer and the resultant magnitudes is a very difficult calculational process. To minimize the uncertainty in these calculations, C-E has chosen to use experimental empirical correlations wherever possible.

These correlations are broken down into two areas, the prediction of the onset of wave formation, which is the necessary precondition for waterhammer, and the prediction of the magnitude of the resultant waterhammer. Wave formation occurs due to the counterflow of steam across the surface of auxiliary feedwater within the thermal sleeve. As the level of water within the sleeve

increases due to an increase in auxiliary feedwater flow or the refill of the steam generator, the available flow area for steam to enter the sleeve from the steam generator is reduced. Since the condensation rate remains relatively constant during this period, the velocity of the steam must continually increase to compensate for the reduced flow area. At some point during the recovery process, the steam velocity reaches a point where the drag forces on the surface of the feedwater cause a wave to form. Once this occurs, the available flow area for the steam is rapidly reduced resulting in total blockage.

When blockage occurs, the necessary preconditions for waterhammer are present. The steam that is trapped within the sleeve continues to condense. This depressurizes the steam pocket creating a differential pressure across the wave. This pressure difference accelerates the wave of water away from the steam generator into the auxiliary feedwater system piping where it impacts the column of water within the pipe. This creates the pressure impulse associated with waterhammer.

The calculation concerning the onset of wave formation is based on a MIT paper, reference A. This paper uses the dimensionless Taitel-Dukler Criteria, which has been correlated to experimental test data, to predict wave formation. A computer code is used to calculate this number at various points along the thermal sleeve, while taking into account the condensation rate, the auxiliary flow rate and the height of the water level within the pipe. From these runs, a curve is plotted, Figure 1, which shows the onset of wave formation as a function of auxiliary flow rate and water level at the exit to the thermal sleeve.

The pressure rise following the collapse of the trapped steam bubble is determined using correlations documented in the Creare waterhammer report, reference B. An attempt has been made to verify this method by comparing the predicted pressure with experimentally obtained Tihange test data. When using this method, the impact velocity of the slug is first computed as a function of the water level within the pipe and the available steam generator pressure. The pressure rise is then calculated using classic waterhammer theory involving the acoustical velocity of the water, its density and the slug velocity. This information is also plotted on Figure 1 as a function of the water level within the pipe.

The maximum pressure rise is determined by the intersection of the wave formation and the pressure rise curves. For other flow conditions the pressure rapidly decreases. Hence, a very unique set of conditions are required before pressure increases of the magnitude assumed in the stress analyses can be achieved.

Recent discussions with plant staff indicate that water hammers have not been detected during low flow conditions, such as during sodium recovery operations, indicating that if waterhammer occurred it was of much lower magnitude than the worst case predicted by the waterhammer calculation. Recently conducted radiograph tests, which identified no pipe wall cracks, provide additional support for this belief.

Question 1 (e):1 List of assumptions.

There are relatively few key assumptions made in these calculations. It is assumed that waterhammer does occur once wave formation is predicted. In reality, these waves may be broken up before complete blockage occurs, thus further limiting the flow conditions under which waterhammer can occur. Another critical assumption is a one-dimensional temperature profile within the auxiliary feedwater. Under actual flow conditions, the surface of the feedwater would heat up more rapidly, creating a temperature profile through the feedwater. If the profile were considered, the rate of heat transfer and hence the condensation rate would be reduced. This would reduce the amount of steam being drawn into the thermal sleeve and further limit the flow conditions under which wave formation is possible.

The magnitude of the pressure impact is very dependent on the condensation rate within the trapped steam pocket. In this analysis, it is assumed that rapid condensation of the magnitude believed to occur at Tihange takes place. However, for this to occur, the surface of the water must be broken up into small droplets, which greatly amplify the condensing area. If the surface doesn't breakup, the pressure within the steam pocket remains relatively high, reducing the slug velocity and ultimately the peak pressure.

Question 1 (f): Degree of conservatism.

In general, this is a best estimate calculation, since all critical correlations are based on empirical data. If wave formation and rapid condensation do occur, significant waterhammers are possible. If these conditions are not present or they are significantly reduced, the magnitude of the waterhammers will be much less. The fact that no waterhammers have been reported during the most recent low flow operations indicates that these calculations are conservative and that other mitigating factors are coming into play.

Question 1 (g): Under what conditions do we have severe waterhammer?

The most severe waterhammer is predicted to occur when the pipe is approximately 60% full. Under these conditions, a worst case waterhammer of approximately 4000 psi is predicted. If wave formation occurs at higher or lower water levels within the pipe, and/or flow rates are either smaller or greater, the predicted pressure pulse is reduced significantly. This has prompted C-E to recommend that an interim minimum auxiliary flow restriction of 70 gpm be placed on plant operations when the level in the steam generator is below the top of the auxiliary feedwater nozzle. Both tests and analytical calculations indicate that, for this flow, the sleeve will flow full, thus preventing the formation of a steam pocket which must be present before waterhammer can occur.

- 4-
- References: (A) R.W. Bjorge, "Initiation of Water Hammer In Horizontal or Nearly-Horizontal Pipes Containing Steam and Subcooled Water," Ph.D. Thesis, MIT, 1983.
- (B) TN 251, "An Evaluation of PWR Steam Generator Water Hammer" Creare Incorporated, February, 1977.

Question 1 (h): Will the pipe fracture?

The pipe should not fracture provided the assumptions delineated in the discussion of 1.(a), (b), (c) above are valid.

Question 1 (i): If the chances are greater for a fatigue type failure-how many cycles are allowable?

Using ASME fatigue curves, approximately 2000 cycles of the postulated pressure pulse would be allowable. If a single violation of the operating restrictions did not result in the accumulation of over 25 water hammer pulses the cumulative usage factor would be negligible ( $u=0.0125$ ). See also calculation SS-801 and the discussion under 1.(a), (b), (c) above.

NOTE: Experimental measurements would be required to determine the rate (waterhammer pulses/time) at which cycles are accumulated if the operating restrictions are violated.

Question 1 (j): Do you recommend NDE on the auxiliary feedwater piping after the modification is complete and the plant has run for awhile?

Yes. Baseline NDE data should be taken before startup. This would provide a basis for comparison should something unforeseen occur. Repeat of the NDE inspection at the next refueling outage would provide confirmation that no degradation had taken place during the operating cycle.

## 2. Operational restrictions

Question 2 (a): If above a certain pressure and below a given steam generator level, what flows are forbidden? What flows should be avoided? What are postulated consequences?

To avoid waterhammer in the auxiliary feedwater system piping adjacent to the steam generator the following restrictions are recommended.

If SG level is below 60% (NR) AFW should only be initiated at flow rates greater than 70 gpm. If auxiliary feedwater flow is initiated manually a flow rate above 70 gpm should be established as quickly as possible to avoid waterhammer while passing through the restricted flow range. Flow should not be reduced below 70 gpm until SG level is recovered and maintained at on above a level of 60% (NR).

Question 2 (b): Is there a tolerance on your calculated flow values?  
If so, what?

As shown on the attached figure there is a theoretical possibility of water hammer over a range of flows of 5 gpm (when the auxiliary feedwater nozzle is being recovered) to 60 gpm. The recommended operational restriction is 70 gpm.

Based on reported operators' recollections, waterhammer (when it was observed) occurred at flow rates of 30 to 40 gpm and ceased when the flow rate was increased to 50 gpm. This is in excellent agreement with our calculations as shown on the attached figure. Based on the operators' observations the actual upper limit for observable water hammer to occur may be approximately 50 gpm.

Question 2 (c): Calculations

See discussions under 1 above.

Question 2 (d): Procedural requirements

The operational requirements mentioned in 2(a) should be incorporated into every procedure that may require that the AFW system be used. SOP 12 Feedwater System and EOP 1 Reactor Trip are being reviewed and changes recommended in the appropriate areas. The additional procedures listed below will also be reviewed.

- Plant Heatup
- Plant Cooldown
- Loss of Main Feedwater
- Loss of Off Site Power
- Turbine Trip
- Loss of Condenser Vacuum

3. Can we justify continuing to operate after having experienced a short interval of operation at low auxiliary feedwater low steam generator level?

Question 3 (a): How long can we stay in this region of low flow/low level?

As indicated above, until justification (experimental or theoretical) can be provided for relaxing the recommended operating restrictions the restricted operating region should be administratively avoided. Should operation in this region occur the following questions would need to be addressed:

- (1) Did waterhammer occur, i.e. was detectable waterhammer observed?
- (2) What was the severity of the water hammer?
- (3) How many cycles (pressure pulses) were accumulated?

As discussed above and delineated in SS-801 the ASME fatigue curves would permit up to approximately 2000 cycles of the worst postulated (calculated) pressure pulse. For 25 cycles the cumulative usage factor is essentially negligible. Experimental measurements would be required to ascertain the rate at which water hammer cycles would actually be accumulated if the recommended operating restrictions are not addressed too. These same experimental measurements could be used to measure the actual magnitude of the pressure pulses and provide a basis for possible relaxation of the restriction.

adhered to.

To put this in better perspective, if the period of the water hammer is once per second and the operator responded to correct the situation within 5 minutes, 300 cycles would be accumulated. If the period was 20 to 30 seconds between waterhammer, consistent with some of the operators' recollections as reported to C-E, the number of cycles accumulated would only be 10 to 15 for the same period of time.

Question 3 (b): What corrective action should be taken?

If a flow rate less than 70 gpm occurs at a steam generator level below 60% (NR) the flow rate should be promptly increased to greater than 70 gpm, or terminated.

PALISADES REGION OF POTENTIAL  
 WATERHAMMER AND IMPACT PRESSURE RISE RELATION

