	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 LICENSE TYPE 30 57 CAT 58
0 1 7 8	REPORT L 6 0 5 0 0 0 2 7 2 7 0 1 0 3 7 9 8 0 1 3 1 7 9 9 SOURCE 50 61 DOCKET NUMBER 58 69 EVENT DATE 74 75 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During normal operation upon exiting containment, a leak rate test on
03	El. 100 air lock showed excessive leak rate. The Action Statement for
0 4	- T/S-3.6.1.3 was implemented. The doors were reworked and the air lock
0 5	was returned to operation within 5 hours. This is the third occurrence
- 06	of this type (78-58, 78-80)
0 7	
0 8	9 80
7 8	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE
	LER/RO EVENT YEAR REPORT NO. 17 REPORT 7 9 23 24 26 27 28 29 30 31 31 30 32 ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. SUBMITTED FORM SUB. 18 D 19 Z 20 Z 21 0 0 0 0 0 Y 23 Y 24 Z 25 C 3 1 0 0 0 0 19 A 18 D 19 Z 20 Z 21 0 0 0 0 0 Y 23 Y 24 Z 25 C 3 1 0 0 0 0 10 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
- 1 0	The inner and outer door seals failed due to a split at the vulcanized
1 1	seam. Both door seals were replaced and the air lock retested satis-
1-12	factorily. Design Change Request 1-ED-0442 has been submitted to up-
13	grade the air locks.
14	9
7 8	FACILITY STATUS
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) - Z (34) N/A N/A N/A 9 10 11 44 45
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 37 Z 38 N/A 9
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41 0 0 0 0 40 N/A
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 1 7 (7)
7 8	VICTOR N/A 9 10 PUBLICITY NRC USE ONLY
2 0	ISSUED DESCRIPTION (45) N/A
020	Ope NAME OF PREPARER A. W. Kapple PHONE: (609) 365-7000 Salem Ext.