

Report Number: 79-37/03L
Report Date: 5/11/79
Occurrence Date: 4/16/79
Facility: Salem Generating Station
Public Service Electric & Gas Company
Hancock's Bridge, New Jersey 08038

IDENTIFICATION OF OCCURRENCE:

Source Range Nuclear Instrumentation Channel N-32 Inoperable

CONDITIONS PRIOR TO OCCURRENCE:

Operational Mode 6
Reactor Vessel Head Bolts Removed
Reactor Vessel Head In Place

DESCRIPTION OF OCCURRENCE:

While in Mode 6, prior to reactor vessel head removal, source range nuclear instrumentation channel N-32 indication started becoming erratic. The channel was declared inoperable and the Action Statement for Technical Specification 3.9.2 was implemented. The erratic indication became an intermittent problem while Performance Department personnel were troubleshooting the channel components and the channel was returned to service and removed from service on 4-16, 4-17, 4-19 and 4-21-79. At 1421 hours on 4-21-79, the channel was repaired and tested satisfactorily. The Action Statement for T/S 3.9.2 was terminated at this time.

DESIGNATION OF APPARENT CAUSE OF OCCURRENCE:

Two coaxial cable shield connections were the cause of this occurrence. A connector on the high voltage cable of the source range drawer was found on 4/16/79 to have a broken shield connection. This seemed to cure the problem but when intermittent erratic operation again occurred, further troubleshooting was done. After replacement of the detector and pre-amp assemblies on 4-21-79, a connector on the signal cable at the outboard containment electrical penetration was found to have a broken solder connection on the shield sleeve, resulting in an intermittent open circuit.

ANALYSIS OF OCCURRENCE:

Technical Specification 3.9.2 requires that if two source range neutron flux monitors, each with continuous visual indication in the Control Room and one with audible indication in the containment and Control Room, are not in operation, immediately suspend all operations involving core alterations or positive reactivity changes. The reactor vessel head was in place throughout this occurrence. Source range channel N-31 operated properly to provide shutdown neutron flux monitoring. The reactor plant parameters were stable and remained stable to minimize reactivity changes.

7905150464 5

CORRECTIVE ACTION:

The coaxial connector on the channel drawer was cleaned and reworked to provide a good shield connection. The connector at the containment penetration was replaced with a spare connector.

FAILURE DATA:

Not Applicable

Prepared By A. W. Kapple

SORC Meeting No. 34-79

P. J. Repoluna
Manager - Salem Generating Station

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T 01 REPORT SOURCE L 6 0 5 0 0 0 2 7 2 7 0 4 1 6 7 9 8 0 5 1 1 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 While in Mode 6, prior to reactor vessel head removal, source range N.I. Channel
03 N-32 indication became erratic. T/S 3.9.2 Action Statement was implemented. After
04 initial repair, intermittent erratic operation required N-32 removal from service on
05 4-16, 4-17, 4-19 and 4-21-79. The channel was repaired and tested satisfactory on
06 4-21-79 and the Action Statement was terminated. Source range N.I. Channel N-31 was
07 operational and plant parameters were stable throughout this occurrence. This is the
08 first occurrence of this type.

09 SYSTEM CODE I D 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE E L E C O N 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 7 9 21 22 SEQUENTIAL REPORT NO. 0 3 7 23 24 25 26 OCCURRENCE CODE 0 3 27 28 29 REPORT TYPE L 30 31 REVISION NO. 0 32
 ACTION TAKEN A 33 FUTURE ACTION Z 34 EFFECT ON PLANT Z 35 SHUTDOWN METHOD Z 36 HOURS 0 0 0 37 38 39 ATTACHMENT SUBMITTED Y 40 41 42 NPRO-4 FORM SUB. N 43 44 PRIME COMP. SUPPLIER L 45 46 47 COMPONENT MANUFACTURER A 3 8 0 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The cause of this occurrence was a disconnected shield on the source range high
11 voltage drawer connector and a broken solder connection on the shield sleeve of the
12 connector for containment electrical penetration 1-19. The drawer connector was
13 reworked and the penetration connector was replaced.

14 FACILITY STATUS H 28 29 % POWER 0 0 0 30 OTHER STATUS N/A 31 METHOD OF DISCOVERY A 32 DISCOVERY DESCRIPTION Operator Observation

15 ACTIVITY CONTENT Z 33 34 RELEASED OF RELEASE Z 35 AMOUNT OF ACTIVITY N/A 36 LOCATION OF RELEASE N/A

16 PERSONNEL EXPOSURES NUMBER 0 0 0 37 38 TYPE Z 39 DESCRIPTION N/A

17 PERSONNEL INJURIES NUMBER 0 0 0 40 41 DESCRIPTION N/A

18 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 43 DESCRIPTION N/A

19 PUBLICITY ISSUED Z 44 45 DESCRIPTION N/A

NAME OF PREPARER A. W. Kapple

PHONE: (609) 365-7000 Salem Ext.