

Distribution w/enclosure:

Docket File  
NRC PDR  
Local PDR  
LWR #3 File  
D. Vassallo  
D. Ross

S. Varga  
F. Williams  
O. Parr  
A. Dromerick  
M. Rushbrook  
R. Mattson

S. Hanauer  
J. Knight  
R. Tedesco  
R. DeYoung  
V. Moore  
W. Kreger  
M. Ernst  
R. Denise

OELD  
IE (3)  
BCC: JBuchanan  
TABernathy  
ACRS (16)

Docket No. 50-311

JUL 30 1979

Mr. R. L. Mittl, General Manager  
Licensing and Environment  
Engineering and Construction Department  
Public Service Electric and Gas Company  
80 Park Place  
Newark, New Jersey 07101

Dear Mr. Mittl:

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION FOR THE REVIEW OF THE SALEM  
UNIT 2 FINAL SAFETY ANALYSIS REPORT (FSAR)

As a result of our continuing review of the Salem FSAR, we find that we need additional information to complete our evaluation. The specific information required is listed in the Enclosure.

Our review schedule is based on the assumption that this additional information will be available for our review by August 10, 1979. If you cannot meet this date, please inform us within seven days after receipt of this letter so that we may revise our schedule accordingly.

Please contact us if you desire any discussion or clarification of the enclosed request.

Sincerely,

Original Signed by  
**O. D. Parr**

Olan D. Parr, Chief  
Light Water Reactors Branch No. 3  
Division of Project Management

Enclosure:  
Request for Additional Information

cc w/enclosure:  
See next page

7908300062

A23  
60

OFFICE	LWR #3/PM	LWR #3/BC				
SURNAME	ADromerick/LM	ODParr				
DATE	7/30/79	7/30/79				

Mr. R. L. Mittl, General Manager - - 2 -

JUL 30 1979

cc: Richard Fryling, Jr., Esq.  
Assistant General Counsel  
Public Service Electric & Gas Company  
80 Park Place  
Newark, New Jersey 07100

Mark Wetterhahn, Esq.  
Conner, Moore & Cober  
1747 Pennsylvania Avenue, N.W.  
Suite 1050  
Washington, D.C. 20006

Mr. Leif J. Norrholm  
U. S. Nuclear Regulatory Commission  
Region I  
Drawer I  
Hancocks Bridge, New Jersey 08038

ENCLOSURE

REQUEST FOR ADDITIONAL INFORMATION

SALEM NUCLEAR GENERATING STATION, UNIT 2

DOCKET NO. 50-311

3.0 REACTOR

3.13 During a recent refueling outage at a W plant (Salem Unit 1), strap damage was observed on a number of fuel spacer grids. It is not known whether the damage occurred during the initial core loading or during the refueling withdrawal. What assurances can you provide that the same type of grid damage will not be experienced at Salem Unit 2?