	■ .							
٠		LICE	ENSE	EE	VEN	T_R	<b>EPO</b>	RT



وراغ	LICENSEE EVENT_REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	NJSGS12000-0000-000341111165 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 2 7 2 7 0 8 2 4 7 9 8 0 9 0 7 7 9 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  During first refueling outage, as follow-up to NRC Inspection 50-311/79-19, three
0 3	snubbers on No. 14 Main Feedwater line were found to have failed in place. These
0 4	snubbers were included in the stress calculations for the seismic safety analysis of
0 5	the nuclear portion of the Main Feedwater piping. Public Service Engineering
0 6	Department is performing a safety analysis of this occurrence which will be sub-
0 7	mitted in a supplemental report. This is the first occurrence of this type.
0 8	9
0 9 7 8	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	C   18   Z   19   Z   20   Z   21   0   0   0   0   Y   (23)   N   (24)   L   (25)   P   0   2   (26)   (
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	The three failed snubbers were replaced in kind. Snubbers on No. 11, 12 and 13 Main
11	Feedwater Systems were checked satisfactory. The cause of the failure is being
1 2	investigated and will be reported in a supplemental report.
1 3	
1 4 7 8	
1 5	FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  G 28 0 0 0 0 29 N/A C 31 Follow-Up Surveillance to NRC Inspection 30  9 10 12 13 44 45 46 80
1 6 R	CTIVITY CONTENT  ELEASED OF RELEASE AMOUNT OF ACTIVITY 35    Z   33   Z   34   N/A    PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35    N/A   M/A   M/A     N/A     N/A   M/A     N/A     N/A
1 7 7 8	NUMBER TYPE DESCRIPTION (39)  0 0 0 37 Z 38 N/A  9 REPRONNEL INJURIES 13
1 3	NUMBER DESCRIPTION (41) N/A
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
7 8	9 10 9 PUBLICITY NRC USE ONLY
7 8	9 10 63 69 80
	NAME OF PREPARER A. W. Kapple PHONE: (609) 365-7000 Salem Ext. 628