£09_935_0000

LICENSEE EVENT REPORT

	. LICENSEE EVENT REFOR!
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 8	N J S G S 1 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 2 7 2 7 0 1 2 8 8 0 8 0 2 1 1 8 0 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 A design deficiency was discovered by the Engineering Department during a review of
013	system diagrams. Demineralized Water Supply check valve to the Auxiliary Feedwater
04	Storage Tank, 1DR7, was determined not to be seismically qualified which could have
0 5	resulted in draining the tank if a seismic occurrence occurred. Action Statement
	3.7.1.3 was entered on January 28, 1980 at 1600 hours. The valve was seismically
0 6	qualified and the Action Statement terminated at 1100 on February 1, 1980.
0 7	qualified and the Action Statement terminated at 1100 on residery 1, 1500.
0 8 7 8	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	W F 10 11 A 12 E 3 V A L V E X 14 C 15 A 16
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 32 20 23 20 2 20 2 20 30 36 21 37 40 41 23 42 43 43 45 44 44 47 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	A piping specification break was made in error, not including 1DR7, when it should have
111	been included. The valve was seismically qualified by an independent laboratory in
1 2	accordance with IEEE Standard 344-1975.
1 3	L
1 4	9
1 5	FACILITY STATUS
	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) N/A PERSONNEL EXPOSURES AMOUNT OF ACTIVITY (35) N/A 44 45 BO BO
1 7 7 8	NUMBER TYPE DESCRIPTION (39) O O O O O O O O O O O O O O O O O O O
1 8	0 0 0 0 DESCRIPTION 41 N/A
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A N/A
2 0	PUBLICITY ISSUED DESCRIPTION 45 N/A 8002140 NRC USE ONLY 868 69 NRC USE ONLY 8002140

NAME OF BERNARER M. J. Murphy