

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | J | S | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 14 15 25 26 30 57 58

CON'T  
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 2 | 7 | 0 | 6 | 2 | 6 | 8 | 0 | 8 | 0 | 7 | 2 | 3 | 8 | 0 | 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0100 hours, during routine operation, it was discovered that service water was  
0 3 | in #12 Charging Pump lube oil reservoir. The pump was declared inoperable and Action  
0 4 | Statement 3.5.2a was entered (76-23, 77-34, 77-72, 79-68).

0 5 | \_\_\_\_\_  
0 6 | \_\_\_\_\_  
0 7 | \_\_\_\_\_  
0 8 | \_\_\_\_\_

0 9 | S | F | 11 | E | 12 | B | 13 | H | T | E | X | C | H | 14 | X | 15 | Z | 16  
7 8 9 10 11 12 13 18 19 20

17 | LER/RO REPORT NUMBER | 8 0 | 21 22 | \_\_\_\_\_ | 23 | 0 3 8 | 24 26 | / | 27 | 0 3 | 28 29 | L | 30 | \_\_\_\_\_ | 31 | 0 | 32  
ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER  
A 18 Z 19 | Z 20 | Z 21 | 0 0 0 0 | Y 23 | Y 24 | X 25 | R 3 7 5 | 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A leak developed in the lube oil cooler due to tube failure. The cooler was  
1 1 | replaced and tested satisfactorily. The Action Statement was terminated at 1445  
1 2 | hours on June 27, 1980.

1 3 | \_\_\_\_\_  
1 4 | \_\_\_\_\_

1 5 | E | 28 | 1 0 0 | 29 | N/A | 30 | B | 31 | Operator Observation | 32  
7 8 9 10 12 13 44 45 46 80

1 6 | Z | 33 | Z | 34 | N/A | 35 | LOCATION OF RELEASE | 36 | N/A  
7 8 9 10 11 44 45 80

1 7 | 0 0 0 | 37 | Z | 38 | N/A | 39  
7 8 9 11 12 13 80

1 8 | 0 0 0 | 40 | N/A | 41  
7 8 9 11 12 80

1 9 | Z | 42 | N/A | 43  
7 8 9 11 12 80

2 0 | N | 44 | N/A | 45  
7 8 9 10 80

8007290 844

GPO 917-926