

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N J S G S 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 0 5 0 0 0 3 1 1 7 0 7 3 1 8 0 8 0 8 2 8 8 0 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 Upon receipt of a diesel trouble alarm, it was found that the jacket water
0 3 heater breaker had tripped and would not reset. Further investigation revealed
0 4 that the heater was leaking. Action Statement 3.8.1.lb was entered at 1400 hours.
0 5 (Docket 50-272, 76-12, 77-59, 77-77, 77-80; Docket 50-311, 80-02)

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
E E 11 E 12 D 13 ENGINE 14 Z 15 Z 16
7 8 9 10 11 12 13 18 19 20

17 LER RO REPORT NUMBER 8 0 2 2 0 3 L 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN: A 18 A 19 Z 20 Z 21 0 0 0 0 22 Y 23 Y 24 L 25 C 3 2 2 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The defective heater was replaced, tested satisfactorily and the Action Statement
1 1 was terminated at 1335 hours on August 1, 1980. A Design Change has been
1 2 issued to install a different type heater and the parts have been ordered.

1 5 FACILITY STATUS B 28 0 0 0 29 OTHER STATUS 30 NA METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION 32 Operator Observation
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT Z 33 Z 34 NA AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41 0 0 0 40 NA
7 8 9 10 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43 Z 42 NA
7 8 9 10 11 12 80

2 0 PUBLICITY ISSUED DESCRIPTION 45 N 44 NA
7 8 9 10 80

NAME OF PREPARER R. J. Newman

PHONE: 609-935-0998

5009090 558

GPO 917-926