## AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 50-272

UNIT Salem #1

DATE October 10, 1980

COMPLETED BY L. K. Miller

TELEPHONE 609-365-7000 X507

MONTH	September 1980		
DAY AVE	RAGE DAILY POWER LEVEL	DAY AVER	AGE DAILY POWER LEVEL
	(MWe-NET)		(MWE-NET)
1	618	17	563
2	679	18	585
3	632	19	488
4	594		0
5	610	21	0
6	604	22	0
7	607	23	0
8	·- 605	24	0
9	583	25	0
10	297	26	0
11	242	27	0
12	18	28	0
13	13		. 0
14	366		0
15	444	31	_
16	527		

Pg. 2 of 20 8.1-7.Rl

#### OPERATING DATA REPORT

50-272

DOCKET NO.:\_

DATE: October 10, 1980
COMPLETED BY: L. K. Miller

TELEPHONE: 609-365-7000 X507

### OPERATING STATUS

	0.1. #1			
1.	Unit Name: Salem #1	Notes:		
2.	Reporting Period: September 1980			
3.	Licensed Thermal Power (MWt): 3338			
4.	Nameplate Rating (Gross MWe): 1135			
5.	Design Electrical Rating (Net MWe): 1090			
6.	Maximum Dependable Capacity (Gross MWe): 1124			
7.	Maximum Dependable Capacity (Net MWe): 1079			
8.	If Changes Occur in Capacity Ratings (Items Number NONE	er 3 Through 7) Since	: Last Report, Give R	eason:
_				
9.	Power Level To Which Restricted, If Any (Net MWe)	): NONE		
10.	Reasons For Restrictions, If Any: NONE	<del></del>		
		<del></del>	<del></del>	· · · · · · · · · · · · · · · · · · ·
		<del></del>		· · · · · · · · · · · · · · · · · · ·
		This Month	Year to Date	Cumulative
				28,536
11.	Hours In Reporting Period —	720	6,575	·
12.	Number Of Hours Reactor Was Critical	431.9	6,097.9	16,185.9
13.	Reactor Reserve Shutdown Hours	0	0	22.7
14.	Hours Generator On-Line	400.3	5,946.3	15,477.4
15.	Unit Reserve Shutdown Hours	0	Ó	Ö
16.	Gross Thermal Energy Generated (MWH)	790,673	18,205,037.8	45,741,334.8
17.	Gross Electrical Energy Generated (MWH)	236,380	5,935,090	15,102,590
18.	Net Electrical Energy Generated (MWH)	213,388	5,664,024	14,293,614
19.	Unit Service Factor	55.6	90.4	54.2
20.	Unit Availability Factor	55.6	90.4	54.2
21.	Unit Capacity Factor (Using MDC Net)	27.5	79.8	46.4
22.	Unit Capacity Factor (Using DER Net)	27.2	79.0	46.0
23.	Unit Forced Outage Rate	12.1	5.8	35.2
24.	Shutdowns Scheduled Over Next 6 Months (Type, Date			
	Refueling - Septemb	er 20, 1980-Dece	ember 7, 1980	<del></del>
25.	If Shut Down At End of Report Period, Estimated I	Date of Startup:	12/7/80	
26.	Units In Test Status (Prior to Commercial Operation	on):	Former	Natha are a
	TAITING AN ANTONE TORE		Forecast 9/30/76	Achieved
	INITIAL CRITICALITY		11/01/76	1 <u>2/11/7</u> 6
8-1-	-7.R2 INITIAL ELECTRICITY		12/20/76	1 <u>2/25/7</u> 6
Pg.	3 of 20 COMMERCIAL OPERATION		77/70/10	<u>6/30/7</u> 7

#### UNIT SHUIDOWNS AND POWER REDUCTIONS

September 1980 REPORT MONTH

50-272 DOCKET NO .:

Salem #1 UNIT NAME:

October 10, 1980

DATE: L. K. Miller COMPLETED BY:

TELEPHONE: 609-365-7000 X507

NO.	DATE	TYPE <sup>l</sup>	DURATION (HOURS)	REASON <sup>2</sup>	MEITIOD OF SHUITIING DOWN REACTOR	LICENSE EVENT REPORT #	SYSTEM CODE <sup>4</sup>	COMPONENT CODE <sup>5</sup>	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
80–187	9/2/80	S	0.0	н	5		RC	ZZZZZZ	Fuel Depletion
80-189	9/5/80	S	0.0	Н	5		RC	ZZZZZZ	Fuel Depletion
80–191	9/6/80	S	0.0	H	5		RC	ZZZZZZ	Fuel Depletion
80–193	9/10/80	S	0.0	H	5		RC	ZZZZZZ	Fuel Depletion
80–195	9/10/80	F	18.05	A	3		нн	VALVOP	Low Level #12 Steam Generator Due to Loss of Control Air to Valve 12BF19
80-197	9/11/80	S	0.0	Н	5		RC	ZZZZZZ	Fuel Depletion
80-199	9/12/80	F	36.81	Н	2		PA	TURBIN	Water in Turbine Lube Oil
80-201	9/14/80	S	0.0	H	5		RC	ZZZZZZ	Fuel Depletion
80-203	9/16/80	S	0.0	H	5 .		RC	ZZZZZZ	Fuel Depletion
80-205	9/17/80	S	0.0	H	5		RC	ZZZZZZ	Fuel Depletion
80-207	9/18/80	S	0.0	H	5	<del>-</del>	RC	ZZZZZZ	Fuel Depletion
80-209	9/19/80	S	0.0	, H	5		RC	ZZZZZZ	Fuel Depletion
80-210	9/19/80	S	264.86	C	1	<b></b> -	RC	FUELXX	Annual Refueling Outage

1

F: Forced S: Scheduled

A-Equipment Failure (Explain)

B-Maintenance or Test

C-Refueling

D-Regulatory Restriction

E-Operator Training & License Examination

F-Administrative

G-Operational Error (Explain)

H-Other (Explain)

3 Method:

1-Manual

2-Manual Scram.

3-Automatic Scram.

4-Continuation of Previous Outage

5-Load Reduction

9-Other

Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

5 Exhibit 1-Same Source MAJOR PLANT MODIFICATIONS
REPORT MONTH
September 1980

DOCKET NO .: \_

UNITIAME:

50-272 Salem #1

DATE:

October 10, 1980

COMPLETED BY:

L. K. Miller

TELEPHONE:

609-365-7000 X507

*DCR NO.	PRINCIPLE SYSTEM	SUBJECT
1EC-0478	Diesel Generator Area Vent	"ODC" Limit Switches
1ET-0629	Leak Detection	Data Requested for NRC
1EC-0766	Auxiliary Feedwater	Cancelled
1EC-0919	Gland Sealing Steam	Install Pressure Traps (Cancelled)
1SC-0161	Waste Disposal Liquid	Resin Decant Filter
	·	
	·	
1		Dec 5 - 5 - 6 00
		Page 5 of 20

<sup>\*</sup> DESIGN CHANGE REQUEST 8-1-7.R1

MAJOR PLANT MODIFICATIONS REPORT MONTH September 1980 DOCKET NO.: 50-272

UN NAME:

Salem #1

DATE:

October 10, 1980

COMPLETED BY: L. K. Miller

TELEPHONE: 609-365-7000 X507

*DCR NO.	10CFR50.59 SAFETY EVALUATION
1EC-0478	This is not a safety related change and does not affect safety related equipment.
1ET-0629	The purpose of this DCR is the accumulation of data for theorefinement of the Salem Leak Detection curves. No change to any system or operating procedure is required. This DCR does not impact any safety related system. Data will be acquired from equipment already installed at Salem.
1EC-0766	The change enhances the Aux. Feedwater system reliability by totally precluding closure of this common suction valve. The change was discussed and approved by the NRC.
1EC-0919	The addition of pressure taps to the turbine gland sealing steam and leakoff lines does not alter the original design concept of the systems in any way. This addition does not change the Technical Specification or the SAR, present an unreviewed environmental question or change the Environmental Technical Specifications.
1SC-0161	This DCR does not present an unreviewed safety question and is in no way related to any safety related system. Its operability is not essential for the operation or shutdown of the plant.
	•
	Page 6 of 20

SORTED BY SALEM GENERATING STATION DEPARTMENT, WORK ORDER NO. SAFETY RELATED EQUIPMENT WORK ORDER LOG	3
DEPARTMENT, WORK ORDER NO. SAFETY RELATED EQUIPMENT WORK ORDER LOG	0001
WORK	6   0
ORDER NUMBER DEPT EQUIPMENT IDENTIFICATION EXPLANATION OF WORK PERFORMED	10   11   12
900610 M 14 FAN COIL UNIT	13 14 15 15
DESCRIPTION OF PROBLEM, DRAIN LINE LEAKS AT SEAL UNDERNO CORRECTIVE ACTION, RESEALED LEAKAGE	18
909008 M 11 FCU AIR COOLING COIL	21
DESCRIPTION OF PROBLEM, SEVERE LEAK  CORRECTIVE ACTION. BLANKED OFF	25 26 27 28
909078 M 13 FCU FLOWMETER ON CONSOLE	30 31 31 32
DESCRIPTION OF PROBLEM, SHOWS ZERO FLOW WITH FAN COIL RI CORRECTIVE ACTION, FA3541-Z1 TRANSMITTER REMOVED FI	30 10 10 10 10 10 10 10 10 10 10 10 10 10
FOR REPAIR ON ZERO ADJUST AND RE	
909094 M 11 CHARGING PUMP	(a) (a) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c
DESCRIPTION OF PROBLEM, SUPPLY TO OIL COOLER HAS A HOUSE Line Between 198917-918	IN SUPPLY
CORRECTIVE ACTION, REPLACED REDUCER BUSHING	45 46 47 48 48
909139 M 15 FAN COIL UNIT  DESCRIPTION OF PROBLEM, PLEASE REPAIR LEAK IN COOLER	
CORRECTIVE ACTION, INSTALLED BLANKS IN INLET AND OUT THIRD COOLER DOWN FROM TOP MOTOR	R SIDE 56
909201 M VALVE, 12 COMPONENT COOLING 199	57 58 59 60
DESCRIPTION OF PROBLEM, REPAIR LEAK ON VENT VALVE CONNE PUMP	CTION OFF 65
	65 66 88
Page 7 of 20	59 70 71

>

The state of the s

3.0

		SALEM GENERATING S	TATION	
ORTED BY EPARTMENT, WORK	ORDER NO. SAF	ETY RELATED EQUIPMENT	WORK ORDER LOG	2000
ORK			•	
RDER UMBER DEPT	EQUIPMENT IDENTIFICA	TION	EXPLANATION OF WORK PERFORMED	
		CORRECTIVE ACTION,	REMOVED VENT VALVE CONNECTION CU THREADS-RETHREADED PIPE AND INST	· -· · - <del>-</del> -
09205 M	12 CHILLEDWATER PUMP	article of the Control of the Contro	LINE BACK IN SERVICE	
,		ESCRIPTION OF PROBLEM,		
09214 M	VALVE. ilsw122	CORRECTIVE ACTION,	ADJUSTED OILER, CLEANED OIL BREA	THER CAP
		ESCRIPTION OF PROBLEM,	STEADY STREAM OF SALTWATER FROM	INSUBATION
	CHARLES PARTE PARTY	CORRECTIVE ACTION,	REWELDED EXISTING PATCH ON 122	TRE CHEN LANGE COME COME COME
0207 M *	"想"的特别是许多特别和自然包含	Bratis Art French Commencer		
0207 M	13 STM GENERATOR FEE	Bratis Art French Commencer		
	13 STM GENERATOR FEE	DWTR NOZZLE THREMO WEL ESCRIPTION OF PROBLEM, CORRECTIVE ACTION,	FURMANITE CLAMP LEAKS	
	13 STM GENERATOR FEE D 11 NUCLEAR SERVICE W	DWTR NOZZLE THREMO WEL ESCRIPTION OF PROBLEM, CORRECTIVE ACTION,	FURMANITE CLAMP LEAKS FURMANITED LEAKS	
	13 STM GENERATOR FEE  0  11 NUCLEAR SERVICE W	DWTR NOZZLE THREMO WEL ESCRIPTION OF PROBLEM, CORRECTIVE ACTION, TR HEADER ESCRIPTION OF PROBLEM,	FURMANITE CLAMP LEAKS  FURMANITED LEAKS  PIN HOLE LEAK LOCATED BETWEEN 11	SW22
2242 M	13 STM GENERATOR FEE  0  11 NUCLEAR SERVICE W	DWTR NOZZLE THREMO WEL ESCRIPTION OF PROBLEM, CORRECTIVE ACTION, TR HEADER ESCRIPTION OF PROBLEM,	FURMANITE CLAMP LEAKS  FURMANITED LEAKS  PIN HOLE LEAK LOCATED BETWEEN 11 119W23  WELD COUPLING AND INSTALLED VALV	SW22
2242 M	13 STM GENERATOR FEE  D  11 NUCLEAR SERVICE W  D  14 FAN COIL UNIT	DWTR NOZZLE THREMO WEL ESCRIPTION OF PROBLEM, CORRECTIVE ACTION, TR HEADER ESCRIPTION OF PROBLEM,	FURMANITE CLAMP LEAKS  FURMANITED LEAKS  PIN HOLE LEAK LOCATED BETWEEN 11 119W23  WELD COUPLING AND INSTALLED VALV HOLE IN 24> PIPE	SW22
8242 M	13 STM GENERATOR FEE  D  11 NUCLEAR SERVICE W  D  14 FAN COIL UNIT	DWTR NOZZLE THREMO WELL ESCRIPTION OF PROBLEM, CORRECTIVE ACTION, TR HEADER ESCRIPTION OF PROBLEM, CORRECTIVE ACTION, ESCRIPTION OF PROBLEM,	FURMANITE CLAMP LEAKS  FURMANITED LEAKS  PIN HOLE LEAK LOCATED BETWEEN 11 119W23  WELD COUPLING AND INSTALLED VALVE HOLE IN 24> PIPE  MTOR COOLER LEAK LEAK IN COOLER COIL INSTALLED NEW COOLER	SW22
12242 M	13 STM GENERATOR FEE  O  11 NUCLEAR SERVICE W  D  14 FAN COIL UNIT	DWTR NOZZLE THREMO WELL ESCRIPTION OF PROBLEM, CORRECTIVE ACTION, TR HEADER ESCRIPTION OF PROBLEM, CORRECTIVE ACTION, ESCRIPTION OF PROBLEM, CAUSE,	FURMANITE CLAMP LEAKS  FURMANITED LEAKS  PIN HOLE LEAK LOCATED BETWEEN 11 119W23  WELD COUPLING AND INSTALLED VALVI HOLE IN 24> PIPE  MTOR COOLER LEAK LEAK IN COOLER COIL	SW22

MORK ORDER NUMBER DEPT EQUIPMENT IDENTIFICATION  DESCRIPTION OF PROBLEM,  CORRECTIVE ACTION,  DESCRIPTION OF PROBLEM,  CORRECTIVE ACTION,  PACKING LEAK  VALVE, 13M3168  DESCRIPTION OF PROBLEM,  CORRECTIVE ACTION,  REMOVE LIFTSET  CORRECTIVE ACTION,  REMOVE LIFTSET  AND REINSTALLED  P14262  M  SPARE FCU MOTOR COOLER  CORRECTIVE ACTION,  DESCRIPTION OF PROBLEM,  CORRECTIVE ACTION,  WELD CEMENT LINED COUPLING ON TO SPARE  FCU MOTOR COOLER 5.  CORRECTIVE ACTION,  WELDED TWO COUPLINGS ON  914350  M  PIPE LEAK BETWEEN 14M8200-199  DESCRIPTION OF PROBLEM,  CORRECTIVE ACTION,  P16822  M  RAD WASTE STORAGE TANK HEAT EXCHANGER  DESCRIPTION OF PROBLEM,  LEAKING WATER	
DESCRIPTION OF PROBLEM, PACKING LEAK  CORRECTIVE ACTION, VALVE HAS BEEN REPACKED  913054 M VALVE, 1C326  DESCRIPTION OF PROBLEM, REMOVE LIFTSET  CORRECTIVE ACTION, REMOVED VALVE, CHECKED FOR 10 PSIG LIFT AND REINSTALLED  914262 M SPARE FCU MOTOR COOLER  DESCRIPTION OF PROBLEM, WELD CEMENT LINED COUPLING ON TO SPARE FCU MOTOR COOLER 5  CORRECTIVE ACTION, WELDED TWO COUPLINGS ON  914350 M PIPE LEAK BETWEEN 14M3200-199  DESCRIPTION OF PROBLEM, STEAM LEAK ON ELBOW BETWEEN 14M3200 14M3199  CORRECTIVE ACTION, REPAIRED HOLE	
CORRECTIVE ACTION, VALVE HAS BEEN REPACKED  913054 M VALVE, 1C926  DESCRIPTION OF PROBLEM, REMOVE LIFTSET  CORRECTIVE ACTION, REMOVED VALVE, CHECKED FOR 10 PSIG LIFT AND REINSTALLED  914262 M SPARE FCU MOTOR COOLER  DESCRIPTION OF PROBLEM, WELD CEMENT LINED COUPLING ON TO SPARE FCU MOTOR COOLER 5  CORRECTIVE ACTION, WELDED TWO COUPLINGS ON  914350 M PIPE LEAK BETWEEN 14M8200-199  DESCRIPTION OF PROBLEM, STEAM LEAK ON FLBOW BETWEEN 14M8200 14M8199  CORRECTIVE ACTION, REPAIRED HOLE  916822 M RAD WASTE STORAGE TANK HEAT EXCHANGER	
913054 M VALVE, 1C326  DESCRIPTION OF PROBLEM, REMOVE LIFTSET  CORRECTIVE ACTION, REMOVED VALVE, CHECKED FOR 10 PSIG LIFT AND REINSTALLED  914262 M SPARE FCU MOTOR COOLER  DESCRIPTION OF PROBLEM, WELD CEMENT LINED COUPLING ON TO SPARE FCU MOTOR COOLER 5  CORRECTIVE ACTION, WELDED TWO COUPLINGS ON  914350 M PIPE LEAK BETWEEN 14M8200-199  DESCRIPTION OF PROBLEM, STEAM LEAK ON ELBOW BETWEEN 14M8200 14M8199  CORRECTIVE ACTION, REPAIRED HOLE  916822 M RAD WASTE STORAGE TANK HEAT EXCHANGER	
CORRECTIVE ACTION, REMOVED VALVE, CHECKED FOR 10 PSIG LIFT AND REINSTALLED  914262 M SPARE FCU MOTOR COOLER  DESCRIPTION OF PROBLEM, WELD CEMENT LINED COUPLING ON TO SPARE FCU MOTOR COOLER 5  CORRECTIVE ACTION, WELDED TWO COUPLINGS ON  914350 M PIPE LEAK BETWEEN 14M8200-199  DESCRIPTION OF PROBLEM, SIEAM LEAK ON ELBOW BETWEEN 14M8200 14M8199  CORRECTIVE ACTION, REPAIRED HOLE  916822 M RAD WASTE STORAGE TANK HEAT EXCHANGER	
DESCRIPTION OF PROBLEM, WELD CEMENT LINED COUPLING ON TO SPARE FOU MOTOR COOLER 5  CORRECTIVE ACTION, WELDED TWO COUPLINGS ON  914350 M PIPE LEAK BETWEEN 14MS200-199  DESCRIPTION OF PROBLEM, STEAM LEAK ON ELBOW BETWEEN 14MS200 14MS199  CORRECTIVE ACTION, REPAIRED HOLE  916822 M RAD WASTE STORAGE TANK HEAT EXCHANGER	
914350 M PIPE LEAK BETWEEN 14MS200-199  DESCRIPTION OF PROBLEM, STEAM LEAK ON ELBOW BETWEEN 14MS200 14MS199  CORRECTIVE ACTION, REPAIRED HOLE  916822 M RAD WASTE STORAGE TANK HEAT EXCHANGER	
DESCRIPTION OF PROBLEM, STEAM LEAK ON ELBOW BETWEEN 14MS200 14MS199  CORRECTIVE ACTION, REPAIRED HOLE  916822 M RAD WASTE STORAGE TANK HEAT EXCHANGER	,
916822 M RAD WASTE STORAGE TANK HEAT EXCHANGER	
DESCRIPTION OF PROBLEM LEAVING WATER	
DESCRIFTION OF PROBLEM, CLARING WATER	
CORRECTIVE ACTION. REPLACED GASKET ON BACK SIDE OF TUBE SHEET	
918522 M 12 FAN COIL UNIT  DESCRIPTION OF PROBLEM, MOTOR COOLER LEAKING	
CORRECTIVE ACTION, INSTALLED NEW COOLER	

. . .

SABEM GENERATING. SAFETY RELATED EQUIPMENT WORK OBDER LOG 0004  DEPARAMENT, HORK OBDER ND. SAFETY RELATED EQUIPMENT WORK OBDER LOG 0004  HORK ONDER DEPT COUTPMENT TOENTIFICATION EXPLANATION OF WORK PERFORMED  918577 M 12 CHARGING PUMP  DESCRIPTION OF PROBLEM, SERVICEMATER LINE TO 12 CHARGING PUMP LUBE COOLER IS LEAKING  CORRECTIVE ACTION, REPLACED 7' SECTION OF JOSS SEN AS PIPE  DESCRIPTION OF PROBLEM, OIL LEAK  CORRECTIVE ACTION, REPLACED OILER AND FILLED PUMP WITH OIL  927700 M CHILLED WITE RH-SERVICEMATER PIPE  DESCRIPTION OF PROBLEM, SERVICEMATER LEAK ABOVE 115W91  CORRECTIVE ACTION, PATCHED LEAK WITH BELZONA SUPER RUBBER SO  929486 M TARK FEED PUMP ROOM COOLER  CORRECTIVE ACTION, NEW SEALS INSTALLED  929490 M TARK FEED PUMP ROOM COOLER  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW OFAIN  929533 M VALUE, L38M65  DESCRIPTION OF PROBLEM, VALUE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLAMBE AREA  PAGE 10 Of 20			2
ORDER NUMBER DEPT COUIPMENT IDENTIFICATION EXPLANATION OF WORK PERFORMED  918577 M 12 CHARGING PUMP  DESCRIPTION OF PROBLEM, SERVICENATER LINE TO 12 CHARGING PUMP LUBE COOLER IS LEAKING:  CORRECTIVE ACTION, REPLACED 7' SECTION OF 1588 SER 88 PIPE  DESCRIPTION OF PROBLEM, OIL LEAK CORRECTIVE ACTION, REPLACED 0' SECTION OF FILED PUMP WITH OIL  P27100 M CHILLED WTR RM-SERVICEMATER PIPE  DESCRIPTION OF PROBLEM, SERVICEMATER LEAK ABOVE 118W91  CORRECTIVE ACTION, PATCHED LEAK WITH RELZONA SUPER RUBBER 80  P22886 M 11 BORIC ACID TRANSFER PUMP CORRECTIVE ACTION, NEW SEALS INSTALLED  CORRECTIVE ACTION, NEW SEALS INSTALLED  DESCRIPTION OF PROBLEM, COOLER LEAKING BADLY  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  O22830 M 7 AUX FEED PUMP ROOM COOLER  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  P22550 M 13 SERVICEMATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  PAGE 10 of 20		BIAUN	5 6
Page 10 of 20	WORK		7 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9
DESCRIPTION OF PROBLEM, SERVICEMATER LINE TO 12 CHARGING PUMP LUBE COOLER IS LEAKING  CORRECTIVE ACTION, REPLACED 7' SECTION OF 1>8S SEN A9 PIPE  18 CHILLED HTR PUMP  DESCRIPTION OF PROBLEM, OIL LEAK  CORPECTIVE ACTION, REPLACED OILER AND FILLED PUMP WITH OIL  DESCRIPTION OF PROBLEM, SERVICEMATER LEAK ABOVE 118W91  DESCRIPTION OF PROBLEM, PATCHED LEAK HOVE 118W91  DESCRIPTION OF PROBLEM, LEAKING SEALS  CORRECTIVE ACTION, NEW SEALS INSTALLED  DESCRIPTION OF PROBLEM, COOLER LEAKING BADLY  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  DESCRIPTION OF PROBLEM, COOLER LEAKING BADLY  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  PAGE 10 of 20  Page 10 of 20	NUMBER DEPT EQUIPMENT IDENTIFICATION	EXPLANATION OF WORK PERFORMED	10 11 12
COOLER IS LEAKING  CORRECTIVE ACTION, REPLACED 7' SECTION OF 138S SEN 80 PIPE  918580 N 12 CHILLED MTR PUMP  DESCRIPTION OF PROBLEM, OIL LEAK  CORRECTIVE ACTION, REPLACED DILER AND FILLED PUMP WITH DIL  927700 N CHILLED MTR RM-SERVICEMATER PIPE  DESCRIPTION OF PROBLEM, SERVICEMATER LEAK ABOVE 118N91  CORRECTIVE ACTION, PATCHED LEAK WITH BELZONA SUPER RUBBER 80  DESCRIPTION OF PROBLEM, LEAKING-SEALS  CORRECTIVE ACTION, NEW SEALS INSTALLED  929490 M 7 AUX FEED PUMP ROOM COOLER  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 138M65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLAME AREA  DESCRIPTION OF PROBLEM, HAS BLONN ITS PACKING  Page 10 of 20	918577 M 12 CHARGING PUMP		14 15 16
918580 M 12 CHILLED HTR PUMP  DESCRIPTION OF PROBLEM, OIL LEAK  CORRECTIVE ACTION, REPLACED DIER AND FILLED PUMP WITH OIL  927700 M CHILLED HTR RM-SERVICEMATER PIPE  DESCRIPTION OF PROBLEM, SERVICEWATER LEAK ABOVE 119W91  CORRECTIVE ACTION, PATCHED LEAK WITH BELZONA SUPER RUBBER 80  92986 M 11 BORIC ACID TRANSFER PUMP  DESCRIPTION OF PROBLEM, LEAKING SEALS  CORRECTIVE ACTION, NEW SEALS INSTALLED  929490 M 7 AUX FEED PUMP ROOM COOLER  DESCRIPTION OF PROBLEM, COOLER LEAKING BADLY  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 139M65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEMATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING		SERVICEWATER LINE TO 12 CHARGING PUMP LUBE COOLER IS LEAKING	17 18 19 20
DESCRIPTION OF PROBLEM, OTL LEAK  CORRECTIVE ACTION, REPLACED OTLER AND FILLED PUMP WITH OIL  927700 M CHILLED WTR RM-SERVICEMATER PIPE  DESCRIPTION OF PROBLEM, SERVICEWATER LEAK ABOVE IISW91  CORRECTIVE ACTION, PATCHED LEAK WITH BELZONA SUPER RUBBER 80  929986 M 11 BORIC ACID TRANSFER PUMP  DESCRIPTION OF PROBLEM, LEAKING-SEALS  CORRECTIVE ACTION, NEW SEALS INSTALLED  DESCRIPTION OF PROBLEM, COOLER LEAKING BADLY  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 138M65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEWATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  Page 10 of 20	CORRECTIVE ACTION,	REPLACED 7' SECTION OF 1>SS SEH 80 PIPE	21 22 22 24
CORRECTIVE ACTION, REPLACED DILER AND FILLED PUMP WITH OIL  927700 M CHILLED WTR RM-SERVICEMATER PIPE  DESCRIPTION OF PROBLEM, SERVICEMATER LEAK ABOVE 118W91  CORRECTIVE ACTION, PATCHED LEAK WITH BELZONA SUPER RUBBER 80  929486 M 11 BORIC ACID TRANSFER PUMP  DESCRIPTION OF PROBLEM, LEAKING-SEALS  CORRECTIVE ACTION, NEW SEALS INSTALLED  929490 M 7 AUX FEED PUMP ROOM COOLER  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 139W65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEMATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  Page 10 of 20	DESCRIPTION OF PROBLEM,	OIL LEAK	25 26 27 21
DESCRIPTION OF PROBLEM, SERVICEWATER LEAK ABOVE 118W91  CORRECTIVE ACTION, PATCHED LEAK WITH BELZONA SUPER RUBBER 80  929486 M 11 BORIC ACID TRANSFER PUMP  DESCRIPTION OF PROBLEM, LEAKING-SEALS  CORRECTIVE ACTION, NEW SEALS INSTALLED  929490 M 7 AUX FEED PUMP ROOM COOLER  DESCRIPTION OF PROBLEM, COOLER LEAKING BADLY  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 138W65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEWATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  Page 10 of 20	CORRECTIVE ACTION,		29 30 - 31
CORRECTIVE ACTION, PATCHED LEAK WITH BELZONA SUPER RUBBER 80  929486 M 11 BORIC ACID TRANSFER PUMP  DESCRIPTION OF PROBLEM, LEAKING SEALS  CORRECTIVE ACTION, NEW SEALS INSTALLED  929490 M 7 AUX FEED PUMP ROOM COOLER  DESCRIPTION OF PROBLEM, COOLER LEAKING BADLY  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 139W65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEWATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING	DESCRIPTION OF PROBLEM,	SERVICEWATER LEAK ABOVE 118W91	33 34 31 31
DESCRIPTION OF PROBLEM, LEAKING SEALS  CORRECTIVE ACTION, NEW SEALS INSTALLED  929490 M 7 AUX FEED PUMP ROOM COOLER  DESCRIPTION OF PROBLEM, COOLER LEAKING BADLY  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 138W65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEWATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  Page 10 of 20	CORRECTIVE ACTION,		37 38 31
CORRECTIVE ACTION, NEW SEALS INSTALLED  929490 M 7 AUX FEED PUMP ROOM COOLER  DESCRIPTION OF PROBLEM, COOLER LEAKING BADLY  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 138W65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEWATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING	DESCRIPTION OF PROBLEM,	LEAKING SEALS	41 44 44 44
DESCRIPTION OF PROBLEM, COOLER LEAKING BADLY  CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 139W65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEWATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  Page 10 of 20	CORRECTIVE ACTION,	والمراق والمرا	45
CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 138W65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEWATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  Page 10 of 20			4
CORRECTIVE ACTION, REPAIRED LEAK ON 7 TUBE ELBOW DRAIN  929533 M VALVE, 139W65  DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEWATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  Page 10 of 20	DESCRIPTION OF PROBLEM,	COOLER LEAKING BADLY	5 5
DESCRIPTION OF PROBLEM, VALVE LEAKING IN CONTAINMENT  CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEWATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  Page 10 of 20	CORRECTIVE ACTION,	REPAIRED LEAK ON 7 TUBE ELBOW DRAIN	5: 5 5
CORRECTIVE ACTION, APPLIED BELZONA TO FLANGE AREA  929560 M 13 SERVICEWATER PUMP STRAINER  DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  Page 10 of 20	DESCRIPTION OF PROBLEM		51 51 5
DESCRIPTION OF PROBLEM, HAS BLOWN ITS PACKING  Page 10 of 20	CORRECTIVE ACTION,	APPLIED BELZONA TO FLANGE AREA	6:
Page 10 of 20	929560 M 13 SERVICEWATER PUMP STRAINER		6·
	DESCRIPTION OF PROBLEM,	HAS BLOWN ITS PACKING	6 6 6
			70
			7 7 7

	rate:			* * * * * * * * * * * * * * * * * * *
SDRTED BY	LEM GENERATING STATION	,		
	LATED EQUIPMENT WORK O		THE RELIEF PROPERTY OF THE PRO	0005
WORK				
ORDER DEPT EQUIPMENT IDENTIFICATION		EXPLANATION OF WORK PERFOR	RMED	
· cc	DRRECTIVE ACTION,	REPACKED PUMP STRAINER		
929612 M 12 SERVICEWATER PUMP STRAI	NER			
DESCRIP	TION OF PROBLEM.	STRAINER RUNS WHEN PUMP I	S OUT OF SERVICE	and the second s
CC	DRRECTIVE ACTION,	INSTALLED NEW DEVICE 286-0	C	
929632 M VALVE, 119W122				
DESCRIP	TION OF PROBLEM.	LEAK 118W122		
·	DRRECTIVE ACTION,	REPAIRED BY WELDING CRACK	AND HOLE	
929658 M 16 SERVICEWATER PUMP				
	TION OF PROBLEM,	*REPACK*		. A . 1.2 - 1.5- 1/2 (\$7 - 88)
CC	DRRECTIVE ACTION,	REPACKED		
932541 M BDRIC ACID INJECTION TANK DESCRIP	起激激烈 化二氯苯二氯苯基二氯苯二	CIRCUIT 627 HEAT TAPE FAIL	ED	
	DRRECTIVE ACTION,	SPLICED HEAT TAPE BACK TO		
933462 M 10> HEADER BETWEEN 148W76-	78			
DESCRIP	TION OF PROBLEM.	1/25 HOLE IN PIPE		
co	DRRECTIVE ACTION,	TEMPORARY PATCH INSTALLED		
933485 MA VALVE, 158W65	TION OF PROBLEM.	FLANGE LEAK		
· · · · · · · · · · · · · · · · · · ·	PRRECTIVE ACTION,	BELZONA FLANGE	12 12 12 13 14	
933573 M 11 SERVICEWATER PMP STRNER				
	TION OF PROBLEM,	REPAIR PACKING GLAND ON ST	またが教題と TRAINER	
Page 11 of 20		Uit		
			The second secon	
	*	<i>&gt;</i> •		;*

6 p 9

Total Control

SORTED BY SALEM GENERATING STA DEPARTMENT, WORK ORDER NO. SAFETY RELATED EQUIPMENT WO	TIDN 0006
WORK	
ORDER NUMBER DEPT EQUIPMENT IDENTIFICATION	EXPLANATION OF WORK PERFORMED
CORRECTIVE ACTION,	REPACKED GLAND
936077 M 11 FAN COIL UNIT DESCRIPTION OF PROBLEM.	MOTOR COOLER LEAKING
CORRECTIVE ACTION,	WELDED IN NEW COOLER
936420 M 11 SERVICEWATER STRAINER  DESCRIPTION OF PROBLEM.	SHEARED SHEAR PIN
CORRECTIVE ACTION,	REPLACED SHEAR PIN, REMOVED A PIECE OF SHOE MATERIAL FROM BOTTOM OF STRAINER
936429 N 12 SERVICEWATER AUTO STRAINER	
DESCRIPTION OF PROBLEM,	STRAINER LOWER HAND HOLE COVER HAS A LEAK
CORRECTIVE ACTION, 936984 M VALVE, 11CV113	REPAIRED LEAK WITH BELZONA, PUT ON NEW GASKET
DESCRIPTION OF PROBLEM,	TIGHTEN OR REPACK VALVE
CORRECTIVE ACTION, 4936988 M VALVE, 14CV106	TIGHTENED DOWN PACKING
DESCRIPTION OF PROBLEM,	TIGHTEN OR REPACK VALVE
CORRECTIVE ACTION, 909051 P 13 STEAM GENERATOR WIDE RNG LEVEL	TIGHTENED PACKING
DESCRIPTION OF PROBLEM,	WIDE RANGE LEVEL ON 13 STEAM GENERATOR FAILED ON RECORDER
Page 12 of 20	

		1
SORTED BY SALEM GENERATING DEPARTMENT, WORK ORDER NO. SAFETY RELATED EQUIPMENT	STATION	3
·	I WORK UNDER LOG	0007
WORK ORDER NUMBER DEPT EQUIPMENT IDENTIFICATION	EXPLANATION OF WORK PERFORMED	8 9 9 11 11 11 11 11 11 11 11 11 11 11 11
CORRECTIVE ACTION	N, RECONNECTED LOOSE WIRE STRING ON PULLY AND	13 14 15 16
909069 P 11 AUXILIARY FEED SUCTION INDICATION		18
DESCRIPTION OF PROBLEM	M, REPAIR 11 AUXILIARY FEED SUCTIONS ON CONTROL CONSOLE	21 22 23 24
909112 P VALVE, 14AF21		25 26 27 27
DESCRIPTION OF PROBLEM	*	25 33 31 32
CORRECTIVE ACTION	N, ADJUSTED LIMIT SWITCH	33 34 35 36 36
909131 P VALVE, 1R14		37 38
DESCRIPTION OF PROBLEM		40 
CORRECTIVE ACTION	N, REPLACED DETECTOR AND RAN PLATEAU FOR HIGH VOLTAGE	44
909292 P VALVE, 12G84	•	46
DESCRIPTION OF PROBLEM	M, WILE NOT OPEN	45
CORRECTIVE ACTION	N. REPLACED DIAPHRAM	51
909330 P VALVE, 125W122		5-5 55 cc
	ERRATIC FLOW CONTROL	7.4 57 58
CORRECTIVE ACTION		59
	MUD CAME OUT	62 63 64 64
	在1000年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1 1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1900年,1	66 66 67
Page 13 of 20		66 70 71 72
		7. A second seco

1 per 44

DEPARTMENT	, WORK	ORDER NO.		SAFETY RELA	TED EQUIPME	ENT WORK	ORDER LOG						0008	3	
NORK DRDER			graga in juris	*	194.6		15(		. 23.500		15 7 6				
T 1 1 1	DÉPT	EQUIPME	NT IDENTIF	ICÁTION		·	EXPLANA	TION OF	WORK PER	FORMED :				· · · · · ·	
910149	P	VALVE,	158W65								······································		· · · · · · · · · · · · · · · · · · ·	anatrama diraktiranda aurte — distagrid	
	" \$ 7. 	e st. 197		DESCRIPT	ON OF PROB	EM,	DISCONN	ECT OPE	RATOR			agent species and	Ž 4 38		9 A
				CORF	RECTIVE ACT	ON.	REMOVED	AIRLIN	ES					3	_
13845	P	INSTRU,	1PR2	grande) Springer Stripe					*			<i>:</i>			
	13, 194			DESCRIPTI	ON OF PROBL	EM,	VALVE I SHOULD		TING AT 3 T 360 PSI						
	<u> </u>		· · · · · · · · · · · · · · · · · · ·	CORF	RECTIVE ACT	ron;	RESET S	HOULD BE	E AT 340,	BUT IS I	N SPEC	<u></u>	وموسوي والمراجوب أستاب المستحدم	<del> </del>	
15128	P	VALVE	14AF21		Albania de distribuita de la constantina della c			114, 1, 114, 7					Cold to any to		
	. Pala Ma Nasatan			DESCRIPTI	ON OF PROBL	EM,	RESTROK	E VALVE	DUE TO O	UT OF CAL	IBRATION		Sagar Big Sa		
							TEST EQ	UIPMENT	USED ON	W.O. 9152	33				
पुरसास्क्षेकाः	. 3 % <b>10</b> 316 1. 5		STATES	CORF	RECTIVE ACT	ION,	STROKED	VALVE	AND TESTE	D EQUIPME	<u>NT</u>	arvivirus	म्बद्धाः सम्बद्धाः । सम्बद्धाः सम्बद्धाः ।	জনজন্ম প্রথ	4,5,3
18416	Pigit 1	DAMPER,	1CAA3											1	
· · · · · · · · · -	<u> </u>			DESCRIPTI	ON OF PROBI	EM,	NO INDI	CATION (	OF VALVE	POSITION	<u> </u>	<u> </u>			
				CORF	RECTIVE ACT	ION,	FREED S	TUCK DAN	PER AND	ADJUSTED	LIMIT				
27600	P	VALVE,	1CV5				SWITCH								
				DESCRIPTI	ON OF PROBL	EM,	NO INDI CONTROL	CATION (	OF OPEN O	R CLOSE:L	IGHT ON				
				CORF	ECTIVE ACT	CON,	REPLACE	D INDICA	ATOR LIGH MIT SWIT				ि स्वभागमा जिल्ह्यासू १९५४ - १९५४ १९५४ - १९५४		34 <u></u>
										,		,			
	4.			ee						1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		F	***************************************		

i Gi

SORTED B	Y NO DE C		ION	
DEPARTME	NI, WURK U	MUER NO. SAFETY RELATED EQUIPMENT WORK	CORDER LOG 0009	
WORK ORDER				
NUMBER	DEPT	EQUIPMENT IDENTIFICATION	EXPLANATION OF WORK PERFORMED	
929494	Р	11 COMPONENT COOLNG HX SERVICEWTR FLOW IND		
		DESCRIPTION OF PROBLEM,	INDICATOR READS HIGH WITH NO SERVICEWATER FLOW ON HEAT EXCHANGER	
			BLEW DOWN TRANSMITTER	
929540	Р	NUCLEAR INSTRU. POWER RANGE		
		DESCRIPTION OF PROBLEM,	REDUCE POWER RANGE HI TRIPS TO 95%	
		CORRECTIVE ACTION,	RESET TO 95%	
929563	P	VALVE, 129W122		· · · · · · · · · · · · · · · · · · ·
		DESCRIPTION OF PROBLEM,	NO CONTROL AT LOW FLOW SETPOINTS	
		CORRECTIVE ACTION,	ADJUSTED FOR PROPER OPERATION	
929588	Р	INSTRU, 1R14		
		DESCRIPTION OF PROBLEM,	FAILED LOW	
		CORRECTIVE ACTION,	REPAIRED CABLE	
932218	ρ	AUXILIARY FEED		
		DESCRIPTION OF PROBLEM,	FLOW INDICATED ON CONSOLE FLOW INDICATORS WITH PUMPS OUT OF SERVICE	•
		CORRECTIVE ACTION,	CALIBRATED 1FA5754 AND 1FA5753	
932486	P	NUCLEAR INSTRU, CHANNEL 1N42		
		DESCRIPTION OF PROBLEM,	ISOLATION ON AMP NM302 OUT OF SPEC	
		CORRECTIVE ACTION,	ADJUSTED OUTPUT	
932467	Р	NUCLEAR INSTRU		
Page	15 of 20			
<u> </u>	<u> </u>			

WORK ORDER NUMBER DE	ЕРТ		EXPLANATION OF WORK PERFORMED	
NUMBER DE	EPT		EXPLANATION OF WORK PERFORMED	1
032515		000000000000000000000000000000000000000		\ 
932515		DESCRIPTION OF PROBLEM,	1N43 P-10 OUT OF SPEC, POSITIVE RATE TRIP OUT OF SPEC	1
932515		CORRECTIVE ACTION,	ADJUSTED P-10 BISTABLE, ADJUSTED POSITIVE RATE TRIP BISTABLE	
/2015	P	TURBINE AUTO STOP OIL		
		DESCRIPTION OF PROBLEM,	PD455 DUT OF SPEC	7
		CORRECTIVE ACTION,	ADJUSTED PD455 TO BRING WITHIN SPEC	
932520	P	INSTRU, R11A	y	3
	<u> </u>	DESCRIPTION OF PROBLEM,	REPLACE DETECTOR, FAILED LOW	
		CORRECTIVE ACTION,	REPLACED MD5B DETECTOR	
933188	P	NUCLEAR INSTRU, 1N43		
		DESCRIPTION OF PROBLEM,	DETECTOR A METER OUT OF SPEC, FLUX RECORDER OUT OF SPEC	
	<del></del>	CORRECTIVE ACTION,	ADJUSTED MECHANICAL ZERO ON DETECTOR A ADJUSTED FLUX RECORDER	
933454	P	11 EXHAUST DAMPER 1CAV8		
		DESCRIPTION OF PROBLEM,	SOLENDID VALVE SV1038 LEAKING AIR, DAMPER WILL NOT GO TO FULL OPEN POSITION	
		CORRECTIVE ACTION,	REPLACED VALVE	
933509	P	INSTRU, 1R12B		ļ
		DESCRIPTION OF PROBLEM,	IDDINE ERRATIC OPERATION	
	·*···	•		6 6 6
Page 16 o	of 20			

EPARTME	NT. WORK	SALEM GENERATING STATI ORDER NO. SAFETY RELATED EQUIPMENT WORK	K ORDER LOG 0011	
	MIP MONIC	THE NULL HELD EGGS TO HOLD	UNDER EGG	
WORK ORDER	· · · · · · · · · · · · · · · · · · ·			
NUMBER	DEPT	EQUIPMENT IDENTIFICATION	EXPLANATION OF WORK PERFORMED	
		CORRECTIVE ACTION,	REPLACED DETECTOR	
933557	P	13 FCU CONT DEW PT TA-6124	The state of the s	<del></del>
		DESCRIPTION OF PROBLEM,	RECORDER ON 1RP1 PANEL INDICATES 13 DEW POINT INDICATING LOWER THAN OTHERS	
<del>-,, , , , , , , , , , , , , , , , , , ,</del>		CORRECTIVE ACTION,	REPLACED WORN OUT DOTS BELT AND RESET POINT SELECTOR	
933586	P	INSTRU, 1R14		·
		DESCRIPTION OF PROBLEM,	FAILED LOW	
<del></del>			REPLACED CABLE END AND PREAMPS	<del></del>
933622	p	CONRECTIVE ACTION,  12 STEAM GENER BLOWDOWN FLOW INDICATION		
<u>,7220cc.</u>		DESCRIPTION OF PROBLEM,		
	· · · · · · · · · · · · · · · · · · ·		LOSS OF AC POWER SUPPLY	<del>,</del>
933657	Р	REACTOR WATER STORAGE HIGH LEVEL ALARM		
		DESCRIPTION OF PROBLEM,	CONTINOUS ALARM	
		CORRECTIVE ACTION,	CALIBRATED BARTON LD-9634	
933663	P	12 STEAM GENERATOR LEVEL CHANNEL 4		<del></del>
· · · · · · · · · · · · · · · · · · ·			LEVEL CHANNEL 4 IS FLUCIATING 6-8% AT A	
		CORRECTIVE ACTION,	BLEWDOWN TRANSMITTER SENSING LINE	
934234	Р	INSTRU, 1FT-930		
e		DESCRIPTION OF PROBLEM,	SENSOR DUT OF CALIBRATION	-
Page	17 of 20			

DRTED BY EPARTMENT,	WORK C	RDER NO.	SAFETY	SALEM GENERATING RELATED EQUIPMEN	STATION IT WORK (	N	· W MARKAGO				0012	
RDER	EPT	EQUIPMENT IDEN	TIFICATIO	IN		EXPLANATION OF WO	RK PERFOR	MED		-		
				CORRECTIVE ACTIO	DN,	RECALIBRATED						
34250	p	INSTRU, R12B	DESC	RIPTION OF PROBLE		REPLACE CHARCOAL (	CARTRIDGE					
				CORRECTIVE ACTIO	n,	REPLACED CHARCOAL	FILTER	•				
35772	•	INSTRU, 1R43,	PLANT VEN	T HIGH ACTIVITY F	EL					· · · · · · · · · · · · · · · · · · ·		
<u> </u>			DESC	RIPTION OF PROBLE	M,	ALARM LIGHT 1RP1 HIGH RADIATION SIG	DOES NOT	ILLUMINAT	E ON			ulin <del>a araba da kaba da k</del>
			dana distribution di distribut	CORRECTIVE ACTIO	ON,	REPLACED 3300 OHM	RESISTOR			<del>a tajana</del>	<u>चाल्यका संस्थान संस्था</u> ती	
OTAL LINES OTAL A-REC	<b>=</b> 000	239 067		·								
AST UPDATE 01010 42900 NTER COMMA	Test Test .		: ' .						**************************************		The state of the s	<del></del>
ND OF RUN												
BRKPT PRIN	т <b>з</b>											
			-, <del>-</del> , - , - <del> , - , -</del> -									<del></del> ;
			<del>,</del>				<u> </u>					
						-						
	of 20											

,

# SALEM UNIT #1 OPERATING SUMMARY SEPTEMBER 1980

9/1	
thru 9/8	Coastdown continues - 65% RTP to 62% RTP.
9/8	Reactor trip at 1302 - Air line to steam generator feed regulating valve broke, valve closed.
9/11	Reactor critical at 0300 and at .8% power. Increased power to 50% by 1200. Held at 50%.
9/12	At 0100, water was discovered in turbine lube oil system. Commenced reactor power reduction. Off-line by 0500. At 1600, increasing reactor power to synchronize generator. Held at less than 5% reactor power for remainder of the day.
9/13	At 1600, turbine run up and synchronized. Increased power by end of day to 38% RTP.
9/14	Increased reactor power to 46% RTP and held there for the remainder of the day.
9/15	At 1400, commenced reactor power increase. At 2400, reactor was at 54% RTP.
9/16	At 0200, reactor was at 60% RTP. Continued with coastdown.
9/16	
thru	Coastdown continued - 60% RTP to 58% RTP.
9/19	
9/19	Power reduction commenced at 2000; off-line by 2400. Commenced Reactor Coolant System boration and cooldown in preparation for refueling.

# REFUELING INFORMATION

DOCKET NO.: 50-272

UNIT:

Salem #1

	DATE:	October 10, 1980
	COMPLETED BY:	L. K. Miller
·	TELEPHONE:	609-365-7000
	**************************************	X 507
September 1980		
ONTH:		
. Refueling information has changed from	last month:	
YES	X NO	
. Scheduled date of next refueling:	September 1981	<del>, , _ , _ , , , , , , , , , , , , ,</del>
. Scheduled date for restart following re	efueling: Novem	ber 15, 1981
. A. Will Technical Specification change	es or other licen	se
amendments be required? YES	NO	
NOT DETE	RMINED TO-DATE	eptember 1980
B. Has the reload fuel design been re	viewed by the Sta	tion Operating
Review Committee? YES		-
If no, when is it scheduled?	August 1981	
Scheduled date(s) for submitting propo	sed licensing act	ion:
. Important licensing considerations ass		eling:
NONE		•
	<del></del>	<del></del>
		<del></del>
	<del></del>	<del></del>
. Number of Fuel Assemblies:	1	0.0
A. In-Core		.93
B. In Spent Fuel Storage		40
. Present licensed spent fuel storage ca	Pacity.	264
Future spent fuel storage capacity:	1]	.70
. Date of last refueling that can be dis	charged to the sp	ent fuel
pool assuming the present licensed cap	acity: September 1	982
	<del></del>	

Page 20 of 20 8-1-7.R4