

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	N	J	S	G	S	1	2	0	0	-	0	0	0	0	0	0	0	3	4	1	1	1	1	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
LICENSEE CODE						LICENSE NUMBER						LICENSE TYPE						CAT		58					

01	L	6	0	5	0	0	0	2	7	2	7	1	1	0	7	8	0	8	1	1	2	4	8	0	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
CON'T		REPORT SOURCE		DOCKET NUMBER						EVENT DATE						REPORT DATE									

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During an investigation of masonry walls pursuant to NRC Bulletin IE 80-11, it was

03 | discovered that a discrepancy exists between the construction specification and the

04 | design drawings for a masonry block wall in the Auxiliary Buidling on Elevation 122'

05 | separating the control equipment room from a corridor and a maintenance room. A field

06 | procedure was used to determine whether or not the horizontal reinforcing was in place.

07 | Although no drawing discrepancies existed, the corridor wall on Elev. 100' separating

08 | Unit 1 from Unit 2 was field tested and found deficient. The probable consequence is

09 | a collapse of these walls during a seismic event. No similar occurrences.

09	Z	Z	11	B	12	C	13	Z	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16	17	8	0	21	22	0	5	6	24	25	0	1	28	29	T	30	0	32								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50		
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE		LER NO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Unresolved conflict between specification and drawings for walls on Elevation 122'.

11 | Continual long term interruptions during construction of wall on Elev. 100'. The

12 | wall on Elev. 122' in each unit will be reanalyzed in accordance with the as-built

13 | condition and reinforced with structural steel columns, if required. The wall on

14 | Elev. 100' will be reinforced with structural steel as required.

15	H	28	0	0	0	29	N/A	30	D	31	NRC Observation	32
7	8	9	10	11	12	13	14	15	16	17	18	19
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
16	Z	33	Z	34	N/A	35	N/A	36	N/A	36		
7	8	9	10	11	12	13	14	15	16	17		
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE						
17	0	0	0	37	Z	38	N/A	39	N/A	39		
7	8	9	10	11	12	13	14	15	16	17		
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION						
18	0	0	0	40	N/A	41	N/A	41	N/A	41		
7	8	9	10	11	12	13	14	15	16	17		
PERSONNEL INJURIES		NUMBER		DESCRIPTION								
19	Z	42	N/A	43	N/A	43	N/A	43	N/A	43		
7	8	9	10	11	12	13	14	15	16	17		
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION								
20	N	44	N/A	45	N/A	45	N/A	45	N/A	45		
7	8	9	10	11	12	13	14	15	16	17		
PUBLICITY ISSUED		DESCRIPTION					NRC USE ONLY					

NAME OF PREPARER J. C. Osuch PHONE: 609-935-0998

8012020652