-,,,,,,	CENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
1 8	N J S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
T'NO:	REPORT L 6 0 5 0 0 2 7 2 7 1 2 0 4 8 0 8 1 2 1 8 8 0 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	VENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During routine surveillance testing, it was found that the Nos. 11 and 12 Auxiliary
0 3	Feedwater Pumps could be stopped from the control console if a Steam Generator low,
0 4	low level signal is received during Safeguards Equipment Control System operation.
0 5	This is a malfunction of a safety-related system and is a violation of Technical
0 6	Specification 6.9.1.8e. No previous occurrences.
0 7	
0 8	80
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	LER RO EVENT YEAR SEQUENTIAL REPORT NO. 17) REPORT OCCURRENCE REPORT TYPE NO. 17) REPORT TYPE OCCURRENCE REPORT
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0	Design error. Design Change Request 1EC 1084 was issued and implemented on
	December 6, 1980 to preclude manual operation of the Auxiliary Feedwater Pumps during
1 2	Safeguards Equipment Control System operation. The Unit No. 2 wiring diagrams are
1 3	being investigated to determine if similar changes will be necessary.
1 4	80
1 5 a	GILITY SPOWER OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) G (28) O O O (29) N/A B (31) Surveillance Test 10 12 13 44 45 46
	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 N/A LOCATION OF RELEASE 36 N/A
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) C O O (37) Z (38) N/A
· -	PERSONNEL INJURIES NUMBER DESCRIPTION 41 0 0 0 40 N/A
	OSS OF OR DAMAGE TO FACILITY 43 Z 42 N/A
2 0	NAC USE ONLY N/A
a	NAME OF PREPARER J. C. Osuch PHONE: 609-935-0998 0