

March 27, 1981

TO ALL LER RECIPIENTS


LER 80-56/01X-2

Please replace previously sent LET 80-56/01X-2
with the attached copy.

Thank you.

LER Coordinator

JDP:rp
Attachment



A002
s
//

8104020587

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | J | S | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
 7 8 9 14 15 25 26 30 57 CAT 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T
 01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 2 | 7 | 1 | 1 | 0 | 7 | 8 | 0 | 8 | 0 | 3 | 2 | 4 | 8 | 1 | 9
 7 8 60 61 68 69 74 75 80
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During an investigation of masonry walls pursuant to NRC Bulletin IE 80-11, it was dis-
 03 | covered that a discrepancy exists between the construction specification and the design
 04 | drawings for a masonry block wall in the Aux Building Elev. 122'. The corridor wall
 05 | on Elev. 100' separating Unit 1 from Unit 2 was found deficient. On 12/1/80, it was
 06 | discovered that the Controlled Facilities Building and its associated walkway exceed
 07 | the allowable design stress during a site seismic event. However, we believe that the
 08 | ultimate structural capacity of this building would not be exceeded during a site safe
 9 shutdown earthquake.

09 | Z | Z | 11 | B | 12 | C | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16
 7 8 9 10 11 12 13 18 19 20
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 17 | 8 | 0 | 21 | 22 | 0 | 5 | 6 | 23 | 24 | 26 | 27 | 0 | 1 | 28 | 29 | X | 30 | 31 | 2 | 32
 7 8 21 22 23 24 26 27 28 29 30 31 32
 LER RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
 F | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | Y | 23 | N | 24 | L | 25 | U | 0 | 8 | 0 | 26
 33 34 35 36 37 40 41 42 43 44 47
 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of the incident is a conflict between specifications and drawings for the walls
 11 | on Elev. 122', continual long term interruptions during construction of the wall on
 12 | Elev. 100' and the wanting design of the walls of the Controlled Facilities Building
 13 | and its associated walkways. The walls on Elev. 100' and 122' in each unit were re-
 14 | inforced with structural steel. The Controlled Facilities Building was reinforced with
 9 tie rods and gusset plates. The walkway was reinforced with cross braces.

15 | H | 28 | 0 | 0 | 0 | 29 | N/A | X | 31 | NRC Observation
 7 8 9 10 12 13 44 45 46 80
 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
 16 | Z | 33 | Z | 34 | N/A | LOCATION OF RELEASE (36)
 7 8 9 10 11 44 45 80
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
 17 | 0 | 0 | 0 | 37 | Z | 38 | N/A
 7 8 9 11 12 13 80
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
 18 | 0 | 0 | 0 | 40 | N/A
 7 8 9 11 12 80
 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
 19 | Z | 42 | N/A
 7 8 9 10 12 80
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
 20 | N | 44 | N/A
 7 8 9 10 80
 PUBLICITY ISSUED DESCRIPTION (45)
 21 | N | 44 | N/A
 7 8 9 10 80

NRC USE ONLY