(7-77)	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 2 7 2 7 0 1 2 9 8 1 8 0 5 0 7 8 1 9  SOURCE 60 61 DUCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  During normal operations on 1/29/81, Containment Sump Pump operation indicated
0 3	that the Containment Sump had 4.3 gpm of unidentified leakage. The excess leakage
0 4	was mistakenly assumed to be coming from the #12 Containment Fan Coil Unit. IAW NRC
0 5	IE Bulletin No. 80-24, the NRC was notified of a service water leak in containment.
06	On 1/30/81, it was discovered that the #12 Sump Pump was operating erratically and
0 7	calculations of its falsely apparent discharge rate led operations to believe that
0 8 7 8	there was an unidentified leak.
0 9 7 B	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE  C I 11
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
110	On March 8, 1981, level detector LD7750 was removed and inspected. No failed components were found. After several unsuccessful calibration attempts, it was
1 2	replaced in kind on March 9, 1981.
13	
14	L
7 8	9 ACILITY ACILITY STATUS  * POWER OTHER STATUS  OTHER STAT
1 6 AE	CTIVITY CONTENT  CLEASED OF RELEASE AMOUNT OF ACTIVITY 35  DEPERSONNEL EXPOSURES  LOCATION OF RELEASE 36  N/A  N/A  80
1 7 7 B	NUMBER TYPE DESCRIPTION (39)  11 12 13 DESCRIPTION (39)  N/A
1 8 7 8 1 9	PERSONNEL INJURIES NUMBER DESCRIPTION 41  0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
2 0 '	PUBLICITY SSUED DESCRIPTION 45 N/A N/A
7 8	N/A  10 8105190 57 W. J. Steele  N/A  68 69 80 5  69 69 80 5