

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N J S G S 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 58

CON'T 0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 1 7 0 4 1 9 8 1 8 0 5 1 8 8 1 9
8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 One of two existing POPS channels had to be declared inoperable three times during
0 3 the period from April 19, 1981 through May 4, 1981. This was required IAW Technical
0 4 Specification 3.4.9.3a while a leaking valve, 2PR1, was being repaired. In order to
0 5 repair 2PR1, the channel had to be isolated by closing valve, 2PR6. With 2PR6 closed,
0 6 reactor coolant temperatures of less than 312°F rendered the channel inoperable IAW
0 7 the applicability statement of Technical Specification 3.4.9.3.a.

0 8 7 8 9 80

0 9 C J 11 E 12 B 13 V A L V E X 14 D 15 B 16
17 LER/RO REPORT NUMBER 8 1 0 0 6 0 3 L 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
B 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 L 25 C 6 3 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The stem and cage of valve 2PR1 had seized and galled causing the valve to leak.
1 1 The stem and cage were replaced. The channel was tested satisfactory and returned
1 2 to service at 1435 hours on May 4, 1981.

1 3 7 8 9 80

1 4 7 8 9 80

1 5 G 28 0 0 0 29 NA 30 A 31 Operator Observation 32
7 8 9 10 12 13 44 45 46 80

1 6 Z 33 Z 34 NA 35 NA 36
7 8 9 10 11 44 45 80

1 7 0 0 0 37 Z 38 NA 39
7 8 9 11 12 13 80

1 8 0 0 0 40 NA 41
7 8 9 11 12 80

1 9 Z 42 NA 43
7 8 9 10 80

2 0 N 44 NA 45
7 8 9 10 80

NAME OF PREPARER W. J. Steele

PHONE: 609-935-0998

8105270332