

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J S G S 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

01 REPORT SOURCE L 0 5 0 0 0 3 1 1 7 0 5 0 5 8 1 8 0 5 1 8 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 DCR-663R1 was issued with the incorrect cable routing for the AC power feed from (2) LASDS 115V AC distribution panel to the Fire Protection Process Rack. This constituted a reportable incident IAW Technical Specification 6.9.1.8.i.

09 SYSTEM CODE A B 11 CAUSE CODE A 12 CAUSE SUBCODE C 13 COMPONENT CODE E L E C O N 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16

17 LER NO REPORT NUMBER 8 1 EVENT YEAR 8 1 SEQUENTIAL REPORT NO. 0 1 4 OCCURRENCE CODE 0 1 REPORT TYPE T REVISION NO. 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 DCP 1EC-1144 provided for the proper routing of cable 1ASDAC2-C2, T214, in accordance with the Fire Protection Cable Interaction Analysis for Unit 1. 12 DCP 2EC-1145 has been revised to change the cable routing for Unit 2. This rerouting will be completed prior to June 5, 1981, and a 24 hour fire watch is being maintained until the work is completed.

15 FACILITY STATUS G 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY Z 31 DISCOVERY DESCRIPTION Engineering Evaluation 32

16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 NA 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED DESCRIPTION NA 44

8105270 340

J. J. Espey

PHONE 609-935-0998 NRC USE ONLY