



# Exelon Generation

Paul Swift  
Plant Manager

R E Ginna Nuclear Power Plant  
1503 Lake Rd  
Ontario, NY 14519

315-791-5205 Office  
www.exeloncorp.com  
paul.swift@exeloncorp.com

March 23, 2018

U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

ATTENTION: Document Control Desk

SUBJECT: R.E. Ginna Nuclear Power Plant  
Renewed Facility Operating License No. DPR-18  
Docket No. 50-244

LER 2017-001, During Surveillance Testing, Lift Pressure Setpoints on Three  
Main Steam Safety Valves Found Outside Technical Specifications Limits  
Due to Stiction.

The attached Licensee Event Report (LER) 2017-001 is submitted under the provisions of  
NUREG-1022, Event Reporting Guidelines. There are no new commitments contained in  
this submittal. This submittal is for revision 1 of the LER.

Should you have any questions regarding this submittal, please contact Kyle Garnish at  
315-791-5321.

Sincerely,

Paul Swift,  
Ginna Plant Manager

PS/ejf

Attachment: LER 2017-001-01

cc: NRC Regional Administrator, Region I  
NRC Project Manager, Ginna  
NRC Resident Inspector, Ginna

IEZZ  
NRR

**Attachment**

---

**LER 2017-001-01**

---



**LICENSEE EVENT REPORT (LER)**

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NE0B-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

|  |   |                          |
|--|---|--------------------------|
| <b>1. FACILITY NAME</b><br>R. E. Ginna Nuclear Power Plant | <b>2. DOCKET NUMBER</b><br>05000      244 | <b>3. PAGE</b><br>1 OF 4 |
|--|---|--------------------------|

**4. TITLE**  
During Surveillance Testing, Lift Pressure Setpoints on Three Main Steam Safety Valves Found Outside Technical Specifications Limits Due to Narrowness of As-Found Acceptance Band.

| 5. EVENT DATE |     |      | 6. LER NUMBER |                   |         | 7. REPORT DATE |     |      | 8. OTHER FACILITIES INVOLVED |               |
|---------------|-----|------|---------------|-------------------|---------|----------------|-----|------|------------------------------|---------------|
| MONTH         | DAY | YEAR | YEAR          | SEQUENTIAL NUMBER | REV NO. | MONTH          | DAY | YEAR | FACILITY NAME                | DOCKET NUMBER |
| 04            | 23  | 2017 | 2017          | 001               | 01      | 03             | 23  | 2018 | FACILITY NAME                | DOCKET NUMBER |
|               |     |      |               |                   |         |                |     |      |                              | 05000         |
|               |     |      |               |                   |         |                |     |      |                              | 05000         |

|                          |  |   |   |   |
|--------------------------|--|---|---|---|
| <b>9. OPERATING MODE</b> | <b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)</b> |   |   |   |
| <b>1</b>                 | <input type="checkbox"/> 20.2201(b)  | <input type="checkbox"/> 20.2203(a)(3)(i)             | <input type="checkbox"/> 50.73(a)(2)(ii)(A)   | <input type="checkbox"/> 50.73(a)(2)(viii)(A) |
|                          | <input type="checkbox"/> 20.2201(d)  | <input type="checkbox"/> 20.2203(a)(3)(ii)            | <input type="checkbox"/> 50.73(a)(2)(ii)(B)   | <input type="checkbox"/> 50.73(a)(2)(viii)(B) |
|                          | <input type="checkbox"/> 20.2203(a)(1)   | <input type="checkbox"/> 20.2203(a)(4)                | <input type="checkbox"/> 50.73(a)(2)(iii)     | <input type="checkbox"/> 50.73(a)(2)(ix)(A)   |
|                          | <input type="checkbox"/> 20.2203(a)(2)(i)  | <input type="checkbox"/> 50.36(c)(1)(i)(A)            | <input type="checkbox"/> 50.73(a)(2)(iv)(A)   | <input type="checkbox"/> 50.73(a)(2)(x)       |
| <b>10. POWER LEVEL</b>   | <input type="checkbox"/> 20.2203(a)(2)(ii)   | <input type="checkbox"/> 50.36(c)(1)(ii)(A)           | <input type="checkbox"/> 50.73(a)(2)(v)(A)    | <input type="checkbox"/> 73.71(a)(4)          |
|                          | <input type="checkbox"/> 20.2203(a)(2)(iii)  | <input type="checkbox"/> 50.36(c)(2)                  | <input type="checkbox"/> 50.73(a)(2)(v)(B)    | <input type="checkbox"/> 73.71(a)(5)          |
|                          | <input type="checkbox"/> 20.2203(a)(2)(iv)   | <input type="checkbox"/> 50.46(a)(3)(ii)              | <input type="checkbox"/> 50.73(a)(2)(v)(C)    | <input type="checkbox"/> 73.77(a)(1)          |
|                          | <input type="checkbox"/> 20.2203(a)(2)(v)  | <input type="checkbox"/> 50.73(a)(2)(i)(A)            | <input type="checkbox"/> 50.73(a)(2)(v)(D)    | <input type="checkbox"/> 73.77(a)(2)(i)       |
|                          | <input type="checkbox"/> 20.2203(a)(2)(vi)   | <input checked="" type="checkbox"/> 50.73(a)(2)(i)(B) | <input type="checkbox"/> 50.73(a)(2)(vii)     | <input type="checkbox"/> 73.77(a)(2)(ii)      |
|                          | <input type="checkbox"/> 50.73(a)(2)(i)(C)   | <input type="checkbox"/> OTHER                        | Specify in Abstract below or in NRC Form 366A |   |

|  |  |
|--|--|
| <b>12. LICENSEE CONTACT FOR THIS LER</b>                       |  |
| LICENSEE CONTACT<br>Kyle Garnish, Regulatory Assurance Manager | TELEPHONE NUMBER (Include Area Code)<br>(315) 791-5321 |

| 13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT |        |           |              |                    |       |        |           |              |                    |
|---|--------|-----------|--------------|--------------------|-------|--------|-----------|--------------|--------------------|
| CAUSE   | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO EPIX | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO EPIX |
| X   | SB     | RV        | C710         | Y                  |       |        |           |              |                    |

|   |                                     |       |     |      |
|---|-------------------------------------|-------|-----|------|
| <b>14. SUPPLEMENTAL REPORT EXPECTED</b>   | <b>15. EXPECTED SUBMISSION DATE</b> | MONTH | DAY | YEAR |
| <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO |                                     |       |     |      |

**ABSTRACT** (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On April 23, 2017, with the plant in Mode 1, during in-place testing of main steam safety valve (MSSV) 3509, the as-found lift pressure did not meet the acceptance criteria of +1% / -3% of setpoint (1140 psig), required by Technical Specifications (TS) surveillance SR 3.7.1.1. This was the second unsatisfactory MSSV as-found lift pressure, as MSSV 3508 had failed to meet the same as-found acceptance criteria during earlier in-place sequential testing (on April 21, 2017). Later, on May 5, 2017, a third MSSV (3512) tested at a vendor's facility failed to meet the same as-found acceptance criteria. (All three of the MSSVs have the same manufacturer and model number.) The most probable cause of exceeding the MSSV upper acceptance limit is the programmatic issue of the narrowness of the as-found acceptance band. A contributing cause was minor stiction on the disc. The as-found settings of all three MSSVs remained within analytical bounds; therefore, operation of the facility in this condition had no impact on the health and safety of the public.

TS LCO 3.7.1, "Main Steam Safety Valves (MSSVs)," requires eight MSSVs to be operable in Modes 1, 2, and 3. Since the acceptance band is fixed and the stiction affecting the three lift pressures may have occurred over a period of time, it is assumed that at least one required MSSV was not operable in the past for a time greater than allowed. Therefore, this occurrence is considered reportable per 10 CFR 50.73(a)(2)(i)(B) as a condition prohibited by the plant's TS.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOF-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

|   |                                    |               |                          |               |
|---|------------------------------------|---------------|--------------------------|---------------|
| 1. FACILITY NAME<br><br>R. E. Ginna Nuclear Power Plant | 2. DOCKET NUMBER<br><br>05000- 244 | 3. LER NUMBER |                          |               |
|   |                                    | YEAR<br>2017  | SEQUENTIAL NUMBER<br>001 | REV NO.<br>01 |

**NARRATIVE**

**I. PRE-EVENT PLANT CONDITIONS:**

At the time the condition was identified, the plant was in Mode 1 at approximately 88% rated thermal power.

**II. DESCRIPTION OF EVENT:**

**A. EVENT:**

On April 23, 2017, with the plant in Mode 1, during in-place testing of main steam safety valve (MSSV) 3509, the as-found lift pressure did not meet the acceptance criteria of +1% / -3% of setpoint (1140 psig), required by Technical Specifications (TS) surveillance SR 3.7.1.1. The initial as-found lift pressure for MSSV 3509 was at +1.2% of setpoint. This was the second unsatisfactory MSSV as-found lift pressure, as MSSV 3508 had failed to meet the same as-found acceptance criteria during earlier in-place sequential testing (on April 21, 2017), with an initial as-found lift pressure at +1.3% of setpoint. Subsequently, the testing scope was expanded to all eight MSSVs. Of the other six valves, MSSV 3512 tested at +1.1% of setpoint; the other five valves tested within range.

TS LCO 3.7.1 requires eight MSSVs to be operable in Modes 1, 2, and 3. Testing of MSSVs is performed one valve at a time, with each valve adjusted if necessary and returned to operable status before proceeding with the testing of another valve. In this manner, a maximum of one valve is known to be inoperable at any time during testing. However, since the acceptance band is fixed and the stiction affecting the three lift pressures may have occurred over a period of time, it is assumed that at least one required MSSV was not operable in the past for a time greater than allowed. Therefore, this occurrence is considered reportable in accordance with 10 CFR 50.73(a)(2)(i)(B) as a condition prohibited by the plant's TS.

**B. INOPERABLE STRUCTURES, COMPONENTS, OR SYSTEMS THAT CONTRIBUTED TO THE EVENT:**

None

**C. DATES AND APPROXIMATE TIMES OF MAJOR OCCURENCES:**

- April 21, 2017, 0800 EDST: MSSV 3508 removed from service for lift setpoint testing and returned to service following adjustment. Lift pressure found outside +1% / -3% of setpoint (at +1.3%).
- April 23, 2017, 0630 EDST: MSSV 3509 removed from service for lift setpoint testing and returned to service following adjustment. Lift pressure found outside +1% / -3% of setpoint (at +1.2%).
- May 5, 2017, 1100 EDST: MSSV 3512 tested for lift setpoint at a vendor's facility. Lift pressure found outside +1% / -3% of setpoint (at +1.1%).

**D. OTHER SYSTEMS OR SECONDARY FUNCTIONS AFFECTED:**

None

**E. METHOD OF DISCOVERY:**

Review of test data associated with as-found setpoint testing.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

|   |                                |               |                          |               |
|---|--------------------------------|---------------|--------------------------|---------------|
| 1. FACILITY NAME<br>R. E. Ginna Nuclear Power Plant | 2. DOCKET NUMBER<br>05000- 244 | 3. LER NUMBER |                          |               |
|   |                                | YEAR<br>2017  | SEQUENTIAL NUMBER<br>001 | REV NO.<br>01 |

**NARRATIVE**

**F. SAFETY SYSTEM RESPONSES:**

No safety systems were actuated.

**III. CAUSE OF EVENT:**

The most probable cause of the MSSVs' as-found lift pressures being outside +1% / -3% of setpoint is the programmatic issue of the narrowness of the as-found acceptance band. A contributing cause was minor stiction in the disc. Note that all the Ginna MSSVs were upgraded in 2009/2012 to Inconel 618 flexi-discs and 316SS nozzles, so corrosion of these sub-components (a contributor to some MSSV failures) is insignificant.

**IV. ASSESSMENT OF THE SAFETY CONSEQUENCES OF THE EVENT:**

This event is reportable in accordance with 10 CFR 50.73, Licensee Event Report System, item (a)(2)(i)(B), which requires a report of, "Any operation or condition which was prohibited by the plant's Technical Specifications."

The operability of the MSSVs ensures that the secondary system pressure will be limited to within 110% of its design pressure of 1140 psig during the most severe anticipated system operational transient. The as-found condition of the MSSVs was compared to the current overpressure analysis prepared in support of extended power uprate, and it was concluded that the analysis remained bounding. As such, the applicable acceptance criteria for design basis events would have been met, and the MSSVs remained capable of performing their intended safety function.

The as-found settings of all three MSSVs remained within analytical bounds; therefore, this event had no impact on the health and safety of the public.

**V. CORRECTIVE ACTIONS:**

**A. ACTION TAKEN TO RETURN AFFECTED SYSTEMS TO PRE-EVENT NORMAL STATUS:**

All three MSSVs (3508, 3509, and 3512) found outside the acceptance criteria of +1% / -3% of their required setpoints were adjusted to within +/- 1% of setpoint.

**B. ACTION TAKEN OR PLANNED TO PREVENT RECURRENCE:**

- Complete the Engineering Change Package (ECP) in support of expanding the as-found Technical Specification limit of (+1% / -3%) to (+3% / -3%) for the last-3-to-open MSSVs on each steam header (total of 6 MSSVs). This will alleviate the programmatic issue of insufficient margin between the TS acceptance criteria and the acceptable as-left acceptance criteria. Also, this action will accommodate possible set-pressure drift related to stiction.
- Evaluate changing the test frequency from 5 years to 3 years. This will prevent the formation of micro-fouling and reduce the likelihood of stiction.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEQB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

|                                 |  |                         |     |                      |                   |         |
|---------------------------------|--|-------------------------|-----|----------------------|-------------------|---------|
| <b>1. FACILITY NAME</b>         |  | <b>2. DOCKET NUMBER</b> |     | <b>3. LER NUMBER</b> |                   |         |
| R. E. Ginna Nuclear Power Plant |  | 05000-                  | 244 | YEAR                 | SEQUENTIAL NUMBER | REV NO. |
|                                 |  |                         |     | 2017                 | 001               | 01      |

**NARRATIVE**

**VI. ADDITIONAL INFORMATION:**

**A. FAILED COMPONENTS:**

No other structures, systems, or components failed as result of this event.

**B. PREVIOUS LERs ON SIMILAR EVENTS:**

A Ginna LER event historical search was conducted which yielded the following results:

- LER 2006-007, Rev. 1, Main Steam Safety Valve Setpoint Exceedance

**C. THE ENERGY INDUSTRY IDENTIFICATION SYSTEM (EII) COMPONENT FUNCTION IDENTIFIER AND SYSTEM NAME OF EACH COMPONENT OR SYSTEM REFERRED TO IN THIS LER:**

|      | COMPONENT     | IEEE 803 FUNCTION NUMBER | IEEE 805 SYSTEM IDENTIFICATION |
|------|---------------|--------------------------|--------------------------------|
| 3508 | Valve, Relief | RV                       | SB                             |
| 3509 | Valve, Relief | RV                       | SB                             |
| 3512 | Valve, Relief | RV                       | SB                             |

Note that all three relief valves were made by the same manufacturer and are the same model number.