

Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038-0236

## Nuclear Business Unit

## JUN 1 3 1996

## LR-N96166

U. S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Gentlemen:

LER 311/96-004-00 SALEM GENERATING STATION - UNIT 2 FACILITY OPERATING LICENSE NO. DPR-75 DOCKET NO. 50-311

This Licensee Event Report Supplement entitled "Missed Technical Specification Action Statement - Compensatory Survey" is being submitted pursuant to the requirements of the Code of Federal Regulations 10CFR50.73(a)(2)(i)(B).

Sincerely,

David F. Gărchow General Manager -Salem Operations

Attachment

SORC Mtg. 96-080

EHV/tcp

C Distribution LER File 3.7



The power is in your hands.

Document Control Desk LR-N96166

## Attachment A

The following items represent commitments that Public Service Electric & Gas (PSE&G) made to the Nuclear Regulatory Commission (NRC) relative to this LER (311/96-004-00). The commitments are as follows:

1. The Technical Specification Surveillance Improvement Project (See LER 311/95-008) will ensure that adequate processes exist to assure conditional surveillances are properly tracked. The project is scheduled to be completed by December 31, 1997.

U.S. NUCLEAR REGULATORY COMMISSION (4-95) LICENSEE EVENT REPORT (LER)						APPROVED BY OMB NO. 3150-0104 EXPIRES 04/30/98 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS, REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY, FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION									
(See reverse for required number of digits/characters for each block)							AND RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPEWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET. WASHINGTON. DC 20503.								
FACILITY NAME (1) SALEM GENERATING STATION, UNIT 2						DOCKET NUMBER (2) 05000311					PAGE (3) 1 of 4				
<del>TITLE(4)</del> Missed	Techni	.cal S	pecificati	on Ac	ction	State	ement	. – C	Comper	satory S	Gurvey				
EVENT	EVENT DATE (5) LER NUMBER (6) REPORT DATE (7) OTHER FACILITIES INVOLVED (8)											(8)			
MONTH	DAY YEA	YEAR	SEQUENTIAL	REVISION	MONTH	DAY	YEAR	FACILIT	FACILITY NAME			DCKETN	UMBER		
		_	NUMBER					Salem, Unit 1				05 DCKET N	000272		
05	15   96	96	004	00	06	14	96					05000			
OPERATING N THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)											r more) (11)				
MODE (S	<i>n</i>	- 20	20.2201(b)			20.2203(a)(2)(v)			50.73(	a)(2)(1)		3(a)(2)(viii)			
LEVEL (1	* <b>0</b>	20	.2203(a)(1) .2203(a)(2)(i)		20.2203	(a)(3)(i) (a)(3)(ii	) )		50.73(	a)(2)(ii) a)(2)(iii)		73.7	3(a)(2)(x) 1		
<u>`</u>	<u>1</u>	20	.2203(a)(2)(ii)		20.2203	(a)(4)	·		50.73(	a)(2)(iv)		ОТН	ER		
		20	.2203(a)(2)(iii)		50.36(c)	)(1)			50.73(	a)(2)(v)	Sp	Decify in	Abstract below Form 366A		
<u> </u>		20	.2203(a)(2)(iv)		50.36(c)	)(2)			50.73(	a)(2)(vii)					
NAME			·····	LICENS	EE CONT	ACT F	OR THI		(12)	IUMBER (Include /	Area Code)				
E. H. V	/illar,	Stat	ion Licens	ing E	nginee	er			·	609-	339-54	56			
	Ċ	OMPLET	E ONE LINE FO	REACH	COMPO	NENT F	AILUR	EDES	CRIBED	IN THIS REP	ORT (13)				
CAUSE	JSE SYSTEM		COMPONENT MANUFACTURER REP TO		PORTABLE O NPRDS		CAUS		SYSTEM	I COMPONENT MANU			REPORTABLE TO NPRDS		
					`										
	<u></u>			EXPECT	FD (14)				<u> </u>						
YES (If yes, complete EXPEC			SUBMISSION DA	TE).		XNO	,	SUBMISSION DATE (15)							
ABSTRACT	Γ (Limit to '	400 spac	es, i.e., approxim	ately 15	single-sp	aced ty	pewritte	en lines	;) (16)	<u></u>	<u></u>				
At 131 Fuel H inoper person	0 hour: andlind able an nel.	s on M g Buil nd app + 2 T	May 14, 199 ding {VG}( propriate n	96, th (FHB) hotifi	ne Sal area icatio	em Un Radia ns we	nit 2 atior ere n	2 cor Mor nade	ntrol nitors to Ra	room dec {IL} (2 adiation	clared 2R5 and Prote	the d 2R ctio	Unit 2 9) n		
states survey once p	in par s of th er 24 h	t: ". ne mon nours.	the Mini itored are	mum C a wit	Channe Channe Ch por	ls OF table	PERAP e mor	SLE 1 Nitor	cequir cing i	ements, nstrumer	perfo ntatio	rm a: n at	#23, rea least		
The fi 1410 ho require hours o	rst cor ours or ements on May	npensa May How 15, 1	tory radio 14, 1996, ever, the 996, appro	logic in ac next ximat	cal su corda sched cely 5	rvey nce v uled hour	of t with surv cs la	he U the rey w ter.	Jnit 2 Techr Vas no	FHB was ical Spe t perfor	s perfo ecifica med un	orme atio: ntil	d at n . 1920		
The roo	ot caus	e of	this event	was	attri	buted	d to	pers	sonnel	error.					
This ev condit:	vent is ion pro	repo hibit	rtable in ed by the	accor plant	dance 's Te	with chnic	n 10 cal S	CFR peci	50.73 ficat	(a) (2) ions.	(i)·	(b),	any		
		<u></u>				<del></del>				<b></b>					

•

•

·

.•;

¥

NRC FORM 366A		U.S. NUCLEAR REGULAT									
(4-95) LICENSEE EVENT REPORT (LER)											
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	' PAGE (3)								
SALEM GENERATING STATION, UNIT 2	05000311	YEAR SEQUENTIAL REVISION NUMBER NUMBER 96 004 00	<sup>NR</sup> 2 OF 4								
TEXT (If more space is required, use additional copies of NRC Fo	rm 366A) <b>(17)</b>										
PLANT AND SYSTEM IDENTIFICATION											
Westinghouse - Pressurized Water Reactor											
* Energy Industry Identification System (EIIS) codes and component function identifier codes appear in the text as (SS/CCC).											
Fuel Handling Building {VG} Radiation Monitoring System {IL}											
CONDITIONS PRIOR TO OCCURRENCE											
At the time of identification, Salem Unit	s 1 and 2 were shu	tdown and defueled.									
DESCRIPTION OF OCCURRENCE											
At 1310 hours on May 14, 1996, the Salem Unit 2 control room declared the Unit 2 Fuel Handling Building (FHB) area radiation monitors (2R5 and 2R9) inoperable. With an inoperable Radiation Monitoring System (RMS) area monitor, Salem Unit 2 Technical Specification (TS) 3.3.3.1. Table 3-3.6 Action #23, states in part: " perform area surveys of the monitored area with portable monitoring instrumentation at least once per 24 hours."											
Inoperability of the RMS area monitor Protection Technician (SRPT) by the c May 14, 1996, Radiation Protection (R compensatory radiological survey of t radiological survey was performed in the time and date for the next schedu	is communicated ontrol room pers P) personnel per he Unit 2 FHB. accordance with led survey is po	to the Shift Rad onnel, and at 14 formed the first The compensatory the requirements sted in the SRPT	diation 10 hours on of TS, and s office.								
At 0645 hours on May 15, the night-sh perform the compensatory survey to th hours RP shift meeting, RP supervisor the 2R5 and 2R9 monitors, but they fa compensatory survey.	ift SRPT turned- e on-coming day- y personnel disc iled to discuss	over the requiren shift SRPT. At t ussed the inopera the need for the	nents to the 0700 ability of								
At 1000 hours the RP manager discussed the survey requirement with the dayshift SRPTs; however, as the SRPTs and the supervisors became involved in their daily activities, they did not recognize that the compensatory survey was not assigned or completed.											
At 1845 hours on May 15, during turn- it was identified that the compensato Radiation Protection supervision was At 1920 hours the survey of the Unit no abnormal radiological conditions w	over between day ry survey was no notified of the n 2 Fuel Handling 1 ere noted.	shift and nightsh t performed, and missed compensatc Building was comp	ift SRPT the ry survey. leted, and								

5

NRC FORM 366A (4-95)		Ū.S.	NUCLEAR RE	GULATO	RY CO	MMISS	SION			
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION										
FACILITY NAME (1)	FACILITY NAME (1) DOCKET NUMBER (2) LER NUMBER (6) PAG									
	05000311	YEAR	SEQUENTIAL NUMBER	REVISION	3	OF	4			
SALEM GENERATING STATION, UNIT 2		96	004 -	- 00						
TEXT (If more space is required, use additional copies of NRC Form	n 366A) (17)	<u></u>								
CAUSE OF OCCURRENCE										
The root cause of this event was attri	buted to persor	nnel	error.							
PRIOR SIMILAR OCCURRENCES						•				
A review of LERs for Salem Units 1 and 2 LERs in the last two years was performed to identify similar occurrences. Four similar LERs were identified.										
LER 311/96-001, "Technical Specification Violation: Failure To Perform Chemistry Sampling Within Required Timeframe" identified an occurrence where the required sample was not taken within the 24 hours required by TS. The corrective actions for this LER were specific to improving the Chemistry Department turnover process.										
LER 272/96-003, "Technical Specification Radiation Monitor Sampling Non- Compliance," identified an occurrence where compensatory samples required to satisfy Technical Specification 3.3.3.8 were not always analyzed within the allotted time defined by Technical Specifications. Corrective action for this LER was to revise the Chemistry procedures.										
LER 311/95-005, "Technical Specificati Sample With Radiation Monitor Inoperab samples had been obtained as required monitor 2R18 was inoperable. Only one release authorization. Corrective act signature requirements for the indepen waste release procedure, and providing Department personnel. Chemistry Depar as a group.	on Violation: F le," identified for releasing 1 of the samples ions included a dent samples to error reductio tment personnel	ailu an iqui was ddir the n tr als	are to An occurren id waste s analyze ng specif e gaseous raining t so discus	alyze ce whe when r d pric ic ver and l o Chem sed th	Seco re t adia r to ific iqui istr e ev	ond two ation cation d ry rent	n on			
LER 272/95-013, "Surveillance Testing of Seismic Monitoring Instrumentation Performed Approximately Six and One Half Hours Late" identified an occurrence where the 31 day surveillance for the Seismic Sensors were missed. Corrective actions associated with this event included improvements to the surveillance planning and scheduling process.										
SAFETY CONSEQUENCES AND IMPLICATIONS										
There were no safety consequences assoce Both 2R5 and 2R9 area radiation monitor provide alarm, and protection, if neces	ciated with this rs were availab ssary.	s ev le a	ent. nd funct	ional	to					
Additionally, the Radiation Protection monitoring and radiation protection ins event of an increase in radiation field	Department main struments that will be a set of the set	ntai woul	ns conti: d alarm .	nuous locall	air y in	the	)			

NRC FOI (4-95)	RM 366A	'ENT REPORT (LI	U.S. ER)	NU	CLEAR F	REG	ULATO	RY CO	OMMISS	SION
	TEXT C		•							
	FACILITY NAME (1)	DOCKET NUMBER (2)		LEF	R NUMBI	ER (	6)	F	AGE (3	3)
	· · · · · · · · · · · · · · · · · · ·	05000311	YEAR	5		L		4	OF	4
SALEM	GENERATING STATION, UNIT 2		96		004		00			-
TEXT (If	nore space is required, use additional copies of NRC Forr	n 366A) <b>(17)</b>								
CORRE	CTIVE ACTIONS	, ;								
1.	The required survey was performe were noted.	d and no abnorm	al r	ad	liolog	ic	al co	ndi	tions	3
2.	The daily RP Survey Schedule was been placed on TS compensatory s they are now being performed onc	revised. Admi urveys of twent e per twelve ho	nist y fc urs	ra our (t	tive freq wice	co ue pe	ntrol ncy s r day	s ha uch ).	ave that	-
з.	The incident was discussed, as w Specification compliance, in two personnel.	ell as the impo daily informat	rtan ion	nce me	of T eting	ec. s	hnica with	l RP		
4.	Alarm clocks were purchased, sta coincide with administratively r	tioned in SRPT equired survey	offi time	.ce es.	and	pr	eset	to		
<u>5</u> .	Disciplinary action is being tak	en with personn	el i	.nv	rolved	i	n thi	s e	vent.	,
6.	The Technical Specification Surve 311/95-008) will ensure that adec surveillances are properly tracke completed by December 31, 1997.	eillance Improve quate processes ed. The project	emen exi : is	t st s	Proje to a chedu	ct ssi lec	(See are co d to d	LEF ondi oe	tion	al
			· ·							
							-			
-										
									,	
	· · · ·									
	·									
	· ·	· .					•		•	
	· ·									
	· .									

٦.