

Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038-0236

Nuclear Business Unit

MAY 0 9 1997

## LR-N97296

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

LER 272/96-038-01 SALEM GENERATING STATION - UNIT 1 FACILITY OPERATING LICENSE NO. DPR-70 DOCKET NO. 50-272

Gentlemen:

This Licensee Event Report (LER) entitled "Switchgear Penetration , Area Ventilation Cannot Maintain Design Temperatures" is being submitted as a Supplement to LER 96-038. This LER is submitted pursuant to the requirements of the Code of Federal Regulations 10CFR50.73(a)(2)(ii).

Sincerely,

David F. Garchow General Manager Salem Operations

Attachment

DVH

C Dis

Distribution LER File 3.7

9705190271 970509 PDR ADOCK 05000272 S PDR

## 190005

The power is in your hands.

I' XU

<u>.</u>											_						
NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION (4-95)						SSION	APPROVED BY OMB NO. 3150-0104										
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)							ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.										
FACILITY NAME (1) SALEM GENERATING STATION UNIT 1							DOCKET NUMBER (2) 05000272				PAGE (3) 1 OF 4						
TITLE (4 Switchg	<b>4)</b> ear F	Penetra	ation A	rea Ventilati	on C	Canr	not Mai	intain i	Desig	n Ter	np	peratu	res				
EVENT	DATE	<u>E (5)</u>	LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES IN				VOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NUM	ISION ABER	MONTH	DAY	YEAR	FACILITY NAME SALEM UNIT 2			05000311				
12	10	96	96	038	C	)1	05		97	FACILITY NAME			DOCKET NUMBER				
OPERAT	ING		THIS R	EPORT IS SUE	MIT	TED	PURSU	ANT TO	THE F	REQUI	RE	MENTS	BOF 10 CFR	§: (Ch	eck c	one or i	nore) (11)
MODE (	9)	N	20.2	2201(b)			20.2203	8(a)(2)(v	)			50.73(a	)(2)(i)			50.73(	a)(2)(viii)
POWER		000	20.2	20.2203(a)(1)			20.2203(a)(3)(i)			X 50.73(a)(2)(ii)				50.73(a)(2)(x)			
	10)		20.2203(a)(2)(i)				20.2203(a)(3)(ii)				50.73(a)(2)(iii)			73.71			
		20.2203(a)(2)(ii)			20.2203(a)(4)				50.73(a)(2)(iv)			_	OTHER				
		20.2203(8)(2)(11)			┿┥	50.36(c)(1)							or in NRC Form 366A				
			20.2	203(8)(2)(IV)	1107		50.30(C	1(4) (A OT =	00 71	DU. /3(8)(2)(VII)							
NAME Brian J.	Thor	nas, L	ER Co	ordinator								PHONE N	UMBER (Include / 609-	Ares Code 339-2	) 022		
		CO	MPLETE	ONE LINE FO	REA	CH (	COMPO	NENT F	AILUR	E DES	SCI	RIBED	IN THIS REP	<b>ORT (1</b>	3)		· · · · · · · · · · · · · · · · · · ·
CAUSE	SÝ	STEM	COMPON	ENT MANUFACT	JRER	REPO TO	NPRDS		CAU	SE	SYSTEM COMPONENT		MANUFACTURE		JRER	REPORTABLE TO NPRDS	
													·		<u> </u>		
													1			l	
		SUP	PLEME	NTAL REPORT	EXP	ECTI	ED (14)					EXP	ECTED	MONT	TH .	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE).						SUBMISSION DATE (15)											
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)																	
LER 96-	038-0	)0 detai	iled a co	ncern with sing	gle fa	ailure	of the l		al Pene	etratio	n E	Exhaus	t Fans. LEF	R 96-03	38-0	1 deta	ils ma
	s ider m (SF	PAV) s	uning a f vstem be	erformance. P	SE&	G de	o. Spece	ancany, ed that i	the SP	ya iev YAV sv	/ie/ /ste	emma	y not be able	e to ma	aintai	in the	minimum

Ventilation (SPAV) system performance, PSE&G determined that the SPAV system may not be able to maintain the minimum design bases temperatures during cold weather. Upon receipt of an accident signal, all three of the SPAV system supply fans would start, and may cause overcooling of the area. In addition, during the review of the SPAV system, dampers that are designed to isolate the area upon  $CO_2$  injection for fire suppression, were noted to fail close on a loss of power. Closure of the  $CO_2$  lsolation dampers upon loss of power could cause a loss of ventilation to the switchgear room, and potentially result in the area temperatures exceeding design temperatures.

The cause of this occurrence is that the SPAV system failure modes were not properly established and evaluated during the initial plant design. The interim corrective actions are to install temporary modifications to ensure design temperatures can be maintained. The Switchgear room temperatures are being monitored to ensure that design temperatures are not exceeded. These interim corrective actions will be in place until permanent corrective actions are installed. The SPAV control logic and the  $CO_2$  isolation damper logic will be revised to ensure that area temperatures can be maintained within design limits. This condition is reportable in accordance with 10 CFR 50.73(a)(2)(ii)(A), any event or condition that resulted in the nuclear power plant being operated outside the design bases.

NRC FORM 366A (4-95)		U.S. NUCLEAR REGULATO	RY COMMISSION					
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION								
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)					
SALEM GENERATING STATION UNIT 1	05000272	year sequential revision number 96 038 01	2 OF 4					
TEXT (If more space is required, use additional copies of NRC Form	n 366A) <b>(17)</b>	لب <u></u>	<u> </u>					
PLANT AND SYSTEM IDENTIFICATION								
Westinghouse - Pressurized Water Reactor								
Switchgear Ventilation System {VF/-}* DC Power {EJ/-} Low Voltage Power System {EC/-}	· · · · ·							
* Energy Industry Identification System (EIIS) codes (SS/CC)	and component fun	ction identifier codes app	bear as					
CONDITIONS PRIOR TO OCCURRENCE								
At the time of identification, Salem Unit 1 was defue was in progress for the Switchgear Penetration Area	led and Unit 2 was in Ventilation (SPAV)	n Mode 5. Post modifica system modification.	tion testing					
DESCRIPTION OF OCCURRENCE								
During a design review of the Switchgear Penetration PSE&G determined that the potential existed for a s {VF/FAN} to place the unit in an unanalyzed condition provide 50 percent of the exhaust flow from the pen- higher than analyzed temperatures in the Electrical centers for the three trains of safety-related, motor-or required instrumentation.	on Area Ventilation (S single failure of the E on. The two Electrica etration areas. The Penetration area, who perated valves and	SPAV) {VF/-} system performed lectrical Penetration Exh al Penetration Exhaust F failure of one fan could r nich contains the motor c other Technical Specific	iormance, aust Fans ans each esult in ontrol ation					
The SPAV system is currently designed to maintain within the areas served, with outdoor ambient condition respectively. The maximum design temperature was	year-round tempera tions of 0 degrees F s recently increased	tures between 65 and 11 winter and 95 degrees F to 110 degrees from 105	0 degrees F summer, 5 degrees F.					
The potential for a single failure of the Electrical Per condition was previously detailed in Revision 0 to LE recently identified concerns with the SPAV system: Auxiliary Control (MAC) 11 panel failure for Unit 1 or	netration Exhaust far ER 96-038. Revisior 1) overcooling and 2 r a MAC 21 panel fai	n to place the unit in an u n 1 to LER 96-038 will de n) overheating on a Misce lure for Unit 2.	inanalyzed tail two Ilaneous					
Overcooling								
During Post Modification Testing for recently completed SPA performance, PSE&G determined that the SPAV system ma cold weather conditions. Upon receipt of a Safeguards Equi start) all three of the SPAV system supply fans would start. A temperatures, area temperatures could drop below the desi	V system modifications ay not be able to mainta pment Cabinet (SEC) s With all three supply fan gn minimum temperatu	and review of the SPAV sys in the minimum design temp ignal (i.e., an Engineered Sa s running, and cold outside a re of 65 degrees F.	tem eratures during fety Feature ir					
	. •							

NRC FORM 366A	<u></u>	U.S. NUCLEAR REGULATO	RY COMMISSION
	ENT REPORT (LI	ER)	
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
SALEM GENERATING STATION UNIT 1	05000272	YEAR SEQUENTIAL REVISION NUMBER NUMBER 96 038 01	3 OF 4
TEXT (If more space is required, use additional copies of NRC Form	n 366A) <b>(17)</b>	l	L
DESCRIPTION OF OCCURRENCE (cont'd)	·	. •	
Overheating on MAC 11/21 panel failure			
During the review of the SPAV system, dampers that are de noted to fail close on a loss of power. This loss of power cou temperatures exceeding design temperatures.	signed to isolate upon ( uld cause a loss of venti	CO <sub>2</sub> injection for fire suppress lation, and potentially result ir	ion, were also narea
Specifically, there are six CO <sub>2</sub> Isolation dampers in each unit fire. The control power for these CO <sub>2</sub> Isolation dampers s is Unit 2. A failure of the MAC 11 panel or the MAC 21 panel v closing of these CO <sub>2</sub> Isolation dampers would interrupt ventile design temperatures.	that are designed to do supplied by the MAC 1 <sup><math>\circ</math></sup> would cause the CO <sub>2</sub> lso ation air flow and could	ose, to control CO <sub>2</sub> flooding in 1 panel for Unit 1, and the MA plation dampers for that unit to result in the area temperatur	the event of a AC 21 panel for o dose. The es exceeding
CAUSE OF OCCURRENCE			
The cause of this occurrence is that the SPAV syste evaluated during the initial plant design, and the imp considered. Damper closure was assessed in terms suppression system in response to 10 CFR 50 Appe	em failure modes we bact of the damper c s of supporting the a endix R concerns.	re not properly establishe losure due to loss of pow utomatic initiation of the	ed and ver was not CO₂
PRIOR SIMILAR OCCURRENCES			
LER 272/95-008-00 reported a similar concern of ex Penetration Supply Fans were operable. This occur LER corrective actions addressed the supply fans a	cceeding 105 degree rrence was caused b nd did not address t	es if only one of the three by the failure of two of the he exhaust fans.	e Electrical e supply fans.
In the past two years there were eleven LERs that a are 272/95-014-00, 272/95-020-00, 272/95-029-00, 018-00, 272/96-019-00, 272/96-020-00, 272/96-034 LERs were specific to the particular issue. As stated assurance that Salem stations are being operated in	addressed design de 272/96-001-00, 272 4-00 and 272/96-037 d in the 50.54(f) resp n accordance with th	ficiencies as the cause. /96-010-00, 272/96-012- 7-00. Corrective actions ponse, PSE&G has reaso eir design bases	These LERs 00, 272/96- for these onable
		· ·	

. .

.

NRC FORM 366A		U.S. NUCLEAR REGULATO	RY COMMISSION						
(4-95) LICENSEE EVENT REPORT (LER) TEXT CONTINUATION									
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)						
	05000272	YEAR SEQUENTIAL REVISION NUMBER NUMBER	4 OF 4						
SALEM GENERATING STATION UNIT 1		96 038 01							
TEXT (If more space is required, use additional copies of NRC Forr	n 366A) (17)								
SAFETY CONSEQUENCES AND IMPLICATIONS	•								
Overcooling									
The overcooling of the Switchgear rooms would occur only with extremely low outside air temperatures, and would be a concern with the "C" 125 Vdc battery room. The "C" 125 Vdc battery room has a non-safety related heater installed. While the heater could not be relied upon to maintain temperatures above 65 degrees F, the heater would most likely prevent the room from falling below design temperature. Further, the plant is designed with sufficient redundant DC power sources to safely shutdown with the failure of the "C" 125 Vdc batteries. In addition, other equipment in the area may be adversely effected.									
Overheating on MAC 11/21 Panel failure									
The maximum room temperature with the $CO_2$ Isolation dampers closed has been preliminary determined to exceed 110 degrees. The maximum room temperature has not been determined, but some safety related equipment may be adversely impacted. The loss of the MAC 11/21 panel is indicated in the Control Room. The Control Room response includes notifying the fire protection personnel. To mitigate the elevated room temperatures, the $CO_2$ Isolation dampers would have to be opened, or the room doors opened.									
The health and safety of the public was not affected	d.								
CORRECTIVE ACTIONS									
1. A design review of the SPAV system in response to LER 96-038-00 has been completed. This review identified the concerns addressed in this LER.									
2. A 10CFR50.59 Evaluation was completed to inc	crease the maximum	design temperature to 1	10 degrees.						
<ol> <li>Administrative controls to address removal from service of an Electrical Penetration Exhaust Fan will be implemented prior to Salem Unit 2 entering Mode 4. The outside air intake dampers were modified to enable them to fully close to preclude reducing area temperatures to below acceptable design minimums.</li> </ol>									
<ol> <li>A modification to the supply fan start logic, and that the minimum design temperature is maintai both Units by May 31, 1997.</li> </ol>	the outside supply danged. This modification	ampers will be implemen on is scheduled to be co	ted to ensure mpleted for						
<ol> <li>As an interim corrective action, the Switchgear in that the maximum design temperature is not explicitly increases in the area.</li> </ol>	room temperature is ceeded, and controls	being routinely monitore are in place to limit tem	d to ensure perature						
<ol> <li>As a permanent corrective action, a modification for both Units Unit by May 31, 1997.</li> </ol>	n to the CO₂ damper	logic is scheduled to be	completed						

NRC FORM 366A (4-95)