

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: N.C. Moseley

FROM: Florida Power & Light Co.
Miami, Florida
A.D. Schmidt

DATE OF DOCUMENT
4-12-76

DATE RECEIVED
4-22-76

LETTER NOTORIZED
 ORIGINAL UNCLASSIFIED
 COPY

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
30

DESCRIPTION

Ltr. trans the following.....

ENCLOSURE

Licensee Event Report (R.O # 76-9) on 3-31-76
Concerning defective mechanical pipe restraints
(30 Carbon Cys. Received)

**DO NOT REMOVE
ACKNOWLEDGED**

PLANT NAME: St. Lucie # 1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

SAB 4-22-76

BRANCH CHIEF: Ziemann
W/3 CYS FOR ACTION
LIC. ASST: Diggs
W/ CYS
ACRS 16 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

REG FILE
NRC PDR
I & E (2)
MIPC (3)
SCHROEDER/IPPOLITO
HOUSTON
NOVAK/CHECK
GRIMES/SCHWENCER
CASE
E. WILLIAMS
HANAUER
TEDESCO/MACCARY
EISENHUT
BAER
SHAO
VOLLMER/BUNCH
KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: Ft. Pierce, Florida.
TIC
NSIC

CONTROL NUMBER

4014

1954

George Washington University
Washington, D.C.

N.C. Wesleyan
Wesleyan University
Fletcher School of Law
Durham, N.C.

Dear Sir:

Re:

.....

Enclosed for you are two copies of a report on the activities of the Communist Party in the Washington area during the past year.

(The report is being furnished to you for your information.)

Very truly yours,

W. J. ...

W. J. ...

Very truly yours,

W. J. ...

W. J. ...

W. J. ...


W. J. ...

W. J. ...


W. J. ...

Regulatory

File Cy



April 12, 1976
PRN-LI-76-77



Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N.W., Suite 818
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-9
ST. LUCIE UNIT I
DATE OF OCCURRENCE: MARCH 31, 1976
DEFECTIVE MECHANICAL PIPE RESTRAINTS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide prompt notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
Vice President
Power Resources

MAS/jn

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (40)
Director, Office of Management Information and
Program Control (3)

4014



1846

1846

CONTROL BLOCK: [] [] [] [] [] [] [] []

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSE NAME

LICENSE NUMBER

LICENSE TYPE

EVENT TYPE

[01] F L S L S 1 | 0 0 - 0 0 0 0 0 0 | - 0 0 | 4 1 1 1 1 | 0 1

CATEGORY

REPORT TYPE

REPORT SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

[01] CONT | T | L | 0 5 0 - 0 3 3 5 | 0 3 3 1 7 6 | 0 4 1 2 7 6

EVENT DESCRIPTION

[02] Preoperational testing of piping restraints (snubbers) was being performed during the heatup for Post Core Hot Functional testing. At the 260°F heatup plateau, five mechanical snubbers were found to be locked up. The immediate action was to promptly replace the defective snubbers with operable snubbers. This was the first occurrence of this type. (335-76-9).

SYSTEM CODE

CAUSE CODE

COMPONENT CODE

PRIME COMPONENT SUPPLIER

COMPONENT MANUFACTURER

VIOLATION

[07] Z Z | B | H A N G E R | A | B 2 1 0 | N

CAUSE DESCRIPTION

[08] The five defective snubbers were Model MSVA-1 snubbers. Two of the defective snubbers were disassembled on site by a manufacturer's representative. It was found

FACILITY STATUS

% POWER

OTHER STATUS

METHOD OF DISCOVERY

DISCOVERY DESCRIPTION

[11] B | 0 0 0 | NA | C | Preoperational test procedure

FORM OF ACTIVITY RELEASED

CONTENT OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

[12] Z | Z | NA | NA

PERSONNEL EXPOSURES

NUMBER

TYPE

DESCRIPTION

[13] 0 0 0 | Z | NA

PERSONNEL INJURIES

NUMBER

DESCRIPTION

[14] 0 0 0 | NA

PROBABLE CONSEQUENCES

[15] NA

LOSS OR DAMAGE TO FACILITY

TYPE

DESCRIPTION

[16] Z | NA

PUBLICITY

[17] NA

ADDITIONAL FACTORS

[18] See Page Two for continuation of Cause Description.

[19]

Cause Description (continued)

that moisture had caused oxidation of internal carbon steel parts which had then caused the snubbers to lock. Followup action was to send the other three snubbers to the manufacturer for laboratory testing and analysis. A followup report will be prepared and submitted upon completion of the investigation.

The five defective snubbers were found in the following order:

<u>S/N</u>	<u>Location</u>	<u>Date</u>
000377	RC-142	3/31 (disassembled on site)
000343	RC-142	3/31
000525	RC-142	4/1
000695	CH-142	4/1 (disassembled on site)
000632	CH-142	4/2

