

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: N.C. Moseley

FROM: Florida Power & Light Co.
Miami, Florida
A.D. Schmidt

DATE OF DOCUMENT
4-9-76

DATE RECEIVED
4-22-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
30

DESCRIPTION

Ltr. trans the following.....

ENCLOSURE

Licensee Event Report (R.O.# 76-5) on 3-10-76
Concerning Containment Area Radiation Monitoring
Instrumentation two inoperable channels.

(30 Carbon Cys. Received)

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: St. Lucie #1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

SAB 4-22-76

BRANCH CHIEF:	Ziemann
W/3 CYS FOR ACTION	
LIC. ASST:	Diggs
W/ CYS	
ACRS 16 CYS	HOLDING SENT TO LA

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE	
<input type="checkbox"/> NRC PDR	
<input type="checkbox"/> I & E (2)	
<input type="checkbox"/> MIPC (3)	
<input type="checkbox"/> SCHROEDER/IPPOLITO	
<input type="checkbox"/> HOUSTON	
<input type="checkbox"/> NOVAK/CHECK	
<input type="checkbox"/> GRIMES/SCHWENCER	
<input type="checkbox"/> CASE	
<input type="checkbox"/> F. WILLIAMS	
<input type="checkbox"/> HANAUER	
<input type="checkbox"/> TEDESCO/MACCARY	
<input type="checkbox"/> EISENHUT	
<input type="checkbox"/> BAER	
<input type="checkbox"/> SHAO	
<input type="checkbox"/> VOLLMER/BUNCH	
<input type="checkbox"/> KREGER/J. COLLINS	

EXTERNAL DISTRIBUTION

LPDR: Ft. Pierce, Florida	
TIC	
NSIC	

CONTROL NUMBER

3996



.....

.....

.....

.....

.....

.....


.....

.....

.....


Regulatory

File Cy.



April 9, 1976

PRN-LI-76-73



Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-5
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: MARCH 10, 1976

CONTAINMENT AREA RADIATION MONITORING INSTRUMENTATION-
TWO INOPERABLE CHANNELS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

J.R. Bensen
for A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME:

01	F	L	S	L	S	1
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

0	3
---	---

CONT:

0	1
---	---

 CATEGORY:

--	--

 REPORT TYPE:

L

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	3	3	5
---	---	---	---	---	---	---	---

 EVENT DATE:

0	3	1	0	7	6
---	---	---	---	---	---

 REPORT DATE:

0	4	0	9	7	6
---	---	---	---	---	---

EVENT DESCRIPTION

02 | During initial core loading, power was lost to the Channel C containment
03 | area radiation monitoring instrumentation. At the time, ESFAS Channel A
04 | was out of service for implementation of a plant change/modification.
05 | This meant that 2 of the 4 containment area radiation monitoring channels
06 |

SYSTEM CODE:

B	A
---	---

 CAUSE CODE:

A

 COMPONENT CODE:

I	N	S	T	R	U
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

A

 COMPONENT MANUFACTURER:

V	1	1	5
---	---	---	---

 VIOLATION:

N

CAUSE DESCRIPTION

08 | This occurrence was caused by a loose electrical connection. The
09 | electrical connection was loose because of improper landing of a
10 | termination. Corrective action was to land the termination correctly.

FACILITY STATUS:

B

 % POWER:

0	0	0
---	---	---

 OTHER STATUS:

NA

 METHOD OF DISCOVERY:

a

 DISCOVERY DESCRIPTION:

NA

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

NA

 LOCATION OF RELEASE:

NA

PERSONNEL EXPOSURES

13 | NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

NA

PERSONNEL INJURIES

14 | NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

NA

PROBABLE CONSEQUENCES

15 |

NA

LOSS OR DAMAGE TO FACILITY

16 | TYPE:

Z

 DESCRIPTION:

NA

PUBLICITY

17 |

NA

ADDITIONAL FACTORS

18 | See Page Two for continuation of Event Description and Cause
19 | Description.

NAME: M. A. Schoppman PHONE: 305/552-3779

REPORTABLE OCCURRENCE 335-76-5
LICENSEE EVENT REPORT
PAGE TWO

EVENT DESCRIPTION (Continued)

were not available. This is contrary to Technical Specification 3.3.3.1. The immediate action was to attempt to restore power to the Channel C instrumentation and to initiate the followup action required by Specification 3.3.3.1. Power was restored quickly, so it was not necessary to complete the followup action. This was the first occurrence of this type. (335-76-5).

CAUSE DESCRIPTION (Continued)

Followup action was to check other circuits for loose terminations. No other loose connections were found.