

50-335

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER  
INCIDENT REPORT

TO:  
MR N C MOSELEY

FROM: FLORIDA POWER & LIGHT CO  
MIAMI, FLA....  
A D SCHMIDT

DATE OF DOCUMENT  
3-18-76

DATE RECEIVED  
3-26-76

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 Signed

DESCRIPTION

LTR TRANS THE FOLLOWING.....

PLANT NAME: ST. LUCIE

ENCLOSURE


LICENSEE EVENT REPORT 50-335/76-3 ON  
3-8-76 RE ESFAS CIRCUITRY DESIGN ERROR THAT  
CAUSED LOSS OF POWER CAUSING SIGNALS TO GO  
TO THE BYPASS MODE....

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY	FOR ACTION/INFORMATION	ENVIRO
BRANCH CHIEF: PAAR		4-2-76 RIS
W/3 CYS FOR ACTION		
LIC. ASST: WILSON		
W/ CYS		
ACRS CYS HOLDING/SENT TO LA		

INTERNAL DISTRIBUTION	
<input checked="" type="checkbox"/> REG FILE	
<input checked="" type="checkbox"/> NRC PDR	
<input checked="" type="checkbox"/> I & E (2)	
<input checked="" type="checkbox"/> MIPC (3)	
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO	
<input checked="" type="checkbox"/> HOUSTON	
<input checked="" type="checkbox"/> NOVAK/CHECK	
<input checked="" type="checkbox"/> GRIMES/SCHWENGER	
<input checked="" type="checkbox"/> CASE	
<input checked="" type="checkbox"/> F. WILLIAMS	
<input checked="" type="checkbox"/> HANAUER	
<input checked="" type="checkbox"/> TEDESCO/MACCARY	
<input checked="" type="checkbox"/> EISENHUT	
<input checked="" type="checkbox"/> BAER	
<input checked="" type="checkbox"/> SHAO	
<input checked="" type="checkbox"/> VOLLMER/BUNCH	
<input checked="" type="checkbox"/> KREGER/J. COLLINS	

EXTERNAL DISTRIBUTION	CONTROL NUMBER
<input checked="" type="checkbox"/> LPDR: FT PIERCE, FL.	3085
<input checked="" type="checkbox"/> TIC	
<input checked="" type="checkbox"/> NSIC	



100  
100  
100

50

100

100

100

100  
100


100

100

Regulatory Docket File



March 18, 1976



Mr. Norman C. Moseley, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 818  
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-3  
ST. LUCIE UNIT 1  
DATE OF OCCURRENCE: MARCH 8, 1976

DESIGN ERROR IN ENGINEERED SAFETY  
FEATURES ACTUATION SYSTEM

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.6.1.a to provide prompt notification of the subject occurrence.

Very truly yours,

*A. D. Schmidt*  
A. D. Schmidt.  
Vice President  
Power Resources


MAS/cpc

Attachment

cc: Jack R. Newman, Esquire  
Director, Office of Inspection and Enforcement (40)  
Director, Office of Management Information and  
Program Control (3)

3085

43



# LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER										LICENSE TYPE					EVENT TYPE						
01	F	L	S	L	S	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1			
7	8	9	14	15	25	26	30	31	32																		
01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER					EVENT DATE				REPORT DATE								
01						T	L	0	5	0	-	0	3	3	5	0	3	0	8	7	6	0	3	1	8	7	6
7	8	57	58	59	60	61	68	69	74	75																	

### EVENT DESCRIPTION

02	During preoperational core loading, an engineering review by the FPL General Office																											80
03	Engineering Staff indicated that upon loss of power all ESFAS signals would go to the																											80
04	bypass mode, whereas only the CSAS and RAS signals should do so. FSAR Section 7.3.1.4																											80
05	requires that signals other than CSAS and RAS go to the trip mode upon loss of power.																											80
06	This is the first occurrence of this type. (335-76-3).																											80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION	
07	I	B	B	I	N	S	T	R	U	A	C	5	6	0	N
7	8	9	10	11	12	17	43	44	47	48					

### CAUSE DESCRIPTION

08	This occurrence was caused by an ESFAS circuitry design error. All ESFAS signals were																											80
09	wired to go to the bypass mode upon loss of power. Circuit modifications are being																											80
10	made to comply with FSAR Section 7.3.1.4 and will be completed before entering																											80

FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION						
11	B	0	0	0	NA	c	Engineering review of ESF circuitry									
7	8	9	10	12	13	44	45	46								

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE						
12	Z	Z	NA	NA											
7	8	9	10	11	44	45									

### PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION														
13	0	0	0	Z	NA													
7	8	9	11	12	13													

### PERSONNEL INJURIES

NUMBER		DESCRIPTION															
14	0	0	0	NA													
7	8	9	11	12													

### PROBABLE CONSEQUENCES

15	NA																											80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

### LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																										
16	Z	NA																										
7	8	9	10																									

### PUBLICITY

17	NA																											80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

### ADDITIONAL FACTORS

18	Cause Description (Cont.): Technical Specification mode 4.																											80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																												80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: M. A. Schoppman

PHONE: (305) 552-3779

