

50-335

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: Mr Moseley

FROM: Florida Pwr & Light Co
Miami, Fla
A D Schmidt

DATE OF DOCUMENT
6-24-76

DATE RECEIVED 7-8-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
none/sighted/ 1CC

DESCRIPTION

Ltr trans the following:

ENCLOSURE

Licensee Event Report (RO#76-24) on 5-24-76
concerning failure of primary makeup water
containment isolation valve.....

**Do Not Remove
ACKNOWLEDGED**

PLANT NAME: St Lucie #1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

7-9-76

ehf

BRANCH CHIEF: *Ziemann*
W/3 CYS FOR ACTION
LIC. ASST.: *Diggs*
W/1 CYS
ACRS 16 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

~~REG FILE~~
NRC PDR
I & E (2)
MIPC
SCHROEDER/IPPOLITO
HOUSTON
NOVAK/CHECK
GRIMES
CASE
BUTLER
HANAUER
TEDESCO/MACCARY
EISENHUT
BAER
SHAO
VOLLNER/BUNCH
KREGER/J. COLLINS


EXTERNAL DISTRIBUTION

LPDR: Ft Pierce, Fla
TIC:
NSIC:

CONTROL NUMBER

6836


Regulatory Docket File



June 24, 1976

PRN-LI-76-160

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303



Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-24
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: MAY 24, 1976

PRIMARY MAKEUP WATER
CONTAINMENT ISOLATION VALVE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

for J.R. Bensen
A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

6836

LICENSEE EVENT REPORT

Regulatory Docket File
(PLEASE PRINT ALL REQUIRED INFORMATION)

CONTROL BLOCK:

Received w/Ltr Dated 6.24.76

LICENSEE NAME: **01** | F | L | S | L | S | 1 | 14 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 25 | 4 | 1 | 1 | 1 | 1 | 30 | 0 | 3 | 32

REPORT TYPE: **01** | CONT | CATEGORY: | | 57 | 58 | REPORT SOURCE: **L** | **L** | 59 | 60 | DOCKET NUMBER: 0 | 5 | 0 | - | 0 | 3 | 3 | 5 | 68 | EVENT DATE: 0 | 5 | 2 | 4 | 7 | 6 | 74 | REPORT DATE: 0 | 6 | 2 | 4 | 7 | 6 | 80

EVENT DESCRIPTION

02 | During preoperational testing, remotely operated containment isolation
03 | valve I-MV-15-1 (primary makeup water) would not close automatically
04 | which is contrary to Technical Specification 3.6.3.1. The primary
05 | makeup to containment was stopped, and the valve was deenergized and
06 | manually closed. It was found that the valve would not close automatically.

SYSTEM CODE: **07** | W | C | 9 | 10 | CAUSE CODE: **A** | 11 | COMPONENT CODE: V | A | L | V | E | X | 12 | 17 | PRIME COMPONENT SUPPLIER: **A** | 43 | COMPONENT MANUFACTURER: L | 2 | 0 | 0 | 44 | 47 | VIOLATION: **N** | 48

CAUSE DESCRIPTION

08 | This occurrence was caused by dirty contacts on a torqueswitch. The con-
09 | tacts were cleaned and valve I-MV-15-1 was returned to service.

10 |

FACILITY STATUS: **11** | B | 9 | % POWER: 0 | 5 | 0 | 10 | 12 | OTHER STATUS: N/A | 13 | METHOD OF DISCOVERY: a | 44 | 45 | DISCOVERY DESCRIPTION: N/A | 46 | 80

FORM OF ACTIVITY RELEASED: **12** | Z | 9 | CONTENT OF RELEASE: Z | 10 | AMOUNT OF ACTIVITY: N/A | 11 | 44 | LOCATION OF RELEASE: N/A | 45 | 80

PERSONNEL EXPOSURES

13 | NUMBER: 0 | 0 | 0 | 11 | TYPE: Z | 12 | DESCRIPTION: N/A | 13 | 80

PERSONNEL INJURIES

14 | NUMBER: 0 | 0 | 0 | 11 | DESCRIPTION: N/A | 12 | 80

PROBABLE CONSEQUENCES

15 | N/A | 80

LOSS OR DAMAGE TO FACILITY

16 | TYPE: Z | 9 | DESCRIPTION: N/A | 10 | 80

PUBLICITY

17 | N/A | 80

ADDITIONAL FACTORS

18 | See Page Two for continuation of Event Description. | 80

19 |

REPORTABLE OCCURRENCE 335-76-24
LICENSEE EVENT REPORT
PAGE TWO

Event Description (continued)

because of dirty contacts on a torqueswitch in the control circuitry. The contacts were cleaned and valve I-MV-15-1 was operated satisfactorily. This was the first occurrence of this type. (335-76-24).