

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER 50-335
INCIDENT REPORT

TO: N.C. Moseley

FROM: Florida Power & Light Co.
Miami, Florida
A.D. Schmidt

DATE OF DOCUMENT
6-14-76

DATE RECEIVED
7-8-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
1

DESCRIPTION

Ltr. trans the following.....

ENCLOSURE

Licensee Event Report (R.O. # 76-23) on 5-24-76
Concerning Temperature Indication Hot ShutDown
Control Panel.....

(1 Carbon Signed Cy. Received)
(3 Pages)

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: St. Lucie # 1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED,
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

SAB 7-10-76

BRANCH CHIEF:

Ziemann

W/3 CYS FOR ACTION

LIC. ASST:

Diggs

W/ CYS

ACRS 16 CYS. ~~XXXXXX~~/SENT TO LA

INTERNAL DISTRIBUTION

REG FILE

NRG-PDR

I & E (2)

MIPC (3)

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES/

CASE

Butler

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLNER/BUNCH

KREGER/J. COLLINS

Deuze

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: Ft. Pierce, Fla.

TIC

NSIC

6837

100-100000

100-100000

100-100000

1

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000


100-100000

100-100000

100-100000

Regulatory


File Cy



FLORIDA POWER & LIGHT COMPANY

June 24, 1976

PRN-LI-76-159



Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-23
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: MAY 24, 1976

HOT SHUTDOWN CONTROL PANEL
TEMPERATURE INDICATION

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

JR Bensen
A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME:

01	F	L	S	L	S	1
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

0	3
---	---

CATEGORY:

01	CONT
----	------

 REPORT TYPE:

L

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	3	3	5
---	---	---	---	---	---	---	---

 EVENT DATE:

0	5	2	4	7	6
---	---	---	---	---	---

 REPORT DATE:

0	6	2	4	7	6
---	---	---	---	---	---

EVENT DESCRIPTION

02

 During performance of a surveillance test on the hot shutdown control panel (HSCP), it was found that the cold leg temperature indication for reactor coolant loop 1A1 was not correct. Indicated temperature at the HSCP was 555 degrees F while the correct reading as indicated in the Control Room was 536 degrees F. The temperature instrumentation

SYSTEM CODE:

I	F
---	---

 CAUSE CODE:

A

 COMPONENT CODE:

I	N	S	T	R	U
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

A

 COMPONENT MANUFACTURER:

S	1	8	5
---	---	---	---

 VIOLATION:

N

CAUSE DESCRIPTION

08

 This occurrence was caused by the HSCP reactor coolant temperature indication being out of calibration. No defective components were found.

FACILITY STATUS:

B

 % POWER:

0	5	0
---	---	---

 OTHER STATUS:

N/A

 METHOD OF DISCOVERY:

b

 DISCOVERY DESCRIPTION:

N/A

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

N/A

 LOCATION OF RELEASE:

N/A

PERSONNEL EXPOSURES

NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

N/A

PERSONNEL INJURIES

NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

N/A

PROBABLE CONSEQUENCES

15

N/A

LOSS OR DAMAGE TO FACILITY

TYPE:

Z

 DESCRIPTION:

N/A

PUBLICITY

17

N/A

ADDITIONAL FACTORS

18

 See Page Two for continuation of Event Description.

19

REPORTABLE OCCURRENCE 335-76-23
LICENSEE EVENT REPORT
PAGE TWO

Event Description (continued)

associated with the HSCP was calibrated and the surveillance test was completed satisfactorily. This was the first occurrence of this type. (335-76-23).