

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO:
MR. NORMAN C. MOSELEY

FROM:
FLORIDA POWER & LIGHT COMPANY
MIAMI, FLORIDA
A. D. SCHMIDT

DATE OF DOCUMENT
5/18/76

DATE RECEIVED
5/27/76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
NONE SIGNED

DESCRIPTION

LTR. TRANS THE FOLLOWING:

PLANT NAME:
ST LUCIE #1

(1-P)

ENCLOSURE

LICENSEE EVENT RPT. (RO 50-335/76-14) ON 4/18/76 CONCERNING THE OUTER PERSONNEL ACCESS DOOR TO CONTAINMENT WHICH WOULD NOT PASS THE AIR LEAKAGE TEST.

ACKNOWLEDGED

DO NOT REMOVE

(2-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

5/27/76

RJL

BRANCH CHIEF: ZIEMANN

W/3 CYS FOR ACTION

LIC. ASST: DIGGS

W/1 CYS

ACRS 16 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIRC (3)

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES/SCHWENCER (1) EA

CASE

E. WILLIAMS

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: FT. PIERCE, FLA.

TIC

NSIC

CONTROL NUMBER

5324

100-100000

100-100000

100-100000

100-100000


100-100000

100-100000

100-100000

100-100000


100-100000



May 18, 1976

PRN-LI-76-122

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 818
Atlanta, Georgia 30303



Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-14
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: APRIL 18, 1976

PERSONNEL AIRLOCK

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

for J.R. Bensen
A. D. Schmidt
Vice President
Power Resources


Regulatory Docket File



MAS/cpc

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)



LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME				LICENSE NUMBER								LICENSE TYPE				EVENT TYPE							
01	F	L	S	L	S	1	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	0	3
7	8	9				14	15					25	26				30				31	32	

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE											
01	CONT	L	L	0	5	0	-	0	3	3	5	0	4	1	8	7	6	0	5	1	8	7	6
7	8	57	58	59	60	61					68	69					74	75					80

EVENT DESCRIPTION

02	At one point during preoperational testing, the outer personnel access																						80
03	door to containment would not pass the air leakage test. The door would																						80
04	not latch properly because of a misaligned latching device. The latching																						80
05	device was repaired, and the outer airlock door was satisfactorily leak																						80
06	tested and returned to service within 24 hours as required by Technical																						80

SYSTEM CODE	CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION				
07	S	A	E	P	E	N	E	T	R	A	C	3	1	0	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	The cause of the occurrence was a bent holding pin in the door latching																						80
09	device. The pivot arm in the latching device became loose, causing the																						80
10	device to misalign and bend the holding pin. The door would not latch																						80

FACILITY STATUS	% POWER	OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION							
11	B	0	0	0	N/A	b	N/A							
7	8	9	10	12	13	44	45						46	80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY			LOCATION OF RELEASE										
12	Z	Z	N/A			N/A									
7	8	9	10										44	45	80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION				
13	000	Z	N/A			
7	8	9	11	12	13	80

PERSONNEL INJURIES

NUMBER	DESCRIPTION				
14	000	N/A			
7	8	9	11	12	80

PROBABLE CONSEQUENCES

15	N/A	80
----	-----	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION			
16	Z	N/A		
7	8	9	10	80

PUBLICITY

17	N/A	80
----	-----	----

ADDITIONAL FACTORS

18	See Page Two for continuation of Event Description and Cause Description																						80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																							80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: M. A. Schoppman

PHONE: 305/552-3779

REPORTABLE OCCURRENCE 335-76-14
LICENSEE EVENT REPORT.
PAGE TWO

EVENT DESCRIPTION (Continued)

Specification 3.6.1.3. The inner door was kept closed the entire time that the outer door was out of service. This was the first occurrence of this type. (335-76-14).

CAUSE DESCRIPTION (Continued)

tightly while the holding pin was bent. It is believed that the pivot arm became loose because of slamming of the access door or because of the high frequency of airlock usage necessitated by preparations for initial criticality. Signs have been posted which instruct personnel to operate the airlock doors carefully.