

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	A	S	P	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

0	1	REPORT SOURCE															DOCKET NUMBER															EVENT DATE															REPORT DATE														
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																																							
		L	6	0	5	0	0	0	2	8	0	7	1	1	1	5	7	8	8	1	2	1	1	7	8	9																																			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	During normal operation, Channel I of the Pressurizer Level (Protection) Instrumen-
---	---	---

03 | tation, LI-1-459, drifted low. This is contrary to Technical Specifications 3.7.B

0	4
---	---

 and is reportable per Technical Specifications 6.6.2.b. (1).

05

0	6	
---	---	--

07

08

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
----------------	---------------	------------------	----------------	------------------	------------------

7 8 9 10 11 12 13 14 15 16 17 18 19 20

(17) LER/RO NUMBER 7 8 — 0 3 9 / 0 3 L — 0
 EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTUR		
E	18	E	19	Z	20	Z	21	0	0	0	0	Y	23	Y	24	N	25	I 2 0
33		34		35		36		37		40		41		42		42		44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of this event is not known at this time. Channel I Pressurizer Level was

11 placed in the trip mode. The transmitter was recalibrated monitored and later returned

12 | to service.

1 3

1 4

FACILITY STATUS	% POWER	OTHER STATUS	(30) METHOD OF DISCOVERY	DISCOVERY DESCRIPTION	(32)

1 5 E (28) 1 0 0 (29) NA A (31) Operator Observation

ACTIVITY		CONTENT		AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1	6	7	23		
1	6	7	23	NA	NA

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION
1	7	0	0	(39) NA

8	9	11	12	13
PERSONNEL INJURIES				
NUMBER		DESCRIPTION (41)		
01	01	NA		

1	8	0	0	0	40	NA
7	8	9	11	12	LOSS OF OR DAMAGE TO FACILITY 13	

TYPE		DESCRIPTION
1	9	Z (42) NA

8 9 10 PUBLICITY
ISSUED DESCRIPTION (45) NRC USE ONLY

NRC USE ONLY

7812140126
NAME OF PREPARATION

T. L. Baucom

PHONE-

(804) 357-3184

017-928

Surry Power Station, Unit 1
Docket No: 50-280
Report No: 78-039/03L-0
Event Date: 11-15-78

Title of Report: Drift in Pressurizer Level Channel

1. Description of Event:

During normal operation, Channel I of the Pressurizer Level (Protection) Instrumentation, LI-1-459, drifted 5% low. This exceeded the margin between Technical Specifications and the administrative limit by 1% and resulted in the inability of this channel to supply a reliable signal of high pressurizer level to the Reactor Trip logics. The required degree of redundancy was not maintained and this is contrary to Technical Specifications 3.7.B and is reportable per Technical Specifications 6.6.2.b.(1).

2. Probable Consequences and Status of Redundant Systems:

Channel I Pressurizer Level was put in the trip mode. All other pressurizer level instrumentation remained operable. Because the required immediate corrective action was taken and the degree of redundancy regained, the health and safety of the general public were not affected.

3. Cause:

It is not known at this time what is causing this intermittent drift of the transmitter's electronics. The results of further investigation will be reported in a supplemental report.

4. Immediate Corrective Action:

Channel I of Pressurizer Level was immediately placed in the trip mode. This regained the required degree of redundancy.

5. Subsequent Corrective Action:

Channel I of Pressurizer Level will be thoroughly examined and the cause determined and corrected at the next unit outage.

The transmitter was recalibrated, monitored and later returned to service. This channel will be monitored closely and the appropriate action taken if an intermittent drift occurs again.

6. Actions Taken to Prevent Recurrence:

It is not known at this time what actions will be necessary to prevent recurrence. If additional nonconservative drifts occur, the system will be placed in the trip mode.

7. Generic Implications:

None

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 V A S P S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0 1 L 6 0 5 0 0 0 2 8 0 7 1 1 2 1 7 8 8 1 2 1 1 7 8 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On 11/21/78, with the unit at full power, while performing PT-39.1, Snubber
0 3 1-WAPD-HSS-141B was observed with zero fluid level in the reservoir. The engineer
0 4 assisting in the test, declared the snubber inoperable. This event is reportable in
0 5 accordance with T.S. 6.6.2.b.(2). Since the snubber was replaced within the time
0 6 allowed by T.S. 3.20.B, there were no consequences and the health and safety of the
0 7 public were not affected.

0 8 9 80

0 9 SYSTEM CAUSE CAUSE COMPONENT COMP. VALVE
CODE CODE SUBCODE CODE SUBCODE SUBCODE
Z Z 11 E 12 B 13 S U P O R T 14 D 15 Z 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION
REPORT NUMBER 7 8 0 4 1 0 3 L 0
21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRO-4 PRIME COMP. COMPONENT
TAKEN ACTION ON PLANT METHOD SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
C 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 A 25 I 2 0 7 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A close inspection of the snubber revealed that the fluid had leaked out through
1 1 faulty reservoir seals. The snubber was replaced with a Q.C. accepted shop spare.
1 2
1 3
1 4 9 80

1 5 FACILITY % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
STATUS 1 0. 0 29 NA B 31 Routine Inspection 32
7 8 9 10 12 13 44 45 46 80
1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 NA 35 NA 36
7 8 9 10 11 44 45 80
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 NA
7 8 9 11 12 13 80
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 NA
7 8 9 11 12 80
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 NA
7 8 9 10 80
2 0 PUBLICITY ISSUED DESCRIPTION 45
N 44 NA
7 8 9 10 80

NRC USE ONLY

T. L. Baucom

(804) 357-3184

NAME OF PREPARER

PHONE:

Surry Power Station, Unit 1
Docket No: 50-280
Report No: 78-041/03L-0
Event Date: 11/21/78

Inoperable Snubber

1. Description of Event:

On 11/21/78, with the unit at full power, while performing PT-39.1, Snubber 1-WAPD-HSS-141B was observed with zero fluid level in the reservoir. This snubber is not listed on PT-39.1, but was observed in the course of performing PT-39.1. The engineer assisting in the test, declared the snubber inoperable. This event is reportable in accordance with T.S. 6.6.2.b.(2).

2. Probable Consequences of Event:

Tech. Spec. 3.20.B allows a period of 72 hrs. in which any snubber found to be inoperable be repaired or replaced before a power rampdown is required. Since the inoperable snubber was replaced within the allowed time, there were no consequences from this event. The health and safety of the public were not affected.

3. Cause of Event:

Upon removal from containment, a close inspection of the snubber was made and revealed that the fluid had leaked out through faulty reservoir seals.

4. Immediate Corrective Action:

The snubber was replaced with a rebuilt Q.C. accepted shop spare.

5. Subsequent Corrective Action:

None required.

6. Actions Taken to Prevent Recurrence:

All snubbers will be inspected under PT-39B at the next required inspection.

7. Generic Implications:

The snubber in question is the newer type ITT Grinnell Fig. 200 model, which comes equipped with all EPR seals. This snubber has not been reworked at the station. Therefore, it is felt that this is not a generic problem but a random failure of factory equipment.

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 V A S P S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 2 8 0 7 1 1 1 7 7 8 8 1 2 1 1 7 8 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal power operation, manual valves 1-BD-8, 18, 28 were closed in an attempt
03 to stop a leak in a service water line on which maintenance was being performed.
04 Closure of these valves terminated flow through the blowdown radiation monitors
05 (RM-SS-112, 113). This is contrary to Technical Specification 3.11.A.6 and is
06 reportable per Technical Specification 6.6.2.b.(2).
07
08

09 SYSTEM CODE H I 11 CAUSE CODE A 12 CAUSE SUBCODE A 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE P 15 VALVE SUBCODE D 16
7 8 9 10 11 12 13 14 15 16
17 LER/RO REPORT NUMBER 7 8 23 24 26 27 28 29 OCCURRENCE CODE 0 3 30 31 REPORT TYPE L 32 REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER V 1 3 5 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Operator error was the cause of the event. Upon discovery of the discrepancy the
11 immediate corrective action was to re-establish flow through the blowdown radiation
12 monitors as required by Technical Specifications.
13
14

15 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY Z 31 DISCOVERY DESCRIPTION NA 32
7 8 9 10 12 13 44 45 46 80
16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 44 45 80
17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 10 11 12 13 80
18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 10 11 12 80
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 80
20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 10 80

NRC USE ONLY

T. L. Baucom

NAME OF PREPARER

PHONE:

(804) 357-3184

Surry Power Station, Unit 1
Docket No: 50-280
Report No: 78-042/03L-0
Event Date: 11/17/78

Title of Event: Blowdown Radiation Monitors Low Flow

1. Description of Event:

During normal power operation, manual valves 1-BD-8, 18, 28 were closed in an attempt to stop a leak in a service water line on which maintenance was being performed. Closure of these valves terminated flow through the blowdown radiation monitors (RM-SS-112, 113). This is contrary to Technical Specification 3.11.A.6 and is reportable per Technical Specification 6.6.2.b.(2).

2. Probable Consequences

Flow through the blowdown radiation monitors was interrupted for four to five minutes. The backup radiation monitor in the discharge tunnel remained operational during this interrupted period. Thus, the health and safety of the general public was not affected and there are no consequences of this event.

3. Cause of Event:

Operator error was the cause of the event. The closure of other valves could have provided leak isolation without interrupting flow to the blowdown radiation monitors.

4. Immediate Corrective Actions:

Upon discovering the discrepancy, the immediate operator action was to re-establish flow to the blowdown radiation monitors as required by Technical Specifications.

5. Subsequent Corrective Actions:

Appropriate personnel have been re-instructed in this matter.

6. Actions Taken to Prevent Recurrence:

None necessary.

7. Generic Implications:

None