LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE TL REQUIRED INFORMATION) $\frac{V | A | S | P | S | 1}{LICENSEE CODE} \xrightarrow{14} 14 \xrightarrow{15} LICENSE NUMBER \xrightarrow{25} 26 \xrightarrow{16} LICENSE TYPE \xrightarrow{30} 57 \text{ CAT 56} 5$ 0 1 CON'T
REPORT
L
6
0
5
0
0
2
8
0
7
9
8
0
1
1
5
7
9
9
80
0
1
1
5
7
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9
9</ 0 1 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) potential non-conservatism has been identified in the calculations performed in 0 2 monitoring the heat flux hot channel factor, F $Q^{(Z)}$, as per T.S.3.12.B.2.b.2 0 3 The impact of this situation has been evaluated with the determination that this 0 4 event did not result in conditions in which the health and safety of the general 0 5 public was endangered. This is reportable per T.S.6.6.2.A.9. 0 6 0 7 0 8 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMP. VALVE COMPONENT CODE SUBCODE SUBCODE D (12)Z Z Z ZZ (15 9 (13) 18 SEQUENTIAL OCCURRENCE REVISION REPORT REPORT NO. CODE LER/RO NO. |0||1REPORT 0 NUMBER NPRD-4 FORM SUI SHUTDOWN PRIME COMP. COMPONENT HOURS (22) TED SUB. Z (21) 0 (20)(23) (25) (26) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) This event results from the failure of the systems and procedures used for this 1 0 surveillance to account for the effects of detector background. Immediate corrective actions were to adjust the input values used by the surveillance systems to conserva-2 tively account for this problem. 3 4 80 NA OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32) NA (31 46 80 AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) NA (33) 80 DESCRIPTION 39 12 INJURIES 80 DESCRIPTION (41) 80 NA 80 PUBLICITY NRC USE ONLY DESCRIPTION 91 7-92 68 69 80 **8°0 1**° W. L. Stewart (804) 357-3184 NAME OF PREPARER -PHONE:

Surry Power Station, Ot No. 1 Docket No. 50-280 Report No. LER 79-001/01X-0 Event Date: 01-02-79

A potential non-conservatism has been identified in the calculations performed in monitoring the heat flux channel factor, $F_Q^{(Z)}$, as per T.S.3.12.B.2.b.2.

This event is reportable under Technical Specification 6.6.2.a.9.

Probable Consequences of Occurrence

There were no adverse consequences associated with this occurrence. A review of the records has shown that for the current operating cycle detector background has been virtually non-existent. In view of these circumstances, it is concluded that the health and safety of the general public were not endangered.

Cause of Occurrence

This event results from the failure of the systems and procedures used for this surveillance to account for the effects of detector background (when present) on the process signal produced by the moveable incore detector system.

Immediate Corrective Action

Immediate corrective action was to adjust the input values used by the surveillance system to insure that the effects of this event are accounted for in a conservative manner.

Subsequent Corrective Action

The system and procedures used for this surveillance will be modified to account for detector background.

Actions Taken to Prevent Recurrence

No actions to prevent recurrence are planned since this event is nonrecurring in nature.

Generic Implications

This report is applicable to VASPS1, VASPS 2.

tachment page 1 of 1