U. S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 - 0 0 0 0 0 0 - 0 0 LICENSE NUMBER](2)[0 AS S | P 8 0 7 0 1 2 4 7 9 3 0 2 2 0 7 59 EVENT DATE 74 73 REPORT DATE REPORT 5 | î $\underline{L}(\hat{a})$ 5 0 0 0 2 SOURCE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) An error was detected in the calibration procedures for the steam flow instrumentation. 0 + 2 This resulted in an error in the high steam flow setpoint of 0.7 percent for Loop A, 3 3 3 7 1.9 percent for Loop B and 0.2 percent for Loop C at a turbine load of less than or 10111 equal to 20 percent full load. This is contrary to Technical Specifications 3.7.D 015 and is reportable as per Technical Specifications 6.6.2.b.(1). 0 15 017 80 3 а SYSTEM CAUSE CAUSE COMP. VALVE SUBCODE CODE CODE SUBCODE COMPONENT CODE SUBCODE |N|S|T|R|U|(14)D Ζ Т B (12 (13) Ι (15 ZI (16 10 12 13 18 19 SEQUENTIAL OCCURRENCE **REVISION** REPORT EVENT YEAR REPORT NO. CODE TYPE LER/RO NO. 0 3 REPORT 9 0 | 3 0 0 L NUMBER 27 26 28 30 22 32 FUTURE EFFECT ON PLANT SHUTDOWN ATTACHMENT SUBMITTED NPRD-4 PRIME COMP. COMPONENT ACTION HOURS (22) METHOD FORM SUB. SUPPLIER MANUFACTURER 0 0 Y (23) N (24) G (19 Ζ (20) Ζ (21) 0 0 2 L (25) (25 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) This event was caused by an error made when the calibration procedures were changed. 110 This resulted in a comparator offset being improperly reset. The procedures were 7 1 7 changed and the instrumentation recalibrated. 112 1 3 1-1 80 OTHER STATUS METHOD OF DISCOVERY FACILIT STATUS % POWER DISCOVERY DESCRIPTION (32) NA NA A[(31 10 13 sà ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) RELEASED OF RELEASE LOCATION OF RELEASE Z (33) Z (34 NA NA 10 80 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE (37)| 0 10 Z (38 NA 13 30 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 (40) NA 13 11 12 80 LCSS OF OR DAMAGE TO FACILITY DESCRIPTION NA 10 7902260429 30 PUBLICITY NRC USE ONLY DESCRIPTION (45) รรมยา N (44) 20-210 NA 10 63 69 80 (804) W. L. Stewart 357-3184 PHONE: NAME OF PREPARER

(Attachment, page 1 of 1)

Surry Power Station, United Docket No: 50-280 Report No: 79-003/03L-0 Event Date: 1-24-79

Title of Report: Steam Flow Instrumentation Calibration Error

1. Description of Event:

An error was detected in the calibration procedures for the steam flow instrumentation. A procedure change was made as a result of Setpoint Change 79-02, High Steam Flow Setpoint, and this change caused a comparator offset to be improperly set. This resulted in an error in the high steam flow setpoints of 0.7 percent for Loop A, 1.9 percent for Loop B, and 0.2 percent for Loop C at a turbine load of less than or equal to 20 percent full load. This is contrary to Technical Specification 3.7.D and is reportable per Technical Specification 6.6.2.b.(1).

2. Probable Consequences and Status of Redundant Systems:

This error affects the high steam flow setpoint at a turbine load of less than 20 percent and it has no effect on the setpoints from 20 to 100 percent turbine load. For the duration of this event, the unit was operating well above 90 percent turbine load, and thus was never in an unconservative operating mode. Therefore, the health and safety of the general public were not affected.

3. Cause:

This event was caused by an error made in the changing of the calibration procedure as a result of Setpoint Change 79-02.

4. Immediate Corrective Action:

The error in the calibration procedure was corrected and the steam flow instrumentation was recalibrated.

5. Subsequent Corrective Action:

No further corrective action will be required.

6. Actions Taken to Prevent Recurrence:

No further corrective action will be required to prevent recurrence.

7. Generic Implications:

None.