

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | | | | | | | | (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

3 | 1 | 1 | | V | A | S | P | S | I | | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | | 4 | | 3 |
7 3 3 14 15 25 25 33 36 36

LICENSEE CODE 14 15 LICENSE NUMBER 25 25 LICENSE TYPE 33 36 CAT 36

CONT

3 | 1 | 1 | | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 0 | 7 | 0 | 4 | 2 | 2 | 7 | 9 | 8 | 0 | 5 | 2 | 2 | 7 | 9 | 9 |
7 3 3 50 51 56 59 74 75 30

REPORT SOURCE 50 51 SOCKET NUMBER 56 59 EVENT DATE 74 75 REPORT DATE 30

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

3 | 1 | 2 | | The Liquid Waste Disposal Radiation monitor failed to give a high alarm and trip the release valve. This is contrary to Technical Specification 3.7.E Table 3.7-5, and is reportable as per Technical Specification 6.6.2.b.(4). The release did not exceed allowable limits specified in 10CFR20. Therefore, the health and safety of the public were not affected.

3 | 1 | 3 | |

3 | 1 | 9 | | M | C | 11 | | E | 12 | | E | 13 | | I | N | S | T | R | U | 14 | | E | 15 | | Z | 16 | |
7 3 9 9 10 11 12 13 18 19 20

17 | 17 | 7 | 9 | | 0 | 1 | 4 | | / | | 0 | 3 | | | L | | | 10 | |
7 3 21 22 23 24 25 27 28 29 30 31 32
ACTION TAKEN 33 34 FUTURE ACTION 35 EFFECT ON PLANT 36 SHUTDOWN METHOD 37 HOURS 40 ATTACHMENT SUBMITTED 41 NPRO-4 FORM SUB 42 PRIME COMP. SUPPLIER 43 COMPONENT MANUFACTURER 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 | 1 | 0 | | The failure of the radiation monitor alarm signal was caused by instrument drift in the high alarm setpoint. At no time were the limits of 10CFR20, Appendix B, or Technical Specification 3.11.A.1 exceeded. All liquid waste releases were secured. The alarm board was calibrated and checked. The monitor was returned to service.

1 | 1 | 5 | | G | 28 | | 0 | 0 | 0 | 29 | | Unit 2 Defueled | | A | 31 | | Operator observation | |
7 3 9 10 12 13 44 45 45 46 46

1 | 1 | 5 | | Z | 33 | | Z | 34 | | NA | | 35 | | NA | | 36 | |
7 3 9 10 11 44 45 46 80

1 | 1 | 7 | | 0 | 0 | 0 | 37 | | Z | 38 | | NA | | 39 | |
7 3 9 11 12 13 80

1 | 1 | 3 | | 0 | 0 | 0 | 40 | | | | 41 | | NA | |
7 3 9 11 12 80

1 | 1 | 3 | | Z | 42 | | | | 43 | | NA | |
7 3 9 10 80

2 | 1 | 3 | | N | 44 | | NA | | NA | | 7905250/56 | | NRC USE ONLY | |
7 3 9 10 53 59 80 80

NAME OF PREPARER W. L. Stewart

PHONE: (804) 357-3184

(Attachment, page 1 of
Surry Power Station, Unit 1
Docket No: 50-280
Report No: 79-014/03L-0
Event Date: 4-22-79

Title: Radiation Monitor RM-LW-108 Malfunction

1. Description of Event:

The Liquid Waste Disposal Radiation monitor RM-LW-108 failed to give a high alarm signal to trip the effluent discharge valve FCV-LW-104A and terminate a liquid release. This event is contrary to Technical Specification Table 3.7-5 (Alarm Setpoint). It is reportable as per Technical Specification 6.6.2.B.4.

2. Probable Consequences and Status of Redundant Systems:

The release limits delineated in Technical Specification 3.11.A (10CFR20 App. B) were not exceeded. Therefore, the health and safety of the public were not affected. The redundant discharge tunnel monitor was operable and verified no significant release occurred.

3. Cause:

The failure of the radiation monitor alarm signal was caused by instrument drift in the high alarm setpoint. At no time were the limits of 10CFR20, Appendix B, or Technical Specification 3.11.A.1 exceeded.

4. Immediate Corrective Action:

All liquid waste releases were secured. The alarm board was calibrated and checked. The monitor was returned to service.

5. Subsequent Corrective Action:

None considered necessary.

6. Actions Taken to Prevent Recurrence:

No further corrective action is required.

7. Generic Implications

None