

208/02/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)  
DISTRIBUTION FOR INCOMING MATERIAL

50-335

REC: OREILLY J P  
NRC

ORG: SCHMIDT A D  
FL PWR & LIGHT

DOCDATE: 07/13/78  
DATE RCVD: 07/31/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED

SUBJECT:

LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-335/78-022) ON 06/15/78 CONCERNING  
DURING PWR OPERATION, THE DIGITAL DATA PROCESSING SYSTEM MANFUNCTIONED, DUE  
TO MALFUNCTIONING MULTIPLEXER CARD.

PLANT NAME: ST LUCIE #1

REVIEWER INITIAL: XJM  
DISTRIBUTOR INITIAL: DL

\*\*\*\*\* DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS \*\*\*\*\*

INCIDENT REPORTS  
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ORB#4 BC\*\*W/4 ENCL

INTERNAL: REG FILE\*\*W/ENCL  
I & E\*\*W/2 ENCL  
I & C SYSTEMS BR\*\*W/ENCL  
NOVAK/CHECK\*\*W/ENCL  
AD FOR ENG\*\*W/ENCL  
HANAUER\*\*W/ENCL  
AD FOR SYS & PROJ\*\*W/ENCL  
ENGINEERING BR\*\*W/ENCL  
KREGER/J. COLLINS\*\*W/ENCL  
K SEYFRIT/IE\*\*W/ENCL

NRC PDR\*\*W/ENCL  
MIPC\*\*W/3 ENCL  
EMERGENCY PLAN BR\*\*W/ENCL  
EEB\*\*W/ENCL  
PLANT SYSTEMS BR\*\*W/ENCL  
AD FOR PLANT SYSTEMS\*\*W/ENCL  
REACTOR SAFETY BR\*\*W/ENCL  
VOLLMER/BUNCH\*\*W/ENCL  
POWER SYS BR\*\*W/ENCL

EXTERNAL: LPDR'S  
FT PIERCE, FL\*\*W/ENCL  
TIC, LIZ CARTER\*\*W/ENCL  
NSIC\*\*W/ENCL  
ACRS CAT B\*\*W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45  
SIZE: Q

CONTROL NBR: 782140096

\*\*\*\*\* THE END \*\*\*\*\*



[The page contains extremely faint, illegible text, likely bleed-through from the reverse side. Two dark circular marks are visible at the top of the page.]



PRN-LI-78-188

July 13, 1978

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 1217  
Atlanta, Georgia 30303

US NRC  
DISTRIBUTION SERVICES  
BRANCH

1978 JUL 31 AM 10 39

DISTRIBUTION  
SERVICES UNIT


Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-78-22  
ST. LUCIE UNIT 1  
DATE OF OCCURRENCE: JUNE 15, 1978

TECHNICAL SPECIFICATION 3.1.3.3  
DIGITAL DATA PROCESSING SYSTEM

The attached Licensee Event Report is being submitted  
in accordance with Technical Specification 6.9 to pro-  
vide 30-day notification of the subject occurrence.

Very truly yours,

  
A. D. Schmidt  
Vice President  
Power Resources

MAS/mal

Attachment

cc: Harold F. Reis, Esquire  
Director, Office of Inspection and Enforcement (30)  
Director, Office of Management Information and  
Program Control (3)

782140096

A002  
5/11





1

1

1

1

1

1



CONTROL BLOCK: | . | | | | | | ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	F	L	S	L	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5	
LICENSEE CODE								LICENSE NUMBER								LICENSE TYPE								CAT					
CONT		REPORT SOURCE		DOCKET NUMBER		EVENT DATE		REPORT DATE																					
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)																													
During power operation, the Digital Data Processing System (DDPS) mal-																													
functioned. This resulted in loss of CEA backup position indication and																													
the incore flux detector system used to monitor flux distribution. Ac-																													
tion required by Specifications 3.1.3.3 and 4.2.1.3 was initiated and																													
power was reduced. The DDPS was repaired and placed back into service in																													
two hours. This was the first occurrence involving loss of the DDPS due																													
to the cause described below in the Cause Description.																													
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE																													
I E 11 E 12 G 13 I N S T R U 14 Y 15 Z 16																													
LEA/RP REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.																													
7 8 0 2 2 0 3 L 0																													
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-1 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER																													
A 18 Z 19 B 20 Z 21 0 0 0 3 N 23 N 24 N 25 F 1 2 0 26																													
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																													
The cause of the DDPS failure was a malfunctioning multiplexer card.																													
The card was replaced and the DDPS returned to service in two hours.																													
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION																													
E 23 0 1 9 9 29 NA A 31 OPERATOR OBSERVATION 32																													
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE																													
Z 33 Z 34 NA NA 36																													
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION																													
0 0 0 37 38 NA																													
PERSONNEL INJURIES NUMBER DESCRIPTION																													
0 0 0 40 41 NA																													
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION																													
Z 42 43 NA																													
PUBLICITY ISSUED DESCRIPTION																													
N 44 45 NA																													
NAME OF PREPARER M. A. Schoppman PHONE: (305) 552-3802																													