

2008/02/14

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL 50-335

REC: OREILLY J P
NRC

ORG: SCHMIDT A D
FL PWR & LIGHT

DOC DATE: 07/07/78
DATE RCVD: 07/31/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-335/78-021) ON 06/08/78 CONCERNING
DURING PWR ASCENSION TESTING FOLLOWING REFUELING OUTAGE, CEA #65 DROPPED FOUR
TIMES DUE TO FAILURE OF ONE OR MORE OF ITS COIL PWR PROGRAMMER TIMING MODULE,
INTEGRAL TIMER, OR 15 VO

PLANT NAME: ST LUCIE #1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: DL

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CASE ORB#4 BC**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL
I & E**W/2 ENCL

I & C SYSTEMS BR**W/ENCL
NOVAK/CHECK**W/ENCL
AD FOR ENG**W/ENCL
HANAUER**W/ENCL
AD FOR SYS & PROJ**W/ENCL
ENGINEERING BR**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
EMERGENCY PLAN BR**W/ENCL
EEB**W/ENCL
PLANT SYSTEMS BR**W/ENCL
AD FOR PLANT SYSTEMS**W/ENCL
REACTOR SAFETY BR**W/ENCL
VOLLMER/BUNCH**W/ENCL
POWER SYS BR**W/ENCL

EXTERNAL:

LPDR'S
FT PIERCE, FL**W/ENCL
TIC, LIZ CARTER**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P+1P

CONTROL NBR: 782140095

AO 4
30


***** THE END *****

10/10/10



The following information was obtained from the records of the
 Department of the Interior, Bureau of Land Management, regarding
 the land parcels described herein. The information is being provided
 for your information and is not intended to constitute a warranty
 of any kind. The information is based on the records of the
 Department of the Interior, Bureau of Land Management, and is
 subject to change without notice. The information is provided
 as a service to the public and is not intended to constitute
 a warranty of any kind. The information is based on the records
 of the Department of the Interior, Bureau of Land Management,
 and is subject to change without notice. The information is
 provided as a service to the public and is not intended to
 constitute a warranty of any kind. The information is based on
 the records of the Department of the Interior, Bureau of Land
 Management, and is subject to change without notice. The
 information is provided as a service to the public and is not
 intended to constitute a warranty of any kind. The information
 is based on the records of the Department of the Interior,
 Bureau of Land Management, and is subject to change without
 notice. The information is provided as a service to the public
 and is not intended to constitute a warranty of any kind.

REGULATORY DOCKET FILE COPY



FLORIDA POWER & LIGHT COMPANY

July 7, 1978

PRN-LI-78-182

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 1217
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-78-21
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: JUNE 8, 1978

TECHNICAL SPECIFICATION 3.1.3.1.e
CEA 68

1978 JUL 31 AM 10 35
RECEIVED DISTRIBUTION SERVICES UNIT
US NRC DISTRIBUTION SERVICES BRANCH

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

cc: Harold F. Reis, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

782140095

*A002
5/11*



100

100

100

100

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | I | L | S | I | S | I | (2) | 0 | 0 | - | 1 | 0 | 1 | 0 | 1 | 0 | - | 1 | 0 | 1 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | 1 | (4) | (5)

CONT REPORT SOURCE (5) | 0 | 1 | 5 | 1 | 0 | 1 | 0 | 1 | 3 | 1 | 3 | 5 | (7) | 0 | 1 | 6 | 1 | 0 | 8 | 7 | 1 | 8 | (3) | 0 | 1 | 7 | 1 | 0 | 1 | 7 | 1 | 7 | 1 | 8 | (3)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 12 | During power ascension testing following a refueling outage, CEA #68
0 13 | dropped four times within an eight and one-half hour time span. After
0 14 | each of the first three drops, CEA #68 was restored to its normal position
0 15 | within the time limit required by the applicable Technical Specification
0 16 | 3.1.3.1.e action statement. After the fourth drop, CEA #68 was declared
0 17 | inoperable. Several components were replaced, after which CEA #68 was
0 18 | operated satisfactorily and declared operable.

0 9 | R | B | (11) | E | (12) | G | (13) | L | I | N | I | S | I | T | R | I | U | (14) | P | (15) | Z | (16)
17 | L | E | A | R | R | O | R | E | P | O | R | T | N | U | M | B | E | R | (17) | 7 | 1 | 8 | (18) | 0 | 2 | 1 | 1 | (19) | 0 | 3 | (20) | L | (21) | 0 | (22)
A | (18) | Z | (19) | B | (20) | Z | (21) | 0 | 1 | 0 | 1 | 5 | (22) | Y | (23) | N | (24) | N | (25) | C | 4 | 9 | 1 | 0 | (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 10 | CEA #68 dropped due to failure of one or more of its coil power programmer
1 11 | timing module, integral timer, or 15 volt power supplier. Since all three
1 12 | were replaced, it is not known which was the cause of the CEA drops. CEA
1 13 | #68 was restored to its normal position and has performed normally for four
1 14 | weeks.

1 5 | B | (28) | 0 | 8 | 1 | 0 | (29) | NA | (30) | A | (31) | Operator Observation (32)

1 15 | Z | (33) | Z | (34) | NA | (35) | NA | (36)

1 17 | 0 | 1 | 0 | 1 | 0 | (37) | Z | (38) | NA

1 18 | 0 | 1 | 0 | 1 | 0 | (40) | NA

1 19 | Z | (42) | NA

2 10 | N | (44) | NA

Additional Event Description

The coil power programmer timing module, the integral timer, and the 15 volt power supplier for CEA #68 were replaced, after which CEA #68 operated satisfactorily. CEA #68 was aligned to its normal position and power ascension testing continued.

As a result of the reactivity insertions of the dropped CEA's, azimuthal power tilt (T_q) increased and twice exceeded the limit requiring action in accordance with Technical Specification 3.2.4. Also, the total planar radial peaking factor (F_{xy}) increased and exceeded the limit requiring action in accordance with Technical Specification 3.2.2 several times. In all of the above cases, reactor power was reduced, and both T_q and F_{xy} were returned to normal within the time limits described in their respective Specifications.